

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2134  
SCHOOL NAME: Clinton School  
ADDRESS OF SCHOOL: 6110 N Fairfield Avenue  
CITY: Chicago, IL, 60645

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/1/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 1143  
IDPH INSPECTOR LICENSE NUMBER: 100-11255  
IDPH LICENSED INSPECTOR NAME(Please Print): Esteban Nunez  
IDPH MP LICENSE NUMBER: 100-04019  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): Arturo Saenz

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Clinton School**

6110 N Fairfield Avenue  
Chicago, IL, 60645

Unit: 22751  
Building ID: 2810

IDPH ID Number: 14-016-2990-2134

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**GSG-Probe Consulting, Inc.**

2942 W. Van Buren

Chicago, IL, 60612

Phone 3123197575

Fax

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

October 14, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

GSG-Probe Consulting, Inc., Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 1, 2 Elementary Schools. Please update your records with the following information.

School District: 299            Unit: 22751            Region: 01            IDPH ID:14-016-2990-2134

School: Clinton School            Building ID: 2810

Address: 6110 N Fairfield Avenue

Chicago, IL, 60645

Building Contact:

Contact Phone:

Current Building Owners: Chicago Public Schools

Review Date: 10/31/2019

Inspector: Esteban Nunez

Inspector IDPH License: 100-11255

Management Planner: Arturo Saenz

Management Planner IDPH License: 100-04019

If you have any questions or comments, please contact us at 3123197575

Sincerely,  
GSG-Probe Consulting, Inc.

Arturo Saenz  
100-04019

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: October 14, 2019

RE: Clinton School, Unit 22751  
6110 N Fairfield Avenue  
Chicago, IL, 60645

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Clinton School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Clinton School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Clinton School Unit: 22751 Region: 01  
Address: 6110 N Fairfield Avenue Chicago, IL, 60645  
IDPH ID: 14-016-2990-2134 Building ID: 2810  
Contact: Phone:

### 2. Description of Facility

Original Construction: 1926 Additional Construction: 1952,1996  
Total Square Footage: 79104 No of Floors: 2  
Current Occupancy: 1143

### 3. LEA Designated Person

Contact: Robert Christlieb Phone: (773) 553-3197  
Address: 42 West Madison Street  
Chicago, IL 60602

### 4. Managing Environmental Consultant

MEC: GSG-Probe Consulting, Inc.  
Contact: Jigar Shah  
Address 2942 W. Van Buren  
Chicago, IL, 60612  
Phone: 3123197575 Fax:

### 5. Inspector

Inspector Name: Esteban Nunez

Inspector IDPH license # 100-11255 Signature:  
Date: 10/14/2019

### 6. Management Planner

Management Planner Name: Arturo Saenz

Management Planner IDPH license # 100-04019 Signature:  
Date: 10/31/2019

### 7. Review Date:10/31/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:  Date: 10/1/2019  
Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

GSG-Probe Consulting, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Clinton School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas (HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 2810:

B. The following new homogenous areas have been identified for Building 2810:

100	Gray Carpet Mastic
101	2' x 2' White w/ Grooves Ceiling Tile
102	Blue Vinyl Stair Tread & Riser
103	Blue Vinyl Stair Tread & Riser Mastic
91	12" x 12" Gray VFT
92	12" x 12" Gray VFT Mastic
93	2' x 2' White Ceiling Tile
94	12" x 12" Blue VFT
95	12" x 12" Blue VFT Mastic
96	12" x 12" Black VFT
97	12" x 12" Black VFT Mastic
98	12" x 12" Yellow VFT
99	12" x 12" Yellow VFT Mastic



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

100	Gray Carpet Mastic
101	2' x 2' White w/ Grooves Ceiling Tile
102	Blue Vinyl Stair Tread & Riser
103	Blue Vinyl Stair Tread & Riser Mastic
40	Brown Linoleum
43	Brown Linoleum Mastic (Not observed)
60	MJP on Fiberglass Pipe Insulation
63	Exterior Window Caulk
64	Interior Window Caulk
65	Exterior Window Caulk
66	Interior Window Caulk
68	12" x 12" White w/Light Brown Streaks VFT
68A	12" x 12" White w/Light Brown Streaks VFT Mastic
69	9" x 9" Brown w/Streaks VFT
69A	9" x 9" Brown w/Streaks VFT Mastic
70	Carpet Mastic
71	12" x 12" Blue & White Streaks VFT
71A	12" x 12" Blue & White Streaks VFT Mastic
72	12" x 12" Yellow w/White Streaks VFT
72A	12" x 12" Yellow w/White Streaks VFT Mastic
73	2' x 2' Ceiling Tiles with Grooves
74	12" x 12" Light Tan w/Tan Specks Floor Tile
75	12" x 12" Light Tan w/Tan Specks Floor Tile MASTIC
76	12" x 12" Blue and White Streaks VFT
76A	12" x 12" Blue and White Streaks VFT Mastic
77	12" x 12" Yellow w/White Streaks VFT
77A	12" x 12" Yellow w/White Streaks VFT Mastic
78	12" x 12" Green VFT
78A	12" x 12" Green VFT Mastic
79	Terrazzo
80	Terrazzo
81	Fire Door
82	Spray on Gray Insulation
83	Spray on White Insulation
84	Spray on Gray Insulation
85	Spray On White Insulation
86	Tectum Panels
87	Decorative Plaster
88	16" x 16" Blue VFT
88A	16" x 16" Blue VFT Mastic
90	2' x 4' Ceiling Tile

91	12" x 12" Gray VFT
92	12" x 12" Gray VFT Mastic
93	2' x 2' White Ceiling Tile
94	12" x 12" Blue VFT
95	12" x 12" Blue VFT Mastic
96	12" x 12" Black VFT
97	12" x 12" Black VFT Mastic
98	12" x 12" Yellow VFT
99	12" x 12" Yellow VFT Mastic
KK	MJP on Fiberglass Pipe Insulation

The following areas were deemed to be inaccessible:

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Esteban Nunez, IDPH License # 100-11255. The Management Plan was updated by Arturo Saenz, IDPH License # 100-04019. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Clinton School Building 2810 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. Atimely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
100	Gray Carpet Mastic	3,600	SF	Library, Room 119, Offices 117	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
101	2' x 2' White w/ Grooves Ceiling Tile	20,000	SF	Throughout Annex	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
102	Blue Vinyl Stair Tread & Riser	1,200	SF	Stairwells - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
103	Blue Vinyl Stair Tread & Riser Mastic	1,200	SF	Stairwells - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	9"x9" Grey w/ Black Streaks VFT	380	SF	Room 114 - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
40	Brown Linoleum	1,000	SF	Room 113 - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	9"x9" Grey w/ Black Streaks VFT Mastic	380	SF	Room 114 - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	Brown Linoleum Mastic (Not observed)	1,000	SF	Room 113 - 1926 Bldg. (Not observed)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
44	12"x12" Grey VFT	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
45	12"x12" Grey VFT Mastic	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	9"x9" Light Grey VFT	600	SF	Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	9"x9" Light Grey VFT Mastic	600	SF	Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	12"x12" Tan VFT	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	12"x12" Tan VFT Mastic	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Bldg.										
52	12"x12" White w/ Brown Streaks VFT	500	SF	Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
53	12"x12" White w/ Brown Streaks VFT Mastic	500	SF	Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
54	9"x9" Grey VFT (ABATED)			1st & 2nd Fl Corridor - 1952 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
55	9"x9" Grey VFT Mastic (ABATED)			1st & 2nd Fl Corridor - 1952 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
56	9"x9" Tan VFT (ABATED)			1st & 2nd Fl Corridor - 1952 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
57	9"x9" Tan VFT Mastic (ABATED)			1st & 2nd Fl Corridor - 1952 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
58	9"x9" Tan w/ Brown Streaks VFT (ABATED)			1st Floor Corridor - 1926 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
59	9"x9" Tan w/ Brown Streaks VFT Mastic (ABATED)			1st Floor Corridor - 1926 Bldg.	ABATED	MISC						Any remaining friable ACBM or friable suspect ACBM		
60	MJP on Fiberglass Pipe Insulation	50	FITTING	Mechanical Areas, Unfinished Areas, Pipe Chases - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	Exterior Window Caulk	10,000	LF	1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	Interior Window Caulk	10,000	LF	1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Exterior Window Caulk	5,000	LF	1952 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Interior Window Caulk	5,000	SF	1952 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Aircell Duct Insulation	700	SF	North and South Unexcavated Area- 1926 Building	CHR	TSI	Y	NONE	0		Yes	ACBM with the potential for damage		LOW
68	12" x 12" White w/Light Brown Streaks VFT	30	SF	Engineer's Office Toilet - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
68A	12" x 12" White w/Light Brown Streaks VFT Mastic	30	SF	Engineer's Office Toilet - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	9" x 9" Brown w/Streaks VFT	120	SF	Engineer's Office - 1926 Bldg.	ASSUMED	MISC	N	NONE	20		No	ACBM with potential for significant damage		MODERATE
69A	9" x 9" Brown w/Streaks VFT Mastic	120	SF	Engineer's Office - 1926 Bldg.	ASSUMED	MISC	N	NONE	20		No	ACBM with potential for significant damage		MODERATE
70	Carpet Mastic	1,500	SF	Assembly Hall and Balcony - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	12" x 12" Blue & White Streaks VFT	5,000	SF	1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71A	12" x 12" Blue & White Streaks VFT Mastic	5,000	SF	1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72	12" x 12" Yellow w/White Streaks VFT	1,200	SF	1st & 2nd Floor Corridors (1926 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
72A	12" x 12" Yellow w/White Streaks VFT Mastic	1,200	SF	1st & 2nd Floor Corridors (1926 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	2' x 2' Ceiling Tiles with Grooves	120	SF	Engineer's Office and Corridor to Annex - 1926 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
74	12" x 12" Light Tan w/Tan Specks Floor Tile	1,000	SF	Main Office (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
75	12" x 12" Light Tan w/Tan Specks Floor Tile MASTIC	1,000	SF	Main Office (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76	12" x 12" Blue and White Streaks VFT	2,000	SF	1st and 2nd Floor Corridor (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
76A	12" x 12" Blue and White Streaks VFT Mastic	2,000	SF	1st and 2nd Floor Corridor (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77	12" x 12" Yellow w/White Streaks VFT	500	SF	1st and 2nd Floor Corridors (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
77A	12" x 12" Yellow w/White Streaks VFT Mastic	500	SF	1st and 2nd Floor Corridors (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
78	12" x 12" Green VFT	1,200	SF	Assembly Hall - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
78A	12" x 12" Green VFT Mastic	1,200	SF	Assembly Hall - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
79	Terrazzo	3,500	SF	All Stairwells and Vestibules; Old Boys Locker Rm. Stairs and 1st and 2nd Floor Corridor Boarders, room 200, Assembly Hall Stage Stairs and Vestibule - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
80	Terrazzo	1,000	SF	Stairwell (1952 Bldg)	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
81	Fire Door	5	EA	Auditorium, Balcony and Projector Room - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
82	Spray on Gray Insulation	4,000	SF	Attic - Building 1952	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
83	Spray on White Insulation	2,000	SF	Attic - Building 1952	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
84	Spray on Gray Insulation	15,000	SF	Attic - Building 1926	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
85	Spray On White Insulation	3,000	SF	Attic - Building 1926	ASSUMED	SURFACE	Y	NONE	0		No	ACBM with the potential for damage		LOW
86	Tectum Panels	6,000	SF	Gymnasium walls above 7 Feet from the ground	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
87	Decorative Plaster	1,000	SF	Auditorium, Stage and Balcony - 1926 Bldg.	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
88	16" x 16" Blue VFT	245	SF	Corridor to Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
88A	16" x 16" Blue VFT Mastic	245	SF	Corridor to Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
89	Carpet Mastic			Room 136 - PO, 216	NO_ACBM	MISC								
90	2' x 4' Ceiling Tile	750	SF	Room 101 - 1629 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW
91	12" x 12" Gray VFT	2,900	SF	Auditorium - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
92	12" x 12" Gray VFT Mastic	2,900	SF	Auditorium - 1926 Bldg.	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
93	2' x 2' White Ceiling Tile	5,000	SF	Gym - 1926 Bldg.	ASSUMED	MISC	Y	NONE	0		No	ACBM with the potential for damage		LOW



# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
94	12" x 12" Blue VFT	17,000	SF	1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
95	12" x 12" Blue VFT Mastic	17,000	SF	1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
96	12" x 12" Black VFT	1,500	SF	1st and 2nd Floor Corridors - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
97	12" x 12" Black VFT Mastic	1,500	SF	1st and 2nd Floor Corridors - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
98	12" x 12" Yellow VFT	3,000	SF	1st and 2nd Floor Corridors - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
99	12" x 12" Yellow VFT Mastic	3,000	SF	1st and 2nd Floor Corridors - Annex	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
A	Boiler Gasket (Boiler #1) (ABATED)			Boiler House - 1926 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
B	Boiler Lagging (Boiler #1) (ABATED)			Boiler House - 1926 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
C	Boiler Gasket (Boiler #2) (ABATED)			Boiler House - 1926 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
D	Boiler Lagging (Boiler #2) (ABATED)			Boiler House - 1926 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
G	Water Tank Insulation (ABATED)			Boiler House - 1926 Bldg.	ABATED	TSI						Any remaining friable ACBM or friable suspect ACBM		
GG	Cardboard Pipe Insulation	300	LF	Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Rm - 1952 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
H	Aircell Pipe Insulation	3,400	LF	Throughout Basement (See Hatching Maps),	CHR	TSI	Y	DIST	274		No	Damaged or significantly damaged friable thermal system	3	MODERATE

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.								insulating ACBM		
HH	Preform Pipe Insulation (Mag)	870	LF	Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Room - 1952 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
I	Preform (Mag Block) Pipe Insulation	600	LF	Boiler House, Throughout Basement (See Hatching Maps) - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
II	MJP on Preform Pipe Insulation (Mag)	110	FITTING	Throughout Basement (See Hatching Maps) - 1952 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Cardboard Pipe Insulation	850	LF	1st Floor Boys/Girls Bathroom Pipe Chases, Tunnels, Unex. Areas, Throughout Basement (See Hatching Maps) - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
JJ	MJP on Cardboard Pipe Insulation	140	FITTING	Throughout Basement (See Hatching Maps), SW Unexcavated Area - 1952 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE
K	MJP on Cardboard Pipe Insulation	125	FITTING	Boiler House, Throughout Basement (See Hatching Maps), Room 100 & Pipe Chases - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
KK	MJP on Fiberglass Pipe Insulation	60	FITTING	Unfinished Pipe Space - 1952 Bldg.	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
S	MJP on Aircell Pipe Insulation	350	FITTING	Throughout Basement (See Hatching Maps).	CHR	TSI	Y	DIST	67		No	Damaged or significantly damaged friable thermal system	3	MODERATE

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.								insulating ACBM		
Y	MJP on Mag Block Pipe Insulation	70	FITTING	Boiler House, Tunnels, Unex. Areas, Throughout Basement(See Hatching Maps) - 1926 Bldg.	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		MODERATE

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>10/14/2019</b>
Inspector Name <b>Esteban Nunez</b>
<b>100-11255</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

### Inspector's Comments

HA Number:	Inspector Comments:
100	
101	
102	
103	
39	
40	
42	
43	possibly under blue floor tile
44	
45	
46	
47	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
63	
64	
65	
66	
67	Repaired
68	
68A	
69	Damage in Engineer's Office
69A	Damage in Engineer's Office
70	
71	
71A	
72	
72A	
73	
74	
75	
76	
76A	
77	
77A	
78	
78A	
79	
80	
81	
82	
83	
84	

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
85	
86	
87	
88	
88A	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
G	
GG	
H	
HH	
I	
II	
J	
JJ	
K	

# Chicago Public Schools

School Clinton School Unit 22751 Building ID 2810

Address 6110 N Fairfield Avenue Region 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
KK	
S	Damage in Boiler room, Engine room, North/South Air Tunnel, South Fan room
Y	

**Table II**

**Management Planner's Review**

---



# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
100	Gray Carpet Mastic	3,600	SF	Library, Room 119, Offices 117	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
101	2' x 2' White w/ Grooves Ceiling Tile	20,000	SF	Throughout Annex	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
102	Blue Vinyl Stair Tread & Riser	1,200	SF	Stairwells - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
103	Blue Vinyl Stair Tread & Riser Mastic	1,200	SF	Stairwells - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	9"x9" Grey w/ Black Streaks VFT	380	SF	Room 114 - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	Brown Linoleum	1,000	SF	Room 113 - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	9"x9" Grey w/ Black Streaks VFT Mastic	380	SF	Room 114 - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	Brown Linoleum Mastic (Not observed)	1,000	SF	Room 113 - 1926 Bldg. (Not observed)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
44	12"x12" Grey VFT	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
45	12"x12" Grey VFT Mastic	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	9"x9" Light Grey VFT	600	SF	Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	9"x9" Light Grey VFT Mastic	600	SF	Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	12"x12" Tan VFT	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
51	12"x12" Tan VFT Mastic	3,800	SF	Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
52	12"x12" White w/ Brown Streaks VFT	500	SF	Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
53	12"x12" White w/ Brown Streaks VFT Mastic	500	SF	Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
54	9"x9" Grey VFT (ABATED)			1st & 2nd FI Corridor - 1952 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
55	9"x9" Grey VFT Mastic (ABATED)			1st & 2nd FI Corridor - 1952 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
56	9"x9" Tan VFT (ABATED)			1st & 2nd FI Corridor - 1952 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
57	9"x9" Tan VFT Mastic (ABATED)			1st & 2nd FI Corridor - 1952 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
										suspect ACBM	
58	9"x9" Tan w/ Brown Streaks VFT (ABATED)			1st Floor Corridor - 1926 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
59	9"x9" Tan w/ Brown Streaks VFT Mastic (ABATED)			1st Floor Corridor - 1926 Bldg.	Abated	MISC				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
60	MJP on Fiberglass Pipe Insulation	50	FITTING	Mechanical Areas, Unfinished Areas, Pipe Chases - 1926 Bldg.	Assumed	MISC	No	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
63	Exterior Window Caulk	10,000	LF	1926 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
64	Interior Window Caulk	10,000	LF	1926 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
65	Exterior Window Caulk	5,000	LF	1952 Bldg.	Assumed	MISC	No	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
66	Interior Window Caulk	5,000	SF	1952 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Aircell Duct Insulation	700	SF	North and South Unexcavated Area- 1926 Building	Chrysotile	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	12" x 12" White w/Light Brown Streaks VFT	30	SF	Engineer's Office Toilet - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68A	12" x 12" White w/Light Brown Streaks VFT Mastic	30	SF	Engineer's Office Toilet - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	9" x 9" Brown w/Streaks VFT	120	SF	Engineer's Office - 1926 Bldg.	Assumed	MISC	No	20	SF	5 ACBM with potential for significant damage	Follow O&M Plan
69A	9" x 9" Brown w/Streaks VFT Mastic	120	SF	Engineer's Office - 1926 Bldg.	Assumed	MISC	No	20	SF	5 ACBM with potential for significant damage	Follow O&M Plan
70	Carpet Mastic	1,500	SF	Assembly Hall and Balcony - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	12" x 12" Blue & White Streaks VFT	5,000	SF	1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71A	12" x 12" Blue & White Streaks VFT Mastic	5,000	SF	1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72	12" x 12" Yellow w/White Streaks VFT	1,200	SF	1st & 2nd Floor Corridors (1926 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
72A	12" x 12" Yellow w/White Streaks VFT Mastic	1,200	SF	1st & 2nd Floor Corridors (1926 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	2' x 2' Ceiling Tiles with Grooves	120	SF	Engineer's Office and Corridor to Annex - 1926 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
74	12" x 12" Light Tan w/Tan Specks Floor Tile	1,000	SF	Main Office (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12" x 12" Light Tan w/Tan Specks Floor Tile MASTIC	1,000	SF	Main Office (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12" x 12" Blue and White Streaks VFT	2,000	SF	1st and 2nd Floor Corridor (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
76A	12" x 12" Blue and White Streaks VFT Mastic	2,000	SF	1st and 2nd Floor Corridor (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	12" x 12" Yellow w/White Streaks VFT	500	SF	1st and 2nd Floor Corridors (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77A	12" x 12" Yellow w/White Streaks VFT Mastic	500	SF	1st and 2nd Floor Corridors (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12" x 12" Green VFT	1,200	SF	Assembly Hall - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78A	12" x 12" Green VFT Mastic	1,200	SF	Assembly Hall - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	Terrazzo	3,500	SF	All Stairwells and Vestibules; Old Boys Locker Rm, Stairs and 1st and 2nd Floor Corridor Boarders, room 200, Assembly Hall Stage Stairs and Vestibule - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
80	Terrazzo	1,000	SF	Stairwell (1952 Bldg)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
81	Fire Door	5	EA	Auditorium, Balcony and Projector Room - 1926 Bldg.	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
82	Spray on Gray Insulation	4,000	SF	Attic - Building 1952	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
83	Spray on White Insulation	2,000	SF	Attic - Building 1952	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
84	Spray on Gray Insulation	15,000	SF	Attic - Building 1926	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
85	Spray On White Insulation	3,000	SF	Attic - Building 1926	Assumed	SURFACE	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
86	Tectum Panels	6,000	SF	Gymnasium walls above 7 Feet from the ground	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
87	Decorative Plaster	1,000	SF	Auditorium, Stage and Balcony - 1926 Bldg.	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88	16" x 16" Blue VFT	245	SF	Corridor to Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
88A	16" x 16" Blue VFT Mastic	245	SF	Corridor to Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
89	Carpet Mastic			Room 136 - PO, 216	No ACBM	MISC					
90	2' x 4' Ceiling Tile	750	SF	Room 101 - 1629 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
91	12" x 12" Gray VFT	2,900	SF	Auditorium - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
92	12" x 12" Gray VFT Mastic	2,900	SF	Auditorium - 1926 Bldg.	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
93	2' x 2' White Ceiling Tile	5,000	SF	Gym - 1926 Bldg.	Assumed	MISC	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
94	12" x 12" Blue VFT	17,000	SF	1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
95	12" x 12" Blue VFT Mastic	17,000	SF	1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
96	12" x 12" Black VFT	1,500	SF	1st and 2nd Floor Corridors - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
97	12" x 12" Black VFT Mastic	1,500	SF	1st and 2nd Floor Corridors - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
98	12" x 12" Yellow VFT	3,000	SF	1st and 2nd Floor Corridors - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
99	12" x 12" Yellow VFT Mastic	3,000	SF	1st and 2nd Floor Corridors - Annex	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Boiler Gasket (Boiler #1) (ABATED)			Boiler House - 1926 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Boiler Lagging (Boiler #1) (ABATED)			Boiler House - 1926 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
C	Boiler Gasket (Boiler #2) (ABATED)			Boiler House - 1926 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
D	Boiler Lagging (Boiler #2) (ABATED)			Boiler House - 1926 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
G	Water Tank Insulation (ABATED)			Boiler House - 1926 Bldg.	Abated	TSI				7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
GG	Cardboard Pipe Insulation	300	LF	Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Rm - 1952 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
H	Aircell Pipe Insulation	3,400	LF	Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.	Chrysotile	TSI	Yes	274	LF	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
HH	Preform Pipe Insulation (Mag)	870	LF	Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Room - 1952 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
I	Preform (Mag Block) Pipe Insulation	600	LF	Boiler House, Throughout Basement (See Hatching Maps) - 1926 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
II	MJP on Preform Pipe Insulation (Mag)	110	FITTING	Throughout Basement (See Hatching Maps) - 1952 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
J	Cardboard Pipe Insulation	850	LF	1st Floor Boys/Girls Bathroom Pipe Chases, Tunnels, Unex. Areas, Throughout Basement (See Hatching Maps) -1926 Bldg.	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
JJ	MJP on Cardboard Pipe Insulation	140	FITTING	Throughout Basement (See Hatching Maps), SW Unexcavated Area - 1952 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
 Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.

2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575

Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
K	MJP on Cardboard Pipe Insulation	125	FITTING	Boiler House, Throughout Basement (See Hatching Maps), Room 100 & Pipe Chases - 1926 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
KK	MJP on Fiberglass Pipe Insulation	60	FITTING	Unfinished Pipe Space - 1952 Bldg.	Assumed	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan
S	MJP on Aircell Pipe Insulation	350	FITTING	Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.	Chrysotile	TSI	Yes	67	FITTING	1 Damaged or significantly damaged friable thermal system insulating ACBM	Repair
Y	MJP on Mag Block Pipe Insulation	70	FITTING	Boiler House, Tunnels, Unex. Areas, Throughout Basement(See Hatching Maps) - 1926 Bldg.	Chrysotile	TSI	Yes	0	FITTING	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
 Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
 2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

*Management Planner's Comments Summarized at the End of the Report*

Review Date	10/31/2019
Manager Planner Name	Arturo Saenz
100-04019	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
100	
101	
102	
103	
39	
40	
42	
43	
44	
45	
46	
47	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	
60	

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
63	
64	
65	
66	
67	
68	
68A	
69	
69A	
70	
71	
71A	
72	
72A	
73	
74	
75	
76	
76A	
77	
77A	
78	
78A	
79	
80	
81	

# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
82	
83	
84	
85	
86	
87	
88	
88A	
89	
90	
91	
92	
93	
94	
95	
96	
97	
98	
99	
A	
B	
C	
D	
G	
GG	
H	Repair Damaged ACM



# Chicago Public Schools

**School** Clinton School  
**Address** 6110 N Fairfield Avenue

**Unit** 22751  
Chicago, IL, 60645

**Building ID** 2810  
**Region** 01

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** GSG-Probe Consulting, Inc.  
2942 W. Van Buren Chicago, IL, 60612

Phone: 3123197575 Fax:

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
HH	
I	
II	
J	
JJ	
K	
KK	
S	Isolate and Repair
Y	

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ Black Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Room 114 - 1926 Bldg.**

MATERIAL QUANTITY: **380**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ Black Streaks VFT**  
MATERIAL LOCATION: **Room 114 - 1926 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 113 - 1926 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **Brown Linoleum**  
MATERIAL LOCATION: **Room 113 - 1926 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ Black Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 114 - 1926 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **9"x9" Grey w/ Black Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 114 - 1926 Bldg.**  
MATERIAL QUANTITY: **380** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic (Not observed)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 113 - 1926 Bldg. (Not observed)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS: **possibly under blue floor tile**

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **Brown Linoleum Mastic (Not observed)**  
MATERIAL LOCATION: **Room 113 - 1926 Bldg. (Not observed)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12"x12" Grey VFT Mastic**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9"x9" Light Grey VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **9"x9" Light Grey VFT**  
MATERIAL LOCATION: **Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9"x9" Light Grey VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **9"x9" Light Grey VFT Mastic**  
MATERIAL LOCATION: **Room 104, 104 Storeroom - 1926 Bldg. (under existing floor tile)**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **12"x12" Tan VFT Mastic**  
MATERIAL LOCATION: **Rooms 238, 235, 232, 234, 236, 231, 135, 133, 131, 138, 132, 233- 1952 Bldg.**  
MATERIAL QUANTITY: **3800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks VFT**  
MATERIAL LOCATION: **Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **12"x12" White w/ Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Room 104 (under existing VFT) Room 214 Storage - 1926 Bldg.**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **9"x9" Grey VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9"x9" Grey VFT (ABATED)**

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **9"x9" Grey VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **9"x9" Grey VFT Mastic (ABATED)**

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **56**

MATERIAL DESCRIPTION: **9"x9" Tan VFT (ABATED)**

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **57**

MATERIAL DESCRIPTION: **9"x9" Tan VFT Mastic (ABATED)**

MATERIAL LOCATION: **1st & 2nd FI Corridor - 1952 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown Streaks VFT (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **58**

MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown Streaks VFT (ABATED)**

MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown Streaks VFT Mastic (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **59**

MATERIAL DESCRIPTION: **9"x9" Tan w/ Brown Streaks VFT Mastic (ABATED)**

MATERIAL LOCATION: **1st Floor Corridor - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Mechanical Areas, Unfinished Areas, Pipe Chases - 1926 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Mechanical Areas, Unfinished Areas, Pipe Chases - 1926 Bldg.**  
MATERIAL QUANTITY: **50** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
MATERIAL LOCATION: **1926 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
MATERIAL LOCATION: **1926 Bldg.**  
MATERIAL QUANTITY: **10000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1952 Bldg.**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Exterior Window Caulk**  
MATERIAL LOCATION: **1952 Bldg.**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1952 Bldg.**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Interior Window Caulk**  
MATERIAL LOCATION: **1952 Bldg.**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **North and South Unexcavated Area- 1926 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **Repaired**

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Aircell Duct Insulation**  
MATERIAL LOCATION: **North and South Unexcavated Area- 1926 Building**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" White w/Light Brown Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office Toilet - 1926 Bldg.**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **12" x 12" White w/Light Brown Streaks VFT**  
MATERIAL LOCATION: **Engineer's Office Toilet - 1926 Bldg.**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68A**  
MATERIAL DESCRIPTION: **12" x 12" White w/Light Brown Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office Toilet - 1926 Bldg.**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **68A**  
MATERIAL DESCRIPTION: **12" x 12" White w/Light Brown Streaks VFT Mastic**  
MATERIAL LOCATION: **Engineer's Office Toilet - 1926 Bldg.**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **5 Damaged or significantly damaged friable misc. ACBM**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Engineer's Office**

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT**  
MATERIAL LOCATION: **Engineer's Office - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69A**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Engineer's Office - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**  
COMMENTS: **Damage in Engineer's Office**

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **69A**  
MATERIAL DESCRIPTION: **9" x 9" Brown w/Streaks VFT Mastic**  
MATERIAL LOCATION: **Engineer's Office - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **20** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall and Balcony - 1926 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
MATERIAL LOCATION: **Assembly Hall and Balcony - 1926 Bldg.**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12" x 12" Blue & White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **12" x 12" Blue & White Streaks VFT**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71A**  
MATERIAL DESCRIPTION: **12" x 12" Blue & White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **71A**  
MATERIAL DESCRIPTION: **12" x 12" Blue & White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors, Rooms 100, 104, 213, 215 (1926 Bldg)**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors (1926 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **72**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors (1926 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **72A**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors (1926 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **72A**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st & 2nd Floor Corridors (1926 Bldg)**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tiles with Grooves**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Engineer's Office and Corridor to Annex - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **2' x 2' Ceiling Tiles with Grooves**  
MATERIAL LOCATION: **Engineer's Office and Corridor to Annex - 1926 Bldg.**  
MATERIAL QUANTITY: **120** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Tan w/Tan Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **12" x 12" Light Tan w/Tan Specks Floor Tile**  
MATERIAL LOCATION: **Main Office (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12" x 12" Light Tan w/Tan Specks Floor Tile MASTIC**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Main Office (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12" x 12" Light Tan w/Tan Specks Floor Tile MASTIC**  
MATERIAL LOCATION: **Main Office (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12" x 12" Blue and White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor (1952 Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12" x 12" Blue and White Streaks VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor (1952 Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76A**  
MATERIAL DESCRIPTION: **12" x 12" Blue and White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor (1952 Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **76A**  
MATERIAL DESCRIPTION: **12" x 12" Blue and White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridor (1952 Bldg)**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Coridors (1952 Bldg)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Coridors (1952 Bldg)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77A**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1st and 2nd Floor Coridors (1952 Bldg)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **77A**  
MATERIAL DESCRIPTION: **12" x 12" Yellow w/White Streaks VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Coridors (1952 Bldg)**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall - 1926 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT**  
MATERIAL LOCATION: **Assembly Hall - 1926 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78A**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Assembly Hall - 1926 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **78A**  
MATERIAL DESCRIPTION: **12" x 12" Green VFT Mastic**  
MATERIAL LOCATION: **Assembly Hall - 1926 Bldg.**  
MATERIAL QUANTITY: **1200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **All Stairwells and Vestibules; Old Boys Locker Rm, Stairs and 1st and 2nd Floor Corridor Boarders, room 200, Assembly Hall Stage Stairs and Vestibule - 1926 Bldg.**

MATERIAL QUANTITY: **3500** MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **79**

MATERIAL DESCRIPTION: **Terrazzo**

MATERIAL LOCATION: **All Stairwells and Vestibules; Old Boys Locker Rm, Stairs and 1st and 2nd Floor Corridor Boarders, room 200, Assembly Hall Stage Stairs and Vestibule - 1926 Bldg.**

MATERIAL QUANTITY: **3500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Terrazzo**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Stairwell (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **80**  
MATERIAL DESCRIPTION: **Terrazzo**  
MATERIAL LOCATION: **Stairwell (1952 Bldg)**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Fire Door**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Balcony and Projector Room - 1926 Bldg.**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **81**  
MATERIAL DESCRIPTION: **Fire Door**  
MATERIAL LOCATION: **Auditorium, Balcony and Projector Room - 1926 Bldg.**  
MATERIAL QUANTITY: **5** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Spray on Gray Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic - Building 1952**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **82**  
MATERIAL DESCRIPTION: **Spray on Gray Insulation**  
MATERIAL LOCATION: **Attic - Building 1952**  
MATERIAL QUANTITY: **4000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **Spray on White Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic - Building 1952**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **83**  
MATERIAL DESCRIPTION: **Spray on White Insulation**  
MATERIAL LOCATION: **Attic - Building 1952**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Spray on Gray Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic - Building 1926**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **84**  
MATERIAL DESCRIPTION: **Spray on Gray Insulation**  
MATERIAL LOCATION: **Attic - Building 1926**  
MATERIAL QUANTITY: **15000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **Spray On White Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Attic - Building 1926**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **85**  
MATERIAL DESCRIPTION: **Spray On White Insulation**  
MATERIAL LOCATION: **Attic - Building 1926**  
MATERIAL QUANTITY: **3000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **Tectum Panels**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Gymnasium walls above 7 Feet from the ground**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **86**  
MATERIAL DESCRIPTION: **Tectum Panels**  
MATERIAL LOCATION: **Gymnasium walls above 7 Feet from the ground**  
MATERIAL QUANTITY: **6000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Auditorium, Stage and Balcony - 1926 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **87**  
MATERIAL DESCRIPTION: **Decorative Plaster**  
MATERIAL LOCATION: **Auditorium, Stage and Balcony - 1926 Bldg.**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **16" x 16" Blue VFT**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor to Annex**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **88**  
MATERIAL DESCRIPTION: **16" x 16" Blue VFT**  
MATERIAL LOCATION: **Corridor to Annex**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **88A**  
MATERIAL DESCRIPTION: **16" x 16" Blue VFT Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Corridor to Annex**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **88A**  
MATERIAL DESCRIPTION: **16" x 16" Blue VFT Mastic**  
MATERIAL LOCATION: **Corridor to Annex**  
MATERIAL QUANTITY: **245** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **89**  
MATERIAL DESCRIPTION: **Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **No ACBM** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Room 136 - PO, 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **89**

MATERIAL DESCRIPTION: **Carpet Mastic**

MATERIAL LOCATION: **Room 136 - PO, 216**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Room 101 - 1629 Bldg.**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **90**  
MATERIAL DESCRIPTION: **2' x 4' Ceiling Tile**  
MATERIAL LOCATION: **Room 101 - 1629 Bldg.**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Boiler Gasket (Boiler #1) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **A**

MATERIAL DESCRIPTION: **Boiler Gasket (Boiler #1) (ABATED)**

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Boiler Lagging (Boiler #1) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Boiler Lagging (Boiler #1) (ABATED)**  
MATERIAL LOCATION: **Boiler House - 1926 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Boiler Gasket (Boiler #2) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **C**

MATERIAL DESCRIPTION: **Boiler Gasket (Boiler #2) (ABATED)**

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Lagging (Boiler #2) (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Boiler Lagging (Boiler #2) (ABATED)**

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Water Tank Insulation (ABATED)**  
HISTORICAL AHERA DAMAGE CATEGORY **7**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7**. **Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **Boiler House - 1926 Bldg.**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **G**  
MATERIAL DESCRIPTION: **Water Tank Insulation (ABATED)**  
MATERIAL LOCATION: **Boiler House - 1926 Bldg.**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Rm - 1952 Bldg.**

MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **GG**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Rm - 1952 Bldg.**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest.,  
Tunnels & Unex. Area - 1926 Bldg.**  
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **274** DAMAGE UNITS: **LF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.**  
MATERIAL QUANTITY: **3400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **274** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Repair Damaged ACM

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation (Mag)**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Room - 1952 Bldg.**

MATERIAL QUANTITY: **870** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **HH**  
MATERIAL DESCRIPTION: **Preform Pipe Insulation (Mag)**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unex. Area, Unfin. Pipe Space, Storage Room - 1952 Bldg.**  
MATERIAL QUANTITY: **870** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Preform (Mag Block) Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **Boiler House, Throughout Basement (See Hatching Maps) - 1926 Bldg.**

MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Preform (Mag Block) Pipe Insulation**  
MATERIAL LOCATION: **Boiler House, Throughout Basement (See Hatching Maps) - 1926 Bldg.**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **MJP on Preform Pipe Insulation (Mag)**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps) - 1952 Bldg.**  
MATERIAL QUANTITY: **110** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **II**  
MATERIAL DESCRIPTION: **MJP on Preform Pipe Insulation (Mag)**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps) - 1952 Bldg.**  
MATERIAL QUANTITY: **110** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **1st Floor Boys/Girls Bathroom Pipe Chases, Tunnels, Unex. Areas, Throughout Basement (See Hatching Maps) -1926 Bldg.**

MATERIAL QUANTITY: **850** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1st Floor Boys/Girls Bathroom Pipe Chases, Tunnels, Unex. Areas, Throughout Basement (See Hatching Maps) -1926 Bldg.**  
MATERIAL QUANTITY: **850** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **JJ**  
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unexcavated Area - 1952 Bldg.**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **JJ**  
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), SW Unexcavated Area - 1952 Bldg.**  
MATERIAL QUANTITY: **140** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Boiler House, Throughout Basement (See Hatching Maps), Room 100 & Pipe Chases - 1926 Bldg.**  
MATERIAL QUANTITY: **125** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **MJP on Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Boiler House, Throughout Basement (See Hatching Maps), Room 100 & Pipe Chases - 1926 Bldg.**  
MATERIAL QUANTITY: **125** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **KK**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Unfinished Pipe Space - 1952 Bldg.**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **KK**  
MATERIAL DESCRIPTION: **MJP on Fiberglass Pipe Insulation**  
MATERIAL LOCATION: **Unfinished Pipe Space - 1952 Bldg.**  
MATERIAL QUANTITY: **60** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **1 Damaged or significantly damaged friable thermal system insulating ACBM**  
HISTORICAL DAMAGE REASON: **Deterioration  
Delamination**  
HISTORICAL RESPONSE ACTION: **Repair**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **1. Damaged or significantly damaged friable thermal system insulating ACBM**

DAMAGE REASON: **Deterioration**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest.,  
Tunnels & Unex. Area - 1926 Bldg.**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **67** DAMAGE UNITS: **FITTING**  
COMMENTS: **Damage in Boiler room, Engine room, North/South Air Tunnel, South Fan room**

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **MJP on Aircell Pipe Insulation**  
MATERIAL LOCATION: **Throughout Basement (See Hatching Maps), Room 100, Assembly Hall NW Vest., Tunnels & Unex. Area - 1926 Bldg.**  
MATERIAL QUANTITY: **350** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **67** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Repair**

Comments:

Isolate and Repair

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School** INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **MJP on Mag Block Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **MODERATE**

MATERIAL LOCATION: **Boiler House, Tunnels, Unex. Areas, Throughout Basement(See Hatching Maps) - 1926 Bldg.**

MATERIAL QUANTITY: **70** MATERIAL UNITS: **FITTING**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUIDLING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **MJP on Mag Block Pipe Insulation**  
MATERIAL LOCATION: **Boiler House, Tunnels, Unex. Areas, Throughout Basement(See Hatching Maps) - 1926 Bldg.**  
MATERIAL QUANTITY: **70** MATERIAL UNITS: **FITTING**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **FITTING**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **98**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **103**  
MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread & Riser Mastic**  
MATERIAL LOCATION: **Stairwells - Annex**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **103**

MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread & Riser Mastic**

MATERIAL LOCATION: **Stairwells - Annex**

MATERIAL QUANTITY: **1200**      MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
MATERIAL LOCATION: **Library, Room 119, Offices 117**  
MATERIAL QUANTITY: **3600**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **100**  
MATERIAL DESCRIPTION: **Gray Carpet Mastic**  
MATERIAL LOCATION: **Library, Room 119, Offices 117**  
MATERIAL QUANTITY: **3600**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **91**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT**  
MATERIAL LOCATION: **Auditorium - 1926 Bldg.**  
MATERIAL QUANTITY: **2900** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**





# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **92**  
MATERIAL DESCRIPTION: **12" x 12" Gray VFT Mastic**  
MATERIAL LOCATION: **Auditorium - 1926 Bldg.**  
MATERIAL QUANTITY: **2900**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**  
MATERIAL LOCATION: **Gym - 1926 Bldg.**  
MATERIAL QUANTITY: **5000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **93**  
MATERIAL DESCRIPTION: **2' x 2' White Ceiling Tile**  
MATERIAL LOCATION: **Gym - 1926 Bldg.**  
MATERIAL QUANTITY: **5000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**      INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **94**

MATERIAL DESCRIPTION: **12" x 12" Blue VFT**

MATERIAL LOCATION: **1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex**

MATERIAL QUANTITY: **17000**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE REASON:

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **94**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex**  
MATERIAL QUANTITY: **17000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**      INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **95**

MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic**

MATERIAL LOCATION: **1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex**

MATERIAL QUANTITY: **17000**      MATERIAL UNITS: **SF**

MATERIAL CATEGORY: **MISC**      FRIABLE:

ASBESTOS TYPE: **Assumed**

DISTURBANCE POTENTIAL: **LOW**      CONDITION:

AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**

ACCESSIBILITY: **Within Reach**      DAMAGE REASON:  
DAMAGE REASON:  
DAMAGE REASON:

DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **95**  
MATERIAL DESCRIPTION: **12" x 12" Blue VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors; Rooms 118, 121, 122, 123, 125, 217, 218, 220, 221, 222, 223, 224, 225, 226 - Annex**  
MATERIAL QUANTITY: **17000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**    REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **97**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **3000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **99**  
MATERIAL DESCRIPTION: **12" x 12" Yellow VFT Mastic**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **3000**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **1500**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **96**  
MATERIAL DESCRIPTION: **12" x 12" Black VFT**  
MATERIAL LOCATION: **1st and 2nd Floor Corridors - Annex**  
MATERIAL QUANTITY: **1500**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **2' x 2' White w/ Grooves Ceiling Tile**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY: **20000**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 10/14/2019

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **22751** BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School** REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue** IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **101**  
MATERIAL DESCRIPTION: **2' x 2' White w/ Grooves Ceiling Tile**  
MATERIAL LOCATION: **Throughout Annex**  
MATERIAL QUANTITY: **20000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (New Homogeneous Area)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **22751**    BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Esteban Nunez**  
SCHOOL NAME: **Clinton School**    INSPECTION DATE: **10/14/2019**  
ADDRESS: **6110 N Fairfield Avenue**    IDPH LICENSE NO: **100-11255**

---

### INFORMATION FROM CURRENT INSPECTION

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread & Riser**  
MATERIAL LOCATION: **Stairwells - Annex**  
MATERIAL QUANTITY: **1200**    MATERIAL UNITS: **SF**  
MATERIAL CATEGORY: **MISC**    FRIABLE:  
ASBESTOS TYPE: **Assumed**  
DISTURBANCE POTENTIAL: **LOW**    CONDITION:  
AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
ACCESSIBILITY: **Within Reach**    DAMAGE REASON:  
DAMAGE QUANTITY: **0**    DAMAGE REASON:  
DAMAGE UNITS: **SF**  
COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

GSG-Probe Consulting, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools**      UNIT NUMBER: **22751**      BUILDING ID: **2810**  
CITY/STATE: **Chicago, Illinois**      MANAGEMENT PLANNER: **Arturo Saenz**  
SCHOOL NAME: **Clinton School**      REVIEW DATE: **10/31/2019**  
ADDRESS: **6110 N Fairfield Avenue**      IDPH LICENSE NO: **100-11255**

HOMOGENEOUS AREA: **102**  
MATERIAL DESCRIPTION: **Blue Vinyl Stair Tread & Riser**  
MATERIAL LOCATION: **Stairwells - Annex**  
MATERIAL QUANTITY: **1200**      MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**      DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

COMMENTS:

Management Planner's Signature: \_\_\_\_\_ Date: **10/31/2019**

# Chicago Public Schools

GSG-Probe Consulting, Inc.

*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ESTEBAN NUNEZ  
has completed the ASBESTOS INSPECTOR'S REFRESHER course and successfully passed the  
examination on 02/09/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.



02/09/2019

Course Dates:

02/09/2020

Expires:

1902BIR20

Certificate Number:

Director of Training  
Nicholas J. Peneff  
Doctor of Public Health

Phone: 312-491-0081

FORM # A-010B



525-535 West Jefferson Street • Springfield, Illinois 62761-0001 • [www.dph.illinois.gov](http://www.dph.illinois.gov)

**ESTEBAN NUNEZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612

4/19/2019

ASBESTOS PROFESSIONAL LICENSE ID NUMBER: 11255

Enclosed is your Asbestos Professional License. Please note the expiration date on the card and in the image depicted below.

**COPY OF THE ASBESTOS PROFESSIONAL LICENSE**

Front of License

Back of License

FRONT OF LICENSE		BACK OF LICENSE	
	<b>ASBESTOS PROFESSIONAL LICENSE</b>	<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER 100 - 11255	ISSUED 4/19/2019	INSPECTOR	2/9/2020
ESTEBAN NUNEZ 2942 W VAN BUREN ST CHICAGO, IL 60612 Environmental Health	EXPIRES 05/15/2020 	PROJECT MANAGER AIR SAMPLING PROFESSIONAL	9/15/2019
		<b>Alteration of this license shall result in legal action</b> This license issued under authority of the State of Illinois Department of Public Health This license is valid only when accompanied by a valid training course certificate.	

If you have any questions or need further assistance, contact the Asbestos Program at (217)782-3517 or fax (217)785-5897.

Our WEB address is: [dph.illinois.gov/topics-services/environmental-health-protection/asbestos](http://dph.illinois.gov/topics-services/environmental-health-protection/asbestos)  
EMAIL Address: [dph.asbestos@illinois.gov](mailto:dph.asbestos@illinois.gov)

**PROTECTING HEALTH, IMPROVING LIVES**  
*Nationally Accredited by PHAB*

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**Arturo Saenz**

has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 2/28/2019

Exam Date: 2/28/2019

Expiration Date: 2/28/2020

Certificate Number: MPR1902280693

---

Kathy DeSalvo, Director



**ASBESTOS  
PROFESSIONAL  
LICENSE**

<b>ID NUMBER</b>	<b>ISSUED</b>	<b>EXPIRES</b>
100 - 04019	4/30/2019	05/15/2020

**ARTURO SAENZ**  
2942 W VAN BUREN ST  
CHICAGO, IL 60612  
Environmental Health



**ENDORSEMENTS**

**TC EXPIRES**

INSPECTOR	2/28/2020
MANAGEMENT PLANNER	2/28/2020

AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health  
This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---



# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed