

**ILLINOIS DEPARTMENT OF PUBLIC HEALTH  
AHERA THREE YEAR REINSPECTION  
ASBESTOS ABATEMENT PROGRAM  
SCHOOL INFORMATION FORM**

**SECTION I**

NAME OF SCHOOL DISTRICT: CHICAGO SCHOOL DIST 299  
SCHOOL ID NUMBER: 14-016-2990-2484  
SCHOOL NAME: Thorp School  
ADDRESS OF SCHOOL: 8914 S Buffalo Avenue  
CITY: Chicago, IL, 60617

DATE LAST THREE YEAR REINSPECTION WAS COMPLETED **3/23/2016**

**If the address on this form is different than the address of the building, submit a written explanation.**

---

**SECTION II** *(Please type or print)*

**PLEASE COMPLETE THE FOLLOWING FOR YOUR THREE YEAR REINSPECTION:**

DATE REINSPECTION COMPLETED: 10/1/2019 ENROLLMENT 296  
IDPH INSPECTOR LICENSE NUMBER: 100-11102  
IDPH LICENSED INSPECTOR NAME(Please Print): Elmer Spraggins II  
IDPH MP LICENSE NUMBER: 100-09786  
IDPH LICENSED MANAGEMENT PLANNER NAME (Please Print): John Fenn

DESIGNATED PERSON (Please Print): Robert Christlieb PHONE: (773) 553-3197



10/1/2019

*Signature of Designated Person*

*Date*

**SECTION III**

PLEASE COMPLETE THE FOLLOWING INFORMATION FOR ANY CHANGES WITHIN THE SCHOOL DISTRICT.

School building has been sold. Date of Sale: \_\_\_\_\_

School has been closed. Date closed: \_\_\_\_\_

School building has been demolished. Date: \_\_\_\_\_

School building is asbestos free since last reinspection: \_\_\_\_\_

**Please explain in writing why the school building is now asbestos free and include the supporting documentation.**

If a new school building has been added to the district, submit either an exclusionary statement or a management plan and inspection report. Include the complete name, address and city of school building.

**Explain in writing if the address of the building is different than the address on this form:**

---

---

---

**THREE-YEAR REINSPECTION**

**CHICAGO SCHOOL DIST 299**

**Thorp School**

8914 S Buffalo Avenue  
Chicago, IL, 60617

Unit: 25601  
Building ID: 6180

IDPH ID Number: 14-016-2990-2484

**REPORT DATE:**

Tuesday, October 01, 2019

**Prepared for:**

**Chicago Public Schools  
42 West Madison Street  
Chicago, IL 60602**

**Prepared by:**

**TEM Environmental, Inc.**

174 N. Brandon Drive

Glendale Heights, IL, 60139

Phone 630-790-0880

Fax 630-790-0882

**DO NOT REMOVE FROM SCHOOL  
REQUIRED BY FEDERAL LAW**

September 17, 2019

Mr. Glen E. Garner  
Asbestos Program  
Illinois Department of Public Health  
525 West Jefferson Street  
Springfield, Illinois 62761

Re: Chicago Public Schools - 2019 Three-Year Reinspections

Dear Mr. Glen:

TEM Environmental, Inc. , Managing Environmental Consultant (MEC), conducted the Three-Year Reinspections and performed management plan updates for the Chicago Public Schools (CPS) facilities in Region 5, 6 Elementary Schools. Please update your records with the following information.

School District: 299                      Unit: 25601                      Region: 06                      IDPH ID:14-016-2990-2484

School: Thorp School                      Building ID: 6180

Address: 8914 S Buffalo Avenue

Chicago, IL, 60617

Building Contact: Balsam, Martin

Contact Phone:208 334 5263

Current Building Owners: Chicago Public Schools

Review Date: 10/14/2019

Inspector: Elmer Spraggins II

Inspector IDPH License: 100-11102

Management Planner: John Fenn

Management Planner IDPH License: 100-09786

If you have any questions or comments, please contact us at 630-790-0880

Sincerely,  
TEM Environmental, Inc.

John Fenn  
100-09786

## **Environmental Notification to Occupants**

To: Faculty, Staff and Parents  
From: Chicago Public Schools  
Date: September 17, 2019

RE: Thorp School, Unit 25601  
8914 S Buffalo Avenue  
Chicago, IL, 60617

Dear Faculty, Staff and Parents,

This letter is to notify you that the 2019 asbestos three year re-inspection has been completed at Thorp School, following the Federal Asbestos Hazard Emergency Response Act (AHERA), 40 CFR Part 763, Subpart E and is available for your review at the main office of the school.

Although asbestos-containing materials have been identified at Thorp School, there is no reason to believe that any threat to the health of students or staff exists at this time. CPS will continue to carefully monitor the condition of asbestos-containing materials and if conditions warrant, all appropriate steps will be taken to maintain the health and safety of all building occupants.

If you have any questions regarding this matter or require additional information, please feel free to contact Robert Christlieb, the designated Local Education Authority's Designated Person at (773) 553-3197 .

## **Table of Contents**

- I. School and Inspection Information
- II. Executive Summary
- III. Methodology
- IV. Abatement History
- V. Reassessments and Recommendations
- VI. Conclusions

Table I: Inspector's Reinspection Findings

Table II: Management Planner's Review

### **APPENDICES:**

- Appendix A: Assessment Sheets, Drawings and Photos
- Appendix B: Inspector and Management Planner Licenses
- Appendix C: Laboratory Accreditations
- Appendix D: Laboratory Results
- Appendix E: Chain of Custody Forms

## SCHOOL AND INSPECTION INFORMATION

### 1. School Information

School: Thorp School  
Address: 8914 S Buffalo Avenue  
IDPH ID: 14-016-2990-2484  
Contact: Balsam, Martin

Unit: 25601  
Chicago, IL, 60617  
Building ID: 6180  
Phone: 208 334 5263

Region: 06

### 2. Description of Facility

Original Construction: 1893  
Total Square Footage: 44587  
Current Occupancy: 296

Additional Construction: 1925,1975  
No of Floors: 3

### 3. LEA Designated Person

Contact: Robert Christlieb  
Address: 42 West Madison Street  
Chicago, IL 60602

Phone: (773) 553-3197

### 4. Managing Environmental Consultant

MEC: TEM Environmental, Inc.  
Contact: Steven Geneser  
Address 174 N. Brandon Drive  
Glendale Heights, IL, 60139  
Phone: 630-790-0880

Fax: 630-790-0882

### 5. Inspector

Inspector Name: Elmer Spraggins II

Inspector IDPH license # 100-11102

Signature:  
Date: 9/17/2019

### 6. Management Planner

Management Planner Name: John Fenn

Management Planner IDPH license # 100-09786

Signature:  
Date: 10/14/2019

### 7. Review Date:10/14/2019

### 8. LEA Designated Person's Acknowledgement

The reinspection report and recommendations have been received by me and appropriate action will be taken by the School District.

Signature:



Date: 10/1/2019

Name: Robert Christlieb

## II. EXECUTIVE SUMMARY

TEM Environmental, Inc. was retained by the Chicago Public Schools (CPS) to perform a three-year asbestos reinspection of the Thorp School. This inspection was conducted in accordance with the United States Environmental Protection Agency (USEPA) Asbestos Hazard Emergency Response Act (AHERA) part 763.85 (b), and the ongoing Operations and Maintenance Program (O&M) originally designed in the School's Asbestos Management Plan. The purpose of this three-year reinspection is to record any condition changes in the asbestos-containing building material (ACBM) in the school since the previous three-year reinspection and the six-month periodic surveillance, to identify, assess, and include any Homogeneous Areas(HA) not identified in the Management Plan, and to recommend an appropriate response action to manage asbestos.

The inspector conducted a three-year reinspection of this facility under Illinois Department of Public Health (IDPH) school reinspection requirements and AHERA, sections 763.85 and 763.88. The main building and each addition to the main building, if constructed at different dates, were inspected separately. Laboratory accreditations are included in Appendix C, laboratory results are included in Appendix D, and chain of custody forms are included in Appendix E.

Note: During previous inspections, some of the HA(s) were identified together as 9" x 9" floor tile (FT), mastics assoc. with 9" x 9" FT, 12" x 12" FT, mastics assoc. with 12" x 12" FT, pipe insulation, etc. Some of these HA(s) have been re-identified by areas that are uniform in color, texture, construction date, application date, and general appearance.

The inspector has determined the following:

A. The following HAs have changed assessment categories for Building 6180:

11	12x12 Grey Floor Tile
30	12x12 Yellow Floor Tile
31	12x12 Yellow Floor Tile Mastic
43	12x12 Beige Floor Tile
44	12x12 Beige Floor Tile Mastic

B. The following new homogenous areas have been identified for Building 6180:



C. This reinspection covered only physically accessible and visible areas and materials that were identified in the LEA's management plan. The following materials were concealed and/or contained in areas that were inaccessible for sampling and have been classified as Assumed:

04	Accoustical Stucco Plaster
11	12x12 Grey Floor Tile
13	Transite
14	Accoustic Plaster
1500	Green Carpet Adhesive
17	12x12 Beige Floor Tile
25	Transite
26	12x12 Beige Floor Tile
28	12x12 Brown Floor Tile
30	12x12 Yellow Floor Tile
31	12x12 Yellow Floor Tile Mastic
32	Brown Carpet Mastic
33	Green Carpet Mastic
34	Insulation in Firedoors
35	Drywall
36	Drywall Compound
39	12x12 Brown Floor Tile
40	12x12 Brown Floor Tile Mastic
41	12x12 Tan Floor Tile
42	12x12 Tan Floor Tile Mastic
43	12x12 Beige Floor Tile
44	12x12 Beige Floor Tile Mastic
45	12x12 Light Brown Floor Tile
46	12x12 Light Brown Floor Tile Mastic
47	Black Carpet Mastic
48	Brown Carpet Mastic
49	Light Brown Carpet Mastic
50	Insulation in Fire Doors
56	12x12 Tan Floor Tile Mastic
57	Insulation in Fire Doors
58	Blue Carpet Mastic
59	12x12 Cream Floor Tile
60	12x12 Cream Floor Tile Mastic
61	12x12 Cream w/Brown Specks Floor Tile
62	12x12 Cream w/Brown Specks Floor Tile Mastic
63	12x12 Brown and Grey Floor Tile
64	12x12 Brown and Grey Floor Tile Mastic
65	Blue Carpet Adhesive
66	Light Blue Carpet Adhesive
67	Mint Colored Terrazzo Flooring
68	Multicolored Mosaic Ceramic Tile Grout
69	Multicolored Mosaic Ceramic Tile Adhesive

70	1 x 1 White Fissured Ceiling Tile
70M	1 x 1 White Fissured Ceiling Tile Mastic
71	Green Terrazzo Flooring
73	White Ceramic Tile Grout
74	White Ceramic Tile Adhesive
75	12x12 Brown w/Streaks Floor Tile
75M	12x12 Brown w/Streaks Floor Tile Mastic
76	12x12 Off-White w/Streaks Floor Tile
76M	12x12 Off-White w/Streaks Floor Tile Mastic
77	Hard Coat Plaster
78	12x12 Black w/Streaks Vinyl Floor Tile
78M	12x12 Black w/Streaks Vinyl Floor Tile Mastic
79	12x12 Beige & Tan Specks Vinyl Floor Tile
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic
F	Fiberglass Ductwrap
J	Cardboard Pipe Insulation
T	Cardboard Pipe Insulation

The following areas were deemed to be inaccessible:

1500	Green Carpet Adhesive
27	12x12 Beige Floor Tile Mastic
29	12x12 Brown Floor Tile Mastic
31	12x12 Yellow Floor Tile Mastic
34	Insulation in Firedoors
38	9x9 Brown Floor Tile Mastic
40	12x12 Brown Floor Tile Mastic
42	12x12 Tan Floor Tile Mastic
46	12x12 Light Brown Floor Tile Mastic
47	Black Carpet Mastic
49	Light Brown Carpet Mastic
50	Insulation in Fire Doors
57	Insulation in Fire Doors
60	12x12 Cream Floor Tile Mastic
62	12x12 Cream w/Brown Specks Floor Tile Mastic
64	12x12 Brown and Grey Floor Tile Mastic
65	Blue Carpet Adhesive
66	Light Blue Carpet Adhesive
69	Multicolored Mosaic Ceramic Tile Adhesive
70M	1 x 1 White Fissured Ceiling Tile Mastic
74	White Ceramic Tile Adhesive
75M	12x12 Brown w/Streaks Floor Tile Mastic
76M	12x12 Off-White w/Streaks Floor Tile Mastic
78M	12x12 Black w/Streaks Vinyl Floor Tile Mastic
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic
K	Pre-Form Pipe Insulation

Materials were also listed as "assumed" if they were in good condition and sampling was not conducted to avoid damage.

This reinspection was conducted by Elmer Spraggins II, IDPH License # 100-11102. The Management Plan was updated by John Fenn, IDPH License # 100-09786. Inspector and Management Planner Licenses are included in Appendix B.

### **III. METHODOLOGY**

Tasks performed on-site included the following:

1. Review current management plan, identify HA(s) and extract appropriate information.
2. Examine and verify abatement records.
3. Touch and visually and physically reinspect and reassess the condition of all friable known or assumed ACBM.
4. Touch and visually and physically reinspect all non-friable known or assumed ACBM to determine whether these materials have become friable since the last inspection or periodic surveillance.
5. Identify any condition changes that may affect Hazard ranking of known ACBM or Assumed ACBM, as well as any HA(s) that have become friable since the last reinspection.
6. Collect bulk samples from each newly discovered friable HA or previously assumed and submit for laboratory analysis.
7. Tabulate reinspection findings and submit for management planner review and recommendations with appropriate response actions based on the AHERA Damage Category of the ACBM.
8. Submit reinspection findings and management planner recommendations to the LEA within thirty (30) days for inclusion into the management plan.

### **IV. ABATEMENT HISTORY**

The information collected from the existing management plan and inspection report(s) and from interviews with the school official revealed that the following asbestos abatement was conducted at the school since the previous Three year Reinspection.

Abatement Dates:	7/5/2019
	8/22/2019
	8/22/2019
	8/22/2019
	8/22/2019

### **V. REASSESSMENTS AND RECOMMENDATIONS**

The reassessments and recommendations are summarized in Tables I and II on the following pages. Detailed Hazard Assessment Sheets and Drawings and Photos (if applicable) are included in Appendix A.

### **VI. CONCLUSIONS**

The Thorp School Building 6180 Three-Year reinspection has been completed and response actions have been recommended for both friable and non-friable materials. A timely execution of the response actions recommended will enable the LEA and the Designated Person(s) to effectively manage the existing ACBM.

This three-year reinspection report should be inspected in the current Management plan at the CPS Central Office, and one (1) copy should be kept at the school for use when planning any renovation and/or demolition activities in areas where ACBM has been identified. Also, periodic surveillance documentation and any summary reports from any response actions that are executed at the school should be used to update the Management Plan.

**Table I**  
**Inspector's Reinspection Findings**

---

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
04	Accoustical Stucco Plaster	7,050	SF	1961 Building- Lunchroom, 1st Floor Corridor	ASSUMED	SURFACE	N	NONE	0		No	ACBM with the potential for damage		LOW
10	9x9 Brown Floor Tile	11,750	SF	1961 Building- 1st & 2nd Floor Classrooms	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
11	12x12 Grey Floor Tile	5,800	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225	ASSUMED	MISC	N	DIST	50		Yes	ACBM with potential for significant damage	5	MODERATE
13	Transite	10	SF	1925 Building- 2nd Floor Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
14	Acoustic Plaster	1,400	SF	1925 Building- 1st & 2nd Floor Corridor	ASSUMED	SURFACE	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
15	9x9 Tan Floor Tile	2,100	SF	1925 Building- 1st & 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
1500	Green Carpet Adhesive	1,500	SF	1925 Building- Rooms 120 & 288	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
16	9x9 Brown Floor Tile	1,430	SF	1888 Building- 2nd Floor Classroom	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
17	12x12 Beige Floor Tile	7,700	SF	1925 Building- Rooms 124, 126, 129 & Main Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
18	12x12 Brown Floor Tile ABATED			1888 Building- 1st Floor Classrooms & Corridor	ABATED									
19	9x9 Brown Floor Tile Mastic	21,750	SF	1925 Building- 1st Floor Classrooms & Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
20	9x9 Tan Floor Tile Mastic	21,000	SF	1925 Building- 1st & 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
21	9x9 Brown Floor Tile Mastic ABATED			1888 Building- 2nd Floor Classrooms Building	ABATED									
22	12x12 Grey Floor Tile Mastic	5,800	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
23	12x12 Beige Floor Tile Mastic	7,700	SF	1925 Building-	CHR	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Rooms 124, 126, 129, and Main Office								potential for damage		
24	12x12 Brown Floor Tile Mastic ABATED			1888 Building- 1st Floor Corridor	ABATED									
25	Transite	800	SF	1888 Building- 1st, 2nd & 3rd Floor Classrooms	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
26	12x12 Beige Floor Tile	5,350	SF	1961 Building-Basement	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
27	12x12 Beige Floor Tile Mastic	5,350	SF	1961 Building-Basement	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
28	12x12 Brown Floor Tile	4,500	SF	1961 Building-Basement, 1st & 2nd Floor Corridor Border	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
29	12x12 Brown Floor Tile Mastic	4,500	SF	1961 Building-Basement, 1st & 2nd Floor Corridor Border	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
30	12x12 Yellow Floor Tile	5,000	SF	1961 Building- 1st & 2nd Floor Corridor	ASSUMED	MISC	N	DIST	75		Yes	ACBM with potential for significant damage	3	MODERATE
31	12x12 Yellow Floor Tile Mastic	5,000	SF	1961 Building- 1st & 2nd Floor Corridors	ASSUMED	MISC	N	DIST	75		Yes	ACBM with potential for significant damage	5	LOW
32	Brown Carpet Mastic	1,800	SF	1925 Building-Room 127, 227 & Library	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
33	Green Carpet Mastic	750	SF	1961 Building-Room 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
34	Insulation in Firedoors	3	EA	1961 Building-Boiler Room	ASSUMED	TSI	N	NONE	0		No	ACBM with the potential for damage		LOW
35	Drywall	400	SF	1925 Building-Rooms 120 and 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
36	Drywall Compound	200	SF	1925 Building-Rooms 120 and 225	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
37	9x9 Brown Floor Tile	2,350	SF	1925 Building- 1st & 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
38	9x9 Brown Floor Tile Mastic	2,350	SF	1925 Building- 1st & 2nd Floor Corridor	CHR	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
39	12x12 Brown Floor Tile	750	SF	1925 Building-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 217								potential for damage		
40	12x12 Brown Floor Tile Mastic	750	SF	1925 Building-Room 217	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
41	12x12 Tan Floor Tile	750	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
42	12x12 Tan Floor Tile Mastic	750	SF	1925 Building-Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
43	12x12 Beige Floor Tile	6,750	SF	1925 Building-Rooms 229, 228, 226R, 224, and 225	ASSUMED	MISC	N	DIST	75		Yes	ACBM with potential for significant damage	5	MODERATE
44	12x12 Beige Floor Tile Mastic	6,750	SF	1925 Building-Rooms 229, 228, 226R, 224, & 225	ASSUMED	MISC	N	DIST	75		Yes	ACBM with potential for significant damage	5	LOW
45	12x12 Light Brown Floor Tile	500	SF	1925 Building-Room 216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
46	12x12 Light Brown Floor Tile Mastic	500	SF	1926 Building-Room 216	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
47	Black Carpet Mastic	750	SF	1925 Building-Room 117 & Room 223	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
48	Brown Carpet Mastic	1,000	SF	1961 Building-Room 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
49	Light Brown Carpet Mastic	780	SF	1925 Building-Room 125, Principal's Office	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
50	Insulation in Fire Doors	2	Each	Adjoining Corridor to 1888 building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
51	9x9 Black Floor Tile ABATED 2009			1888 Building-Room 145 Closet	ABATED	MISC								
52	9x9 Black Floor Tile Mastic ABATED 2009			1888 Building-Room 145 Closet	ABATED	MISC								
53	9x9 Red Floor Tile ABATED 2009			1888 Building-Room 132 Closet	ABATED	MISC								
54	9x9 Red Floor Tile Mastic ABATED 2009			1888 Building-Room 132 Closet	ABATED									
55	12x12 Tan Floor Tile ABATED 2009			1888 Building- 1st Floor Classrooms & Corridor	ABATED									
56	12x12 Tan Floor Tile Mastic	3,470	SF	1888 Building- 1st Floor Classrooms & Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
57	Insulation in Fire Doors	2	EA	Adjoining Corridor to 1925 Building	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
58	Blue Carpet Mastic	700	SF	1960 Building-	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Room 200								potential for damage		
59	12x12 Cream Floor Tile	600	SF	1925 Building-Room 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
60	12x12 Cream Floor Tile Mastic	600	SF	1925 Building-Room 122	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
61	12x12 Cream w/Brown Specks Floor Tile	500	SF	1925 Building-Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
62	12x12 Cream w/Brown Specks Floor Tile Mastic	500	SF	1925 Building-Room 120	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
63	12x12 Brown and Grey Floor Tile	2,000	SF	1925 Building-Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
64	12x12 Brown and Grey Floor Tile Mastic	2,000	SF	1925 Building-Auditorium	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
65	Blue Carpet Adhesive	2,340	SF	1960 Building-Room 212, 211, 209	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
66	Light Blue Carpet Adhesive	624	SF	1960 Building-Room 200	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
67	Mint Colored Terrazzo Flooring	1,260	SF	1960 Building-Stairways	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
68	Multicolored Mosaic Ceramic Tile Grout	1,335	SF	1960 Building-Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
69	Multicolored Mosaic Ceramic Tile Adhesive	1,335	SF	1960 Building-Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
70	1 x 1 White Fissured Ceiling Tile	1,560	SF	1960 Building-Rooms 209 & 211	ASSUMED	MISC	Y	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
70M	1 x 1 White Fissured Ceiling Tile Mastic	1,560	SF	1960 Building-Rooms 209 & 211	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
71	Green Terrazzo Flooring	1,600	SF	1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor	ASSUMED	MISC	N	NONE	0		No	ACBM with the potential for damage		LOW
73	White Ceramic Tile Grout	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	ASSUMED	MISC	N	NONE	0		No	Any remaining friable ACBM or friable suspect ACBM		LOW
74	White Ceramic Tile Adhesive	1,570	SF	1925 Building- 1st	ASSUMED	MISC	N	NONE	0		No	ACBM with the		LOW



# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room										
I	Aircell Pipe Insulation	400	LF	1888 Building-Boiler Room/Basement Area	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
J	Cardboard Pipe Insulation	300	LF	1888 Building-Basement Area	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
K	Pre-Form Pipe Insulation	100	LF	1888 Building-Basement Area	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
N	Fiberglass Joint Insulation	200	LF	Basement/Tunnel & Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
O	Fiberglass Joint Insulation	40	LF	1961 Building-Boiler Room, Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
P	Aircell Pipe Joint Insulation	80	LF	1888 Building-Boiler Room/Tunnel & Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Q	Aircell Pipe Joint Insulation	30	LF	1961 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
R	Aircell Pipe Insulation	400	LF	1926 Building-Boiler Room/Tunnel	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
S	Aircell Pipe Insulation	300	LF	1961 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
T	Cardboard Pipe Insulation	100	LF	Tunnels Unexcavated Areas	ASSUMED	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
U	Pre-form Pipe Insulation	100	LF	1898 Building-Boiler Room, Unexcavated Areas	AMO	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
V	Cardboard Pipe Joint Insulation	10	LF	1925 Building-Tunnels/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
W	Cardboard Pipe Joint Insulation	15	LF	1888 Building-Basement/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
X	Pre-Form Pipe Joint Insulation	10	LF	1888 Building-Boiler Room/Unexcavated Areas	CHR	TSI	Y	NONE	0		No	ACBM with the potential for damage		LOW
Y	Pre-form Pipe Joint Insulation	10	LF	1888 Building-	CHR	TSI	Y	NONE	0		No	ACBM with the		LOW

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	Damage Category	Damage Reason	Disturbance Potential
				Boiler Room/Unexcavated Areas								potential for damage		

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

Reinspection Date <b>9/17/2019</b>
Inspector Name <b>Elmer Spraggins II</b>
<b>100-11102</b> <b>5/15/2020</b>
Inspector's IDPH License Number / Expiration Date

#### Inspector's Comments

HA Number:	Inspector Comments:
04	
10	
11	1st Floor Corridors
13	
14	
15	NOT OBSERVED ON 1ST FLOOR CORRIDOR
1500	
16	NOT OBSERVED
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	1st Floor Corridor Damage
31	1st Floor Corridor Damage

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
32	
33	NOT OBSERVED
34	
35	
36	
37	NOT OBSERVED
38	NOT OBSERVED
39	
40	
41	
42	
43	Room 229 & 229R Damage
44	Room 229 damaged
45	
46	
47	NOT OBSERVED
48	NOT OBSERVED
49	
50	
51	ABATED 2009
52	ABATED 2009
53	ABATED 2009
54	ABATED 2009
55	ABATED 2009
56	
57	
58	NOT OBSERVED
59	
60	

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
70M	
71	
73	
74	
75	
75M	
76	
76M	
77	
78	
78M	
79	
79M	
A	
B	
C	
D	
E	
F	

# Chicago Public Schools

School Thorp School Unit 25601 Building ID 6180

Address 8914 S Buffalo Avenue Region 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Inspector's Reinspection Findings Table 1

Managing Environmental Consultant (MEC) TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

*Inspector's Comments are Summarized at the End of the Report*

---

HA Number:	Inspector Comments:
H	
I	
J	
K	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	



**Table II**

**Management Planner's Review**

---

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
04	Accoustical Stucco Plaster	7,050	SF	1961 Building- Lunchroom, 1st Floor Corridor	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
10	9x9 Brown Floor Tile	11,750	SF	1961 Building- 1st & 2nd Floor Classrooms	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
11	12x12 Grey Floor Tile	5,800	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225	Assumed	MISC	No	50	SF	5 ACBM with potential for significant damage	Follow O&M Plan
13	Transite	10	SF	1925 Building- 2nd Floor Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
14	Accoustic Plaster	1,400	SF	1925 Building- 1st & 2nd Floor Corridor	Assumed	SURFACE	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
15	9x9 Tan Floor Tile	2,100	SF	1925 Building- 1st & 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
1500	Green Carpet Adhesive	1,500	SF	1925 Building- Rooms 120 & 288	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
16	9x9 Brown Floor Tile	1,430	SF	1888 Building- 2nd Floor Classroom	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
17	12x12 Beige Floor Tile	7,700	SF	1925 Building- Rooms 124, 126, 129 & Main Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
18	12x12 Brown Floor Tile ABATED			1888 Building- 1st Floor Classrooms & Corridor	Abated						
19	9x9 Brown Floor Tile Mastic	21,750	SF	1925 Building- 1st Floor Classrooms & Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
20	9x9 Tan Floor Tile Mastic	21,000	SF	1925 Building- 1st & 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
21	9x9 Brown Floor Tile Mastic ABATED			1888 Building- 2nd Floor Classrooms Building	Abated						
22	12x12 Grey Floor Tile Mastic	5,800	SF	1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
23	12x12 Beige Floor Tile Mastic	7,700	SF	1925 Building- Rooms 124, 126, 129, and Main Office	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
24	12x12 Brown Floor Tile Mastic ABATED			1888 Building- 1st Floor Corridor	Abated						
25	Transite	800	SF	1888 Building- 1st, 2nd & 3rd Floor Classrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
26	12x12 Beige Floor Tile	5,350	SF	1961 Building- Basement	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
27	12x12 Beige Floor Tile Mastic	5,350	SF	1961 Building- Basement	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
28	12x12 Brown Floor Tile	4,500	SF	1961 Building- Basement, 1st & 2nd Floor Corridor Border	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
29	12x12 Brown Floor Tile Mastic	4,500	SF	1961 Building- Basement, 1st & 2nd	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				Floor Corridor Border							
30	12x12 Yellow Floor Tile	5,000	SF	1961 Building- 1st & 2nd Floor Corridor	Assumed	MISC	No	75	SF	5 ACBM with potential for significant damage	Follow O&M Plan
31	12x12 Yellow Floor Tile Mastic	5,000	SF	1961 Building- 1st & 2nd Floor Corridors	Assumed	MISC	No	75	SF	5 ACBM with potential for significant damage	Follow O&M Plan
32	Brown Carpet Mastic	1,800	SF	1925 Building- Room 127, 227 & Library	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
33	Green Carpet Mastic	750	SF	1961 Building- Room 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
34	Insulation in Firedoors	3	EA	1961 Building- Boiler Room	Assumed	TSI	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
35	Drywall	400	SF	1925 Building- Rooms 120 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
36	Drywall Compound	200	SF	1925 Building- Rooms 120 and 225	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
37	9x9 Brown Floor Tile	2,350	SF	1925 Building- 1st & 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
38	9x9 Brown Floor Tile Mastic	2,350	SF	1925 Building- 1st & 2nd Floor Corridor	Chrysotile	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
39	12x12 Brown Floor Tile	750	SF	1925 Building- Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
40	12x12 Brown Floor Tile Mastic	750	SF	1925 Building- Room 217	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
41	12x12 Tan Floor Tile	750	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
42	12x12 Tan Floor Tile Mastic	750	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
43	12x12 Beige Floor Tile	6,750	SF	1925 Building- Rooms 229, 228, 226R, 224, and 225	Assumed	MISC	No	75	SF	5 ACBM with potential for significant damage	Follow O&M Plan
44	12x12 Beige Floor Tile Mastic	6,750	SF	1925 Building- Rooms 229, 228, 226R, 224, & 225	Assumed	MISC	No	75	SF	5 ACBM with potential for significant damage	Follow O&M Plan
45	12x12 Light Brown Floor Tile	500	SF	1925 Building- Room 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
46	12x12 Light Brown Floor Tile Mastic	500	SF	1926 Building- Room 216	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
47	Black Carpet Mastic	750	SF	1925 Building- Room 117 & Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
48	Brown Carpet Mastic	1,000	SF	1961 Building- Room 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
49	Light Brown Carpet Mastic	780	SF	1925 Building- Room 125, Principal's Office	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
50	Insulation in Fire Doors	2	Each	Adjoining Corridor to 1888 building	Assumed	MISC	No	0	Each	6 ACBM with the potential for damage	Follow O&M Plan
51	9x9 Black Floor Tile ABATED 2009			1888 Building- Room 145 Closet	Abated	MISC					
52	9x9 Black Floor Tile Mastic ABATED 2009			1888 Building- Room 145 Closet	Abated	MISC					
53	9x9 Red Floor Tile ABATED 2009			1888 Building- Room 132 Closet	Abated	MISC					
54	9x9 Red Floor Tile Mastic ABATED 2009			1888 Building- Room 132 Closet	Abated						
55	12x12 Tan Floor Tile ABATED 2009			1888 Building- 1st Floor Classrooms & Corridor	Abated						

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### Management Planner's Comments Summarized at the End of the Report

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
56	12x12 Tan Floor Tile Mastic	3,470	SF	1888 Building- 1st Floor Classrooms & Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
57	Insulation in Fire Doors	2	EA	Adjoining Corridor to 1925 Building	Assumed	MISC	No	0	EA	6 ACBM with the potential for damage	Follow O&M Plan
58	Blue Carpet Mastic	700	SF	1960 Building- Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
59	12x12 Cream Floor Tile	600	SF	1925 Building- Room 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
60	12x12 Cream Floor Tile Mastic	600	SF	1925 Building- Room 122	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
61	12x12 Cream w/Brown Specks Floor Tile	500	SF	1925 Building- Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
62	12x12 Cream w/Brown Specks Floor Tile Mastic	500	SF	1925 Building- Room 120	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
63	12x12 Brown and Grey Floor Tile	2,000	SF	1925 Building- Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
64	12x12 Brown and Grey Floor Tile Mastic	2,000	SF	1925 Building- Auditorium	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
65	Blue Carpet Adhesive	2,340	SF	1960 Building- Room 212, 211, 209	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
66	Light Blue Carpet Adhesive	624	SF	1960 Building- Room 200	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
67	Mint Colored Terrazzo Flooring	1,260	SF	1960 Building- Stairways	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
68	Multicolored Mosaic Ceramic Tile Grout	1,335	SF	1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
69	Multicolored Mosaic Ceramic Tile Adhesive	1,335	SF	1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
70	1 x 1 White Fissured Ceiling Tile	1,560	SF	1960 Building- Rooms 209 & 211	Assumed	MISC	Yes	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
70M	1 x 1 White Fissured Ceiling Tile Mastic	1,560	SF	1960 Building- Rooms 209 & 211	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
71	Green Terrazzo Flooring	1,600	SF	1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
73	White Ceramic Tile Grout	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
74	White Ceramic Tile Adhesive	1,570	SF	1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75	12x12 Brown w/Streaks Floor Tile	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
75M	12x12 Brown w/Streaks Floor Tile Mastic	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76	12x12 Off-White w/Streaks Floor Tile	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
76M	12x12 Off-White w/Streaks Floor Tile Mastic	360	SF	1925 Building- Room 223	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
77	Hard Coat Plaster	114,000	SF	1898 Building- 1st, 2nd & 3rd Floor	Assumed	SURFACE	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
78	12x12 Black w/Streaks Vinyl Floor Tile	8,500	SF	1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209,	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
				211, 212, 2nd Floor Teachers' Lounge							
78M	12x12 Black w/Streaks Vinyl Floor Tile Mastic	8,500	SF	1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209, 211, 212, 2nd Floor Teachers' Lounge	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79	12x12 Beige & Tan Specks Vinyl Floor Tile	250	SF	Teachers Lounge (287)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
79M	12x12 Beige & Tan Specks Vinyl Floor Tile Mastic	250	SF	Teachers' Lounge (287)	Assumed	MISC	No	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
A	Fiberglass Joint Insulation	45	LF	1960 Boiler Room	Chrysotile	TSI	Yes	0	LF	7 Any remaining friable ACBM or friable suspect ACBM	Follow O&M Plan
B	Aircell Joint Insulation ABATED			1888 Building- Boiler Area	Abated	TSI					
C	Hand Packing ABATED			1888 Building- Boiler Room	Abated	TSI					
D	Boiler Insulation ABATED			1888 Building- Boiler Room	Abated	TSI					
E	Tank Insulation ABATED			1888 Building- Boiler & Tank Room	Abated	TSI					
F	Fiberglass Ductwrap	160	SF	1888 Building- Boiler Room	Assumed	TSI	Yes	0	SF	6 ACBM with the potential for damage	Follow O&M Plan
H	Aircell Ductwrap ABATED			1888 Building- Boiler Room	Abated	TSI					
I	Aircell Pipe Insulation	400	LF	1888 Building- Boiler Room/Basement Area	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
J	Cardboard Pipe Insulation	300	LF	1888 Building- Basement Area	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
K	Pre-Form Pipe Insulation	100	LF	1888 Building- Basement Area	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
N	Fiberglass Joint Insulation	200	LF	Basement/Tunnel & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
O	Fiberglass Joint Insulation	40	LF	1961 Building- Boiler Room, Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
P	Aircell Pipe Joint Insulation	80	LF	1888 Building- Boiler Room/Tunnel & Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Q	Aircell Pipe Joint Insulation	30	LF	1961 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
R	Aircell Pipe Insulation	400	LF	1926 Building- Boiler Room/Tunnel	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
S	Aircell Pipe Insulation	300	LF	1961 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
T	Cardboard Pipe Insulation	100	LF	Tunnels Unexcavated Areas	Assumed	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
U	Pre-form Pipe Insulation	100	LF	1898 Building- Boiler Room, Unexcavated Areas	Amosite	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
V	Cardboard Pipe Joint Insulation	10	LF	1925 Building- Tunnels/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Quantity	Damage Units	Damage Category	Response
W	Cardboard Pipe Joint Insulation	15	LF	1888 Building- Basement/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
X	Pre-Form Pipe Joint Insulation	10	LF	1888 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan
Y	Pre-form Pipe Joint Insulation	10	LF	1888 Building- Boiler Room/Unexcavated Areas	Chrysotile	TSI	Yes	0	LF	6 ACBM with the potential for damage	Follow O&M Plan

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.  
 174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880 Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

Review Date	10/14/2019
Manager Planner Name	John Fenn
100-09786	5/15/2020
Manager IDPH License No/Expiration	

HA Number	Management Comments
04	
10	
11	
13	
14	
15	
1500	
16	
17	
18	
19	
20	
21	
22	
23	
24	
25	
26	
27	
28	
29	
30	
31	
32	
33	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
34	
35	
36	
37	
38	
39	
40	
41	
42	
43	
44	
45	
46	
47	
48	
49	
50	
51	
52	
53	
54	
55	
56	
57	
58	
59	



# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
 Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
60	
61	
62	
63	
64	
65	
66	
67	
68	
69	
70	
70M	
71	
73	
74	
75	
75M	
76	
76M	
77	
78	
78M	
79	
79M	
A	
B	

# Chicago Public Schools

**School** Thorp School  
**Address** 8914 S Buffalo Avenue

**Unit** 25601  
Chicago, IL, 60617

**Building ID** 6180  
**Region** 06

## ASBESTOS REINSPECTION FINDINGS AND RECOMMENDATIONS

### Management Planner's Review Table II

**Managing Environmental Consultant (MEC)** TEM Environmental, Inc.

174 N. Brandon Drive Glendale Heights, IL, 60139

Phone: 630-790-0880

Fax: 630-790-0882

### *Management Planner's Comments Summarized at the End of the Report*

HA Number	Management Comments
C	
D	
E	
F	
H	
I	
J	
K	
N	
O	
P	
Q	
R	
S	
T	
U	
V	
W	
X	
Y	

# Chicago Public Schools

TEM Environmental, Inc.

## 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Accoustical Stucco Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Lunchroom, 1st Floor Corridor**  
MATERIAL QUANTITY: **7050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **04**  
MATERIAL DESCRIPTION: **Accoustical Stucco Plaster**  
MATERIAL LOCATION: **1961 Building- Lunchroom, 1st Floor Corridor**  
MATERIAL QUANTITY: **7050** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Classrooms**  
MATERIAL QUANTITY: **11750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **10**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Classrooms**  
MATERIAL QUANTITY: **11750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225**  
MATERIAL QUANTITY: **5800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50**    DAMAGE UNITS: **SF**  
COMMENTS: **1st Floor Corridors**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **11**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **50** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **13**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **1925 Building- 2nd Floor Corridor**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Accoustic Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **14**  
MATERIAL DESCRIPTION: **Accoustic Plaster**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **1400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2100**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS: **NOT OBSERVED ON 1ST FLOOR CORRIDOR**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **15**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2100** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **1500**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 120 & 288**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **1500**  
MATERIAL DESCRIPTION: **Green Carpet Adhesive**  
MATERIAL LOCATION: **1925 Building- Rooms 120 & 288**  
MATERIAL QUANTITY: **1500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- 2nd Floor Classroom**  
MATERIAL QUANTITY: **1430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **16**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **1888 Building- 2nd Floor Classroom**  
MATERIAL QUANTITY: **1430** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129 & Main Office**  
MATERIAL QUANTITY: **7700**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **17**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129 & Main Office**  
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **18**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **18**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile ABATED**

MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: **21750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **19**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: **21750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **21000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **20**  
MATERIAL DESCRIPTION: **9x9 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **21000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **21**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 2nd Floor Classrooms Building**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **21**

MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1888 Building- 2nd Floor Classrooms Building**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **22**  
MATERIAL DESCRIPTION: **12x12 Grey Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Rooms 124, 126, 127, 129, 224, 225**  
MATERIAL QUANTITY: **5800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129, and Main Office**  
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **23**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 124, 126, 129, and Main Office**  
MATERIAL QUANTITY: **7700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **24**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **24**

MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic ABATED**

MATERIAL LOCATION: **1888 Building- 1st Floor Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Transite**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- 1st, 2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **25**  
MATERIAL DESCRIPTION: **Transite**  
MATERIAL LOCATION: **1888 Building- 1st, 2nd & 3rd Floor Classrooms**  
MATERIAL QUANTITY: **800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Basement**  
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **26**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1961 Building- Basement**  
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Basement**  
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **27**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Basement**  
MATERIAL QUANTITY: **5350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Border**  
MATERIAL QUANTITY: **4500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **28**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Border**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Border**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **29**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Basement, 1st & 2nd Floor Corridor Border**  
MATERIAL QUANTITY: **4500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Deterioration  
Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**  
COMMENTS: **1st Floor Corridor Damage**

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **30**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**  
COMMENTS: **1st Floor Corridor Damage**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **31**  
MATERIAL DESCRIPTION: **12x12 Yellow Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- 1st & 2nd Floor Corridors**  
MATERIAL QUANTITY: **5000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 127, 227 & Library**  
MATERIAL QUANTITY: **1800**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **32**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Room 127, 227 & Library**  
MATERIAL QUANTITY: **1800** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Room 209**  
MATERIAL QUANTITY: **750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **33**  
MATERIAL DESCRIPTION: **Green Carpet Mastic**  
MATERIAL LOCATION: **1961 Building- Room 209**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Insulation in Firedoors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Boiler Room**  
MATERIAL QUANTITY: **3**    MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **34**  
MATERIAL DESCRIPTION: **Insulation in Firedoors**  
MATERIAL LOCATION: **1961 Building- Boiler Room**  
MATERIAL QUANTITY: **3** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Drywall**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **35**  
MATERIAL DESCRIPTION: **Drywall**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Drywall Compound**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **200**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **36**  
MATERIAL DESCRIPTION: **Drywall Compound**  
MATERIAL LOCATION: **1925 Building- Rooms 120 and 225**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2350**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **37**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2350**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **38**  
MATERIAL DESCRIPTION: **9x9 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridor**  
MATERIAL QUANTITY: **2350** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 217**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **39**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 217**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 217**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **40**  
MATERIAL DESCRIPTION: **12x12 Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 217**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **41**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **42**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **MODERATE**  
MATERIAL LOCATION: **1925 Building- Rooms 229, 228, 226R, 224, and 225**  
MATERIAL QUANTITY: **6750**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75**    DAMAGE UNITS: **SF**  
COMMENTS: **Room 229 & 229R Damage**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **43**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile**  
MATERIAL LOCATION: **1925 Building- Rooms 229, 228, 226R, 224, and 225**  
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **5 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **5. ACBM with potential for significant damage**

DAMAGE REASON: **Physical Damage**  
DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Rooms 229, 228, 226R, 224, & 225**  
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**  
COMMENTS: **Room 229 damaged**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **44**  
MATERIAL DESCRIPTION: **12x12 Beige Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Rooms 229, 228, 226R, 224, & 225**  
MATERIAL QUANTITY: **6750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **75** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 216**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **45**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 216**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **46**  
MATERIAL DESCRIPTION: **12x12 Light Brown Floor Tile Mastic**  
MATERIAL LOCATION: **1926 Building- Room 216**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Black Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 117 & Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **47**  
MATERIAL DESCRIPTION: **Black Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Room 117 & Room 223**  
MATERIAL QUANTITY: **750** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Room 209 & 211**  
MATERIAL QUANTITY: **1000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **48**  
MATERIAL DESCRIPTION: **Brown Carpet Mastic**  
MATERIAL LOCATION: **1961 Building- Room 209 & 211**  
MATERIAL QUANTITY: **1000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Light Brown Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 125, Principal's Office**  
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **49**  
MATERIAL DESCRIPTION: **Light Brown Carpet Mastic**  
MATERIAL LOCATION: **1925 Building- Room 125, Principal's Office**  
MATERIAL QUANTITY: **780** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Adjoining Corridor to 1888 building**  
MATERIAL QUANTITY: **2**    MATERIAL UNITS: **Each**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **Each**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **50**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
MATERIAL LOCATION: **Adjoining Corridor to 1888 building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **Each**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **Each**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **51**  
MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED 2009**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **ABATED 2009**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **51**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **52**  
MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED 2009**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **ABATED 2009**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **52**

MATERIAL DESCRIPTION: **9x9 Black Floor Tile Mastic ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 145 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **53**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile ABATED 2009**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **ABATED 2009**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **53**

MATERIAL DESCRIPTION: **9x9 Red Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **54**  
MATERIAL DESCRIPTION: **9x9 Red Floor Tile Mastic ABATED 2009**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS: **ABATED 2009**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **54**

MATERIAL DESCRIPTION: **9x9 Red Floor Tile Mastic ABATED 2009**

MATERIAL LOCATION: **1888 Building- Room 132 Closet**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **55**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile ABATED 2009**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS: **ABATED 2009**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **55**

MATERIAL DESCRIPTION: **12x12 Tan Floor Tile ABATED 2009**

MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: **3470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **56**  
MATERIAL DESCRIPTION: **12x12 Tan Floor Tile Mastic**  
MATERIAL LOCATION: **1888 Building- 1st Floor Classrooms & Corridor**  
MATERIAL QUANTITY: **3470** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Adjoining Corridor to 1925 Building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **57**  
MATERIAL DESCRIPTION: **Insulation in Fire Doors**  
MATERIAL LOCATION: **Adjoining Corridor to 1925 Building**  
MATERIAL QUANTITY: **2** MATERIAL UNITS: **EA**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **EA**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Room 200**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**  
COMMENTS: **NOT OBSERVED**

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **58**  
MATERIAL DESCRIPTION: **Blue Carpet Mastic**  
MATERIAL LOCATION: **1960 Building- Room 200**  
MATERIAL QUANTITY: **700** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 122**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **59**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 122**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 122**  
MATERIAL QUANTITY: **600**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **60**  
MATERIAL DESCRIPTION: **12x12 Cream Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 122**  
MATERIAL QUANTITY: **600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **61**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **62**  
MATERIAL DESCRIPTION: **12x12 Cream w/Brown Specks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 120**  
MATERIAL QUANTITY: **500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **63**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **64**  
MATERIAL DESCRIPTION: **12x12 Brown and Grey Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Auditorium**  
MATERIAL QUANTITY: **2000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Room 212, 211, 209**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **65**  
MATERIAL DESCRIPTION: **Blue Carpet Adhesive**  
MATERIAL LOCATION: **1960 Building- Room 212, 211, 209**  
MATERIAL QUANTITY: **2340** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Light Blue Carpet Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Room 200**  
MATERIAL QUANTITY: **624** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **66**  
MATERIAL DESCRIPTION: **Light Blue Carpet Adhesive**  
MATERIAL LOCATION: **1960 Building- Room 200**  
MATERIAL QUANTITY: **624** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Mint Colored Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Stairways**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **67**  
MATERIAL DESCRIPTION: **Mint Colored Terrazzo Flooring**  
MATERIAL LOCATION: **1960 Building- Stairways**  
MATERIAL QUANTITY: **1260** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **68**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Grout**  
MATERIAL LOCATION: **1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **69**  
MATERIAL DESCRIPTION: **Multicolored Mosaic Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1960 Building- Vestibules, Boys and Girls Washrooms on 1st and 2nd Floors**  
MATERIAL QUANTITY: **1335** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **70**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **70M**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **70M**  
MATERIAL DESCRIPTION: **1 x 1 White Fissured Ceiling Tile Mastic**  
MATERIAL LOCATION: **1960 Building- Rooms 209 & 211**  
MATERIAL QUANTITY: **1560** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Green Terrazzo Flooring**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **71**  
MATERIAL DESCRIPTION: **Green Terrazzo Flooring**  
MATERIAL LOCATION: **1925 Building- 1st & 2nd Floor Corridors, Stairways, and adjoining Corridor**  
MATERIAL QUANTITY: **1600** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**  
HISTORICAL AHERA DAMAGE CATEGORY: **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **73**  
MATERIAL DESCRIPTION: **White Ceramic Tile Grout**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **74**  
MATERIAL DESCRIPTION: **White Ceramic Tile Adhesive**  
MATERIAL LOCATION: **1925 Building- 1st and 2nd Floor Boys' and Girls' Washrooms**  
MATERIAL QUANTITY: **1570** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **75**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **75M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **75M**  
MATERIAL DESCRIPTION: **12x12 Brown w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **76**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **76M**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed**    FRIABLE: **No**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360**    MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **76M**  
MATERIAL DESCRIPTION: **12x12 Off-White w/Streaks Floor Tile Mastic**  
MATERIAL LOCATION: **1925 Building- Room 223**  
MATERIAL QUANTITY: **360** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1898 Building- 1st, 2nd & 3rd Floor**  
MATERIAL QUANTITY: **114000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **77**  
MATERIAL DESCRIPTION: **Hard Coat Plaster**  
MATERIAL LOCATION: **1898 Building- 1st, 2nd & 3rd Floor**  
MATERIAL QUANTITY: **114000** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12 Black w/Streaks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209, 211, 212, 2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: **8500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **78**  
MATERIAL DESCRIPTION: **12x12 Black w/Streaks Vinyl Floor Tile**  
MATERIAL LOCATION: **1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209, 211, 212, 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **78M**  
MATERIAL DESCRIPTION: **12x12 Black w/Streaks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**

MATERIAL LOCATION: **1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209, 211, 212, 2nd Floor Teachers' Lounge**

MATERIAL QUANTITY: **8500**

MATERIAL UNITS: **SF**

DAMAGE QUANTITY: **0**

DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **78M**  
MATERIAL DESCRIPTION: **12x12 Black w/Streaks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **1961 Building- Rooms 103, 105, 109, 110, 113, 200, 200R, 202, 205, 209, 211, 212, 2nd Floor Teachers' Lounge**  
MATERIAL QUANTITY: **8500** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers Lounge (287)**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **79**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile**  
MATERIAL LOCATION: **Teachers Lounge (287)**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **79M**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile Mastic**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **No**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Teachers' Lounge (287)**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **79M**  
MATERIAL DESCRIPTION: **12x12 Beige & Tan Specks Vinyl Floor Tile Mastic**  
MATERIAL LOCATION: **Teachers' Lounge (287)**  
MATERIAL QUANTITY: **250** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **7 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **7. Any remaining friable ACBM or friable suspect ACBM**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1960 Boiler Room**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **A**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
MATERIAL LOCATION: **1960 Boiler Room**  
MATERIAL QUANTITY: **45** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **B**  
MATERIAL DESCRIPTION: **Aircell Joint Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **B**

MATERIAL DESCRIPTION: **Aircell Joint Insulation ABATED**

MATERIAL LOCATION: **1888 Building- Boiler Area**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Hand Packing ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_

Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **C**  
MATERIAL DESCRIPTION: **Hand Packing ABATED**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: MATERIAL UNITS:  
DAMAGE QUANTITY: DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **D**  
MATERIAL DESCRIPTION: **Boiler Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY: MATERIAL UNITS:

DAMAGE QUANTITY: DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **D**

MATERIAL DESCRIPTION: **Boiler Insulation ABATED**

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **E**  
MATERIAL DESCRIPTION: **Tank Insulation ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler & Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **E**

MATERIAL DESCRIPTION: **Tank Insulation ABATED**

MATERIAL LOCATION: **1888 Building- Boiler & Tank Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Fiberglass Ductwrap**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **F**  
MATERIAL DESCRIPTION: **Fiberglass Ductwrap**  
MATERIAL LOCATION: **1888 Building- Boiler Room**  
MATERIAL QUANTITY: **160** MATERIAL UNITS: **SF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **SF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **H**  
MATERIAL DESCRIPTION: **Aircell Ductwrap ABATED**  
HISTORICAL AHERA DAMAGE CATEGORY  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION:  
ASBESTOS TYPE: **Abated** FRIABLE:

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be .

DAMAGE REASON:

DISTURBANCE POTENTIAL:

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **H**

MATERIAL DESCRIPTION: **Aircell Ductwrap ABATED**

MATERIAL LOCATION: **1888 Building- Boiler Room**

MATERIAL QUANTITY:

MATERIAL UNITS:

DAMAGE QUANTITY:

DAMAGE UNITS:

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Basement Area**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **I**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Basement Area**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **J**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **100**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **K**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Insulation**  
MATERIAL LOCATION: **1888 Building- Basement Area**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Basement/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **N**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
MATERIAL LOCATION: **Basement/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **200** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **0**  
MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **0**

MATERIAL DESCRIPTION: **Fiberglass Joint Insulation**

MATERIAL LOCATION: **1961 Building- Boiler Room, Unexcavated Areas**

MATERIAL QUANTITY: **40** MATERIAL UNITS: **LF**

DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **P**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Tunnel & Unexcavated Areas**  
MATERIAL QUANTITY: **80** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **Q**  
MATERIAL DESCRIPTION: **Aircell Pipe Joint Insulation**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **30** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1926 Building- Boiler Room/Tunnel**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **R**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1926 Building- Boiler Room/Tunnel**  
MATERIAL QUANTITY: **400** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools**    UNIT NUMBER: **25601**    BUILDING ID: **6180**  
CITY/STATE: **Chicago, Illinois**    AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School**    INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue**    IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY: **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile**    FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and its condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **300**    MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0**    DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **S**  
MATERIAL DESCRIPTION: **Aircell Pipe Insulation**  
MATERIAL LOCATION: **1961 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **300** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Assumed** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **Tunnels Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **T**  
MATERIAL DESCRIPTION: **Cardboard Pipe Insulation**  
MATERIAL LOCATION: **Tunnels Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Pre-form Pipe Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Amosite** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1898 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **U**  
MATERIAL DESCRIPTION: **Pre-form Pipe Insulation**  
MATERIAL LOCATION: **1898 Building- Boiler Room, Unexcavated Areas**  
MATERIAL QUANTITY: **100** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1925 Building- Tunnels/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **V**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
MATERIAL LOCATION: **1925 Building- Tunnels/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

### INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

### RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Basement/Unexcavated Areas**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **W**  
MATERIAL DESCRIPTION: **Cardboard Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Basement/Unexcavated Areas**  
MATERIAL QUANTITY: **15** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**



# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: 09/17/2019

# Chicago Public Schools

## TEM Environmental, Inc. 2019 AHERA REINSPECTION

### Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **X**  
MATERIAL DESCRIPTION: **Pre-Form Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Inspector Assessment Form (REASSESSMENT)

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** AHERA INSPECTOR: **Elmer Spraggins II**  
SCHOOL NAME: **Thorp School** INSPECTION DATE: **9/17/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

## INFORMATION FROM PREVIOUS INSPECTION

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Pre-form Pipe Joint Insulation**  
HISTORICAL AHERA DAMAGE CATEGORY **6 ACBM with the potential for damage**  
HISTORICAL DAMAGE REASON:  
HISTORICAL RESPONSE ACTION: **Follow O&M Plan**  
ASBESTOS TYPE: **Chrysotile** FRIABLE: **Yes**

---

## RESULTS OF REINSPECTION AND REASSESSMENT

This homogeneous area was re-inspected and reassessed in accordance with Section 763.85 and 763.88 of AHERA and it's condition HAS NOT CHANGED when compared to the conditions of the last AHERA reinspection.

The current AHERA DAMAGE CATEGORY is determined to be **6. ACBM with the potential for damage**

DAMAGE REASON:

DISTURBANCE POTENTIAL: **LOW**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

COMMENTS:

Inspector's Signature: \_\_\_\_\_ Date: **09/17/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
2019 AHERA REINSPECTION

## Management Planner Review Form

LEA NAME: **Chicago Public Schools** UNIT NUMBER: **25601** BUIDLING ID: **6180**  
CITY/STATE: **Chicago, Illinois** MANAGEMENT PLANNER: **John Fenn**  
SCHOOL NAME: **Thorp School** REVIEW DATE: **10/14/2019**  
ADDRESS: **8914 S Buffalo Avenue** IDPH LICENSE NO: **100-11102**

---

HOMOGENEOUS AREA: **Y**  
MATERIAL DESCRIPTION: **Pre-form Pipe Joint Insulation**  
MATERIAL LOCATION: **1888 Building- Boiler Room/Unexcavated Areas**  
MATERIAL QUANTITY: **10** MATERIAL UNITS: **LF**  
DAMAGE QUANTITY: **0** DAMAGE UNITS: **LF**

---

In accordance with Sections 763.88 and 763.90 of the Asbestos Hazard Emergency Response Act (AHERA) the LEA must select a management planner to review the results of the inspection and assessment and recommend appropriate response actions. The original inspection of the above identified homogeneous area has been reviewed in accordance with Sections 763.88 and 763.90 with the following recommendations.

The RESPONSE ACTION recommendation is:

**Follow O&M Plan**

Comments:

Management Planner's Signature: \_\_\_\_\_ Date: **10/14/2019**

# Chicago Public Schools

TEM Environmental, Inc.  
*2019 AHERA REINSPECTION*

# APPENDIX B

## Inspector and Management Planner Licenses

---

# CERTIFICATE OF ACHIEVEMENT ASBESTOS ABATEMENT

Accredited by the Illinois Department of Public Health

This is to certify that ELMER SPRAGGINS II  
has completed the ASBESTOS INSPECTOR'S INITIAL course and successfully passed the  
examination on 01/30/2019 with a minimum score of 70% or better. Training was in accordance  
with U.S. E.P.A. 40 CFR 763 Subpart E, Appendix C, Asbestos Containing Materials in Schools:  
Model Accreditation Plan, TSCA II, Authorized by both AHERA & ASHARA.

01/28/2019-01/30/2019

Course Dates:

01/30/2020

Expires:

1901BI06

Certificate Number:



**PUBLIC HEALTH & SAFETY** inc.

Environmental and Occupational Services  
275 Ashland Ave., Chicago, IL 60607

[www.public-health-safety.com](http://www.public-health-safety.com)

Office: 312-491-0081

Fax: 312-421-2921

Director of Training

Nicholas J. Peneff

Doctor of Public Health




Phone: 312-491-0081

FORM # A-010

COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License

		<b>ASBESTOS PROFESSIONAL LICENSE</b>		<b>ENDORSEMENTS</b>	<b>TC EXPIRES</b>
ID NUMBER	ISSUED	EXPIRES		INSPECTOR	1/30/2020
100 - 11102	4/16/2019	05/15/2020		PROJECT MANAGER	3/29/2020
<b>ELMER SPRAGGINS II</b>				AIR SAMPLING PROFESSIONAL	
12823 S GREEN				<b>Alteration of this license shall result in legal action</b>	
CHICAGO, IL 60643				This license issued under authority of the State of Illinois	
Environmental Health				Department of Public Health	
				This license is valid only when accompanied by a valid training course certificate.	



2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Building Inspector Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**

has successfully completed the Asbestos Building Inspector Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: BIR1903191011

A handwritten signature in black ink that reads 'Kathy DeSalvo'.

---

Kathy DeSalvo, Director

2019



**OCCUPATIONAL TRAINING & SUPPLY, INC.**

7233 S. Adams Street ♦ Willowbrook, IL 60527 ♦ (630) 655-3900 ♦ [www.otssafety.com](http://www.otssafety.com)

# Asbestos Management Planner Refresher

Occupational Training & Supply, Inc. certifies that

**John Fenn**


has successfully completed the Asbestos Management Planner Refresher course and has passed the competency exam with a minimum score of 70%. The course is accredited by the Illinois Department of Public Health and Indiana Department of Environmental Management for purposes of accreditation in accordance with EPA 40 CFR 763, Asbestos Hazard Emergency response Act (AHERA) and TSCA Title II.

Course Date: 3/19/2019

Exam Date: 3/19/2019

Expiration Date: 3/19/2020

Certificate Number: MPR1903191035



---

Kathy DeSalvo, Director

# COPY OF THE ASBESTOS PROFESSIONAL LICENSE

Front of License

Back of License



## ASBESTOS PROFESSIONAL LICENSE

### ENDORSEMENTS

### TC EXPIRES

INSPECTOR

3/19/2020

ID NUMBER

ISSUED

EXPIRES

MANAGEMENT PLANNER

3/19/2020

100 - 09786

4/11/2019

05/15/2020

PROJECT MANAGER

3/18/2020

**JOHN H FENN**

2829 N TROY ST

CHICAGO, IL 60618

Environmental Health



AIR SAMPLING PROFESSIONAL

**Alteration of this license shall result in legal action**  
This license issued under authority of the State of Illinois  
Department of Public Health

This license is valid only when accompanied by a valid  
training course certificate.

# APPENDIX C

## Laboratory Accreditations

---

# APPENDIX D

## Laboratory Results

---

# APPENDIX E

## Chain of Custody Forms

---

## Three-Year Reinspection Key to Terms

	<b>CODE</b>	<b>KEY</b>
<b>MATERIAL</b>		
	ACBM	Asbestos Containing Building Materials
<b>MATERIAL CATEGORY</b>		
	MISC	Miscellaneous
	SURF	Surfacing
	TSI	Thermal System Insulation
<b>MATERIAL UNITS</b>		
	LF	Linear Feet
	SF	Square Feet
	CF	Cubic Feet
<b>DAMAGE TYPE</b>		
	Loc	Localized
	Dist	Distributed