Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

22161

Oracle Unit:

Address: 1140 W. 66th Region: 05 Mail Room: Asbestos Surveyor: Dixon, Mr. Charles Wayne X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/20/2016 Email Address: cwdixon@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Type Quantity Units X NO YES 01 hard coat plaster 75000 SF throughout 1894 building Surface No None 0 2016 - Fall: No Change Comments: HA No Material Description Material Location Change in Assessment Category Material Material Asbestos Material Friable Damage Damage Damage Category Units Quantity Units Type Type Quantity 1894 - rm 08, 07, 01 & X NO bsmnt crrdr & playrms, YES rm 106, 103, 104, 107 & 108 & 1st flr storage & 02 12x12 beige floor tile 6000 SF Miscellaneous No Dist 20 wardrobes, rooms 303-306, counselor's office, and principals office 2016 - Fall: No Change Comments:

Perkins Bass School

School:

2180

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
2	12x12 beige floor tile	2850	SF	Rms. 301, 302, and 308		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments	:												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
03	9x9 black with white streaks floor tile	100	SF	1894 bldg - engineer's office, toilet		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
04	hardcoat plaster	10400	SF	1939 building- basement assembly hall & platform		Surface	No	None	0		YES		X NO
2016 - Fall	: No Change				1								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
07	9x9 Dark and Light Brown floor tile	3000	SF	1960 bldg- 1st & 2nd floor west and north corridor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
09	Mastic Associated w/ 12x12 beige floor tile	6000	SF	1894 - rm 08,07,01 & bsmnt crrdr & playrms, rm 106,103, 104 & 1st flr strge & wardrobes, rm 303-306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	to onango				1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
10	9x9 floor tile mastic	100	SF	1894 bldg - engineer's office & toilet	,,	Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	10 Orlange				-							
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damana	Damasa	I Damasa	Ohanas in Aa	sessment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
11	mastic Associated w/ 9x9 Dark and light brown floor tile	3000	SF	1960 bldg- 1st & 2nd floor west and north corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	to change											
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in As	sessment Category
12	2' x 2' Speckled Ceiling Tile	1500	SF	1st Floor Lunch Room and Adjacent Corridor		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
13	Spray-on Insulation	300	SF	Metal Pan Ceiling in Kitchen (N)		TSI	Yes	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments	:												
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
14	Brown Ceramic Floor Tile w/ Grout	600	SF	Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
15	Adhesive Associated w/ Brown Ceramic Floor Tile w/ Grout	600	SF	Door #8 and #5, North Entrance Foyer, Boy's and Girl's Bathrooms on 1st and 2nd Floor of 1960 Building		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments													
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
BB-1	baseboard			1st, 2nd, 3rd floor corridors - 1894 building		Miscellaneous					YES		X NO
2016 - Fall:	No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
BBM-1	baseboard mastic			1st, 2nd, 3rd floor corridors - 1894 building		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
CM-1	blue carpet mastic			Room 303, 305, Art Room		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
CM-2	light blue carpet mastic	180	SF	assistant principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
CT1	2 X 4 Smooth Ceiling Tile	1000	SF	Kitchen		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	22922	ment Category
TIANO	Watchar Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onange in A	33033	ment Category
CT2	2 X 4 Ceiling Tile	2730	SF	Room 303, 305, Art Room, Principal Office, Assistant Principal's Office, Lunchroom		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall	: No Change				٦								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
FT-1	9x9 tan floor tile	100	SF	basement bathroom, engineer's toilet		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				٦								
Comments	Ţ												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
FT-10	12x12 blue floor tile	15	SF	Faculty room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
FT-11	12x12 brown floor tile	75	SF	Principal rest room, storage closet, main office safe		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments					7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
FT-12	12x12 brown floor tile mastic	75	SF	Principal rest room, storage closet, main office safe		Miscellaneous	No	None	0		YES X NO	
2016 - Fall:	No Change	<u> </u>		·	1							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
FT-2	12x12 light brown w/white specks floor tile	600	SF	stair case landing-1894		Miscellaneous	No	None	0		YES X NO	
2016 - Fall:	No Change]							
Comments												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
FT-3	12x12 brown w/white flecks floor tile	750	SF	room 302 and Wardrobes		Miscellaneous	No	Loc	40		YES X NO	
2016 - Fall:	No Change				1							
Comments	<u> </u>]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
FT-4	12x12 white w/ tan and gray flecks floor tile	750	SF	Room 308		Miscellaneous	No	None	0		YES X NO	
2016 - Fall	No Change				 1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
FT-5	linoleum			room 109, 113		Miscellaneous					YES		X NO
2016 - Fall	: No Change				1		•						
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
FT-6	9x9 dark tan w/brown streaks floor tile	5950	SF	room 115, 213, 214, 216, 208, 210,209,217,2nd floor faculty room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change				1								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
FT-7	12x12 off white w/brown & gray flecks floor tile			room 211		Miscellaneous					YES		X NO
2016 - Fall:	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
FT-8	12x12 brown w/white specks floor tile	300	SF	hall between 1939, 1960		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	No Change	•	•	•	1	•	-	•	•	•			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FT-9	12x12 blue floor tile	3200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				Ī							
Comments												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FTM-1	mastic beneath 9x9 tan floor tile	100	SF	basement bathroom, engineer's office toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments	<u>~</u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FTM-2	12x12 light brown w/white specks floor tile mastic	600	SF	stair case landing-1894		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
FTM-3	12x12 brown w/white flecks floor tile mastic	750	SF	room 302		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments	U											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	ent Category
FTM-4	12x12 white w/ tan and gray flecks floor tile mastic	750	SF	room 308		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:	J												
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	ent Category
FTM-5	linoleum mastic			room 109, 114, 113		Miscellaneous					YES		X NO
2016 - Fall: N Comments:	lo Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	ent Category
FTM-6	9x9 dark tan w/ light brown streaks floor tile mastic	5950	SF	room 115, 213, 214, 216, 208, 210,209,217, 2nd floor faculty room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:	J]								
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	ent Category
FTM-7	12x12 off wht w/brwn & gray flecks flr tile mastic			room 211		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change			·]								
Comments:	<u> </u>												

Comments:	No Change				-								
004C F-II	No Change		1	1	1	1		1	_1		L		
I	aircell pipe	200	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room		TSI	Yes	None	0		YES		X NO
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
Comments:]								
2016 - Fall:	No Change]								
G	Acoustical Plaster			1960 building, rms 117,115,113,110,108,111 ,109, girls&boys rr, JC, stairs		Surface					YES		X NO
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
Comments:	:				-								
	No Change]								
FTM-9	12x12 blue floor tile mastic	3200	SF	N. Entrance Foyer, Room 210, 2nd Floor Corridor, Engineer's Office, Auditorium		Miscellaneous	No	None	0		YES		X NO
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
Comments:	:				_								
	No Change												
FTM-8	12x12 brown w/white specks floor tile mastic	300	SF	hall between 1939, 1960		Miscellaneous	No	None	0		YES		X NO
TIANO		Quantity	Units	iviaterial Location	Type	Category	Thable	Type	Quantity	Units	Change in A	33033	ment Category
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	2222	ment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
J	aircell joints	30	LF	1894 bldg - boys playroom, storage, book room, girls playroom, fan room		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	cardboard pipe	200	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
Commonto	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L	cardboard joints	20	LF	1894 bldg- basement boys & girls playroom, fan room, toilets, corridors		TSI	Yes	Loc	1		YES	X NO
2016 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
N	fiberglass joints			1894 bldg-basement boys & girls toilets & playrooms, toilets, fan room		TSI					YES	X NO
2016 - Fall	: No Change				1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
0	aircell pipe lag	900	LF	1939 building- basement assembly room, platform, fan room		TSI	Yes	Loc	1		YES		X NO
2016 - Fall	: No Change				1								
Comments					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
Р	aircell pipe-1960 bldg	100	LF	1960 bldg- 2nd floor stairwells (between room 217 & 210, between rooms 209 &mens bathroom)		TSI	Yes	None	0		YES		X NO
2016 - Fall	: No Change				7								
Comments					1								
Commonto	,,												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Ssessr	ment Category
Q	aircell joints	50	LF	1939 bldg - plaform, fan room		TSI	Yes	None	0		YES		X NO
2016 - Fall	: No Change				1								
Comments					1								
Commonto	, <u>, </u>				_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Ssessr	ment Category
R	fiberglass joints- ABATED			1960 bldg- 2nd floor west corridor		Miscellaneous					YES		X NO
2016 Fall	· No Chango												
Comments	: No Change				-								
) .				1								

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Perkins Bass School
Date: 12/20/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.