## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2016 - Fall

22231

01

**Oracle Unit:** 

Region:

Building ID: 2270

Mail Room:

X CHEC	K HERE IF NO CHA	ANGE T	O ASBE	STOS	Asbestos Surveyor: Survey Date: Email Address:	12/14/20	z, Mr. Sergio 16 z2@cps.edu						
	A copy of the 2016/20  Each child's backpa				g the asbestos mana			was distribut ool's calenda		her			
HA No	Material Description	Material Quantity	Material Units	Material Locat	tion Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
01	Skim Coat and Hard Coat Plaster			Main Building		Surface	No	None			YES		X NO
2016 - Fall: Comments:	No Change												
HA No	Material Description	Material Quantity	Material Units	Material Locat	tion Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
02	2'x4' Ceiling Tile			Throughout		Miscellaneous	Yes	Unknown			YES		X NO
2016 - Fall: Comments:	No Change												
HA No	Material Description	Material Quantity	Material Units	Material Locat	tion Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
05	Carpet Mastic	72000	SF	Throughout		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: Comments:	No Change												

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Alexander Graham Bell School

Address: 3730 N Oakley Avenue

School:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
06	12"x12" White w/ Gray Vinyl Floor Tile	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments	S:											
			_									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
07	9"x9" Gray Vinyl Floor Tile	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
08	Green Linoleum	900	SF	Kindergarten (112)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
09	12"x12" White w/ Gray Vinyl Floor Tile Mastic	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments	<u> </u>				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	9"x9" Gray Vinyl Floor Tile Mastic	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 107		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	9"x9" Brown Vinyl Floor Tile	360	SF	Room 307, 309 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	:											
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12A	9"x9" Brown Vinyl Floor Tile Mastic	360	SF	Room 307, 309 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	12"x12" Beige Vinyl Floor Tile	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
15	12"x12" Beige Vinyl Floor Tile Mastic	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0		YES		X NO
0040 5 11 1					7								
2016 - Fall: N	lo Change												
Comments:													
					]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
16	Brown Linoleum	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES		X NO
0040 5.11 1	I. Ol				1								
2016 - Fall: N	lo Change				-								
Comments:													
					]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
17	Brown Linoleum Mastic	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Chango			•	1								
Comments:	io Change				1								
Comments:					-								
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
18	9'x9" Beige w/ Brown Streaks VFT NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				]								
Comments:					1								
					i								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
19	9'x9" Beige w/ Brown Streaks VFT Mastic NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				7								
Comments					1								
					]								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A		ment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in A	.556551	ment Category
20	9"x9" Light Tan VFT - NOT OBSERVED	80	SF	Lunchroom North and South Storage Rooms, now under HA# 06, HA# 09 - NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				٦								
Comments					=								
	144 : 15 : :		T. n. a. a. a. a.	I Maritine e		T. A	Levis	T 5	T.5		1 01		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
21	9"x9" Light Tan VFT Mastic - NOT OBSERVED			Lunchroom North and South Storage Rooms - NOT OBSERVED							YES		X NO
2016 - Fall	: No Change				7								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	issessi	ment Category
22	12"x12" White w/ Green Specks VFT	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				7								
Comments					+								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
23	12"x12" White w/ Green Specks VFT Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
24	1 x 1 ft Ceiling Tiles	1000	SF	Students Lunch Room		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
25	12"X12" White w/ Blue Specks VFT	800	SF	Lunch Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
26	12" X 12" Gray/Blue w/Gray Specks	300	SF	Lunch Room		Miscellaneous	No	None	0		YES	]	X NO
2016 - Fall:	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
27	12"X12" Tan w/Brown Specks	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
28	12"X12" Pink w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<b>V</b>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	12"X12" Yellow w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
30	Mastic associated with the new HA numbers 25, 26, 27, 28, and 29.	1400	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
31	12" X 12" light beige with beige-and-white streaks, VFT	800	SF	Room 314 B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
31A	12" X 12" light beige with beige-and-white streaks, Mastic	800	SF	Room 314 B		Miscellaneous		None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32	12" X 12" white with black specks, VFT	1100	SF	Rm 312		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	U											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32A	12" X 12" white with black specks, Mastic	1100	SF	Rm 312		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change			<u> </u>								
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	18 " X 18" brown VFT	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33A	18" X 18" brown, Mastic	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	Mudded joint packing on fiberglass runs	50	LF	Attic, 3rd floor corridor above ceiling tiles, Auditorium vestibules, Book Room by balcony 200S.		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:	rto Onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
35	Decorative plaster	2500	SF	Auditorium and balcony		Surface	No	None	0		YES	X NO
2016 - Fall	No Change	•	•	•	]	•	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
36	1'x1' Ceiling Tile			Rooms 317 and 105		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
36A	1'x1' Ceiling Tile Mastic			Rooms 317 and 105		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	No Change											
Comments:	Ü											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
С	Aircell Pipe Insulation	600	LF	1st Floor Assembly Vestibule (5 LF); Throughout Attic (95 LF)		Miscellaneous	Yes	Dist	100		YES	Х NO
2016 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
E	Preformed Pipe Insulation	530	LF	2nd & 3rd Fl Boys and Girls Pipe Chases, Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change			·	]							

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _/	Alexander Graham Bell School
Date: _	12/14/2016
the Asbesto	tify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of s Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. Dection was completed in 2016.  Inveillances are conducted every six months.
CHECK ONE	
A cop	by of this notice was sent home in each child's backpack.
X A cop	by of this notice was printed in the school's newsletter and sent home with each child
A cop	by of this notice was printed in the school's calendar and sent home with each child
Other	r.
A COPY	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 22231

SCHOOL'S ASBESTOS MANAGEMENT PLAN.