Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

	Address: 2450 W. R	ice Street				Re	gion:	02		Mail Ro	oom: 35		
X CHECK	HERE IF NO CHA	NGE TO) ASBE			Rivera, M 12/20/201 rrivera@c	6						
	A copy of the 2016/201 Each child's backpace		· 	d staff regarding the asb				vas distribute pol's calendar		per			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
01	12x12 Green VFT	1500	SF	NW, NE, SE, & SW Stairwells 1st to 2nd Floors		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N Comments:	o Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
1-C	MJP Elbow on Air Cell Pipe Insulation	10	LF	Fan Rooms, Bathrooms, Basement South Corridor		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	o Change]								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	ent Category
02	Pre-formed (Mag Block) Pipe Insulation	408	LF	Air Tunnels and Under Auditorium in Crawl Space		TSI	Yes	Loc	25		YES]	X NO
2016 - Fall: N Comments:	o Change												

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Frederic Chopin School

School:

Building ID: 2770

22721

Oracle Unit:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03	Plaster	160000	SF	Throughout School		Surface	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04	Blown In Insulation	10000	SF	Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	1x1 Ceiling Tile	1500	SF	2nd Floor Gym		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06	12"x12" Green Vinyl Floor Tile Mastic	1500	SF	NW, NE, SE, & SW Stairwells 1st to 2nd Floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
08	Drywall	450	SF	Room #101, #112 bath.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
11	1x1 Ceiling Tile Brown Mastic	1500	SF	2nd Floor Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
13	12"x12" Red/Brown Vinyl Floor Tile	900	SF	Auditorium Stairwells, Engineers Office & Closet, Rooms 106, 105 - Not observed in Room 105, 106 and 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				1							
Comments:					1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
14	12"x12" Red/Brown Vinyl Tile Mastic	900	SF	Auditorium Strairwell, Engineers Office & Closet, Rooms 106, 105, 104 - Not observed in ROOM 105, 106 and 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
15	12"x12" White Vinyl Floor Tile	1700	SF	2nd Floor Main Offices, Rooms 106, 105, 104 (Lunch Rooms)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:	140 Onlange												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
16	12"x12" White Vinyl Floor Tile Mastic	1700	SF	2nd Floor Main Offices, Rooms 106, 105, 104 (Lunch Rooms)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:	i to onango												
	T							Т _		1 _			-
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
17	12x12 Grey/Brown VFT	400	SF	Engineers Office		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change				7								
Comments:													
LIA NI-	Material Description	I Maradal	I Maria dal	I Material Landon	A -11 -	I Martania I	Legania	I B	I Daniel	I D	Ob ' A		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
18	12x12 Grey/Brown VFT Mastic	400	SF	Engineers Office		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change				7								
Comments:	<u>U</u> -												

					•	•			•			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
19	12x12 Light Brown/Yellow VFT	1200	SF	NW, NE, SE, SW Stairwells 2nd -3rd Flrs, NW & NE 3rd Flr Balcony Landings (Under Carpet) - Could not verify under cabinet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	10 0.1.a.1.go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20	12x12 Light Brown/Yellow VFT Mastic	1200	SF	NW, NE, SE, SW Stairwells 2nd-3rd FIrs, NW & NE 3rd FIr Balcony Landings (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
23	12"x12" Tan VFT	800	SF	Room 104, 105		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	12"x12" Tan VFT Mastic	800	SF	Room 104, 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•			1		•	•	•	•		

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	12"x12" Brown VFT	800	SF	Room 104, 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	-											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
26	12"x12" Brown VFT Mastic	800	SF	Room 104, 105, 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	3											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	· · · · · · · · · · · · · · · · · · ·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
27	Carpet Mastic (yellow and black mastic under red carpet), no VFT observed.	1800	SF	Room 20 and Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to change				1							
]							
LIA No	Material Description	Matarial	Matarial	Material Lagration	A = h = = 4 = =	Matarial	Frields	Damana	Damana	Damasa	Channa in Assa	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
D	Air Cell Pipe Insulation	160	LF	Fan Rooms, Bathrooms, Basement South Corridor, Tunnel Entrance and 101 Bathroom		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
E	MJP E/F/V on Fiberglass Pipe Insulation	25	LF	Bathroom Pipe Chases and 211 Wardrobe		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change				7								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
F	Incinerator - Fire Yellow Brick	35	SF	Boiler Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				7								
Comments:	<u> </u>												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
G	Mortar (Associated with Incinerator Fire Brick)	20	SF	Boiler Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				7								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
Н	12' x 12" VFT - Pink with White Streaks	15	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				7								

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
1	Mastic Associated with New VFT Pink with White Streaks	15	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES	X NO
204C Fall I	No Change				\neg							
2016 - Fall: I Comments:	vo Change											
Comments.					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
J	12" x 12" VFT - Green with Dark Green Streaks	24	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Chango				\neg							
Comments:	NO Change											
Comments.												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
К	Mastic - Associated with HA #J - 12" x 12" Green with Dark Green Streaks	24	SF	Room 112 - New Bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				\neg							
Comments:	10 Onlange											
Commonto.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
L	2' x 2' White Ceiling Tile	48	SF	Room 112 - New Bathroom		Miscellaneous	Yes	None	0		YES	X NO
2016 Fall: I	No Chango											
2016 - Fall: I Comments:	NO CHAILIGE				\dashv							
LOUITINETIES.					I							

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Frederic Chopin School
Date:	12/20/2016
This is to n	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
the Asbesto	os Management Plan is available at each school during school hours by appointment.
Requests to	o review the Asbestos Management Plan must be made at least 24 hours in advance.
•	e be advised that CPS conducts asbestos inspections of all Schools every three years.
	spection was completed in 2016.
Asbestos s	surveillances are conducted every six months.
CHECK ON	IE
OF ILON ON	<u>IL</u>
A co	opy of this notice was sent home in each child's backpack.
A co	ppy of this notice was printed in the school's newsletter and sent home with each child
A co	opy of this notice was printed in the school's calendar and sent home with each child
Othe	er.
A COPV	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 22721