Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

	Address: 4837 W. I	Erie Street				Re	egion:	02		Mail Ro	oom: 36		
X CHEC	K HERE IF NO CH	ANGE TO	O ASBE			12/8/2016	Mr. Kevin O						
	A copy of the 2016/20 Each child's backpa		_	d staff regarding the asl				was distribute ool's calenda		her			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
01	Hard Coat Plaster			Throughout- 1895 Building							YES		X NO
Comments:	No Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
02	9"x9" Grey w/ White Streaks VFT - NOT OBSERVED	1800	SF	Rm 105 and 105 Closet, - 1895 Bldg.		Miscellaneous	No	None	0		YES		Х NO
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in I	Assess	sment Category
03	12"x12" Brown w/ White Specks VFTABATED IN 2012			Rm 312, 1st, 2nd & 3rd Fl Corridor - 1895 Bldg. ABATED IN 2012		Miscellaneous					YES		X NO
2016 - Fall: Comments:	No Change												

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Henry H Nash School

School:

Building ID: 5050

24641

Oracle Unit:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
04	2'x4' Ceiling Tile w/ Grooves - NOT OBSERVED			Lunchroom- 1918 Building			No				YES		X NO
2016 - Fall: N	lo Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
08	9"x9" Grey w/ White Streaks VFT Mastic - NOT OBSERVED	1800	SF	Rm 105 and 105, Closet - 1895 Bldg.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:	io oriango												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
09	12"x12" Brown w/ White Specks VFT Mastic - ABATED IN 2012			Rm 312, 1st, 2nd, 3rd Fl Corridors, 1st flr women's toilet- 1895 Bldg. ABATED IN 2012		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:	go												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
13	12"x12" Orange Speckled VFT	4810	SF	1st-3rd Flr Corridor (Abated 2012), Basement Lun. Rm, Rm 103 A/Closet (Abated 2012) , Gym Strge, E Stair Land (Abated 2012) 1918 Bldg.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
15	12"x12" Orange Speckled VFT Mastic	4870	SF	1st-3rd Flr Corridor (Abated 2012), Basement Lun. Rm, Rm 103 A/Closet (Abated 2012), Gym Strge, E Stair Land (Abated 2012) 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	10 Onango											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
27	12"x12" Beige w/ Brown Specks VFT - ABATED IN 2012			1st-3rd FI Corridors, 1st & 2nd FIr. Womens Toilet, 3rd FIr. Mens Toilet - 1895 Bldg. ABATED IN 2012		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Change											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
28	12"x12" Beige w/ Brown Specks VFT Mastic - ABATED IN 2012			1st-3rd FI Corridors, 1st & 2nd FIr. Womens Toilet, 3rd FIr. Mens Toilet - 1895 Bldg. ABATED IN 2012		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 0.101.1go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	12"x12" Orange w/ White Specks VFT	1260	SF	Rm 112, West Stair Landing Between 2nd & 3rd Floor Corridor, and Library Closet - 1895 Bldg. (NOT OBSERVED)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	12"x12" Orange w/ White Specks VFT Mastic	1200	SF	Rm 112, West Stair Landing Between 2nd & 3rd Floor Corridor, and Library Closet - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
31	12"x12" Tan w/ White Specks VFT - NOT OBSERVED			Engineers Offices - 1895 Bldg.							YES	X NO
2016 - Fall: N	lo Change											
Comments:	V											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
32	12"x12" Tan w/ White Specks VFT Mastic - NOT OBSERVED			Engineers Offices - 1895 Bldg.							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
33	12"x12" Dark Brown w/ White Specks VFT (NOT OBSERVED)	850	SF	Rm 006 - 1895 Bldg Doesn't Exist		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
34	12"x12" Dark Brown w/ White Specks VFT Mastic (Not Observed)	800	SF	Rm 006 - 1895 Bldg Couldn't Find Classroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
35	12"x12" Grey Speckled VFT - ABATED IN 2012			1st FI Teachers Rm (Under Carpet) - 1918 Bldg. ABATED IN 2012		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
36	12"x12" Grey Speckled VFT Mastic - ABATED IN 2012			1st Fl Teachers Rm (Under Carpet) - 1918 Bldg. ABATED IN 2012		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	to onango											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
37	12"x12" Tan Speckled VFT - NOT OBSERVED	800	SF	Main Office - 1918 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
38	12"x12" Tan Speckled VFT Mastic- NOT OBSERVED	800	SF	Main Office - 1918 Bldg.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:	V												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
39	Ceramic Tile Grout	3200	SF	1895 and 1918 Buildings - All Girls and Boys Restrooms, Mens and Womens Restrooms, Basement Vestibule		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	No Chango				1								
Comments:	NO Change												
Comments.													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
39A	Ceramic Tile Adhesive	3200	SF	1895 and 1918 Buildings - All Girls and Boys Restrooms, Mens and Womens Restrooms, Basement Vestibule		Miscellaneous	No	None	0		YES		X NO
2016 Falls N	la Changa				1								
2016 - Fall: N	No Change												
Comments.													
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
40	9 x 9 Green Floor Tile- NOT OBSERVED	500	SF	Paint Room in Basement		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change	-]								
Commonts:	NO OHAHYE				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
41	9 x 9 Green Floor Tile Mastic- NOT OBSERVED	500	SF	Paint Room in Basement		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
42	Carpet Adhesive	4000	SF	Engineer's Office , Library (Rooms 101 and 103), Principal's Office - 1895 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
43	12 x 12 Light Brown Floor Tile- Not Observed	100	SF	Room 006 Closet- Doesn't Exist		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
44	12 x 12 Light Brown Floor Tile Mastic-NOT OBSERVED	100	SF	Room 006 Closet - Doesn't Exist		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	sment Category
45	12 X 12 Offwhite w/ Beige Specks VFT	6000	SF	1st, 2nd, 3rd Floor Corridors, Room 312, 105 & Closet, 112 & Closet, 012, Pre-K Room Bldg 1895		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	sment Category
46	12 x 12 Offwhite w/ Beige Specks Mastic	6000	SF	1st, 2nd, 3rd Floor Corridors, Room 312, 105 & Closet, 112 & Closet, 012, Pre-K Room Bldg 1895		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	No Change				1								
Comments													
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in	Asses	sment Category
	· ·	Quantity	Units		Туре	Category		Туре	Quantity	Units	J		3 ,
47	12 x 12 Beige Speckled VFT & Mastic	3120	SF	1st, 3rd Flr Teachers Toilet, 1,2,3 Fur Corridors, Basement Offices Bldg 1895		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	No Change				1								
Comments	<u> </u>												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in	A c c o c	sment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in 7	15565	smem category
48	12 x 12 Beige Speckled Mastic	3120	SF	1st, 3rd Flr Teachers Toilet, 1,2,3 Fur Corridors, Basement Offices Bldg 1895		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
49	12 x 12 Offwhite w/ Beige VFT	4000	SF	Basement 3rd, 2nd, 1st Elevator Lobby, 1, 2, 3 Flr Corridors. Room 102, Lunchroom Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
]							
		T	T	T	T		1 =	T	T	1_	I a	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	12 x 12 Offwhite w/ Beige Mastic	4000	SF	Basement 3rd, 2nd, 1st Elevator Lobby, 1, 2, 3 Flr Corridors. Room 102, Lunchroom Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments	<u> </u>											
]							
IIA NIa	Material Description	Matarial	Matarial	Matarial Laustina	A shootes	Matarial	Frieble	Domesia		Domesti	Channa in An	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
51	12 x 12 Beige Speckled VFT	3000	SF	1,2,3 Floor Corridors. 3, 2 Copy Room, Main Office, Fire Panel Room 1st Flr. Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments	<u>~</u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
52	12 x 12 Beige Speckled Mastic	3000	SF	1,2,3 Floor Corridors. 3, 2 Copy Room, Main Office, Fire Panel Room 1st Flr. Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
53	12 x 12 Orange Speckled VFT	2800	SF	Room 312 & Storage 105 & Closet, 112, 012, Pre-K Room Bldg 1895		Miscellaneous	No	None	0		YES	Х NO
2016 - Fall:	No Change	•		•	1							
Comments:	140 Offarigo											
]							
		T		1				T _	1 -	1 _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
54	12 x 12 Orange Speckled Mastic	2800	SF	Room 312 & Storage 105 & Closet, 112, 012, Pre-K Room Bldg 1895		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	110 Onlango											
	Tara de la composição	1	T. A. A	I sa e e e e	T A 1 .	1	Term	1.5	T.5	T.5	l oı	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
55	Fire Doors	168	SF	Assembly Balcony & Projector Room Bldg 1895		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	V											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
56	12 x 12 Orange Speckled VFT	1200	SF	102, Lunchroom Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
57	12 x 12 Orange Speckled Mastic	1200	SF	102, Lunchroom Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:]							
			_		<u>.</u>		_					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
58	Spray on FireProofing	200	SF	3rd, 2nd Floor Copy Room, Library Closet, 1st Floor Fire Pane Room, Basement Machine Room Bldg 1918		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	_											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
59	2 x 2 Smooth Ceiling Tile	2200	SF	012, Pre-K Room Bldg 1895		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
60	Drywall System	5000	SF	Basement Throughout Bldg 1895		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
61	2 x 2 Smooth Ceiling Tile	1600	SF	Lunchroom Bldg 1918		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
62	12 x 12 Sand w/ Specks VFT	1200	SF	Auditorium Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
63	12 x 12 Sand w/ Specks Mastic	1200	SF	Auditorium Bldg 1918		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
В	MJP E/F/V on Fiberglass	20	LF	Coal Rm, 3rd Floor Men's Toilet and Women's Restroom - 1895 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
D	MJP on Fiberglass	25	LF	Assembly Hall Foyer, Womans, Girls and Boys Restrooms - 1918 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												
]							
HA No	Material Decoriation	Matarial	Matarial	Matarial Laurtina		Matarial	Frields	Damasa		Domesia	Change in Acc	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
E	Aircell Pipe Insulation	230	LF	Gym Attic, Gym Office, Gym Storage, 006 Closet, and Paint Room - 1918 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
					j							
		,	_	T		1		1		_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
L	Texture Popcorn Ceiling	300	SF	Rm 110 Closet - 1895 Bldg,		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments	<u> </u>				1							
	•				<u> </u>							
			•						•			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
N	MJP on Aircell Pipe Insulation	27	LF	Gym Attic, Gym Office, Gym Storage; DOES NOT EXIST in 006 Closet - 1918 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments	· .											

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Henry H Nash School
Date: 12/9/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 24641