## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2016 - Fall

	Address: 5250 S. R	ockwell				R	egion:	04		Mail Ro	oom: 43		
X CHECK	HERE IF NO CHA	NGE TO	) ASBE			3/28/201	y, Mr. Craig 7 ey@cps.edu						
	A copy of the 2016/201	7 notice to	parents an	d staff regarding the asl	bestos manaç	gement plan no	otifications v	vas distribute	d via:				
	Each child's backpa	ck	X Notice	orinted in school's news	sletter	Notice pr	inted in sch	ool's calenda	r Otl	ner			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
1	Ceiling plaster	59700	SF	throughout original building		Surface	Yes	None	0		YES		X NO
2016 - Fall: N Comments:	lo Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
2	wall plaster	99280	SF	thourghout original building		Surface	Yes	None	0		YES		X NO
2016 - Fall: N Comments:	lo Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
9	Aircell Pipe Insulation	350	LF	Control Room, Basement and Tunnel		TSI	Yes	None	0		YES		X NO
2016 - Fall: N Comments:	lo Change												

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

Florence Nightingale School

School:

Building ID: 5090

24671

Oracle Unit:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
9b	Aircell Pipe Insulation	350	LF	Control Basement & Tunnel		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
24	Vinyl Baseboard Mastic	160	LF	Kindergarten Rooms 103 and 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
25	Drywall (Wallboard)	600	SF	Kindergarten Rooms 103 and 105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
26	Terrazzo- Grey Mix	1500	SF	1st and 2nd Floors and Stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			·	]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment C	Category
27	Exterior Brick - Not AHERA			Main Building - West Side		Miscellaneous					YES	X	NO
2016 - Fall:	No Change				]								
Comments:	•				1								
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment C	Category
28	Exterior Brick Mortar - Not AHERA			Main Building - West Side		Miscellaneous					YES	X	NO
2016 - Fall:	No Change				]								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment C	Category
29	Exterior Concrete - Not AHERA			Main Building - West Side		Miscellaneous					YES	X	NO
2016 - Fall:	No Change				]								
Comments:	Ţ.												
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment C	Category
30	Exterior Brick - Not AHERA			Boiler House - West Side		Miscellaneous					YES	X	NO
2016 - Fall:	No Change			<u> </u>	]								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
31	Exterior Brick Mortar - Not AHERA			Exterior of Boiler House - West Side		Miscellaneous					YES		X NO
2016 - Fall:	No Change				1								
Comments:					]								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
32	Exterior Concrete - Not AHERA			Exterior of Boiler House - West Side		Miscellaneous					YES		X NO
2016 - Fall:	No Change				1								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessr	ment Category
33	12" x 12" White w/Grey Floor Tile	18000	SF	Throughout 1st Floor and 2nd Floor Corridors of Old Building.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:					]								
					]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
34	12" x 12" White w/Grey Floor Tile Mastic	18000	SF	Throughout 1st Floor and 2nd Floor Corridors of Old Building.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	Roofing Materials - Not AHERA			Roof		Miscellaneous					YES	X NO
	No Change				]							
Comments	:				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units	3	,
38	Spray-on	780	SF	Boiler Room Around Receiving Tank, Chilled & Condensate Water Supply, Air Intake Room		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39	9" x 9" Brown w/Green & White Specs Floor Tile	120	SF	Room 107 Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments	:											
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
40	9" x 9" Brown w/Green & White Specs FT Mastic	120	SF	Room 107 Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
41	12" x 12" Beige w/Tan Speckles FT	1400	SF	Rooms 110, 113A, 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	U											
_	1	_			_			_				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
42	12" x 12" Beige w/Tan Speckles FT Mastic	1400	SF	Rooms 110, 113A, 100		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
43	12" x 12" Beige w/Brown & Green FT	5500	SF	Rooms 102 and 104 - 108, Counselor's Office, 211A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments	U											
	T	1			1		T =	T =		T =	T	-
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
44	12" x 12" Beige w/Brown & Green FT Mastic	5500	SF	Rooms 102 and 104 - 108, Counselor's office, 211A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
45	Brown Carpet Adhesive	400	SF	Room 199		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
					<u>_</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
46	Multicolor Carpet Adhesive	2500	SF	Library, 310, 320, Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
47	12" x 12" Beige w/Brown Streaks FT	120	SF	Bathroom, Hallway and Storage in Room 199		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	12" x 12" Beige w/Brown Streaks FT Mastic	120	SF	Bathroom, Hallway and Storage in Room 199		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
49	12" x 12" White w/Gray Specks FT	3300	SF	2003 Modular Mechanical Room, Storage 1-4, Rooms 1-4 and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change				]							
Comments					-							
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIANO	Waterial Description	Quantity	Units	Waterial Location	Type	Category	Thabic	Type	Quantity	Units	Onange in Ass	acasment dategory
50	12" x 12" White w/Gray Specks FT Mastic	3300	SF	2003 Modular Mechanical Room, Storage 1-4, Rooms 1-4 and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change				]							
Comments					-							
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Thable	Type	Quantity	Units	Change in Ass	sessifient Category
51	Beige Baseboard	600	LF	2003 Modular Mechanical Room, Storage 1-4, Rooms 1-4 and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
11/(140	Waterial Description	Quantity	Units	Waterial Education	Туре	Category	Thable	Type	Quantity	Units	Onango in 7 tot	occoment outegory
52	Beige Baseboard Adhesive	600	LF	2003 Modular Mechanical Room, Storage 1-4, Rooms 1-4 and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
53	2' x 2' Speckled Ceiling Tile	3700	SF	In all 2003 Modular Rooms		Miscellaneous	No	None	0		YES		X NO
204C Fall. N	la Changa				7								
2016 - Fall: N Comments:	io Change				-								
Comments.					-								
					1								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	22022	ment Category
10000	Waterial Description	Quantity	Units	Waterial Education	Type	Category	THADIO	Type	Quantity	Units	Change in 70	30000	mont outogory
				2003 Modular Men's and		"		71					
54	Wall Panels	400	SF	Women's Washrooms, Mechanical Room		Miscellaneous	No	None	0		YES	I	X NO
2016 - Fall: N	la Changa				7								
Comments:	io Change				+								
Comments.					+								
					1								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units			
				2003 Modular Men's and								 I	
55	Wall Panel Adhesive	600	SF	Women's Washrooms, Mechanical Room		Miscellaneous	No	None	0		YES	l	X NO
2016 - Fall: N	lo Change				1								
Comments:	io Change				1								
Comments.					1								
					1								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units			
56	Pink Linoleum	200	SF	2003 Modular - Girl's Washroom		Miscellaneous	No	None	0		YES		X NO
2016 Fall: N	lo Chango				1								
2016 - Fall: N	io Change				1								
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
57	Pink Linoleum Adhesive	200	SF	2003 Modular - Girl's Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
58	12" x 12" Beige w/Tan Speckles FT	16500	SF	1998 Addition Rooms 400-409, 419, 421, 300- 308, 310, 311, 313 and 315-318.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
59	12" x 12" Beige w/Tan Speckles FT Mastic	16500	SF	1998 Addition Rooms 400-409, 419, 421, 300- 308, 310, 311, 313 and 315-318.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
60	12" x 12" Aqua/Green Floor Tile	2000	SF	1998 Addition Rooms 400-409 and 300-318		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
61	12" x 12" Aqua/Green Floor Tile Mastic	2000	SF	1998 Addition Rooms 400-409 and 300-318		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
62	Beige Baseboard	3000	LF	1998 Addition - 1st and 2nd Floor Classrooms and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
63	Beige Baseboard Adhesive	3000	LF	1998 Addition - 1st and 2nd Floor Classrooms and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
64	Multi-colored Carpet Adhesive	4000	SF	1998 Addition - 2nd Floor Library, Rm. 310, Principal's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	U											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
65	2' x 4' Fissured Ceiling Tiles w/2' x 2' Pattern	20000	SF	1998 Addition - 1st and 2nd Floor Classrooms, Offices and Corridors		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
66	Spray-on	2000	SF	1998 Addition - 2nd Floor Fan Room, 1st Floor Mechanical and Electrical Rooms		TSI	Yes	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments					]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
67	Vibration Collars	70	LF	1998 Addition - 2nd Floor Fan Room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	I: No Change				7							
Comments	•											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
68	Beige w/Purple Streaks Linoleum	2600	SF	Gym/Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				]							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
69	Beige w/Purple Streaks Linoleum Adhesive	2600	SF	Gym/Lunch Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
70	2' x 4' Smooth Ceiling Tile	2500	SF	Rooms 324, 328, 330 and the Kitchen		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
71	Acoustical Wall Panels	7000	SF	Gym/Lunch Room		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
72	12" x 12" Pink Floor Tile	2200	SF	Mobile Unit - Pre-K All Rooms, 116 & 117		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
73	12" x 12" Pink Floor Tile Mastic	2200	SF	Mobile Unit - Pre-K All Rooms, 116 & 117		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
74	2' x 4' Fissured Ceiling Tile	2200	SF	Mobile Unit - Pre-K All Rooms, 116 & 117		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
75	Blue Linoleum	200	SF	2003 Modular - Boy's Washroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
76	Blue Linoleum Mastic	200	SF	2003 Modular - Boy's Washroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cate	gory
77	12"x12" Cream/Beige Speckled Floor Tile	405	SF	Old Building - Teacher's Lunchroom		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cate	gory
78	12"x12" Cream/Beige Spwckled Floor Tile Mastic	405	SF	Old Building - Teacher's Lunchroom		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change				7								
Comments:	<u> </u>												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cate	gory
79	Vault Door Insulation	21	SF	Main Office		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change				7								
Comments:	<u> </u>												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cate	gory
80	Drywall	280	SF	1998 Addition-1st Floor Under Staris (North), Rooms 411, 413		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
81	Drywall Tape	84	SF	1998 Addition-1st Floor Under Stairs (North), Rooms 411, 413		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				٦							
Comments:												
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
82	Drywall Compound	84	SF	1998 Addition-1st Floor Under Staris (North), Rooms 411, 413		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
83	Plaster Walls	10000	SF	Auditorium		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change				٦							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
84	Plaster Ceiling	5000	SF	Auditorium		Surface	No	None	0		YES	X NO
2016 Fall:	No Chango	•	•			•	-	•	•	•	•	
Comments:	No Change				-							
i Commenta.	•				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
85	2'x4' Ceiling Tile - White Pinhole w/ Worms	60000	SF	Throughout classrooms & Hallways		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: I	No Change				]								
Comments:	i to onango				-								
					]								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	coccr	ont Catagory
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in As	5699111	ieni Calegory
86	Plaster Walls	99280	SF	Throughout Original Building		Surface	No	None	0		YES		X NO
2016 - Fall: I	No Chango	•	•		1	•	•	•	•	1			
Comments:	NO Change				-								
				1		1				Τ =			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	nent Category
F	Aircell Pipe Insulation	1550	LF	Air Tunnel and Control Room		TSI	Yes	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:	110 Onlango				-								
	T	1	1	1				Γ_	1_	T _			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessm	ent Category
Н	Fiberglass Pipe Joint Insulation	100	LF	Basement Chase and Crawlspace		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: I	No Change				]								
Comments:					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Aircell Joints	150	LF	Basement Chase and Crawlspace		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Florence Nightingale School
Date:	3/28/2017
the Asbes	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of tos Management Plan is available at each school during school hours by appointment. to review the Asbestos Management Plan must be made at least 24 hours in advance.
The last in	se be advised that CPS conducts asbestos inspections of all Schools every three years. aspection was completed in 2016. surveillances are conducted every six months.
CHECK O	<u>NE</u>
A c	copy of this notice was sent home in each child's backpack.
X A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
A 00D	V OF THE NOTICE MILET DE DI ACED IN THE
A COP	Y OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 24671

SCHOOL'S ASBESTOS MANAGEMENT PLAN.