Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

24731

Building ID:

2640

Oracle Unit:

Address: 1250 W. Erie Street Region: 02 Mail Room: 33 Asbestos Surveyor: Robinson, Zurbanus X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2016 Email Address: zrobinson8@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Location Friable Change in Assessment Category Material Asbestos Material Damage Damage Damage Quantity Quantity Units Type Category Type 9" x 9" Grey w/ White Art Room (234), 2nd YES X NO 01 Miscellaneous Streaks VFT - ABATED Floor Corridor 2016 - Fall: No Change Comments: HA No Material Description Change in Assessment Category Material Material **Material Location** Asbestos Material Friable Damage Damage Damage Quantity Units Type Category Type Quantity Units Unexcavated Area, Boiler X NO 1C LF YES Aircell Pipe Insulation 80 TSI Yes 0 Room, Fan Room, None Kitchen Manager Office 2016 - Fall: No Change Comments: HA No Change in Assessment Category **Material Description** Material Material Material Location Asbestos Material Friable Damage Damage Damage Type Quantity Units Quantity Units Type Category 2nd floor NE corridor. YES X NO 02 SF Spray-on Ceiling Material 14900 Throughout Corridors, Surface Yes None 0 Room 232, & Auditorium 2016 - Fall: No Change Comments:

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

William B Ogden School

School:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
06	9"x9" Grey w/white streaks VFT Mastic - ABATED			Art Room (234), 2nd floor corridor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07	12"x12" Tan w/Brown Streaks VFT	20000	SF	2nd floor corridor, 2035, 2030, 2032, 2026, 2024, 2013, 2011, 2014, 2012, 2010		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
08	12"x12" Tan w/Brown Streaks VFT Mastic	20000	SF	Throughout (See Hatching Maps) and Vault in Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
09	Tan Linoleum - ABATED			Vestibule of Room 236		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
10	Tan Linoleum Mastic - ABATED			Vestibule of Room 236		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:	to change												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	00000	ment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in A	55655	ment Category
11	Hard Coat Plaster	25000	SF	Throughout		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change	•	•	•	7	•							
Comments:	NO Change												
									•				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
12	9x9 Tan w/White Streaks VFT - ABATED 2014			1st Floor East Corridor		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				7								
Comments:	10 0.1.ago												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	22022	ment Category
TIANO	Material Description	Quantity	Units	Material Education	Type	Category	Thable	Type	Quantity	Units	Change in A	33633	ment Category
13	9x9 Tan w/White Streaks VFT Mastic- ABATED 2014			1st Floor East Corridor		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
14	12x12 Brown VFT Mastic	700	SF	Rooms 1118, 1120 & MDF Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
14A	12x12 Brown VFT	700	SF	Rooms 1118, 1120 & MDF Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
15	12x12 Off-white w/tan streaks VFT Mastic	500	SF	Gym		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
18	12x12 Off-white w/ tan streaks VFT	500	SF	Gym		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change	•		•	.		•	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
21	1x1 Ceiling Tile	1000	SF	Lunchroom (1031), Kitchen and 1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	: No Change				7							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
22	12x12 Tan w/ Tan Spots VFT	3200	SF	Rooms 2017, 2001, 1012 and West (N-S) Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change				1							
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
23	12x12 Tan w/ Tan Spots VFT Mastic	3200	SF	Rooms 2017, 2001, 1012 and West (N-S) Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	: No Change				7							
Comments	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
24	12x12 Cream VFT (Not Observed)			Room 217		Miscellaneous					YES	X NO
2016 - Fal	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
25	12x12 Cream VFT Mastic (Not Observed)			Room 217		Miscellaneous					YES		X NO
0040 Fall N	In Ohanana				7								
2016 - Fall: N	No Change				4								
Comments:					4								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
26	12x12 Cream w/ Brown Streaks VFT	300	SF	2nd Floor Hallway in West Hall	7.	Miscellaneous	No	None	0		YES		X NO
			1							l.			
2016 - Fall: N	No Change				4								
Comments:													
	Two sip is a	T 84 4 4 1	1	I sa e e e e		T. A. C. C. C.	Levis	T 5		T.5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
27	12x12 Cream w/ Brown Streaks VFT Mastic	300	SF	2nd Floor Hallway in West Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:	to onango				1								
					1								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
28	12x12 Green VFT	250	SF	Old Main Office Corridor		Miscellaneous	No	None	0		YES		X NO
0040 Fall N	In Ohaman	•	•	•	- 1	•	•	•	•	•	•		
2016 - Fall: N	No Change				4								
Comments:					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
29	12x12 Green VFT Mastic	250	SF	Old Main Office Corridor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
33	2x4 Ceiling tile	2500	SF	Weight Room (1028); Room 2019		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change]								
Comments:					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
34	MJP E/F/V on Fiberglass pipe insulation	200	LF	Unexcavated Area		TSI	Yes	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:					1								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
35	12"x12" White w/ Blue & Red VFT - ABATED			Room 119							YES		X NO
2016 - Fall:	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
36	12"x12" White w/ Blue & Red VFT Mastic ABATED			Room 119							YES	X	NO
2016 - Fall: N	Vo Change												
Comments:	10 Change												
Обинионко:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
37	12 x 12 inch White w/Blue Streaks VFT ABATED			Room 122		Miscellaneous					YES	Х	NO
2016 - Fall: N	Vo Change												
Comments:	10 Orlange												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
37 A	12 x 12 inch White w/Blue Streaks VFT Mastic ABATED			Room 122		Miscellaneous		None			YES	X	NO
2016 - Fall: N	No Change												
Comments:	10 Onlango												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
38	12 x 12 inch White w/Blue Spots VFT - ABATED			Room 234		Miscellaneous					YES	X	NO
2016 Fall: N	No Change	•				•		•	•				
2016 - Fall: N	vo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
38 A	12 x 12 inch White w/Blue Spots VFT Mastic - ABATED			Room 234		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:	itto onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
39	12 x 12 inch Brown w/Brown & White Streaks VFT - NOT OBSERVED	750	SF	Room 122		Miscellaneous	No		0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
39 A	12 x 12 inch Brown w/Brn & Wht Streaks VFT Mastic - NOT OBSERVED	750	SF	Room 122		Miscellaneous	No		0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
40	12 x 12 inch Brown Mottled Pattern VFT	4000	SF	1st Floor Corridor, Rooms: 1007, 1010, 1011		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change	•	•	•		•	•	•		•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
40 A	12 x 12 inch Brown Mottled Pattern VFT Mastic	4000	SF	1st Floor Corridor, Rooms: 1007, 1010, 1011		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Chango				7							
Comments:	io Change				-							
Comments.												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
41	Terrazo	2000	SF	All Entry Lobbies and E/W Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to change				1							
Commonto.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
42	Carpet Mastic	800	SF	Rm 2018		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to change				1							
Common.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
43	Paper Wrap Pipe Insulation	222	LF	Un-excavated Area, 1st Floor Staff Washroom Slop Sink Closets		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
44	Interior Window Caulk			Throughout		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
45	Ceramic Tile Grout	2500	SF	Restrooms, MDF 1st Floor		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
45A	Ceramic Tile Adhesive	2500	SF	Restrooms, MDF 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
46	12 x 12 Beige with Streaks VFT	45	SF	Elevator		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
47	12 x 12 Green with White Streaks VFT	455	SF	Old Main Office and Restroom		Miscellaneous	No	None	0		YES	X	NO
0040 Fall	No Observe												
	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
48	12 x 12 Beige with Streaks Floor Tile Mastic	45	SF	Elevator		Miscellaneous	No	None	0		YES	X	NO
2016 Fall:	No Change		1	1	_	1	1	1	•	1	1		
Comments:					\dashv								
Comments.					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
49	Mottled Linoleum ABATED			Room 120 Closet and Room 118 Closet		Miscellaneous		None			YES	X	NO
2016 - Fall	No Change												
Comments:	<u> </u>												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment	t Category
50	Mottled Linoleum Mastic ABATED			Room 120 Closet and Room 118 Closet		Miscellaneous					YES	X	NO
2016 - Fall-	No Change				7								
Comments:					\dashv								
Comments.	i.				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cat	tegory
51	9 x 9 Tan VFT	70	SF	Auditorium		Miscellaneous	No	None	0		YES	X NC)
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cat	tegory
52	9 x 9 Tan VFT Mastic	70	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change												
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cat	tegory
53	12 x 12 White with Red and Blue Streaks Floor Tile	920	SF	Cafeteria (1031, 1033, 1035)		Miscellaneous	No	None	0		YES	X NC)
2016 - Fall:	No Change												
Comments	·												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cat	tegory
54	12 x 12 White with Red and Blue Streaks Floor Tile Mastic	920	SF	Cafeteria (1031, 1033, 1035)		Miscellaneous	No	None	0		YES	X NC)
2016 - Fall	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
55	12 x 12 Brown with Tan Streaks Floor Tile	120	SF	Cafeteria (1031, 1033, 1035)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
56	12 x 12 Brown with Tan Streaks Floor Tile Mastic	120	SF	Cafeteria (1031, 1033, 1035)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
57	12 x 12 Tan with White Streaks Floor Tile	355	SF	Kitchen Storage		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
58	12 x 12 Tan with White Streaks Floor Tile Mastic	355	SF	Kitchen Storage		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
59	12 x 12 Grey with White and Green Streaks Floor Tile	205	SF	Engineer's Office (121) and Engineer's Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	- J											
	T				1	1			T _		T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
60	12 x 12 Grey with White and Green Streaks Floor Tile Mastic	205	SF	Engineer's Office (121) and Engineer's Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	40 Onange											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
61	12 x 12 Beige with Light Brown Streaks, Floor Tile	16300	SF	Room 2025 Janitors Closet; Rooms 2019, 2015, 2016, 2008, 2006, 2004, 2002, 1001, 1002, 1004, 1003, 1006, 1005, 1008, 1007, 1009, 1011, 1013, 1022		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	NO Change											
Comments.												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
62	12 x 12 Beige with Light Brown Streaks Floor Tile Mastic	16300	SF	Room 2025 Janitors Closet; Rooms 2019, 2015, 2016, 2008, 2006, 2004, 2002, 1001, 1002, 1004, 1003, 1006, 1005, 1008, 1007, 1009, 1011, 1013, 1022		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
63	12 x 12 Green with White Streaks VFT Mastic	455	SF	Old Main Office and Rest Rooms		Miscellaneous	No	None	0		YES		X NO
2016 - Fall [.]	No Change				1								
Comments:													
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
64	Carpet Squares Mastic	12000	SF	Rooms 2028, 2017, 2022, 2020, 1010, 1014D, 1014A, 1016, 1018 (Media Center); Video Conference Rm 2nd Floor; Main office (1024, 1024A, 1024B)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:]								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
65	Tan Sheet Flooring	1500	SF	Rooms 2007, 2005, 2003, 2034, 2034A, 2036 & Vestibule		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:	<u>~</u>]								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
66	Tan Sheet Flooring Adhesive	1500	SF	Rooms 2007, 2005, 2003, 2034, 2034A, 2036 & Vestibule		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
67	Lab Table Tops	2000	SF	Rms 2036, 2034, 2034A, 2007, 2005, 2003, 2006		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
68	12" X 12" yellow with blue& red specks VFT	800	SF	Auditorium		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:	:				4								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
69	12" X 12" yellow with blue& red specks, mastic	800	SF	Auditorium		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
70	2X2 smooth ceiling tile	1200	SF	Weight Room (1028)		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall	No Change	•	•	•]	•	•	•	•		•		

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assessment Category
71	2x4 smooh ceiling tile	700	SF	New kitchen storage room		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall	: No Change										
Comments											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12x12 White VFT	65000	SF	1st Fl. Corridors Throughout		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change										
Comments	S:										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12x12 White VFT Mastic	65000	SF	1st Fl. Corridor Throughout		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change										

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William B Ogden School
Date: 12/22/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 24731

SCHOOL'S ASBESTOS MANAGEMENT PLAN.