Chicago Public Schools

6 Month Asbestos Surveillance

2016 - Fall

	School: Address:	Enrico Ton 5815 S. Ho						-	Pracle Unit: Region:	256 05	31	Buildin Mail Ro		6220 44	
						Asbesto	os Surveyor:	Jeske, N Robert	Ir. Michael						
	HERE IF N	NO CHA	NGE TC) ASBE	STOS	Survey L	Date:	1/10/201	7						
						Email Ac	ddress:	mrjeske	@cps.edu						
	A copy of th	ne 2016/201	7 notice to r	parents and	J staff regardi	ng the ask	pestos manag	gement plan no	otifications w	vas distribute	d via:				
	Each chil	ld's backpac	:k	Notice	printed in scho	ool's news	sletter	Notice pr	inted in scho	ool's calenda	r Otl	her			
HA No	Material Desci	ription	Material Quantity	Material Units	Material Loca	ation	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Chang	e in Asses	ssment Category
06	fiberglass joints	- abated			boiler room pip	bechase		TSI						ES	XNO
2016 - Fall: N	lo Change						7								
Comments:							1								
]								
			<u> </u>	<u> </u>				<u>.</u>				· · · · · · · · · · · · · · · · · · ·	.		
HA No	Material Desci	ription	Material Quantity	Material Units	Material Loca	ation	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Chang	e in Asses	ssment Category
	1		ſ		1		1								

07	boiler insulation - abated		boiler room	TSI		
2016 - Fall: N	o Change					
Comments:						

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	boiler joints packing - abated			boiler room		TSI					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	tank insulation			storage room off boiler room (ABATED 1988)		TSI					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	tank joints packing			storage room off boiler room (ABATED 1988)		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	air cell pipe insulation	300	LF	airtunnels, pipe chases, blower room, storage rooms (basement)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	pipe covering cardboard			pipe chases, tunnels, air blower rooms		TSI					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	aircell packing joints			airtunnels, fan rooms, basement storage areas		TSI					

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	cardboard joints and elbows			pipechases, air tunnels, boiler room storage areas		TSI					YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	aircell duct cover			storage areas, basement area		TSI					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9x9 brown w/orange floor tile	125	SF	engineer's office & adjacent storage room		Miscellaneous	No	Dist	5		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12x12 off white w/white specks floor tile	1700	SF	kitchen office, 3rd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	brown linoleum flooring	1140	SF	kitchen cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	9x9 brown w/orange floor tile mastic	125	SF	engineer's office & adjacent storage room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12x12 off white w/ white specks floor tile mastic	2050	SF	kitchen office, 3rd floor corridor,. Counselor's office, nurses station		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
22	brown linoleum mastic	1140	SF	kitchen cafeteria flooring		Miscellaneous	No	None	0		YES	XNO
2016 - Fall: N Comments:	o Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12x12 tan w/brown streaks floor tile	1950	SF	1st floor offices, 1st floor conference room, room 209, 211		Miscellaneous	No	Dist	15		
2016 - Fall: N Comments:	lo Change										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12x12 tan w/brown streaks floor tile mastic	1950	SF	1st floor offices, 1st floor conference room, room 209, room 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12x12 gray w/brown streaks floor tile	6150	SF	1st floor corridor, room 209, 2nd floor corridor		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24A	12x12 gray w/brown streaks floor tile mastic	6150	SF	1st floor corridor, room 209, 2nd floor corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	9x9 maroon floor tile	900	SF	auditorium		Miscellaneous	No	Loc	2		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25A	9x9 maroon floor tile mastic	900	SF	auditorium		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	9x9 black floor tile	900	SF	assembly room		Miscellaneous	No	Loc	3		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26A	9x9 black floor tile mastic	900	SF	assembly room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	9x9x tan w/brown streaks floor tile	125	SF	engineer's storage and office		Miscellaneous	No	Loc	2		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27A	9x9x tan w/brown streaks floor tile mastic	30	SF	engineer's storage and office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	black baseboard	1140	SF	kitchen, cafeteria		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	black baseboard mastic	1140	SF	kitchen, cafeteria		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12x18 black edging floor tile	285	SF	engineer's office & storage, assembly room		Miscellaneous	No	Loc	2		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29A	12x18 black edging floor tile mastic	285	SF	engineer's office storage, assembly room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	green carpet mastic	440	SF	assembly room		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	dark mauve carpet mastic	622	SF	rooms 102		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	metal stall partitions- REMOVED			boys washrooms		Miscellaneous					YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	cementitious partitions	1400	SF	all wash rooms except boys		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	textured plaster on ceilings and walls	3100	SF	air tunnels, janitors storage (off of boiler room, top of stairs)		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	gray carpet mastic	224	SF	main office, principal's office		Miscellaneous	No	None	0		YES XNO
2016 - Fall: No Change]						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	window caulk (interior)	64	LF	basement windows		Surface	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	windows interior glazing	240	LF	4 basement windows		Miscellaneous	No	None	0		

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12x12 gray w/brown specks floor tile	325	SF	room 202		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40A	12x12 gray w/brown streaks floor tile mastic	325	SF	room 202 (teachers lounge)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	terrazzo	3996	SF	stairway edging on hall auditorium, Border of 1st- 3rd Floor Hallways, Stairways		Miscellaneous	No	None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	fire brick under boilers	600	SF	boiler room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	firedoor	84	SF	boiler room, assembly room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	boiler gasket	10	LF	boiler room		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	2x2 ceiling tile	6000	SF	gym		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-01	12x12 gray w/dark specks floor tile	4500	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-01A	12x12 gray w/dark specks floor tile mastic	4500	SF	throughout annex		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-02	12x12 blue w/dark specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-02A	12x12 blue w/dark specks floor tile mastic	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-03	12x12 peach w/dark specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-03A	12x12 peach w/dark specks floor tile mastic	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-04	12x12 beige w/dark specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-04A	12x12 beige w/dark specks floor tile mastic	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-05	12x12 green w/specks floor tile	60	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-05A	12x12 green w/specks floor tile mastic	60	SF	throughouot annex		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-06	gray vinyl baseboard	2500	LF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-06A	gray vinyl baseboard mastic	2500	LF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-07	2x4 bisected white ceiling tile	4000	SF	throughout annex		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Annex-08	drywall ceiling	120	SF	men's and women's washrooms, mechanical room, vestibules		Surface	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Alunhu /2

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Enrico Tonti Schoo

Date: 11/9/2016

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

CHECK ONE

	A copy of this notice was sent home in each child's backpack.
--	---

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.