Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

26091

02

Oracle Unit:

Region:

Asbestos Surveyor: Smith, Joshua X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/21/2016 Email Address: jsmith297@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Each child's backpack Notice printed in school's newsletter Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type SF 2 YES X NO 01 9"x9" Brown VFT 2400 No Auditorium Miscellaneous Loc 2016 - Fall: No Change Comments: HA No Material Description Change in Assessment Category Material Material **Material Location** Asbestos Material Friable Damage Damage Damage Quantity Units Type Category Type Quantity Units 1st Flr Corr., Rm 103, X NO YES 109, Main Off, Tchrs 12"x12" Taupe VFT Lunchrm, 201-203, 205-02 (ABATED 2008) 207, 211, 212, 303, 306, 307, 402 ABATED 2008 2016 - Fall: No Change Comments:

Morton School of Excellence

431 North Troy Street

School:

Address:

6800

Building ID:

Mail Room:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	9"x9" Brown VFT Mastic	2400	SF	Auditorium		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
08	12"x12" Taupe VFT Mastic (ABATED 2008)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 211, 212, 303, 306, 307, 402 (ABATED 2008)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
09	9"x9" Gray VFT (ABATED)			Lunchroom, Attendance Office, Room 106 - 1st Floor Storage ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
10	9"x9" Gray VFT Mastic (ABATED)			Lunchroom, Attendance Office, Room 106 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change	·			1							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
11	12"x12" Cream VFT (ABATED)			1st Fir Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402ABATED							YES [X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
12	12"x12" Cream VFT Mastic (ABATED 2008)			1st Fir Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
13	12"x12" Brown w/ Rust Streaks VFT (ABATED 2008)			Corridor Outside Auditorium, Room 304 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	nt Category
14	12"x12" Brown w/ Rust Streaks VFT Mastic (ABATED 2008)			Corridor Outside Auditorium, Room 304 ABATED 2008							YES	X NO
2016 - Fall	No Change			-	7							
Comments:	:				+							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
15	12"x12" Sand VFT (ABATED 8/22/08)			Room 110, 2nd Floor Corridor, Room 305		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
16	12"x12" Sand VFT Mastic (ABATED 2008)			Room 110, 2nd Floor Corridor, Room 305 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	J]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
17	12"x12" Beige VFT (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
18	12"x12" Beige VFT Mastic (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
19	9"x9" Dark Gray VFT (ABATED 2008)			2nd Floor Corridor, 4th Floor Corridor, Room 204		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	•]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
20	9"x9" Dark Gray VFT Mastic (ABATED 2008)			2nd & 4th Floor Corridors, Room 204 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
21	9"x9" Light Green VFT (ABATED 2008)			2nd Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	· · ·											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
22	9"x9" Light Green VFT Mastic (ABATED 2008)			2nd Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
23	9" x 9" Beige VFT (ABATED 2008)			Throughout (See Hatching Maps) ABATED 2008		Miscellaneous					YES		X NO
2016 - Fall: N	No Change				7								
Comments:	To Onlango]								
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
24	9"x9" Beige VFT Mastic (ABATED 2008)			Throughout (See Hatching Maps) ABATED 2008		Miscellaneous					YES		X NO
2016 - Fall: N	No Change	•		•	1	•	•	-	•	•	•		
Comments:	10 Onlange				-								
]								
HA No	Material Description	Matarial	Matarial	Matarial Lagation		Matarial	Frields	D	D	Damasa	Channa in As		
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	nent Category
25	9"x9" Dark Green VFT (ABATED 2008)			Kitchen, Elevator ABATED 2008		Miscellaneous					YES		X NO
2016 - Fall: N	No Change				1								
Comments:	<u> </u>												
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessn	ment Category
26	9"x9" Dark Green VFT Mastic (ABATED 2008)			Kitchen, Elevator ABATED 2008		Miscellaneous					YES		X NO
2016 - Fall: N	No Change				1								
Comments:	<u> </u>				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
27	9"x 9" Moss Green VFT (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES	X NO
204C Fall I	No Change				7							
2016 - Fall: I Comments:	vo Change				4							
Comments.					+							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
28	9"x9" Moss Green VFT Mastic (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES	X NO
					7	'	· I					
2016 - Fall: I	No Change				4							
Comments:					4							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIA NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Filable	Type	Quantity	Units	Change in As	sessment Category
29	Interior Window Caulk	250	EA	Interior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	-				1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
32	12 x 12 inch Gray w/ White & Brown Streaks VFT (ABATED 2008)			Elevator ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: I	No Change				7							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32 A	12 x 12 inch Gray w/ White & Brown VFT Mastic (ABATED 2008)			Elevator ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
33	Carpet Mastic (ABATED 2008)			Rooms 102, 103, Main Office ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34	12 x 12 inch Brown w/Yellow Streaks VFT	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
34 A	12 x 12 inch Brown w/ Yellow Streaks VFT Mastic	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change			<u> </u>	7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
35	12 x 12 Burgundy Floor Tile	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change												
Comments													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
35A	12 x 12 Burgundy Floor Tile Mastic	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change												
Comments	:												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
36	12 x 12 Light Blue Floor Tile	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change				7								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
36A	12 x 12 Light Blue Floor Tile Mastic	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change		•		- 1	•	•	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
37	12 x 12 Beige Floor Tile	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
37A	12 x 12 Beige Floor Tile Mastic	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
38	12 x 12 Blue Floor Tile	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
38A	12 x 12 Blue Floor Tile Mastic	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
39	Incinerator Insulation	50	SF	Engine Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
40	Black Spray on Under Sink Coating	20	SF	Room #304 Art Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
41	Boiler Rope Gasket	40	LF	Boiler/Engine Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
42	Vinyl Baseboard Mastic/Adhesive	4500	LF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Mag Block Tank Insulation	300	SF	Boiler Room		TSI	Yes	None	0		YES X NO
2016 - Fall: N	No Change				1						
Comments:	10 Orlango				-						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
		Quantity	Offits	Boiler Room & Above	Турс	Category		Турс	Quantity	Offits	
С	MJP E/F/V on Fiberglass Pipe Insulation	657	LF	Suspended Ceiling Tiles Throughout 1st - 4th Floors		TSI	Yes	None	0		YES X NO
2016 - Fall: N	No Change	•			1						
Comments:					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	KILN	15	LF	Throughout 1st Floor & 1st Floor Storage Room		Miscellaneous	Yes	None	0		YES X NO
2016 Fell N	la Changa				1						
2016 - Fall: 1	NO Change				-						
Comments:	Comments:										

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Morton School of Excellence
Date: 12/22/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.