## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2016 - Fall

|                         |  | Park Elemen<br>Vashtenaw | tary School       |  |                                   |                         | acle Unit:<br>egion: | 26 <sup>2</sup><br>04          | 151                | Buildir<br>Mail Ro |              |                   |
|-------------------------|--|--------------------------|-------------------|--|-----------------------------------|-------------------------|----------------------|--------------------------------|--------------------|--------------------|--------------|-------------------|
| X CHEC                  | K HERE IF NO CH                            | ANGE T                   | O ASBE            | STOS Survey  | os Surveyor:<br>Date:<br>Address: | 12/23/20                | 16                   |                                |                    |                    |              |                   |
|                         | A copy of the 2016/20  Each child's backpa |                          | _                 | d staff regarding the as                           |                                   |                         |                      | was distribut<br>ool's calenda |                    | ther               |              |                   |
| HA No                   | Material Description                       | Material<br>Quantity     | Material<br>Units | Material Location                                  | Asbestos<br>Type                  | Material<br>Category    | Friable              | Damage<br>Type                 | Damage<br>Quantity | Damage<br>Units    | Change in As | sessment Category |
| 1                       | 2'x4' Ceiling Panels                       |                          |                   | Classrooms of Original<br>Building                 |                                   | Miscellaneous           |                      |                                |                    |                    | YES          | X NO              |
| Comments                | : No Change : Material Description         | Material                 | Material          | Material Location                                  | Asbestos                          | Material                | Friable              | Damage                         | Damage             | Damage             | Change in As | sessment Category |
| 2                       | 1'x1' Ceiling Tiles                        | Quantity                 | Units             | Classrooms and<br>Hallways of Original<br>Building | Туре                              | Category  Miscellaneous |                      | Type                           | Quantity           | Units              | YES          | X NO              |
| 2016 - Fall<br>Comments | : No Change<br>:                           |                          |                   |  |                                   |                         |                      |                                |                    |                    |              |                   |
| HA No                   | Material Description                       | Material<br>Quantity     | Material<br>Units | Material Location                                  | Asbestos<br>Type                  | Material<br>Category    | Friable              | Damage<br>Type                 | Damage<br>Quantity | Damage<br>Units    | Change in As | sessment Category |
| 4                       | 4"x4" Red and Black Floor<br>Tile          | 250                      | SF                | Girl's and Boy's<br>Washrooms- Gym<br>Building     |                                   | Miscellaneous           | No                   | None                           | 0                  |                    | YES          | X NO              |
| 2016 - Fall<br>Comments | : No Change<br>:                           |                          |                   |  |                                   |                         |                      |                                |                    |                    |              |                   |

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

|                | Taranta da     |                      |                   | I was a state of     |                  | T. B. A              | Levis   | T 6            | T.6                | T.5             |               |                   |
|----------------|--|----------------------|-------------------|----------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|---------------|-------------------|
| HA No          | Material Description                               | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass | sessment Category |
| 5              | 4'x10' Ceiling Panels                              | 3500                 | SF                | Gym                  |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES           | X NO              |
| 2016 - Fall: N | No Change  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| Comments:      | , , , , , , , , , , , , , , , , , , ,              |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
|                |  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| HA No          | Material Description                               | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass | sessment Category |
| 14             | 12"x12" Light Brown/Off<br>White Floor Tile        | 4000                 | SF                | Hallways, and Office |                  | Miscellaneous        | No      | None           | 0                  |                 | YES           | X NO              |
| 2016 - Fall: N | No Change  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| Comments:      |  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
|                |  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| HA No          | Material Description                               | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass | sessment Category |
| 16             | 12"x12" Light Brown/Off<br>White Floor Tile Mastic | 4000                 | SF                | Hallways, and Office |                  | Miscellaneous        | No      | None           | 0                  |                 | YES           | X NO              |
| 2016 - Fall: N | No Change  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| Comments:      | <u> </u>   |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
|                |  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |
| HA No          | Material Description                               | Material<br>Quantity | Material<br>Units | Material Location    | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass | sessment Category |
| 19             | Insulation Inside of Fire Door                     | 35                   | SF                | Boiler Room          |                  | TSI                  | No      | None           | 0                  |                 | YES           | X NO              |
| 2016 - Fall: N | No Change  |                      |                   |                      |                  |                      |         |                |                    |                 |               |                   |

| HA No       | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
|-------------|---------------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------------------|
| 20          | Drywall                   |                      |                   | Classrooms                            |                  | Miscellaneous        |         |                |                    |                 | YES         | X NO               |
| 2016 - Fall | : No Change               |                      |                   |                                       | 7                |                      |         |                |                    |                 |             |                    |
| Comments    |                           |                      |                   |                                       | ]                |                      |         |                |                    |                 |             |                    |
|             |                           |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 22          | Transite Panels           | 500                  | SF                | Behind Grills on Both<br>Sides of Gym |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | X NO               |
| 2016 - Fall | : No Change               |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |
| Comments    | :                         |                      |                   |                                       | _                |                      |         |                |                    |                 |             |                    |
|             |                           |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 23          | 12"x12" Floor Tile        | 150                  | SF                | Entrance Foyer of Gym<br>Building     |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | X NO               |
| 2016 - Fall | : No Change               |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |
| Comments    |                           |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |
|             |                           |                      |                   |                                       | _                |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description      | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 24          | 12"x12" Floor Tile Mastic | 150                  | SF                | Entrance Foyer of Gym<br>Building     |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | X NO               |
| 2016 - Fall | : No Change               |                      |                   |                                       |                  |                      |         |                |                    |                 |             |                    |

|              |   |                      |                   |   | •                |                      |         | _              |                    |                 |             |       |               |
|--------------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|-------|---------------|
| HA No        | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 25           | Floor Tile Mastic                             | 500                  | SF                | Girl's and Boy's Gym<br>Washroom Vestibules |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         |       | X NO          |
| 2016 - Fall: | No Change                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| Comments     |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
|              |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| HA No        | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 26           | 1"x1" White Ceramic Wall<br>Tile Grout        |                      |                   | Girl's Gym Washroom                         |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO          |
| 2016 - Fall: | No Change                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| Comments     |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
|              |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| HA No        | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 27           | 1"x1" Light Brown Ceramic<br>Floor Tile Grout |                      |                   | Girl's Gym Washroom                         |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO          |
| 2016 - Fall: | No Change                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| Comments     |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
|              |   |                      |                   |   |                  |                      |         |                |                    |                 |             |       |               |
| HA No        | Material Description                          | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 28           | 1"x1" Brown Ceramic Floor<br>Tile Grout       |                      |                   | Boy's Gym Washroom                          |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO          |
| 2016 - Fall  | No Change                                     |                      |                   |   | 7                |                      |         |                |                    |                 |             |       |               |

| HA No          | Material Description          | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
|----------------|-------------------------------|----------------------|-------------------|-------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|-------|----------------|
| 29             | Ceramic Wall Tile Grout       |                      |                   | Boy's Gym Washroom                  |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: I | No Change                     |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      | •                             |                      |                   |                                     | ]                |                      |         |                |                    |                 |             |       |                |
|                |                               |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description          | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 30             | Terrazzo Flooring             |                      |                   | Landing Between<br>Washrooms by Gym |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: I | No Change                     |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      | -                             |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
|                |                               |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description          | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 31             | 2' x 4' Lay In Ceiling Panels |                      |                   | Girl's and Boy's Gym<br>Washrooms   |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: I | No Change                     |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      | Ü                             |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
|                |                               |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description          | Material<br>Quantity | Material<br>Units | Material Location                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 32             | Interior Brick                |                      |                   | Gym                                 |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: I | No Change                     |                      |                   |                                     |                  |                      |         |                |                    |                 |             |       |                |

| HA No        | Material Description              | Material<br>Quantity | Material<br>Units | Material Location                       | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in | Asses | sment Category |
|--------------|-----------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------|-------|----------------|
| 33           | Interior Brick Mortar             |                      |                   | Gym                                     |                  | Miscellaneous        |         |                |                    |                 | YES       |       | X NO           |
| 2016 - Fall: | No Change                         |                      |                   |   | 7                |                      | •       | •              |                    |                 |           |       |                |
| Comments:    | <u> </u>                          |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
|              |                                   |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
| HA No        | Material Description              | Material<br>Quantity | Material<br>Units | Material Location                       | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in | Asses | sment Category |
| 34           | Block                             |                      |                   | Gym                                     |                  | Miscellaneous        |         |                |                    |                 | YES       |       | X NO           |
| 2016 - Fall: | No Change                         |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
| Comments:    | J                                 |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
|              |                                   |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
| HA No        | Material Description              | Material<br>Quantity | Material<br>Units | Material Location                       | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in | Asses | sment Category |
| 35           | Block Mortar                      |                      |                   | Gym                                     |                  | Miscellaneous        |         |                |                    |                 | YES       |       | X NO           |
| 2016 - Fall: | No Change                         |                      |                   |   |                  |                      |         |                |                    | •               |           |       |                |
| Comments:    | J                                 |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
|              |                                   |                      |                   |   |                  |                      |         |                |                    |                 |           |       |                |
| HA No        | Material Description              | Material<br>Quantity | Material<br>Units | Material Location                       | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in | Asses | sment Category |
| 36           | Cementitious Patching<br>Material |                      |                   | Boy's Gym Washroom<br>Vestibule Windows |                  | Miscellaneous        |         |                |                    |                 | YES       |       | X NO           |
| 2016 - Fall: | No Change                         |                      |                   |   | $\neg$           |                      |         |                |                    |                 |           |       |                |

| HA No          | Material Description    | Material<br>Quantity | Material<br>Units | Material Location                                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
|----------------|-------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|-------|----------------|
| 37             | Window Grout            |                      |                   | Bleachers in Gym                                    |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: N | No Change               | •                    |                   |   |                  |                      |         |                | •                  |                 |             |       |                |
| Comments:      | ¥                       |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
|                |                         |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description    | Material<br>Quantity | Material<br>Units | Material Location                                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 38             | Green Wall Tile Caulk   |                      |                   | Girl's and Boy's<br>Washrooms- Original<br>Building |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: N | No Change               |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      |                         |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
|                |                         |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description    | Material<br>Quantity | Material<br>Units | Material Location                                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 39             | Green Terrazzo Flooring |                      |                   | Girl's and Boy's<br>Washrooms- Original<br>Building |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: N | No Change               |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      |                         |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
|                |                         |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |
| HA No          | Material Description    | Material<br>Quantity | Material<br>Units | Material Location                                   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | sment Category |
| 40             | Wall Tile Adhesive      |                      |                   | Girl's and Boy's<br>Washrooms- Original<br>Building |                  | Miscellaneous        |         |                |                    |                 | YES         |       | X NO           |
| 2016 - Fall: N | No Change               |                      |                   | · · · · · · · · · · · · · · · · · · ·               |                  |                      |         |                |                    |                 |             |       |                |
| Comments:      | <u> </u>                |                      |                   |   |                  |                      |         |                |                    |                 |             |       |                |

| HA No       | Material Description         | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
|-------------|------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------------------|
| 41          | 1'x1' Ceiling Tiles Adhesive |                      |                   | Throughout Original Building                |                  | Miscellaneous        |         |                |                    |                 | YES         | X NO               |
| 2016 - Fall | : No Change                  |                      |                   |   | 7                |                      |         |                |                    |                 |             |                    |
| Comments    |                              |                      |                   |   | -                |                      |         |                |                    |                 |             |                    |
|             |                              |                      |                   |   | _                |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description         | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 42          | Terrazzo                     |                      |                   | Stairways and Landings in Original Building |                  | Miscellaneous        |         |                |                    |                 | YES         | X NO               |
|             | : No Change                  |                      |                   |   | ]                |                      |         |                |                    |                 |             |                    |
| Comments    | :                            |                      |                   |   | _                |                      |         |                |                    |                 |             |                    |
|             |                              |                      |                   |   |                  |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description         | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 43          | Interior Brick               |                      |                   | Throughout Original Building                |                  | Miscellaneous        |         |                |                    |                 | YES         | X NO               |
| 2016 - Fall | : No Change                  |                      |                   |   | 7                |                      |         |                |                    |                 |             |                    |
| Comments    |                              |                      |                   |   |                  |                      |         |                |                    |                 |             |                    |
|             |                              |                      |                   |   | _                |                      |         |                |                    |                 |             |                    |
| HA No       | Material Description         | Material<br>Quantity | Material<br>Units | Material Location                           | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment Category |
| 44          | Interior Brick Mortar        |                      |                   | Throughout Original Building                |                  | Miscellaneous        |         |                |                    |                 | YES         | X NO               |
| 2016 - Fall | : No Change                  |                      |                   | <u> </u>                                    | 7                |                      |         |                |                    |                 |             |                    |

| HA No        | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Asses  | sment Category |
|--------------|-----------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|----------------|
| 45           | Terrazzo Wall Panels  |                      |                   | Girl's Washroom- Original<br>Building |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change             |                      |                   |                                       | ]                |                      |         |                |                    |                 |             |        |                |
| Comments:    | - Transfer            |                      |                   |                                       |                  |                      |         |                |                    |                 |             |        |                |
|              |                       |                      |                   |                                       | _                |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 46           | Grey Baseboard        |                      |                   | Rooms 106, 107, 108                   |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change             |                      |                   |                                       | ]                |                      |         |                |                    |                 |             |        |                |
| Comments:    | Ü                     |                      |                   |                                       |                  |                      |         |                |                    |                 |             |        |                |
|              |                       |                      |                   |                                       | ]                |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in / | Assess | sment Category |
| 47           | Grey Baseboard mastic |                      |                   | Rooms 106, 107, 108                   |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change             |                      |                   |                                       | <u> </u>         |                      |         |                |                    | •               |             |        |                |
| Comments:    | <u> </u>              |                      |                   |                                       |                  |                      |         |                |                    |                 |             |        |                |
|              |                       |                      |                   |                                       | _                |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description  | Material<br>Quantity | Material<br>Units | Material Location                     | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in / | Assess | sment Category |
| 48           | Brown Baseboard       |                      |                   | Rooms 110, 111, 204 & 205             |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change             |                      |                   |                                       | 7                |                      |         |                |                    |                 |             |        |                |

| HA No          | Material Description       | Material<br>Quantity | Material<br>Units | Material Location         | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As  | sessm  | nent Category |
|----------------|----------------------------|----------------------|-------------------|---------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|---------------|--------|---------------|
| 49             | Brown Baseboard Mastic     |                      |                   | Rooms 110, 111, 204 & 205 |                  | Miscellaneous        |         |                |                    |                 | YES           |        | X NO          |
| 2016 - Fall: N | lo Change                  |                      |                   |                           | 7                |                      |         |                |                    |                 |               |        |               |
| Comments:      |                            |                      |                   |                           |                  |                      |         |                |                    |                 |               |        |               |
|                |                            |                      |                   |                           |                  |                      |         |                |                    |                 |               |        |               |
| HA No          | Material Description       | Material             | Material          | Material Location         | Asbestos         | Material             | Friable | Damage         | Damage             | Damage          | Change in As  | sessn  | nent Category |
|                |                            | Quantity             | Units             |                           | Type             | Category             |         | Туре           | Quantity           | Units           |               |        | ,             |
| 50             | Ceiling Material           |                      |                   | Garage                    |                  | Miscellaneous        |         |                |                    |                 | YES           |        | X NO          |
| 2016 - Fall: N | lo Change                  |                      |                   |                           | 7                |                      |         |                |                    |                 |               |        |               |
| Comments:      | to Orlange                 |                      |                   |                           | =                |                      |         |                |                    |                 |               |        |               |
|                |                            |                      |                   |                           | ]                |                      |         |                |                    |                 |               |        |               |
| HA No          | Material Description       | Material             | Material          | Material Location         | Asbestos         | Material             | Friable | Domogo         | Domoso             | Domose          | Change in As  |        | nent Category |
| HA NO          | Material Description       | Quantity             | Units             | Material Location         | Type             | Category             | Filable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As  | sessii | ieni Calegory |
| 51             | Pegboard                   |                      |                   | Room 211                  |                  | Miscellaneous        |         |                |                    |                 | YES           |        | X NO          |
| 2016 - Fall: N | lo Change                  |                      |                   |                           | 7                |                      |         |                |                    |                 |               |        |               |
| Comments:      | <u> </u>                   |                      |                   |                           |                  |                      |         |                |                    |                 |               |        |               |
|                |                            |                      |                   |                           |                  |                      |         |                |                    |                 |               |        |               |
| HA No          | Material Description       | Material             | Material          | Material Location         | Asbestos         | Material             | Friable | Damage         | Damage             | Damage          | Change in As  | sessn  | nent Category |
|                | material 2 cooliption      | Quantity             | Units             | material 200allon         | Туре             | Category             |         | Туре           | Quantity           | Units           | onango m 7 to |        | ioni Galogoly |
| 52             | Exterior Brick - Non AHERA |                      |                   | Original Building         |                  | Miscellaneous        |         |                |                    |                 | YES           |        | X NO          |
| 2016 - Fall: N | lo Change                  |                      |                   |                           | 7                |                      |         |                |                    |                 |               |        |               |
| Comments:      | io chango                  |                      |                   |                           | =                |                      |         |                |                    |                 |               |        |               |

| HA No          | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessment C | ategory |
|----------------|---|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|--------------|------------|---------|
| 53             | Exterior Brick Mortar - Non<br>AHERA        |                      |                   | Original Building |                  | Miscellaneous        |         |                |                    |                 | YES          | XN         | 10      |
| 2016 - Fall: N | lo Change                                   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
| Comments:      | o Ondrigo                                   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   | T                 |                  |                      |         |                |                    |                 |              |            |         |
| HA No          | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessment C | ategory |
| 54             | Exterior Door Grout - Non<br>AHERA          |                      |                   | Original Building |                  | Miscellaneous        |         |                |                    |                 | YES          | XN         | 10      |
| 2016 - Fall: N | lo Change                                   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
| Comments:      | o Onange                                    |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   | T                 |                  |                      |         |                |                    |                 |              |            |         |
| HA No          | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessment C | ategory |
| 55             | Fire Block                                  |                      |                   | Basement Stairs   |                  | Miscellaneous        |         |                |                    |                 | YES          | XN         | 10      |
| 2016 - Fall: N | o Change                                    |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
| Comments:      | 90  |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
|                |   |                      |                   | T                 |                  |                      |         |                |                    |                 |              |            |         |
| HA No          | Material Description                        | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessment C | ategory |
| 56             | 12" x 12" White w/ Blue & Yellow Floor Tile | 2000                 | SF                | Library           |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          | XN         | 10      |
| 2016 - Fall: N | o Change                                    |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |
| Comments:      | o onango                                    |                      |                   |                   |                  |                      |         |                |                    |                 |              |            |         |

|                |   |                      |                   |                   |                  |                      |           |                |                    | •               |                   |                   |
|----------------|---|----------------------|-------------------|-------------------|------------------|----------------------|-----------|----------------|--------------------|-----------------|-------------------|-------------------|
| HA No          | Material Description                                  | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable   | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass     | sessment Category |
| 57             | 12"x12" White w/ Blue and<br>Yellow Floor Tile Mastic |                      |                   | Library           |                  | Miscellaneous        |           |                |                    |                 | YES               | X NO              |
| 2016 - Fall: N | No Change   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
| Comments:      | 10 Change   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
|                |   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
|                |   |                      |                   |                   |                  |                      |           | _              |                    |                 |                   |                   |
| HA No          | Material Description                                  | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable   | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass     | sessment Category |
| 58             | 12" x 12" Blue Floor Tile                             | 2000                 | SF                | Library           |                  | Miscellaneous        | No        | None           | 0                  |                 | YES               | X NO              |
| 2016 - Fall: N | No Change   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
| Comments:      | 10 0.1.dgo  |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
|                |   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
|                | T   | T                    | T                 | T                 |                  | T                    | 1         | T              | T =                |                 | <del> </del>      |                   |
| HA No          | Material Description                                  | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable   | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass     | sessment Category |
| 59             | 12"x12" Blue Floor Tile<br>Mastic                     |                      |                   | Library           |                  | Miscellaneous        |           |                |                    |                 | YES               | X NO              |
| 2016 - Fall: N | No Change   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
| Comments:      | <u> </u>  |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
|                |   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
| LIA NI-        | Material December                                     | I Martanial          | I Martanial       | Material Landon   | A -11 -          | I Martanial          | L Estable | T.D            |                    |                 | L Observation Ass |                   |
| HA No          | Material Description                                  | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable   | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Ass     | sessment Category |
| 60             | 12" x 12" Yellow Floor Tile                           | 2500                 | SF                | Cafeteria         |                  | Miscellaneous        | No        | None           | 0                  |                 | YES               | X NO              |
| 2016 - Fall: N | No Change   |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |
| Comments:      | <u> </u>  |                      |                   |                   |                  |                      |           |                |                    |                 |                   |                   |

| HA No        | Material Description                | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
|--------------|-------------------------------------|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|----------------|
| 61           | 12"x12" Yellow Floor Tile<br>Mastic |                      |                   | Library   |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change                           |                      |                   |   | 7                |                      |         |                |                    |                 |             |        |                |
| Comments:    |                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|              |                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description                | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 62           | 4" Blue Vinyl Baseboard             |                      |                   | Library   |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change                           |                      |                   |   | 7                |                      |         |                |                    |                 |             |        |                |
| Comments:    | J                                   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|              |                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description                | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 63           | 4" Blue Vinyl Baseboard<br>Adhesive |                      |                   | Library   |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change                           |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| Comments:    |                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|              |                                     |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No        | Material Description                | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | \ssess | sment Category |
| 64           | 12" x 12" Brown Floor Tile          | 4500                 | SF                | Classrooms- Original<br>Building with the<br>Exception of 224 & 225 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         |        | X NO           |
| 2016 - Fall: | No Change                           |                      |                   |   | 7                |                      |         |                |                    |                 |             |        |                |

| HA No        | Material Description               | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As                  | ssessment Category |  |
|--------------|------------------------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|--------------------|--|
| 65           | 12"x12" Brown Floor Tile<br>Mastic |                      |                   | Classrooms - Original<br>Building with the<br>Exception of 224 & 225 |                  | Miscellaneous        |         |                |                    |                 | YES                           | X NO               |  |
| 2016 - Fall  | : No Change                        |                      |                   |  | 7                |                      |         |                |                    |                 |                               |                    |  |
| Comments     |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |
|              |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |
| HA No        | Material Description               | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Category |                    |  |
| 66           | 12" X 12" Beige Floor Tile         | 4500                 | SF                | Classrooms- Original<br>Building with the<br>Exception of 224 & 225  |                  | Miscellaneous        | No      | None           | 0                  |                 | YES                           | X NO               |  |
| 2016 - Fall: | : No Change                        |                      |                   |  | 7                |                      |         |                |                    |                 |                               |                    |  |
| Comments     |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |
|              |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |
| HA No        | Material Description               | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As                  | ssessment Category |  |
| 67           | 12"x12" Beige Floor Tile<br>Mastic |                      |                   | Classrooms - Original<br>Building with the<br>Exception of 224 & 225 |                  | Miscellaneous        |         |                |                    |                 | YES                           | X NO               |  |
| 2016 - Fall: | No Change                          |                      |                   |  | -<br>            | •                    | •       | •              | •                  | •               |                               |                    |  |
| Comments     |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |
|              |                                    |                      |                   |  | _                |                      |         |                |                    |                 |                               |                    |  |
| HA No        | Material Description               | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As                  | ssessment Category |  |
| 68           | 2' x 4' Lay-in Ceiling Panels      | 544                  | SF                | Rear Room in Library   |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES                           | X NO               |  |
| 2016 - Fall  | : No Change                        |                      |                   |  | 7                |                      |         |                |                    |                 |                               |                    |  |
| Comments     |                                    |                      |                   |  |                  |                      |         |                |                    |                 |                               |                    |  |

| HA No                    | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
|--------------------------|---|----------------------|-------------------|---|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|----------------|
| 69                       | Floor Tile Beneath 12" x<br>12" Floor Tile        | 9400                 | SF                | All rooms of original<br>building except Rooms<br>224 and 225         |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         |        | X NO           |
| 2016 - Fall:             | No Change   | •                    |                   | *   |                  | •                    | •       | •              | •                  | •               | •           |        |                |
| Comments:                |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|                          |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No                    | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 70                       | Floor Tile Beneath 12" x<br>12" Floor Tile Mastic | 9400                 | SF                | All rooms of original<br>building except Rooms<br>224 and 225         |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         |        | X NO           |
| 2016 - Fall:             | : No Change                                       |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| Comments:                |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|                          |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No                    | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 71                       | Blue Carpet Adhesive                              |                      |                   | Room 229  |                  | Miscellaneous        |         |                |                    |                 | YES         |        | X NO           |
| 2016 - Fall <sup>.</sup> | No Change   |                      |                   |   |                  |                      |         |                |                    | •               |             |        |                |
| Comments:                |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
|                          |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| HA No                    | Material Description                              | Material<br>Quantity | Material<br>Units | Material Location   | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | Assess | sment Category |
| 72                       | 2' x 4' Ceiling Panels                            | 24250                | SF                | Rooms 224, 225, & the<br>2001 Addition<br>Classrooms and<br>Corridors |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES         |        | X NO           |
| 2016 - Fall:             | : No Change                                       |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |
| Comments:                |   |                      |                   |   |                  |                      |         |                |                    |                 |             |        |                |

| HA No          | Material Description  | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
|----------------|-----------------------|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|-------|---------------|
| 73             | Green Carpet Adhesive |                      |                   | 2001 Addition, Office,<br>Rooms 105, 107, 109,<br>111, 205 |                  | Miscellaneous        |         | None           |                    |                 | YES         |       | X NO          |
| 2016 - Fall: N | No Change             |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
| Comments:      | 10 Onango             |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
|                |                       |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
| HA No          | Material Description  | Material             | Material          | Material Location  | Asbestos         | Material             | Friable | Damage         | Domogo             | Damage          | Change in A | 00000 | ment Category |
| HA NO          | Material Description  | Quantity             | Units             | Material Location  | Type             | Category             | Filable | Type           | Damage<br>Quantity | Units           | Change in A | 55655 | ment Category |
| 74             | Drywall               | 25000                | SF                | 2001 Addition  |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES         |       | X NO          |
| 2016 - Fall: N | Vo Change             |                      |                   |  | 1                |                      | •       |                |                    |                 |             |       |               |
| Comments:      | 10 Orlange            |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
|                |                       |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
|                | 1                     |                      |                   | 1  |                  |                      |         | T _            |                    | T _             |             |       |               |
| HA No          | Material Description  | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 75             | Drywall Compound      | 25000                | SF                | 2001 Addition  |                  | Miscellaneous        | Yes     | None           | 0                  |                 | YES         |       | X NO          |
| 2016 - Fall: N | No Change             |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
| Comments:      | 10 0.1ago             |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
|                |                       |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
|                | T.M. (115) (10)       |                      | T                 | I sa e e e e   |                  | T                    | Term    | 1.5            | 1.5                | T 5             |             |       |               |
| HA No          | Material Description  | Material<br>Quantity | Material<br>Units | Material Location  | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssess | ment Category |
| 76             | Sink Undercoat        | 10                   | SF                | Office, Room 101   |                  | Surface              | No      | None           | 0                  |                 | YES         |       | X NO          |
| 2016 - Fall: N | No Change             |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |
| Comments:      |                       |                      |                   |  |                  |                      |         |                |                    |                 |             |       |               |

| HA No       | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location                | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in Assessment Categor |       | sment Category |
|-------------|--------------------------------------|----------------------|-------------------|----------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|------------------------------|-------|----------------|
| 77          | 12" x 12" Aqua Floor Tile            | 9117                 | SF                | 2001 Addition<br>Classrooms      |                  | Miscellaneous        | No      | None           | 0                  |                 | YES                          |       | X NO           |
| 2016 - Fall | : No Change                          |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| Comments    |                                      |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
|             |                                      |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| HA No       | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location                | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A                  | ssess | sment Category |
| 78          | 12" x 12" Aqua Floor Tile<br>Mastic  | 9532                 | SF                | 2001 Addition<br>Classrooms, 205 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES                          |       | X NO           |
| 2016 - Fall | : No Change                          |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| Comments    | ):                                   |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
|             |                                      |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| HA No       | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location                | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A                  | sses  | sment Category |
| 79          | 12" x 12" Beige Floor Tile           | 12447                | SF                | 2001 Addition<br>Classrooms      |                  | Miscellaneous        | No      | None           | 0                  |                 | YES                          |       | X NO           |
| 2016 - Fall | : No Change                          |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| Comments    |                                      |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
|             |                                      |                      |                   |                                  |                  |                      |         |                |                    |                 |                              |       |                |
| HA No       | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location                | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A                  | ssess | sment Category |
| 80          | 12" x 12" Beige Floor Tile<br>Mastic | 12447                | SF                | 2001 Addition<br>Classrooms      |                  | Miscellaneous        | No      | None           | 0                  |                 | YES                          |       | X NO           |
| 2016 - Fall | : No Change                          | •                    | •                 |                                  |                  |                      | -       | •              | •                  | -               | •                            |       |                |

| HA No        | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment | t Category |
|--------------|--------------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|-----------|------------|
| 81           | 4" Green Vinyl Baseboard             | 1300                 | LF                | 2001 Addition     |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | Х         | NO         |
| 2016 - Fall: | No Change                            |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| Comments:    |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
|              |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| HA No        | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment | t Category |
| 82           | 4" Green Vinyl Baseboard<br>Adhesive | 1300                 | LF                | 2001 Addition     |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | X         | NO         |
|              | No Change                            |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| Comments:    |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
|              |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| HA No        | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment | t Category |
| 83           | Spray On Insulation                  | 12000                | SF                | 2001 Addition     |                  | TSI                  | Yes     | None           | 0                  |                 | YES         | X         | NO         |
| 2016 - Fall: | No Change                            |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| Comments:    |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
|              |                                      |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |
| HA No        | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in A | ssessment | t Category |
| 84           | Vibration Collars                    | 100                  | LF                | 2001 Addition     |                  | Miscellaneous        | No      | None           | 0                  |                 | YES         | Х         | NO         |
| 2016 - Fall: | No Change                            |                      |                   |                   |                  |                      |         |                |                    |                 |             |           |            |

| HA No          | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location        | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessme   | ent Category |
|----------------|--------------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|--------------|----------|--------------|
| 85             | Chalk Board/Marker Board<br>Adhesive | 2000                 | SF                | Original Building        |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          |          | X NO         |
| 2016 - Fall: N | lo Change                            |                      |                   |                          |                  |                      |         |                |                    |                 |              |          |              |
| Comments:      | to onlange                           |                      |                   |                          |                  |                      |         |                |                    |                 |              |          |              |
|                |                                      |                      |                   |                          | ]                |                      |         |                |                    |                 |              |          |              |
| HA No          | Material Description                 | Material             | Material          | Material Location        | Asbestos         | Material             | Friable | Damage         | Damage             | Damage          | Change in As | coccmo   | ent Catagory |
| TIA NO         | Material Description                 | Quantity             | Units             | Waterial Location        | Type             | Category             | Filable | Type           | Quantity           | Units           | Change in As | Sessifie | ant Category |
| 86             | Chalk Board/Marker Board<br>Adhesive | 2400                 | SF                | 2001 Addition            |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          |          | X NO         |
| 2016 - Fall: N | lo Change                            |                      | 1                 |                          |                  |                      | •       |                |                    |                 |              |          |              |
| Comments:      | 10 Orlange                           |                      |                   |                          |                  |                      |         |                |                    |                 |              |          |              |
|                |                                      |                      |                   |                          | ]                |                      |         |                |                    |                 |              |          |              |
|                | Inc. 15 12                           |                      | T                 | Lagaretta e              | T A 1 .          | T. A                 | Levis   | T 5            | 1.5                | T 5             |              |          |              |
| HA No          | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location        | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessme   | ent Category |
| 87             | Core in Green Pads                   | 2520                 | SF                | 2001 Gym                 |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          |          | X NO         |
| 2016 - Fall: N | lo Change                            |                      |                   |                          | 7                |                      |         |                |                    |                 |              |          |              |
| Comments:      | 10 0.1a.1g0                          |                      |                   |                          | -                |                      |         |                |                    |                 |              |          |              |
|                |                                      |                      |                   |                          | ]                |                      |         |                |                    |                 |              |          |              |
| HA No          | Motorial Description                 | Motorial             | Motorial          | Material Location        | Ashastas         | Material             | Friable | Domogo         | Domose             | Domose          | Change in As |          | ant Cotogoni |
| HA NO          | Material Description                 | Material<br>Quantity | Material<br>Units | Material Location        | Asbestos<br>Type | Category             | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessme   | ent Category |
| 88             | 2' x 4' Smooth Ceiling<br>Panels     | 1368                 | SF                | Kitchen and Serving Area |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          |          | X NO         |
| 2016 - Fall: N | lo Change                            |                      |                   |                          | <br>]            |                      |         |                |                    |                 |              | _        |              |
| Comments:      |                                      |                      |                   |                          |                  |                      |         |                |                    |                 |              |          |              |

| HA No          | Material Description                           | Material<br>Quantity | Material<br>Units | Material Location                            | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessmer | nt Category |
|----------------|--|----------------------|-------------------|--|------------------|----------------------|---------|----------------|--------------------|-----------------|--------------|---------|-------------|
| 89             | 12" x 12" Green and White<br>Floor Tile        | 3500                 | SF                | Cafeteria                                    |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          | )       | NO          |
| 2016 - Fall: N | o Change                                       |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
| Comments:      | o Change                                       |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  | •                    |                   |  |                  |                      | •       |                |                    |                 |              |         |             |
| HA No          | Material Description                           | Material<br>Quantity | Material<br>Units | Material Location                            | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessmer | nt Category |
| 90             | 12" x 12" grean and White<br>Floor tile Mastic | 3500                 | SF                | Cafeteria                                    |                  | Miscellaneous        | No      | None           | 0                  |                 | YES          | )       | K NO        |
| 2016 - Fall: N | lo Change                                      |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
| Comments:      | o Ondrigo                                      |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  |                      |                   |  |                  |                      |         |                | _                  |                 |              |         |             |
| HA No          | Material Description                           | Material<br>Quantity | Material<br>Units | Material Location                            | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessmer | nt Category |
| Α              | Boiler Lag                                     | 50                   | SF                | Boiler Room                                  |                  | TSI                  | Yes     | None           | 0                  |                 | YES          | )       | NO          |
| 2016 - Fall: N | lo Change                                      |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
| Comments:      | o Chango                                       |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |
|                |  |                      |                   |  |                  |                      | •       |                |                    |                 |              |         |             |
| HA No          | Material Description                           | Material<br>Quantity | Material<br>Units | Material Location                            | Asbestos<br>Type | Material<br>Category | Friable | Damage<br>Type | Damage<br>Quantity | Damage<br>Units | Change in As | sessmer | nt Category |
| F              | Aircell Lag                                    | 10                   | LF                | Girl's Washroom<br>Vestibule in Gym Building |                  | TSI                  | Yes     | None           | 0                  |                 | YES          | )       | K NO        |
| 2016 - Fall: N | o Change                                       |                      | <del>-</del>      |  | <u></u>          |                      |         |                |                    |                 |              |         |             |
| Comments:      |  |                      |                   |  |                  |                      |         |                |                    |                 |              |         |             |

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: Brighton Park Elementary School  |
|--|
| Date: 12/23/2016   |
|  |
|  |
| This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance. |
| Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.  |
| CHECK ONE  |
| A copy of this notice was sent home in each child's backpack.  |
| A copy of this notice was printed in the school's newsletter and sent home with each child   |
| A copy of this notice was printed in the school's calendar and sent home with each child   |
| Other.   |
|  |
| A COPY OF THIS NOTICE MUST BE PLACED IN THE  |

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 26451