## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2016 - Fall

	School: Address:	Thomas A Edison Regional Gifted Center 6220 N Olcott Avenue		Oracle Unit: Region:	29011 01	Building ID: Mail Room:	2220 31
	HERE IF I	NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date: Email Address:	4/26/2017	-		
Γ	A copy of t	he 2016/2017 notice to parents and staff regar	ding the asbestos managen	nent plan notifications was	distributed via:		

	Each child's backpack Notice printed in school's newsletter					Notice printed in school's calendar Other					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01	Hard Coat Plaster	0		Throughout 1948							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Brown w/ Orange Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Beige w/ Brown Specks VFT	9000	SF	Main Office, 1st & 2nd Floor Corridors, Rooms 103, & 106, 1948		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	2'x2' Acoustic Ceiling Tile	1400		Room 102, 104, 1948							YES XNO
-											

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Brown w/ Orange Streaks VFT Mastic	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12"x12" Beige w/ Brown Specks VFT Mastic	9000	SF	Main Office, 1st & 2nd Floor Corridors, Room 103, 1948		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Beige w/ Brown Specks VFT	8600	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Beige w/ Brown Specks VFT Mastic	9000	SF	1st & 2nd Floor Corridors, 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	Linoleum Under 12"x12" Gray VFT	700	SF	Room 107, 1954		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Hard Coat Plaster	0		Throughout 1954							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Duct Vibration Isolators	0	SF	Fan Room, 1948		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	2'x2' Tectum Ceiling Tile	2000	SF	Gym, 1948							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Orange w/ Beige Streaks VFT	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	9"x9" Orange w/ Beige Streaks VFT Mastic	40	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	1'x2' Black VFT	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	1'x2' Black VFT Mastic	20	SF	Main Office Storage, 1948		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	12"x12" White w/ Beige Specks VFT	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 (Under HA# 41)		Miscellaneous	No	None	0		YES X NO

201	- Fall: No Change
Cor	nents:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" White w/ Beige Specks VFT Mastic	2250	SF	Main Office & Rooms 202, 200A & 200B, Room 103 (Under HA# 41)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Gray w/ White & Gray Specks VFT	1350	SF	Room 107, 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" Gray w/ White & Gray Specks VFT	1350	SF	Room 107, 1954; 1st Floor Boys and Girls Toilets and 1st Floor Corridor Patch Near Rm 102		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Tan w/ Brown Specks VFT	80	SF	Room 107 Toilet & Teacher's Toilet, 1954		Miscellaneous	No	None	0		

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"x12" Tan w/ Brown Specks VFT Mastic	80	SF	Room 107 Toilet & Teacher's Toilet, 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	1
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Dark Brown w/ Cream Streaks VFT	50	SF	107 Store Room, 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	12"x12" Dark Brown w/ Cream Streaks VFT Mastic	50	SF	107 Storeroom, 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige w/ Cream & Brown Streaks VFT	2750	SF	Rooms 109, 211, & 209, Rm 109 (under exisring floor tile)1954		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change					]						

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
30	12"x12" Beige w/ Cream & Brown Streaks VFT Mastic	2750	SF	Rooms 109, 211, & 209, 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" White VFT	0		Room 111 Countertop, 1954Not observed							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12"x12" White VFT Mastic	0		Room 111 Countertop, 1954 Not observed							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	2'x4' Speckled Ceiling Tile	9000	SF	Throughout 1948			Yes				YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	2'x4' Speckled Ceiling Tile	9000	SF	Throughout 1954		Miscellaneous	Yes	None			YES X NO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Light Gray w/ Black Streaks Linoleum	0		Room 211 Countertop, 1954 Not observed							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	Light Gray w/ Black Streaks Linoleum Mastic	0		Room 211 Countertop, 1954 Not observed							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	Exterior Window Caulk (Not Observed)	0	LF	Throughout 1948		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" White w/ Tan Spots VFT	1400	SF	Room 109;  111 (under HA#47), 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" White w/ Tan Spots VFT Mastic	1400	SF	Room 109; 111 (under HA#47), 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" White w/ Black & Grey Streaks VFT	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" White w/ Black & Grey Streaks VFT Mastic	50	SF	MDF Room (In Library Room 207), 1954		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Gray & Tan VFT	50	SF	1st and 2nd floors near elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Gray & Tan VFT Mastic	50	SF	1st and 2nd floors near elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12"x12" Tan w/Cream Streaks VFT	50	SF	First and Second Floor Near Elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
46	12"x12" Tan VFT w/cream Stks Mastic	50	SF	1st and 2nd Floors Near Elevator		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	12"X 12" Lt. Beige Floor Tile	850	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	12"X 12" Lt. Beige Floor Tile MASTIC	850	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	Carpet Mastic	1500	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Drywall, Tape, and Compounds	1000	SF	Rms 207, 208 (1954 Bldg)		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	Vinyl Baseboard Matic	150	LF	Rms 207, 208 (1954 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
52	Terrazzo	1200	SF	Stairwells (1948 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	Terrazzo	600	SF	Stairwells (1954 Bldg)		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	Carpet Mastic	200	SF	Principal's Office (1948 Bldg)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12"x12" brown and white VFT	800	SF	Room 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55A	12"x12" brown and white VFT MASTIC	800	SF	Room 206		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Paperwrap Pipe Insulation	0	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		Miscellaneous	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Paperwrap Pipe Insulation	17	LF	1st & 2nd Floor Boys Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Aircell Pipe Insulation	20	LF	1st & 2nd Floor Boy's Toilet Pipe Chases, 1948		TSI	Yes	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Blown-In Insulation	0		Attic, 1948							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	2" Fiberglass Insulation	0		Attic, 1948							YES XNO

2016 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Alunhu /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Thomas A Edison Regional Gifted Center
Date:	4/28/2017

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

A copy of this notice was sent home in each child's backpack

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.