Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

		Gunsaulus S Sacramento	cholastic Ac	ademy School			racle Unit: egion:	291 04	21	Buildir Mail Ro		
	/ LIEDE IE NO CU	ANCE T	O A CDE	CTOC	Asbestos Surveyor:	-	<u>Ir. Kevin Ba</u>	rry				
CHECK	K HERE IF NO CH	ANGE I) ASBE	5105	Survey Date: Email Address:	12/7/2016	-					
					Email Address:	kbdeane	@cps.edu					
	A	047		.1 -1-111			· · · · · · · · · · · · · · · · · · ·					
	A copy of the 2016/2	017 notice to	parents an	a starr regardi	ing the asbestos manag	gement plan no	tifications	was distribute	ed via:			
	Each child's backp	ack	Notice	printed in sch	ool's newsletter	Notice pri	nted in sch	ool's calenda	or Ot	her		
HA No	Material Description	Material Quantity	Material Units	Material Loca	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
1	Hard Plaster	31000	SF	Throughout		Surface	No	None	0		X YES	NO
2016 - Fall: Comments:N	Minor holes in walls											
HA No	Material Description	Material Quantity	Material Units	Material Loca	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
2	2' x 4' Ceiling Tile	50000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	. to onango											
HA No	Material Description	Material Quantity	Material Units	Material Loca	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
3	1' x 1' Ceiling Tile			Not Observed		Miscellaneous					YES	X NO
2016 - Fall:	No Change Located in Gymnasiun	· 1	•				•	•	•	•		

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4	12" x 12" Brown w/White Speck Floor Tile	4000	SF	2nd, 3rd Floor Halls,2nd, 3rd Floor Teacher's Lounges,Rooms 312A,108, Engineer's Office		Miscellaneous	No	None	0		X YES NO
2016 - Fall:	Repaired				7						
	Minor damage										
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
5	9" x 9" Brown Floor Tile	1500	SF	Assembly Hall and engineers office		Miscellaneous	No	Dist	60		X YES NO
2016 - Fall:	Deteriorated				7						
Comments:	Many pieces cracked a	ınd missing									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	Linoleum			Was in Gym and Gym has New Floor		Miscellaneous					YES X NO
2016 - Fall:	No Change				7						
Comments:	5										
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
7	12" x 12" Brown w/White Speck Floor Tile Mastic	4000	SF	2nd, 3rd Floor Halls and Teacher's Lounge See HA 4		Miscellaneous	No	None	0		X YES NO
2016 - Fall:	Repaired				7						

Comments:Minor damage

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
8	9" x 9" Brown Floor Tile Mastic	1800	SF	Assembly Hall		Miscellaneous	No	None	0		X YES	NO
2016 - Fall:	Deteriorated											
	Many pieces cracked ar	nd missing]									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
9	Linoleum Mastic			See HA 6		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments:	ito onango				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	1' x 1' Ceiling Tile Adhesive	6020	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	110 Onango				1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
TIANO	Material Description	Quantity	Units	Material Location	Type	Category	Thable	Type	Quantity	Units	Change in Ass	sessifient Category
11	12" x 12" Tan Floor Tile	400	SF	Room 312A and 2nd Floor Teachers' Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
12	12" x 12" Tan Floor Tile Mastic	300	SF	3rd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:	•												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
13	12" x 12" Speckled Gray Floor Tile	900	SF	1st and 3rd Floor Teacher's Lounges		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:	Ü												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
14	12" x 12" Speckled Gray Floor Tile Mastic - HA13			Room 312A		Miscellaneous					X YES		NO
2016 - Fall: A	bated												
Comments:D	ecember 2015												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
15	12" x 12" Cream Floor Tile w/Black Specs	600	SF	Front Office and Principle's Office		Miscellaneous	No	None	0		X YES		NO
2016 - Fall: A	bated												

Comments: August 2016

				T			T =	Т_					
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in i	Asses	sment Category
16	12"x12" Cream Floor Tile w/Black Specs Mastic- HA15	600	SF	Front Office and Principle's Office		Miscellaneous	No	None	0		X YES	Î	NO
2016 - Fall:	: Abated				1								
Comments	:August 2016												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in	10000	sment Category
TIA NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Filable	Type	Quantity	Units	Change in 7	15565	smem Category
17	9" x 9" Green Floor Tile	400	SF	1st Floor Principal Office		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change												
Comments	· ·												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Asses	sment Category
18	9" x 9" Green Floor Tile Mastic - HA17	400	SF	1st Floor Principal Office		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change				7								
Comments	:												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Asses	sment Category
19	12" x 12" Cream w/Brown Specks Floor Tile	1500	SF	Room 115, 206		Miscellaneous	No	None	0		X YES		NO
2016 - Fall:	: Repaired				7								
	:Minor cracks				1								

HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Damage Type Quantity Units Change in Assessm Quantity Units Change in Assessm Type Quantity Units	X NO
Specks Floor Tile Mastic 1500 SF Room 115 Miscellaneous No None 0 LYES	nt Category
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Prize Quantity Un	
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Prize Quantity Un	
Quantity Units Type Category Type Quantity Units	
Quantity Units Type Category Type Quantity Units	
Quantity Units Type Category Type Quantity Units	
21 Unknown Size Floor Tile 3rd Floor Teacher's Lounge Miscellaneous Miscellaneous X YES 2016 - Fall: Repaired Comments: Minor cracks HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Damage Quantity Units Size Floor Tile Mastic Masterial Side Floor Teacher's Miscellaneous Miscellaneous X YES X YES	NO
HA No Material Description Material Quantity Units Material Location Asbestos Type Material Category Friable Damage Quantity Units Damage Quantity Units Proper Category Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Material Category Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Miscellaneous Miscellaneo	
HA No Material Description Material Quantity Units Material Location Asbestos Type Material Category Friable Damage Quantity Units Damage Quantity Units Proper Category Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Material Category Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Material Damage Quantity Units Proper Change in Assessm Miscellaneous Miscellaneo	
HA No Material Description Material Quantity Units Material Location Asbestos Type Category Friable Damage Quantity Units Damage Quantity Units Priable Damage Quantity Units Change in Assessm 22 Unknown Size Floor Tile Mastic Miscellaneous Miscellaneous Miscellaneous Miscellaneous	
Quantity Units Type Category Type Quantity Units Unknown Size Floor Tile Mastic Size Floor Tile Mastic Size Floor Tile Mastic Size Floor Tile Mastic Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous	
22 Unknown Size Floor Tile 3rd Floor Teacher's Miscellaneous X YES	nt Category
	NO
2016 - Fall: Repaired	
Comments:Minor cracking	
HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Change in Assessm	nt Catagory
Quantity Units Waterial Description Water	it Category
23 9" x 9" Beige Floor Tile 300 SF Assembly Hall Miscellaneous No None 0 X YES	
2016 - Fall: Deteriorated	NO
Comments:Cracked and missing tiles	NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Catego	ry
24	9" x 9" Beige Floor Tile Mastic	100	SF	Assembly Hall		Miscellaneous	No	None	0		X YES		NO	
2016 - Fall: D	Deteriorated													
	cracked and missing tile	es												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Catego	ory
25	4" Red Baseboard	350	LF	Gym		Miscellaneous	No	None	0		YES		X NO	
2016 - Fall: N	No Change													
Comments:	V													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Catego	ory
26	4" Red Baseboard Mastic	300	LF	Gym		Miscellaneous	No	None	0		YES		X NO	
2016 - Fall: N	lo Change													
Comments:	10 Onlango													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Catego	ory
27	Carpet Mastic	1000	SF	Rooms 212 and 310, Office, Kindergarten Room, and Library		Miscellaneous	No	None	0		X YES		NO	
2016 - Fall: A	\hatad				٦									

Comments:roms 212, 310, main office carpets removed

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Catego	ry
28	Blue Carpet Mastic	500	SF	Room 110, Office, Principal's Office, 112		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall	: No Change				7								
Comments]								
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Catego	ry
29	Green Carpet Mastic	750	SF	Rooms 212A Computer, Library and 310		Miscellaneous	No	None	0		X YES	NO	
2016 - Fall	: Abated				7								
Comments	:Room 310 abated Aug	ust 2015											
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Catego	ry
30	Brick/Brown Multi Color Ceramic Floor Tile Grout	6200	SF	All Boys' and Girls' Washrooms on 1st, 2nd, and 3rd Floors		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall	: No Change				7								
Comments]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Catego	ry
31	Yellow Ceramic Wall Tile Grout	6200	SF	All Boys' and Girls' Washrooms on 1st,2nd and 3rd Floors		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall	: No Change]								
Comments	•				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessmen	nt Category
32	Yellow Ceramic Wall Tile Grout Adhesive	420	SF	All Boys' and Girls' Washrooms on 1st,2nd and 3rd Floors		Miscellaneous	No	None	0		YES)	NO
2016 - Fall:	No Chango				7								
Comments:	No Change				+								
Comments.					+								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessmen	nt Category
33	Brown Carpet Mastic	120	SF	Room 312		Miscellaneous	No	None	0		YES)	X NO
2016 - Fall:	No Chango				7								
Comments:	INO Change												
Comments.					+								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessmen	nt Category
		Quantity	Units		Type	Category		Туре	Quantity	Units			
34	Drywall-Wall	830	SF	Rooms 207,217 and 208		Miscellaneous	No	None	0		YES)	X NO
2016 - Fall:	No Change				٦								
Comments:	140 Onlange				-								
Comments.					1								
					_								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessmen	nt Category
		Quantity	Units		Type	Category		Type	Quantity	Units			
35	Drywall-Compound	142	LF	Rooms 207,217 and 208		Miscellaneous	No	None	0		YES)	X NO
2016 - Fall:	No Change		·]			<u></u>					
Comments:	ino Griariye				1								
Locitiniento.					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Categor	y
36	Drywall-Wall Tape	142	LF	Rooms 207,217 and 208		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change]								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Categor	у
37	Drywall-Ceiling	102	SF	Rooms 207,217 and 208		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Categor	у
38	Drywall-Ceiling-Compound	37	LF	Rooms 207,218 and 208		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change				1								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Categor	у
39	Drywall-Ceiling-Tape	37	LF	Rooms 207,218 and 208		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
40	Orange Carpet Mastic	918	SF	Room 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
41	9"x 9" Brick Floor Tile	300	SF	1st Floor Principal Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
42	9"x9" Brick Floor Tile Mastic	300	SF	1st Floor Principal Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
43	12"x12" Brown Floor Tile w/Brown and While Streaks	200	SF	Assembly Hall Patch, 1st Floor Principal Office and Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
44	12"x12" Brwn Floor Tile w/ Brwn&Wht Streaks Mastic	200	SF	Assembly Hall Patch and 1st Floor Principal Office and Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
45	12"x12" Brown Speckled Floor Tile Patch	2000	SF	Lunchroom, Front Office		Miscellaneous	No	None	0		X YES	NO
2016 - Fall:	: Repaired]							
Comments	:Cracked and missing til	es repaire	d in lunch	room]							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
46	12"x12" Brwn Speckled Floor Tile Mastic	2000	SF	Lunchroom, Front Office		Miscellaneous	No	None	0		X YES	NO
2016 - Fall:	: Repaired				1							
	:Cracked and missing til	es repaire	d in lunch	room]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
47	White Spray on Fireproofing	200	SF	Air Handling Room (Basement Mech. Room)		Surface	Yes	None	0		YES	X NO
2016 - Fall	No Change				 1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
D	Pre-formed Pipe Lagging	300	LF	Boiler Room		TSI	Yes	None	0		X YES		NO
2016 - Fall:	Damaged												
Comments:	Pipe leaks												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
E	Fittings Off Pre-formed Pipe Lagging	50	LF	Boiler Room		TSI	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:	-												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
F	Cardboard Pipe Insulation	120	LF	Boiler Room		TSI	Yes	None	0		X YES		NO
2016 - Fall:	Damaged												
Comments:Pipe leaks													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
G	Fittings Off Cardboard Pipe Insulation	50	LF	Boiler Room		TSI	Yes	None	0		YES		X NO
2016 - Fall:	No Change				\neg								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
Н	Air Cell Duct Insulation	50	LF	Basement		TSI	Yes	None	0		YES		X NO
2016 - Fall	: No Change						·	•	·				
Comments	:				_								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
J	Pipe Fittings Off Fiberglass Pipe	50	LF	Basement		TSI	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
К	Air Cell Pipe Insulation (Covering)	240	LF	Basement - Crawl Space		TSI	Yes	Dist	150		YES		X NO
2016 - Fall	: No Change				1								
Comments					_								
LIA NIa	Material Description	Matarial	Matarial	Material Leasting	A = b = = 4 = =	Matarial	Felabla	D	Damana	D	Channa in A		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
L	Fittings Off Air Cell Pipe Runs	90	LF	Basement - Crawl Space		TSI	Yes	None	50		YES		X NO
2016 - Fall	: No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
М	Gaskets Off Boiler	20	LF	Boiler Room		TSI	No	None	0		YES	X NO
2016 - Fall Comments	l: No Change s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
N	Refractory Brick - Non AHERA		SF	Boiler Room		Miscellaneous	No	Unknown	0		YES	X NO
0040 5.11	l. N.a. Oh anna	•	•	•	i		*	•	•	•	•	

2016 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Frank W Gunsaulus Scholastic Academy School
Date: 9/12/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.