## **Chicago Public Schools**

### 6 Month Asbestos Surveillance

2016 - Fall

School:Air Force Academy High SchoolAddress:3630 S. Wells		Oracle Unit: Region:	45231 04	Building ID: Mail Room:	2010 38
CHECK HERE IF NO CHANGE TO ASBESTOS	Asbestos Surveyor: Survey Date:	Guerrero, Mr. Samuel S 12/22/2016			
	Email Address:	ssguerrero@cps.edu			

	A copy of the 2016/201	7 notice to	parents and	d staff regarding the asl	bestos manaç	gement plan no	tifications v	vas distribute	d via:			
	Each child's backpa	ck	Notice	printed in school's news	sletter	Notice pri	nted in scho	ool's calenda	Oth	ier		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
006	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present							YES	XNO
2016 - Fall: N Comments:	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
007	12"x12" Lt Brown Floor Tile w/Brn & White Streaks			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

Χ

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
008	Mastic on 9" x 9" Dark Brown Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
009	Mastic on 12x12 Dk Brn w/Brn & Wh Strks Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
010	Mastic on 12x12 Lt. Brown w/Brn & Wh Streaks FT			1953 Building, Room 212A (MDF Room)		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
011	Partition Floor Joiner Compound			1946/53 Connection by Room 104				None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
012	12"x12" Lt Brown w/Brn & White Streaks Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
013	Mastic on 12 x 12 Lt Brn w/Brn & White Strks FT			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
014	Carpet Adhesive			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
015	Black Vinyl Baseboard			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
016	Black Vinyl Baseboard Adhesive			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
017	Sink Bottom Caulking			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
018	Plaster			1946 Building				None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
019	Interior Brick Walls			1946 Building				None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
020	Interior Brick Walls Mortar			1946 Building				None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
021	12" x 12" Green Floor Tile			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
022	Mastic on 12" x 12" Green Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
023	Tar Paper and Mastic in Vault Closet Areas			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
024	Vibration Isolator			1946 Building, Attic Above 200 and 201				None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
025	Fan Unit Door Lining			1946 Building, Attic above 200 and 201				None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
026	Dirt on Floor			Material Not Present		TSI		Loc			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
027	Mastic on 12"x12" Beige w/Brown & White Streaks FT			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
028	Partition Wall Joiner Compound	10	LF	1946/1953 Buildings by 104 & 204		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
029	12" x 12" Dark Gray w/White & Brown Streaks FT			Material Not Present							YES XNO

Comments:	2016 - Fall: No Change	
Comments:	Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Cate	gory
030	12" x 12" Dark Gray Floor Tile w/Beige Mix			Material Not Present							YES X NO	
2016 - Fall: N Comments:	lo Change				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
031	Mastic on 12"x12" Dark Gray w/Beige Mix Floor Tile			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
032	12" x 12" Light Beige Mix Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
033	Mastic on 12" x 12" Light Beige Mix Floor Tile			Material Not Present		Miscellaneous		None			

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
034	12" x 12" Dark Pink Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
035	Adhesive for 12" x 12" Dark Pink Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
036	12" x 12" Dark Beige w/ Brown & White Streaks FT			Material Not Present							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
037	Mastic on 12x12 Dk Beige w/Brn & White Strks FT			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
038	12" x 12" Light Gray Mix Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
039	Mastic on 12" x 12" Light Gray Mix Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
040	Gray and Yellow Mix Linoleum			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
041	Burlap with Adhesive Under Grey & Yellow Linoleum			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
042	12" x 12" Blue Floor Tile			Material Not Present							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
043	Mastic on 12" x 12" Blue Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
044	Mastic 12x12 Dk. Gray w/White & Brown Streaks FT			Material Not Present		Miscellaneous		Loc			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
045	Interior Brick			1953 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
046	Interior Brick Mortar			1953 Building							YES X NO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
047	Plaster			1953 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
048	Light Gray Vinyl Baseboard			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
049	9" x 9" Brown Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
050	Mastic on 9" x 9" Brown Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
051	Desk Top Linoleum			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
052	Desk Top Linoleum Adhesive			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
053	Black Vinyl Baseboard			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
054	Black Vinyl Baseboard Adhesive			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
055	12x12 Dk Beige w/Brown & White Streaks Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
056	12" x 12" Blue Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
057	12" x 12" Blue Floor Tile Adhesive			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
058	Dark Gray Vinyl Baseboard			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
059	Dark Gray Vinyl Baseboard Adhesive			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
060	12" x 12" Gray Mix Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
061	Mastic on 12" x 12" Gray Mix Floor Tile			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
062	Cork Insulation			Fan Room by 214							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
063	Vibration Isolator			Fan Room by 214							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
064	12" x 12" Beige Floor Tile w/Brown & White Streaks			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
065	Mastic on 12"x12" Beige FT w/Brn & White Streaks			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
066	12" x 12" Light Brown Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
067	12" x 12" Light Brown Floor Tile Adhesive			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
068	12" x 12" Dark Pink Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change	
Comments:	
	_

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
069	12" x 12" Dark Pink Floor Tile Adhesive			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
070	Fan Unit Door Lining Insulation			1946 Building, Basement							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
071	9" x 9" Gray Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
072	Mastic on 12" x 12" Gray Floor Tile			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
073	Partition Wall Compound			Between 1953/60 Buildings, 1st and 2nd Floor Corridors							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
074	9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office		Miscellaneous	No	Loc	10		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
075	Mastic on 9" x 9" Light Brown Floor Tile	200	SF	1960 Building, Store Room by Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
076	Dark Gray Vinyl Baseboard			Material Not Present							YES X NO
	o Change										

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
077	Dark Gray Vinyl Baseboard Adhesive			Material Not Present							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
078	Pump Floor/Unit Caulk			1960 Building, Boiler Room							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
079	Boiler Gasket Material			Material Not Present		TSI					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
080	Interior Brick			1960 Building							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
081	Interior Brick Mortar			1960 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
082	12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
083	Mastic on 12" x 12" Sandy Beige Floor Tile	250	SF	1960 Building, Engineer's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
084	9" x 9" Orange Floor Tile	50	SF	1960 Building, Engineer's Office Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
085	Mastic on 9" x 9" Orange Floor Tile	50	SF	1960 building, Engineer's Office Corridor		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
086	12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office		Miscellaneous	No	None	0		
2016 - Fall: N	lo Change										

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
087	Mastic on 12" x 12" Off White Floor Tile	30	SF	1960 Building, Store Room Toilet Across from Engineer's Office		Miscellaneous	No	None	0		YES	XNO
2016 - Fall: Comments	: No Change				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
088	12" x 12" Light Gray Mix Floor Tile			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
089	12" x 12" Light Gray Mix Floor Tile Mastic			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
090	Radiator Grill Lining Material			1960 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
091	Incinerator Gasket Material by Fire Hole			Material Not Present		TSI					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
092	Incinerator Interior Brick			Material Not Present							

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
093	Incinerator Ash Chamber Brick			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
094	Vibration Isolator			1946 Building, Fan Unit							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
095	White Chalky Material and Soil Mix			1953 Building, Unfinished Pipe Space							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
096	Vault Door Insulation			Material Not Present		Miscellaneous					YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
097	Light Gray Vinyl Baseboard			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
098	Light Gray Vinyl Baseboard Adhesive			Material Not Present							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
099	Beaver Board			Material Not Present							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	Exterior Brick			1946 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	Exterior Brick Mortar			1946 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
102	Exterior Brick			1953 Building							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Exterior Brick Mortar			1953 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
104	Exterior Brick			1960 Building							YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
105	Exterior Brick Mortar			1960 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	Exterior Door Caulk (NON AHERA)			1960 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Roofing Materials (NON AHERA)			1946 Building							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
108	Roofing Materials (NON AHERA)			1953 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109	Roofing Materials (NON AHERA)			1960 Building							YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
110	Interior Window Caulk			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
111	12" x 12" Lt. Beige w/Brwn & Wt. Streaks FT			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
112	12" x 12" White w/Off White & Beige Streaks			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	Mastic for HA 111 & HA 112 Checkerboard FT Pattern			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
114	12" x 12" Red Floor Tile			Material Not Present		Miscellaneous		None			YES	XNO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
115	12" x 12" Red Floor Tile Mastic			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116	12" x 12" Blue Floor Tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117	12" x 12" Blue Floor Tile Mastic			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
118	Green Carpet Adhesive			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
119	Acoustical Ceiling	1600	SF	Throughout Hallways of the 1960 Building		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
120	12x12 beige mix floor tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121	mastic associated with 12x12 beige mix floor tile			Material Not Present		Miscellaneous		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
122	Red Carpet Adhesive			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
123	Black Board/ Marker Board Adhesive	5000	SF	Classrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
124	Grey and Black Mix Terrazzo Flooring	4000	SF	East Enterances and Stairwells		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
125	12" X 12" Tand w/Brown and White Streaks Floor Tile			Material Not Present		Miscellaneous		None			YES XNO

2016 - Fall: No Change	
Comments:	
	-

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
126	12" X 12" Tand w/Brown and White Streaks Floor Tile Mastic			Material Not Present		Miscellaneous		None			YES X NO
2016 - Fall: N	lo Change	-									

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
127	Cork Board Adhesive			Material Not Present		Miscellaneous		None			YES	X NO
2016 - Fall: N Comments:	lo Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
128	Green Carpet Adhesive			Material Not Present		Miscellaneous		None			YES XNO
2016 - Fall: N Comments:	o Change				]						

VFT = Vinyl Floor Tile
<i>Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.</i>

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
129	12"x12" White Mottled Floor Tile			Thtoughout Corridors, Classrooms, and Offices		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
130	12"x12" White Mottled Floor Tile Mastic			Thtoughout Corridors, Classrooms, and Offices		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
131	12"x12" Blue Mottled Floor Tile			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules		Miscellaneous					

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
132	12"x12" Blue Mottled Floor Tile Mastic			Throughout First and Second Floor Corridors, Elevator Room, and Stage Vestibules		Miscellaneous					YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
133	2'x2' Lay-in Ceiling Tile			First Floor Corridor		Miscellaneous					YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
134	2'x4' Lay-in Ceiling Tile			Rooms 112A, 126, and 226		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	4" Gray Baseboard			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
136	4" Gray Baseboard Mastic			Rooms 115, 117, 133, 128, 130, 132, 134, 215, 217, 216, 225, 227, 229, 233, 231, 226, 228, 230, 234, 232, Main Office, Stage Vestibule, Gym Storage, Lunch Room, and 2nd Floor Store Room.		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137	Gray Sink Undercoating			Rooms 128, 130, and 133		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
138	Carpet Mastic			Rooms 134 and 212		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139	Transite Laboratory Countertop	400	SF	Rooms 109 and 226		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
140	Wood Pattern Sheet Flooring			Gymnasium		Miscellaneous					YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
141	Wood Pattern Sheet Flooring Mastic			Gymnasium		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
142	Blue Sheet Flooring	650	SF	Room 126		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	Blue Sheet Flooring Mastic	650	SF	Room 126		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
144	Transite Electrical Panel	200	SF	Basement Electrical Vault		Miscellaneous	No	None	0		YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
145	Electrical Wiring Associated with Wall Mounted Clocks	150	LF	Throughout Building		Miscellaneous	No	Unknown	0		YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	Distributed Pipe Insulation on Floor			Material Not Present		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases		TSI					

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	Joint Compound off Fiberglass Pipe Insulation			Material Not Present		TSI		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Joint Compound Off Fiberglass Pipe Insulation			Material Not Present		TSI		None			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Distributed Pipe Insulation in Dirt on Floor			Material Not Present		TSI		Dist			YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Distributed Pipe Insulation in Dirt on Floor			Material Not Present		TSI		Dist			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
н	Aircell Pipe Insulation			Material Not Present		TSI		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	Aircell Pipe Insulation			Material Not Present		TSI		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	Paperwrap Pipe Insulation			1946 Building, Pipe Chases							YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
к	Hard Joint Compound off Paperwrap Pipe Insulation	75	LF	1946 Building, Walls and Pipe Chases		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		Dist			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L-1	Hard Joint Compound off Aircell Pipe Insulation			1946 Building, Walls and Pipe Chases		TSI					YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		None			YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ν	Hard Joint Compound off Aircell Pipe Insulation			Material Not Present		TSI		None			YES X NO

2016 - Fall: No Change	
Comments:	

F	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C	С	Duct Interior Insulation			1960 Building, Boiler Room							YES X NO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Ρ	Magblock Pipe Insulation			Material Not Present		TSI		Loc			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Magblock Pipe Insulation Joint Compound			Material Not Present		TSI		None			YES X NO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	Water Tank Insulation			Material Not Present		TSI		None			YES XNO

2016 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Aircell Duct Insulation			Material Not Present		TSI					YES XNO

2016 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
т	Magblock Insulation	15	LF	1946 Building, Coal/Ash Room Abandoned Mech. Unit		ты	Yes	None	0		
2016 - Fall: No Change			]								

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	Duct Insulation - Black Tar Like Adhesive			1953 Building, Unfinished Pipe Spaces		TSI					YES X NO

2016 - Fall: No Change			
Comments:			

ALL LEA Responsibilities, for this school, will be met.

Alunhu /2

Robert Christlieb

#### NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Air Force	Academy	High	School
---------	-----------	---------	------	--------

Date: 12/23/2016

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016.

Asbestos surveillances are conducted every six months.

#### CHECK ONE

	A copy of this notice was sent home in each child's backpack.
--	---

A copy of this notice was printed in the school's newsletter and sent home with each child

A copy of this notice was printed in the school's calendar and sent home with each child

Other.

# A COPY OF THIS NOTICE MUST BE PLACED IN THE SCHOOL'S ASBESTOS MANAGEMENT PLAN.