Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

	School: Harlan Co Address: 9652 S. M	ommunity Ac Michigan	ademy High	School			racle Unit: egion:	510 06	21	Buildin Mail Ro)	
X CHECK	HERE IF NO CHA	ANGE TO	O ASBE	STOS	Asbestos Surveyor: Survey Date: Email Address:	12/9/2016	6						
	A copy of the 2016/20 Each child's backpa		_	_	ing the asbestos managool's newsletter			was distribute		her			
HA No	Material Description	Material Quantity	Material Units	Material Loc	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
01	Acoustical Ceiling Plaster	9000	SF	Auditorium		Surface	No	None	0		YES		X NO
2016 - Fall: N Comments:			1			1							
HA No	Material Description	Material Quantity	Material Units	Material Loc	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
02	Hard Plaster	108000	SF	Throughout Fa	acility	Surface	No	None	0		YES		X NO
2016 - Fall: N Comments:	No Change												
HA No	Material Description	Material Quantity	Material Units	Material Loc	ation Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
03	1'x1' Ceiling Tile	120000	SF	Throughout Fa	acility	Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N Comments:	No Change												

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

				1	T	T = = = = = =							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
04A	12x12 12x12 Various Shades of Beige Floor Tile (REMOVED)			1st Floor West Exit & Corridor, SW Exits, NE Corridor & Mens Washroom (1st FLoor), Swimming Pool Corridor		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				7								
Comments:	9												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
04B	12x12 Various Shades of Tan Floor Tile (REMOVED)			Corridor outside room 134, water fountain, outside room 124 & 126 patchwork		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				7								
Comments:	<u> </u>												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
04C	12x12 Multicolor Dark Beige Floor Tile	1920	SF	Rooms 220 and 222		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
04D	12x12 Light Blue Floor Tile (REMOVED)			Room 134		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04E	12x12 cream w/brown specks floor tile	7120	SF	Rooms 115A, 116, 117, 117B, 119, 124, 126, 133, 134, 135, 138A, 139, 210, 211, 213, 217, 218A, Girls Locker Room Office.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	ito onango											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04F	12x12 grey (dark tan) w/white strikes floor tile (REMOVED)			2nd floor corridor		Miscellaneous					YES	Х МО
2016 - Fall:	No Change				1							
Comments:	<u> </u>]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04G	12x12 beige w/brown & white streaks floor tile (NOT OBSERVED)	16000	SF	Mens Faculty, 1st fl: corridor, SE stair well, main office sitting area, ladies restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	U											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04H	12x12 crème w/ tan & white streaks floor tile	7050	SF	faculty dinning room & cafeteria, ladies restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	gory
041	12x12 beige w/white specks floor tile (REMOVED)			1st floor SE exit		Miscellaneous					YES	X NO	
2016 - Fall:	No Change												
Comments:	No Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	gory
04J	12x12 taupe w/brown & white specks floor tile	216	SF	Room 212		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change												
Comments:	140 Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	∍gory
04K	12x12 Multicolor Cream Floor Tile	2108	SF	Rooms 220 and 222		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	gory
05A	9x9 tan w/ white streaks	4560	SF	Rooms 224, 229, 230, 242, 216, 121, 123 and Office Vault		Miscellaneous	Yes	None	0		YES	X NO	
2016 - Fall:	No Change												
Comments:					7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
05B	9x9 beige w/brown streaks floor tile- NOT OBSERVED	1500	SF	Rooms 135 and 136 (Not Observed)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:	io change				1								
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
06A	9x9 tan w/White Streaks Floor Tile Mastic	3500	SF	Rooms 230, 229, 230, 242, 216, 121, 123, 224, Office Vault	71.	Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Chango				1								
Comments:	io Change				_								
Commonto:					<u> </u>								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
06B	9x9 beige w/brown streaks floor tile mastic	1000	SF	Rooms 135 and 136		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:	io onange				-								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
07A	12x12 Various Shades of Beige Floor Tile Mastic (NOT OBSERVED_	2081	SF	1st fl west exit & corridor, sw exits, ne corridor & mens washroom (1st fl), swimming pool corridor		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				1								
Comments:					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
07B	12x12 Various Shades of Tan Floor Tile Mastic (NOT OBSERVED)			corridor outside room 134, water fountain, outside room 124 & 126 patchwork		Miscellaneous					YES		X NO
2016 - Fall	: No Change				1								
Comments					-								
		•	•						•				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
07C	12x12 Multicolor Dark Beige Floor Tile Mastic	1920	SF	Rooms 220 and 222		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				7								
Comments					-								
		_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
07D	12x12 Light Blue Floor Tile Mastic (REMOVED)			Room 134		Miscellaneous					YES		X NO
2016 - Fall	: No Change				7								
Comments					-								
	•												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
07E	12x12 cream w/brown specks floor tile mastic	7120	SF	Rooms 115A, 116, 117, 117B, 119, 210, 211, 213, 218A and 133, 135, 138A, 139, Girls locker room office.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				7								
Comments					1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07F	12x12 grey (dark tan) w/white streaks floor tile mastic (REMOVED)			2nd floor corridor		Miscellaneous					YES	X NO
2016 - Fall	I: No Change				1							
Comments	3:]							
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07G	12x12 beige w/brown & white streaks mastic floor tile (NOT OBSERVED)	17020	SF	Mens Faculty, 1st fl: corridor, SE stair well, main office sitting area, ladies restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments	3:											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07H	12x12 crème w/ tan & white streaks mastic floor tile	7050	SF	faculty dinning room & cafeteria, ladies restroom		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
071	12x12 beige w/white specks floor tile mastic (REMOVED)			1st floor SE exit		Miscellaneous	No				YES	X NO
2016 - Fall	I: No Change]							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07J	12x12 taupe w/brn & white specks floor tile mastic	216	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	_]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
07K	12x12 multicolor cream mastic floor tile	2108	SF	Rooms 220 and 222		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
08	1x1 ceiling tile mastic	120000	SF	1st & 2nd floor corridors & classrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	J											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
09	drywall (gypsum board)	120000	SF	above 1x1 ceiling tile		Miscellaneous	No	None	0		YES	X NO
2016 - Fall [.]	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
10	1x2 ceiling tile (REMOVED)			Boys' gym		Miscellaneous					YES	X NO
2016 - Fall:	No Change				\neg							
Comments:	V											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
11A	gray baseboard	65	LF	rm. 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
11B	black baseboard	800	LF	Rooms 104-105,121, main office, gym 110, 112, 113, 115, 134		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				\neg							
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
11C	Cream baseboard	142	LF	Rooms 106 and 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				¬							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
12A	Gray Baseboard Mastic	65	LF	Room. 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
12B	Black Baseboard Mastic	800	LF	Rooms 104-105,121, main office, gym 110, 112, 113, 115, 134		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	:											
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
12C	Cream Baseboard Mastic	142	LF	Rooms 106 and 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
13	Yellow Sheet Goods Mastic	208	SF	Counter tops, rooms 109, 103-105		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
13A	Light Grey Linoleum	3300	SF	Room 109 and 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
13C	Black with Gray Linoleum	840	SF	Rooms 106, 107 and 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
14A	Light Grey Linoleum Mastic	3300	SF	Rooms 109 and 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
14C	Black with Gray Linoleum Mastic	840	SF	Rooms 106, 107 and 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							

	T			T				1 _					
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in As	ssess	ment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>		
15A	Blue Carpet Mastic	4800	SF	attnd ofc & srrdng ofcs;ast princ ofc;crrdr;offcs D,E,F,H;main ofc,princ ofc,grls lckr rm ofc,rm		Miscellaneous	No	None	0		YES		X NO
	l .			101		-1	1				<u></u>		
2016 - Fall: N	lo Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
15B	Burgandy Carpet Mastic	80	SF	Boy's Locker Room and Coach's Office		Miscellaneous	No	None	0		YES		X NO
0040 Fall N	I. Ol		•										
2016 - Fall: N	io Change				_								
Comments:					_								
					_								
	I Maria de la compansión de la compansió		T 8.4 () 1	Lag et la ce		I se e e e	Levis	T 5	1.5	T 5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
15P	12 x 12 Black with Maroon Checkerboard VFT.	1390	SF	Room 217 Corridor		Miscellaneous	No	None	0		YES		X NO
					_				I .	<u> </u>	L		
2016 - Fall: N	lo Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
16	Wood panel mastic (Panels have been removed)			Room 124		Miscellaneous					YES		X NO
			•	•	· ¬	•			•				
2016 - Fall: N	lo Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
17	interior window glazing (REMOVED)			thoughout 1st & 2nd floor		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
17A	Interior Window Glazing (REMOVED/REPLACED)			Throughout 1st&2nd floor		Miscellaneous					YES	X NO
	No Change]							
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
18	2x4 celing tile	840	SF	room 108		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
19	Drywall	400	SF	Room 108		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
20	Transite Countertops (REMOVED)			Room 108		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25	12" x 12" dark blue floor tile	4960	SF	Rooms 135,136, 208, 226, 214, 218, 241, 2nd Floor Teachers Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25C	12x12 Tan w/streaks VFT	700	SF	Room 215		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25D	12x12 Tan w/streaks VFT Mastic	700	SF	Room 215		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25M	12 x 12 dark blue floor tile mastic NOT OBSERVED	4960	SF	Rooms 136, 208, 214, 218, 226, 241, 2nd fl. teacher lounge, 135, 136		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments												
	The constant	I sa e e e	T. A. A. A. A. A.	T. 6		1	Term	T 5				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26	12 x 12 White w/ Beige Streaks Floor Tile	12000	SF	Rooms 112, 115, 122, 124, 125, 126, 130, 133, 134A, 207, 209, 219, 219A, 221, 228, 227A, 231, 232, 234, 236, 238, 240, Lunchrom and Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments					1							
]							
			T	T	T		T =	Т _		T =	T	_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26M	12 x 12 White w/ Beige Streaks Floor Tile Mastic	12000	SF	Rooms 112, 115, 122, 124, 125, 126, 130, 133, 134A, 207, 209, 219, 219A, 221, 228, 227A, 231, 232, 234, 236, 238, 240, and Library, and lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
27	12" x 12" Brown and White Floor Tile	1500	SF	Hallway in Modular Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				<u></u>						- 	
Comments	<u> </u>				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
27M	12" x 12" Brown and White Floor Tile Mastic	1500	SF	Hallway in Modular Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Chango				7							
Comments:	No Change											
Comments.												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
28	2' x 4' White Fissured Ceiling Tiles	5000	SF	Hallway and Classrooms Throughout Modular Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	140 Onlange											
-												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	12 x 12 Red Floor Tile - NOT OBSERVED	1000	SF	Rooms 112 and 114- NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	No Change				1							
COMMITTEE .												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
30	12 x 12 Red Floor Tile Mastic- NOT OBSERVED	1000	SF	Rooms 112 and 114- NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 Fall: 1	No Chango				7							
2016 - Fall: Comments:	ino Change				-							
COMMENTS.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
31	12 x 12 Light Blue Floor Tile- NOT OBSERVED	1000	SF	Rooms 112 and 114- NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				1								
Comments:	10 Change				1								
]								
LIA NIS	Material Description	Matarial	Matarial	Material Laurtina		Matarial	Estable	Damasa	D	Damana	Channa in A		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
32	12 x 12 Light blue Floor Tile Mastic- NOT OBSERVED	1000	SF	Rooms 112 and 114-NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change		•		1				•				
Comments:	10 Change				-								
					<u> </u>								
		r				_	•	1	1		1		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
33	12 x 12 White Floor Tile- NOT OBSERVED	1000	SF	Rooms 112 and 114-NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	10 0ago				1								
]								
	T	T	T	T	1	T	1 =	T	T	T	T a		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssess	ment Category
34	12 x 12 White Floor Tile Mastic- NOT OBSERVED	1000	SF	Rooms 112 and 114-NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	<u> </u>				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
35	12 x 12 Dark Blue Floor Tile	12000	SF	Corridors Border, Stairwells, Rooms 218, 214, 208, 241 and 226		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	140 Onlange											
			_						•			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
36	12 x 12 Dark Blue Floor Tile Mastic	12000	SF	Corridors Border, Stairwells, Rooms 218, 214, 208, 241 and 226		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
	Material December	I Mariantal	I Maria dal	I Material Landin	A -11 -	I Marta dal	Leann	I B	I B	I D	Observe to As	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
37	12 x 12 Sky Blue Floor Tile	10500	SF	Corridors and Room 138A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	110 Onlango											
	T						T =			1 -		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
38	12 x 12 Sky Blue Floor Tile Mastic	10500	SF	Corridors and Room 138A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u>J</u> -											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
39	22 x 22 White Floor Tile	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change			•				•	·	·			
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
40	22 x 22 White Floor Tile Mastic	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change												
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
41	22 x 22 Light Blue Floor tile	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change			•			•	•			•		
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
42	22 x 22 Light Blue Floor Tile Mastic	5000	SF	Main Hall		Miscellaneous	No	None	0		YES	Ì	X NO
2016 - Fall	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
43	22 x 22 Dark Blue Floor Tile	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change	•						•	·				
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
44	22 x 22 Dark Blue Floor Tile Mastic	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
45	22 x 22 Orange Floor Tile	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
46	22 x 22 Orange Floor Tile Mastic	5000	SF	Main Hall		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	· No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
47	2 x 2 Ceiling Tile	5000	SF	Main Hall		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	: No Change]								
Comments					1								
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
48	12 X 12 H Blue Mix Speckled VFT	3300	SF	Throughout Class Rooms (Annex Building)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change]								
Comments	:				_								
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
48M	12 x 12 H Blue Mix Speckled Mastic	3300	SF	Throughout Class Rooms (Annex Building)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change]								
Comments					=								
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
49	12 x 12 Dark Blue Mixed Speckled VFT	3300	SF	Throughout Class Rooms (Annex)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	: No Change]								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
49M	12 x 12 Dark Blue Mixed Speckled Mastic	3300	SF	Throughout Class Rooms (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
50	2 x 4 CT w/ grooved	5000	SF	Throughout (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
51	12 x 12 Cream w/ Beige Specs VFT	800	SF	1ST Floor Corridor (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
51M	12 x 12 Cream w/ Beige Specs Mastic	800	SF	1st Floor Corridor (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
52	12 x 12 Tan w/ Cream Specs VFT	800	SF	1st Floor Corridor (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	140 Onlange				-							
]							
	1									1 _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
52M	12 x 12 Tan w/ Cream Specs Mastic	800	SF	1st Floor Corridor (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	140 Ondrigo											
	T.			1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
53	Blue BAseboard Mastic	1000	SF	Throughout Classrooms (Annex)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	140 Ondrigo				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
54	12 x 12 Brown Mixed Speckled VFT	200	SF	Boys & Girls Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	110 Offurigo				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
54M	12 x 12 Brown Mixed Speckled Mastic	200	SF	Boys & Girls Washroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
55	12 x 12 Baby Blue VFT	500	SF	Rm 138		Miscellaneous	No	None	0		YES	[X NO
2016 - Fall:	No Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
55M	12 x 12 Baby Blue Mastic	500	SF	Rm 138		Miscellaneous	No	None	0		YES	[X NO
2016 - Fall:	No Change												
Comments:	<u> </u>												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
56	2 x 4 CT	560	SF	Rm 138 and 137		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment	Category
57	Tan Linoleum VFT	550	SF	Rm 104		Miscellaneous	No	None	0		YES	Х	NO
2016 - Fall:	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment	Category
57M	Tan Linoleum Mastic	550	SF	Rm 104		Miscellaneous	No	None	0		YES	X	NO
2016 - Fall:	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment	Category
58	Lab Counter Tops VFT	2000	SF	Rm 104, 106,107, 109, 110		Miscellaneous	No	None	0		YES	х	NO
2016 - Fall:	: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment	Category
59	Fume Hoods	40	SF	Rm 106		Miscellaneous	No	None	0		YES	Х	NO
2016 - Fall:	: No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessi	ment Category
60	12 x 12 Teal Mix Speckled VFT	200	SF	Rm 112		Miscellaneous	No	None	0		YES	I	X NO
2016 - Fall: N	lo Change												
Comments:	io onango												
	T		T. s. s. s. s. s.	Laaren e		T. A	Levis	T 5	T 5	T 5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	3Sessi	ment Category
60A	Linoleum Mastic	800	SF	Room 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change								•				
Comments:	io onango												
	T		T			T		T _	T_	T _	T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessi	ment Category
60M	12 x 12 Teal Mix Speckled Mastic	200	SF	Rm 112		Miscellaneous	No	None	0		YES	I	X NO
2016 - Fall: N	lo Change												
Comments:	<u> </u>												
	I waa a saa		T	T. A. C. C. C. C.		T	Levis	T 5	1.5	T 5			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	3Sessi	ment Category
61	12 x 12 Salmon (Pink) Mix Speckled VFT	200	SF	Rm 112		Miscellaneous	No	None	0		YES	l	X NO
2016 - Fall: N	lo Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
61M	12 x 12 Salmon (Pink) Mastic	200	SF	Rm 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
62	12 x 12 White w/ Green Specs VFT	200	SF	Rm 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:	_												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
62M	12 x 12 White w/ Green Specs Mastic	200	SF	Rm 112		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
63	12 x 12 H Gray Mixed Speckled VFT	600	SF	Rm 113 & 118		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	egory
63M	12 x 12 H Gray Mixed Speckled Mastic	600	SF	Rm 113 & 118		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	Vo Change				\neg								
Comments:	10 Onango												
	T	T						1 -	Т_	1-			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	egory
64	Orange Linoleum	300	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change												
Comments:	ge												
LIANI	Material Bereichten	Maradal	I Maria dal	Material Landon	A -11 -	I Martanial	Lezania	T.D		I D	Observation As		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	egory
64M	Orange Linoleum Mastic	300	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	No Change												
Comments:	J												
HA No	Motorial Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domoso	Domogo	Change in Ac	accoment Coto	0000
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Cate	egory
65	White Linoleum	600	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	Vo Change												
Comments:	10 Ondingo				_								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Ca	ategory
65M	White Linoleum Mastic	600	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	X NO	0
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Ca	ategory
66	Blue Linoleum VFT	300	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	X NO	0
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Ca	ategory
66M	Blue Linoleum Mastic	300	SF	Rm 114, 116		Miscellaneous	No	None	0		YES	XNO	0
2016 - Fall:	No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Ca	ategory
67	12 x 12 Beige Mixed Speckled VFT	200	SF	Rms. 239, 204, 206, Kitchen and Locker Room		Miscellaneous	No	None	0		YES	X NO	0
2016 - Fall	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67M	12 x 12 Beige Mixed Speckled Mastic	2000	SF	Rms 239, 204, 206, Kitchen and Locker Room		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change		<u> </u>	·	1						
Comments											
					J						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	12 x 12 White w/ Black Specs VFT	160	SF	Elevator Vestibule, Eng. Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change				1						
Comments											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68M	12 x 12 White w/ Black Specs Mastic	0	SF	Elevator Vestibule, Eng. Office		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change]						
Comments	u										
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
E	Insulation in Fire Rated Doors	240	SF	At Fire Stops Throughout Facility		Miscellaneous	No	None	0		YES X NO
2016 - Fall	· No Change]						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
G	MJV on Fiberglass Pipe Insulation	700	LF	Throughout Basement Crawl Space		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:	-												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
Н	Vibration collars	5	SF	Basement Boiler room.		TSI	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
HA-100	2'x4' plain white Ceiling Tile	150	SF	1st floor Boy's restroom		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:	J												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
HA-101	2'x4' white ceiling tile with grooves and pinholes	7000	SF	Classrooms		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	No Change												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-102	Acoustical "Pop Corn" Plaster	9000	SF	Auditorium		Surface	Yes	None	0		YES	х мо
2016 - Fall:	No Change											
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-103	2'x4' white ceiling tile with randow fissures and	1800	SF	classroom, corridor, men's room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-104	2'x4' White Ceiling Tile with Regular Holes	200	SF	Ladies Room		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-105	12"x12" beige VFT with brown and white specks	400	SF	restrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall [.]	No Change				\neg							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-105m	Adhesive for 12"x12" beige VFT with brown and white specks	400	SF	restrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	NO Orlange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Chango in As	sessment Category
TIA NO	Material Description	Quantity	Units	Iviaterial Location	Type	Category	Filable	Type	Quantity	Units	Change in As	ssessment Category
HA-106	12"x12" off white with beige specks floor tile (NOT OBSERVED)	500	SF	corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change	•		•		•	•	•	•	•	•	
Comments:	10 Onlange											
LIA NI-	Material December	I Maradal	I Maria dal	I Material Landon	I Ashastas	T Marta dal	Legania	I B	I Daniel	I B	Ob 1- A	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA- 106/107m	12"x12" off white and brown floor tile adhesive (NOT OBSERVED)	1000	SF	corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
HA-107	12"X12" Brown with Specks Floor Tile	500	SF	Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	c.iango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
HA-108	Red Carpet Adhesive (NOT OBSERVED)	3000	SF	classrooms		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				1								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
HA-109	Gray Carpet Adhesive	3000	SF	Rooms 102A, 120, 224A, Attendance Office, 131A, 130, Auditorium, Main Office, Assitant Principals Office		Miscellaneous	No	None	0		YES	II	X NO
2016 - Fall: N	No Change				1								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
HA-110	4" black baseboard	5000	LF	throughout		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change				1								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
HA-110m	Adhesive for 4" blackbaseboard	5000	LF	throughout		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change				1								
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
HA-111	Hard Joint Mudded Fittings on Fiberglass Insulated Pipe	4	LF	Utility Sink Room by the Water Heater		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:					1								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
I	12x12 light blue floor tile (NOT OBSERVED)	12000	SF	1st and 2nd floor corridors		Miscellaneous					YES		X NO
2016 - Fall: N	No Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
J	12x12 Dark blue floor tile (NOT OBSERVED)	6000	SF	1st and 2nd floor corridors.		Miscellaneous		None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	<u> </u>												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
К	Brown Linoleum	1000	SF	Rooms 104 and 104A		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
L	Brown Linoleum Mastic	1000	SF	Rooms 104 and 104A		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:	:												
					<u> </u>								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
М	12x12 light blue floor tile mastic (NOT OBSERVED)	12000	SF	1st and 2nd floor corridor		Miscellaneous		None	0		YES		X NO
2016 - Fall:	No Change												
Comments:	:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
N	12x12 dark blue floor tile mastic (NOT OBSERVED)	6000	SF	1st and 2nd floor corridors.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
0	1x1 Slotted Acoustical Ceiling Tile	800	SF	Boy's & Girl's Gym		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall	No Change]								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Р	1x1 Slotted Acoustical Ceiling Tile Adhesive	800	SF	Boy's & Girl's Gym		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Harlan Community Academy High School
Date: 12/15/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 51021

SCHOOL'S ASBESTOS MANAGEMENT PLAN.