Chicago Public Schools

6 Month Asbestos Surveillance 2016 - Fall

		Ada S McKinl Wabash Ave.	ey - Lakesid	e HS			racle Unit: egion:	6610	07	Buildir Mail Ro		3	
X CHEC	K HERE IF NO CH	ANGE T	O ASBE			12/28/201	16						
	A copy of the 2016/20 Each child's backp			d staff regarding the as				was distribute ool's calenda		ther mail It			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
1	12" x 12" Teal Floor Tile	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom		Miscellaneous	No	None	0		YES		X NO
Comments	: No Change :												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
2	12" x 12" Teal Floor Tile Mastic	220	SF	North Building- Rm. 17, Patching in Hallway, Patching in Lunchroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: Comments	: No Change :												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
3	9" x 9" Green w/ Beige Floor Tile	3000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: Comments	: No Change :]								

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
4	9" x 9" Green w/ Beige Floor Tile Mastic	3000	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Storage, Library		Miscellaneous	No	None	0		YES		X NO
004C Fall N	In Ohaman				7								
2016 - Fall: N	io Change				_								
Comments:													
					_								
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units			
5	9" x 9" Beige w/ Green Specks Floor Tile	3570	SF	North Building- Rm. 10, 11, 12, Hallway Rm. 15, 16, 14, Library		Miscellaneous	No	None	0		YES		X NO
	<u> </u>		1	16, 14, Library									
2016 - Fall: N	lo Change												
Comments:													
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
	'	Quantity	Units		Type	Category		Type	Quantity	Units	J		0 ,
	9" x 9" Beige w/ Green			North Building- Rm. 10,									
6	Specks Floor Tile Mastic	3570	SF	11, 12, Hallway Rm. 15, 16, 14, Library		Miscellaneous	No	None	0		YES	l	X NO
		•			7		•						
2016 - Fall: N	lo Change				4								
Comments:													
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units			
7	12" x 12" Beige Mix Floor Tile	1200	SF	North Building- Rm. 11, Hallway, and 13		Miscellaneous	No	None	0		YES		X NO
	I	I.	1	I .		1	1	L	1	1	1		
2016 - Fall: N	lo Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
8	12" x 12" Beige Mix Floor Tile Mastic	1200	SF	North Building- Rm. 11, Hallway, and 13		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
9	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	North Building- Rm. 12		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	North Building- Rm. 12		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
11	9" x 9" Green w/ White and Black Streaks Floor Tile	90	SF	North Building- Rm. 14 and Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
12	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	90	SF	North Building- Rm. 14 and Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				٦							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
13	9" x 9" Dark Green w/ White Streaks Floor Tile	8	SF	North Building- Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				٦							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssessment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in As	ssessment Category
14	9" x 9" Dark Green w/ White Streaks Floor Tile Mastic	8	SF	North Building- Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
15	9" x 9" White w/ Black Floor Tile	8	SF	North Building- Rm. 10		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
16	9" x 9" White w/ Black Floor Tile Mastic	8	SF	North Building- Rm. 10		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change]								
Comments													
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
17	12" x 12" White w/ Brown Floor Tile	20	SF	North Building- Custodian Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change]								
Comments]								
					1								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
18	12" x 12" White w/ Brown Floor Tile Mastic	20	SF	North Building- Custodian Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change				1								
Comments													
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	sment Category
19	12" x 12" Green w/ White Streaks Floor Tile	25	SF	North Building- Custodian Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall	: No Change			•]		•	•	•	•	•		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Asses	sment Category
20	12" x 12" Green w/ White Streaks Floor Tile Mastic	25	SF	North Building- Custodian Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Asses	sment Category
21	6" Vinyl Baseboard	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:	<u>~</u>												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
22	6" Vinyl Baseboard Mastic	955	LF	North Building- Rm. 11, 12, Hallway, Rm. 13, 16, and Girls' and Boys' Washrooms		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				1								
Comments:													
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Asses	sment Category
23	1' x 1' Ceiling Tile	3800	SF	North Building- Throughout		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
24	1' x 1' Ceiling Tile w/ Fissures	1000	SF	North Building- Rm. 13		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
25	Carpet Mastic	300	SF	North Building- Rm. 17		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26	Drywall	500	SF	North Building- Rm. 16 and 17 Washrooms, Storage, and Custodian Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
27	TSI on Water Heater	15	SF	North Building- Storage/Mechanical Room		TSI	Yes	None	0		YES	X NO
2016 - Fall	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessr	ment Category
28	Hard Elbows on Fiberglass Pipe Insulation	3	EA	North Building- Storage/ Mechanical Room		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:					=								
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessr	ment Category
29	Roofing Material- Not AHERA			North Building- Exterior Roof							YES		X NO
2016 - Fall: N	lo Change]								
Comments:	<u> </u>												
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessr	ment Category
30	12" x 12" Teal Floor Tile	280	SF	South Building- Entry Foyer and Janitor's Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	Ŭ												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessr	ment Category
31	12" x 12" Teal Floor Tile Mastic	280	SF	South Building- Entry Foyer and Janitor's Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	<u> </u>				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Beige Mix Floor Tile	250	SF	South Building- Entry Foyer		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change]						
Comments):]						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	12" x 12" Beige Mix Floor Tile Mastic	250	SF	South Building- Entry Foyer		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change				7						
Comments): 										
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	9" x 9" Dark Green w/ Beige Floor Tile	1540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change				7						
Comments											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9" x 9" Dark Green w/ Beige Floor Tile Mastic	1540	SF	South Building- Entry Foyer, Under Bench, Reception Area, Safe, Hallway, Computer Room, and North Social Science Classroom		Miscellaneous	No	None	0		YES X NO
2016 - Fall	: No Change				7						
Comments	<u> </u>				1						

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
36	9" x 9" Beige w/ Green Specks Floor Tile	450	SF	South Building- Reception Area and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	9" x 9" Beige w/ Green Specks Floor Tile Mastic	450	SF	South Building- Reception Area and Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38	9" X 9" Brown w/ Tan Floor Tile	1560	SF	South Building- Office and Science Classroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39	9" X 9" Brown w/ Tan Floor Tile Mastic	1560	SF	South Building- Office and Science Classroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
40	9" x 9" Tan w/ Brown Floor Tile	80	SF	South Building- Office and Science Classroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	-												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
41	9" x 9" Tan w/ Brown Floor Tile Mastic	80	SF	South Building- Office and Science Classroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
42	9" x 9" Red Floor Tile	850	SF	South Building- Math/Science Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:	Ü												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
43	9" x 9" Red Floor Tile Mastic	850	SF	South Building- Math/Science Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
44	9" x 9" Grey w/ Black Streaks Floor Tile	80	SF	South Building- Computer Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	110 Chango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
45	9" x 9" Grey w/ Black Streaks Floor Tile Mastic	80	SF	South Building- Computer Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1		•					
Comments:	140 Onlange											
]							
LIANI	Mariadal Basadaria	Maradal	I Maria dal	Material Leading	A -11	T Marta de l	Legania	T.D			01	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
46	12" x 12" White w/ Green Specks Floor Tile	210	SF	South Building- Hallway and Foyer		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
47	12" x 12" White w/ Green Specks Floor Tile Mastic	210	SF	South Building- Hallway and Foyer		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	c.iango				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
48	12" x 12" Light Brown Mix Floor Tile	8	SF	South Building- Janitor's Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
	•]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
49	12" x 12" Light Brown Mix Floor Tile Mastic	8	SF	South Building- Janitor's Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments					1							
]							
_		_		1				_				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
50	12" x 12" White w/ Black Specks Floor Tile	290	SF	South Building- South Social Science Room and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments					1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
51	12" x 12" White w/ Black Specks Floor Tile Mastic	290	SF	South Building- South Social Science Room and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments	: :				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
52	12" x 12" Pink Mix Floor Tile	660	SF	South Building- South Social Science Room and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
53	12" x 12" Pink Mix Floor Tile Mastic	660	SF	South Building- South Social Science Room and Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change		<u> </u>	<u> </u>]							
Comments	U											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
54	9" x 9" Beige w/ Black and Brown Floor Tile	80	SF	South Building- South Social Science Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
55	9" x 9" Beige w/ Black and Brown Floor Tile Mastic	80	SF	South Building- South Social Science Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
56	9" x 9" Blue w/ White Floor Tile	15	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
57	9" x 9" Blue w/ White Floor Tile Mastic	15	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
58	9" x 9" Green w/ White and Black Streaks Floor Tile	10	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
59	9" x 9" Green w/ White and Black Streaks Floor Tile Mastic	10	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
60	9" x 9" Beige w/ White Streaks Floor Tile	6	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:					1								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
61	9" x 9" Beige w/ White Streaks Floor Tile Mastic	6	SF	South Building- Hallway		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:]								
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
62	9" x 9" Brown w/ Red and White Floor Tile	10	SF	South Building- Math/Science Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssess	ment Category
63	9" x 9" Brown w/ Red and White Floor Tile Mastic	10	SF	South Building- Math/Science Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall:	No Change				7								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
64	Carpet Mastic	1000	SF	South Building- Office by Reception, Washroom in Office, and Math Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	rto orialigo											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Domogo	Damage	Change in Ac	sessment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Damage Quantity	Units	Change in As	sessment Category
65	1' x 1' Ceiling Tile	720	SF	South Building- Hallway		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1	•	1	•	•	•	•	
Comments:	ino change											
	1				1			T _		1 -		-
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
66	Drywall	1225	SF	South Building- Office and Washroom in Office next to Reception Area		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
	material Decempora	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units	onango mi no	occoment category
67	Plaster	6680	SF	South Building- Throughout		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	enange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
68	Aircell Pipe Insulation	15	LF	South Building- Safe Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	-											
	The state of the s		T	T		1		T =	T =	T =		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
69	Aircell Pipe Fitting Insulation	6	EA	South Building- Safe Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
70	Fittings on Fiberglass Pipe Insulation	35	EA	South Building- Office by Reception, Math/Science Room, Computer Room, Boys and Girls Washroom, Math Room, Science Walls, South Social Science, Office, and North Social Science Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	_											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
71	Vault Door Insulation	35	SF	South Building- Safe Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: Comments:	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	Roofing Material- Not AHERA			South Building- Exterior Roof							YES X NO
2016 - Fall: N	lo Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	Plaster	13680	SF	Church- Main Floor		Surface	Yes	None	0		YES X NO
204C Fall N	la Channa				7						

2016 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: YCCS - Ada S McKinley - Lakeside HS
Date: 9/30/2016
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
X Other. mail It
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 66107

SCHOOL'S ASBESTOS MANAGEMENT PLAN.