Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

Louisa May Alcott College Preparatory ES 22041 2040 School: **Oracle Unit: Building ID:** 2625 N. Orchard Street Address: Region: 02 Mail Room: Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/14/2017 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Hallways & Classrooms -Spray Applied Acoustical YES 07 SF X NO 10000 Yes 50 Surface Loc 1961 Bldg. 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

10	MJP E/F/V on Aircell Pipe Insulation	150	LF	Fan Room #1, S. & W. Unex. Area-1936 Bldg.	TSI	Yes	None	0	YES	X NO
2016 - Fal	I: No Change									
Comments	s:									
2017 - Fal	I: No Change									
Comments	S:									
2017 - Spi	ring: No Change									
Comments	S:									

Category

Asbestos

Type

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	Aircell Pipe Insulation	800	LF	Fan Room #1, S. & W. Unex. Area, 1936 Bldg.		TSI	Yes	None	20		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	Aircell Duct Insulation	1500	SF	Unexcavated Areas - 1936 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	Boiler #1 Insulation (ABATED)			Boiler Room, 1936 Building		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:												

		Quantity	Units		Туре	Category		Type	Quantity	Units		
15	Boiler #2 Insulation (ABATED)			Boiler Room, 1936 Building		TSI					YES	X NO
2016 - Fall:	No Change				1							
Comments:	<u> </u>											
2017 - Fall:												
Comments:												
	ıg: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	Tank Insulation (ABATED)			Boiler Rm, 1936 Building		TSI					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	ıg: No Change											
Comments:												

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

17	9"x9" Tan w/ Black Streaks Floor Tile	10225	SF	Rms 314, 312, 313, 311, 212, 214, 213, 211, Clinic and 1st Floor Admin Office - 1961 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	ŭ											
2017 - Fal	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	9'x9" Tan w/ Black Streaks Floor Tile Mastic	10225	SF	Rms 314, 312, 313, 311, 212, 214, 213, 211, Clinic and 1st Floor Admin Office - 1961 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change			-								

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	12"x12" White w/ Grey Streaks Floor Tile	700	SF	Room 109 - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	: No Change											
Comments:]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	9"x9" Green w/ White Streaks Floor Tile - NOT OBSERVED			Storage in Room 109 - 1936 Bldg.		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:												
	<u> </u>			<u> </u>								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	12"x12" White w/ Grey Streaks Floor Tile Mastic	700	SF	Room 109 - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	•]							
2017 - Fall: N	lo Change				-							
Comments:]							
2017 - Spring	: No Change				-							
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
22	9"x9" Green w/ White Streaks Floor Tile Mastic- NOT OBSERVED			Storage in Room 109 - 1936 Bldg.		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change				7							
Comments:	J											
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change				-							
Comments:	. 110 Onango				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Hard Plaster	80000	SF	Throughout, 1961 Bldg.		Surface	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	12"x12" Tan w/Brown Streaks Floor Tile (Over exsting Tile)-NOT OBSERVED			Teachers Lunchroom in Cafeteria, Hallway to Cafeteria-1961 Bldg.			No				YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<u> </u>				1							
2017 - Fall: I	No Change				-							
Comments:	.											
2017 - Sprin	g: No Change				-							
Comments:	<u> </u>											
1					1							

HA No

26	12"x12" Tan w/ Brown Streaks Floor Tile Mastic- NOT OBSERVED		Teachers Lunchroom in Cafeteria, Hallway to Cafeteria-1961 Bldg.							YES	X NO
2016 - Fall: N	lo Change	•	•	1	•	•	•	•	•	•	
Comments:	lo Change										
]							
2017 - Fall: N	lo Change										
Comments:											
]							
2017 - Spring	յ։ No Change										
Comments:											
]							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"x12" Beige Floor Tile	200	SF	3rd Floor Hall, All Janitors Closets, Clinic Bathroom, 1961 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

	28	12"x12" Beige Floor Tile Mastic	200	SF	3rd Floor Hall, All Janitors Closets, Clinic Bathroom, 1961 Bldg.		Miscellaneous	No	None	0		YES	X NO
I	2016 - Fall: N	o Change	•	•	*]	•	•	•	•	•		
	Comments:	o onango											
	0047 F.II N	. 01											
	2017 - Fall: N	o Change											
	Comments:												
	2017 0 :	N. 01											
	2017 - Spring	: No Change											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	9"x9" Brown w/ White Streaks Floor Tile-NOT OBSERVED	900	SF	1st through 3rd Floor Corridors - 1961 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

30	9"x9" Brown w/ White Streaks Floor Tile Mastic- NOT OBSERVED	900	SF	1st through 3rd Floor Corridors, Teachers Lunchroom in Cafeteria - 1961 Bldg.		Miscellaneous		None	0		YES X NO
2016 - Fall: N	No Change				1						
Comments:	10 Onlange										
					1						
2017 - Fall: N	No Change										
Comments:	-				1						
2017 - Sprin	g: No Change										
Comments:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units	
31	2'x4' Dot Pattern Ceiling Tile	1000	SF	Cafeteria - 1961 Bldg		Miscellaneous	Yes	None	0		YES X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:	_		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

								Туре	Quantity	Units		
	IP E/F/V on Fiberglass be Insulation	100	LF	North and SE Crawlspaces, Bathroom Chases - 1961 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:												

Material

Damage

Friable

Damage

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Material Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33	MJP E/F/V on Fiberglass Pipe Insulation	50	LF	Bathroom Chases - 1936 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Damage Change in Assessment Category

34	12"x12" Off White w/ Brown Streaks Floor Tile	2600	SF	3rd Fl Corridor - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments												
2017 - Fall:	No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
					I							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	Sment Category
35	12"x12" Off White w/ Brown Streaks Floor Tile Mastic	2600	SF	3rd Fl Corridor - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9"x9" Tan w/ Red Streaks Floor Tile-NOT OBSERVED	3000	SF	1st & 2nd Floor Hallways - 1936 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•		•]						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2047 0 : N 01	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	9"x9" Tan w/ Red Streaks Floor Tile Mastic-NOT OBSERVED	3000	SF	1st & 2nd Floor Corridors - 1936 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	12" x 12" White w/ Yellow Spots Floor Tile	480	SF	Rm 202 - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	· No Change											
Comments:	. 110 Onlango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
39	12"x12" White w/ Yellow Spots Floor Tile Mastic	480	SF	Rm 202 - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				_							
Comments:	2017 - Fall: No Change Comments:											
2017 Carina	. No Change]										
2017 - Spring Comments:	: No Change				\dashv							
Comments.					_							

40	9"x9" Tan w/ White Streaks Floor Tile-NOT OBSERVED	150	SF	Bathroom Within Cafeteria - 1961 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change			·]					·	
Comments:											
2017 - Fa	II: No Change										
Comment	S:										
2017 - Sp	ring: No Change]									

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	9"x9" Tan w/ White Streaks Floor Tile Mastic-NOT OBSERVED	150	SF	Bathroom Within Cafeteria - 1961 Bldg.		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

42	12"x12" White w/ Grey Streaks Floor Tile	700	SF	Room 109 - 1936 Bldg.		Miscellaneous	No	None	0		YES X NO	
2016 - Fall	: No Change]							
Comments	:]							
2017 - Fall	: No Change				-							
Comments	S:				_							
	ing: No Change				-							
Comments	:											
			1		-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ	jory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

700

Material

Quantity

Material

Units

SF

Material Location

Room 109 - 1936 Bldg.

HA No

43

Material Description

12"x12" White w/ Grey Streaks Floor Tile Mastic Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
44	12"x12" White Floor Tile	900	SF	Rm 109 (Under Tile) - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
	2017 - Spring: No Change Comments:											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asse	essinent Gategory
45	12"x12" White Floor Tile Mastic	900	SF	Rm 109 (Under Tile) - 1936 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												

46	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Shower Room, Break Room, South Unexcavated Area, Fan Room- 1936 Bldg.		TSI	Yes	None	0		YES X NO
2016 - Fall:	No Change										
Comments:	.										
2017 - Fall:	No Change										
Comments:	Ţ.										
2017 - Sprin	g: No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	Cardboard Pipe Insulation	25	LF	Shower Room, Break Room, South Unexcavated Area, Fan Room- 1936 Bldg.		TSI	Yes	None	0		YES X NO
2016 - Fall:	No Change]						

Type

Material

Category

Friable

Damage

Type

Damage Quantity Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

48	12"x12" Brown w/ Brown Specks Floor Tile-NOT OBSERVED		Cafeteria, Teachers Lunchroom, Cafeteria Hallway		No		YES	X NO
2016 - Fall: N	lo Change]				
Comments:]				
2017 - Fall: N	lo Change							
Comments:				1				
2017 - Spring	: No Change							
Comments:				 				
				J				

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	12"x12" Brown w/ Brown Specks Floor Tile Mastic- NOT OBSERVED			Cafeteria, Teachers Lunchroom, Cafeteria Hallway			No				YES	X NO
 2016 - Fall: N	o Change]							

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

50	12"x12" Beige Speckled Floor Tile	700	SF	1961 Building - Old Teacher Lunchroom in Cafeteria, New Kitchen		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change			<u>. </u>	1					·	
Comme	~				-						
2017 - F	all: No Change										
Comme	nts:				_						
2017 - S	Spring: No Change]						
Comme	nts:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

1961 Building - Old

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12"x12" Beige Speckled Floor Tile mastic	700	SF	Kitchen (Former Teacher Lunchroom) - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
52	Cardboard Pipe Wrap Insulation	300	LF	1961 Crawlspace (classroom and lunchroom side)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
53	9"x9" Black Floor Tile (ABATED)			Engineers Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change				\dashv							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
53A	9"x9" Black Floor Tile Mastic (ABATED)			Engineers Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
54	9"x9" Maroon Floor Tile (ABATED)			Engineers Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
54A	9"x9" Maroon Floor Tile Mastic (ABATED)			Engineers Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
55	Boiler Gasket	50	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	,											

56	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Comments: 2017 - Fall: No Change Comments:	56	12 x 12 Black Floor Tile	200	SF	Engineer's Office		Miscellaneous	No	None	50		YES	X NO
2017 - Fall: No Change Comments:		o Change											
Comments:	Comments:												
	2017 - Fall: No	o Change											
	Comments:												
2017 - Spring: No Change	2017 - Spring	· No Change				_							
Comments:		. 140 Onlange											
			T	T	Lare to the contract		I a a a a a a	Levis	T 5	T 5	1.5		
HA No Material Description Material Quantity Units Material Location Asbestos Type Asbestos Type Damage Quantity Units Category Type Damage Quantity Units Category	HA No	Material Description			Material Location			Friable				Change in Asses	sment Category
57 12 x 12 Black Floor Tile 200 SF Engineer's Office Miscellaneous No None 0 Tyes X NO	57		200	SF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change	2016 - Fall: No	o Change				7							
Comments:	Comments:												
2017 - Fall: No Change	2017 - Fall: No	n Change											
Comments:		o onango											
		N. O.											
2017 - Spring: No Change		: No Change											
Comments:	Comments:					+							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
58	12x12 Beige Speckled VFT	5000	SF	1st and 2nd Flr Corridors- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
	: No Change]							
Comments					_							
2017 - Fall	: No Change				-							
Comments												
2017 Cpr	ing. No Changa				1							
Comments	ng: No Change				1							
Comments	·				1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
59	12x12 Beig Speckled VFT Mastic	5000	SF	1st and 2nd Flr Corridors -1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1		•		•			
Comments					1							
]							
	: No Change											
Comments	:				1							
2017 - Spr	ing: No Change				1							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	12x12 Dark Beige Speckled VFT	600	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	i i i o o i a i go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
61	12x12 Dark Beige Speckled VFT Mastic	600	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 - Spring	ı: No Chango											
Comments:	. 140 Onange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
62	12x12 Off White w/ Gray Specks VFT	900	SF	Rm 103-1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	· ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63	12x12 Off White w/ Gray Specks VFT Mastic	900	SF	Rm 103-1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r. No Change											
Comments:	,											
		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
64	12x12 Offwhite w/ gray Speckles VFT	900	SF	Rm 114 -1961 bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Fall: N Comments:	o Change											
2017 - Spring Comments:	: No Change											
LIANG	I Matarial Decariation	Matarial	Matarial	Material Legation	Ashastas	Matarial	Levabla	Damana	Damaga	Damaga	Channa in Assa	Cotomont Cotomon
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
65	12x12 Offwhite w/ gray Speckles VFT Mastic	900	SF	Rm 114- 1961 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
	o Change											
Comments:	2017 - Fall: No Change Comments:											
	2017 - Spring: No Change											
Comments:	Comments:											

66	12x12 Blue Speckled VFT	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Chango			·	1						
	NO Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

1st floor Corridor,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
67	12x12 Blue Speckled VFT Mastic	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

68	12x12 Maroon w/ Speckles VFT	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•		•]	•	•	•	•	•	•	
Comments:												
2017 - Fall:	No Change											
Comments:	110 Onango											
2017 Sprin	g: No Change											
2017 - Spilit	g. No Change											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
69	12x12 Maroon w/ Speckles	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
70	12x12 Green W/ Speckles VFT	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0		YES X NO
		•	•	•	1	•	•	•	•	•	•

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	12x12 Green w/ Speckles VFT Mastic	70	SF	1st floor Corridor, Corridor outside of Cafeteria - 1961 Bldg		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
72	12x12 Beige Speckled VFT	3000	SF	1st, 2nd, 3rd Floor Corridors, Corridor outside of Cafeteria, Cafeteria, Toilet in Cafeteria, Rms-111,112		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change				1						
Comments:											
2017 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12x12 Beige Speckled VFT Mastic	3000	SF	1st, 2nd, 3rd Floor Corridors, Corridor outside of Cafeteria, Cafeteria, Toilet in Cafeteria, Rms-111,112		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
74	12x12 Blue Speckled VFT	20	SF	Main Entrance Corridor- 1936		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	ı: No Change				_							
Comments:	,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
75	12x12 Blue Speckled VFT Mastic	20	SF	Main Entrance Corridor- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	017 Spring: No Change											
2017 - Spring: No Change Comments:					1							
- Commonto												

HA No

76	12 x12 Maroon Speckled VFT	20	SF	Main Entrance Corridor- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:					<u> </u>							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category
77	12x12 Maroom Speckled VFT Mastic	20	SF	Main Entrance Corridor- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 Fall: N	lo Chango	•		_	1					•		

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category			
78	12x12 Green Speckled VFT	20	SF	Main Entrance Corridor- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO			
2016 - Fall: N	lo Change														
Comments:					_										
2017 - Fall: N	lo Change														
Comments:															
2017 - Spring	ı: No Change				-										
Comments:	J. NO Change				-										
	1			T		_									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category			
79	12x12 Green Speckled VFT Mastic	20	SF	Main Entrance Corridor- 1936 Bldg		Miscellaneous	No	None	0		YES	X NO			
2016 - Fall: N	lo Change				7										
Comments:															
2017 - Fall: No Change															
Comments:															
2017 - Spring	ı: No Change				1										
Comments:	on one of the state of the stat														
Commente.															

		Quantity	Units		Type	Category		Type	Quantity	Units		
80	Terrazo	2000	SF	Stairwells and Landings - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				_							
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
81	Terrazo	3000	SF	Stairwells and Landings - 1936		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:	No Change				1							
Comments:												
2017 - Sprii	ng: No Change				_							
Comments:					1							
					_							

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
84	Decorative Plaster	300	SF	Auditorium		Surface	No	Loc	10		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g: No Change											
Comments:					-							
		_										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
85	Carpet Mastic	800	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:					_							
2017 - Fall: I	No Change											
Comments:					_							
	g: No Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

Page 39

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Louisa May Alcott College Preparatory ES
Date:12/22/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.