Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

22231

Oracle Unit:

Address: 3730 N Oakley Avenue Region: 01 Mail Room: Asbestos Surveyor: Gonzalez, Mr. Sergio X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/20/2017 Email Address: sgonzalez2@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity Skim Coat and Hard Coat YES 01 X NO Main Building No None Surface 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Alexander Graham Bell Elementary School

School:

2270

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
02	2'x4' Ceiling Tile			Throughout		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	j. 140 Onango											
<u> </u>				1	Т .		T =	Τ _	T =	Т _	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
05	Carpet Mastic	72000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	la Changa											
Comments:	io Change											
	g: No Change											
Comments:												

06	12"x12" White w/ Gray Vinyl Floor Tile	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES	X NO
	•	•	•	•	•	•	•	•	•	•	•	
2016 - Fall	: No Change											
Comments	ζ·											
Commonto	·											
2017 - Fall	l: No Change											
2017 1 411	. 140 Onlange											
Comments	S:											
23	*											

Asbestos Type Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
07	9"x9" Gray Vinyl Floor Tile	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 101		Miscellaneous	No	None	0		YES X NO		

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08	Green Linoleum	900	SF	Kindergarten (112)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09	12"x12" White w/ Gray Vinyl Floor Tile Mastic	200	SF	Janitor's Closets on the 1st, 2nd & 3rd Floors by Boy's & Girl's Toilets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	Ţ.											
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>]							
2017 - Spring	ı: No Change				1							
Comments:]							

HA No

10	9"x9" Gray Vinyl Floor Tile Mastic	400	SF	200E, Book Rm by Balcony, 1st Fl Toilet by 107		Miscellaneous	No	None	0		YES	X NO
0010 = 11		•	•	•	1	•	•	•	•	•	•	
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	9"x9" Brown Vinyl Floor Tile	360	SF	Room 307, 309 (Under Carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

12A	9"x9" Brown Vinyl Floor Tile Mastic	360	SF	Room 307, 309 (Under Carpet)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige Vinyl Floor Tile	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

15	12"x12" Beige Vinyl Floor Tile Mastic	1500	SF	Engineers Office, Lunchroom Toilet, Rooms 304 and 314		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Brown Linoleum	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
17	Brown Linoleum Mastic	60	SF	Main Office Closet, Phone Booths		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
18	9'x9" Beige w/ Brown Streaks VFT NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES	Х NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											

Comments:

Comments:

2017 - Spring: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessn	nent Category
19	9'x9" Beige w/ Brown Streaks VFT Mastic NOT OBSERVED	600	SF	1st Floor Former Teachers Lunchroom Under the Carpet (Rm 105)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change]								
Comments:													
2017 - Fall: I	No Change												
Comments:	ito onango												
2017 - Sprin	g: No Change												
Comments:													
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessn	nent Category
20	9"x9" Light Tan VFT - NOT OBSERVED	80	SF	Lunchroom North and South Storage Rooms, now under HA# 06, HA# 09 - NOT OBSERVED		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:	ito onango												
	N. 61												
2017 - Fall: I	No Change				_								
Comments:													

2017 - Spring: No Change

Comments:

21	9"x9" Light Tan VFT Mastic - NOT OBSERVED			South Storage Rooms - NOT OBSERVED							YES	X NO
2016 - Fall: N	lo Change	•		•								
Comments:	io Orlange				-							
Comments.					-							
2017 - Fall: N	lo Change											
Comments:												
_												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asses	amont Cotogony
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	Sment Category
22	12"x12" White w/ Green Specks VFT	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io Gridingo				1							
2017 - Fall: N	lo Change											
Comments:												
				<u> </u>	_							
2017 - Spring	g: No Change											

Type

Material

Category

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
23	12"x12" White w/ Green Specks VFT Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	o Change]								
Comments:													
2017 - Fall: N	o Change												
Comments:													
2017 - Spring	· No Change												
Comments:	. 110 Griarige												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in	Λοοοοο	ment Category
HANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onange in 7	100000	ment dategory
24	1 x 1 ft Ceiling Tiles	1000	SF	Students Lunch Room		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	o Change												
Comments:	Ü												
2017 - Fall: N	lo Change												
Comments:	o onange												
2017 0 :	N. O.												
Comments:	: No Change				_								
Comments.													

											1	
25	12"X12" White w/ Blue Specks VFT	800	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	io onango											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	g. 140 Onlange											
Comments.												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
26	12" X 12" Gray/Blue w/Gray Specks	300	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]	•						
Comments:	io Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	յ։ No Change											

Material

Category

Asbestos

Type

Damage Quantity

Damage

Units

Damage

Type

Friable

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

27	12"X12" Tan w/Brown Specks	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	g. 110 Ondingo											
2017 - Fall: I	No Change											
Comments:	10 Onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
28	12"X12" Pink w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	To onango											
2017 - Sprin	g: No Change											
Comments:	g. No onange				_							
2017 - Fall: I	No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	12"X12" Yellow w/White- Marbled VFT	100	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	ı: No Change											
Comments:	,go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
30	Mastic associated with the new HA numbers 25, 26, 27, 28, and 29.	1400	SF	Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ŭ											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 - Spring	ı: No Change											
Comments:	g. 140 Onlange											

31	12" X 12" light beige with beige-and-white streaks, VFT	800	SF	Room 314 B		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change	<u> </u>		·]						
Comme	nts:] -						
2017 - 8	Spring: No Change										
Comme	nts:										
2017 - F	all: No Change										

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31A	12" X 12" light beige with beige-and-white streaks, Mastic	800	SF	Room 314 B		Miscellaneous		None	0		YES X NO

2010 5 11 11 21	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

32	12" X 12" white with black specks, VFT	1100	SF	Rm 312		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
32A	12" X 12" white with black specks, Mastic	1100	SF	Rm 312		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
33	18 " X 18" brown VFT	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES	ĺ	X NO
2016 - Fall: N	No Change]								
Comments:													
2017 - Fall: N	No Change												
Comments:	Ü												
2017 - Spring	g: No Change												
Comments:													
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Asses	sment Category
33A	18" X 18" brown, Mastic	500	SF	3rd floor toilet by Rm 312; 2nd floor toilet by Rm 212		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:													
2017 - Spring	g: No Change												
Comments:													

2017 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
34	Mudded joint packing on fiberglass runs	50	LF	Attic, 3rd floor corridor above ceiling tiles, Auditorium vestibules, Book Room by balcony 200S.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	Decorative plaster	2500	SF	Auditorium and balcony		Surface	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category		
36	1'x1' Ceiling Tile			Rooms 317 and 105		Miscellaneous	Yes	Unknown			YES	X NO		
2016 - Fall: N	lo Change													
Comments:														
2017 - Spring	g: No Change													
Comments:														
2017 - Fall: N	lo Change													
Comments:	3													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category		
36A	1'x1' Ceiling Tile Mastic			Rooms 317 and 105		Miscellaneous	No	None			YES	X NO		
2016 - Fall: N	lo Change													
Comments:														
2017 - Fall: N	lo Change													
Comments:	Ü													
2017 - Spring	r: No Change													
Comments:														

С	Aircell Pipe Insulation	600	LF	1st Floor Assembly Vestibule (5 LF); Throughout Attic (95 LF)		Miscellaneous	Yes	Dist	100		YES	X NO
2016 - Fa	II: No Change				7							
Comment	<u> </u>											
2017 - Fa	II: No Change											
Comment	s:											
	ring: No Change											
Comment	S:											
					_							
HA No	Material Description	Materia	l Materia	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ement Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

	Quanti		Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	omone catogory
E Preformed Pip	pe Insulation 530	LF	2nd & 3rd Fl Boys and Girls Pipe Chases, Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No Change Comments:											

Comments: 2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

1st Floor Assembly

Comments:

HA No

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Alexander Graham Bell Elementary School
Date:10/20/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 22231