Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

22591

Oracle Unit:

Building ID:

5760

Address: 640 W. Scott Street Region: 02 Mail Room: 33 Asbestos Surveyor: Rosas, Mr. Manuel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/10/2017 Email Address: mrosas@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Material Damage Quantity Units Type Category Type Quantity Auditorium, Boys and YES X NO 01 Hardcoat Plaster SF Yes 5000 Girls Toilets, Janitors Surface None 0 Closets 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Skinner North

School:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
02	1'x1' Ceiling Tile	10000	SF	Throughout (See Hatching)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03	Acoustic Ceiling	3500	SF	Gymnasium		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

04	Fireproofing	2500	SF	Boiler Room		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Commonto.												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	9"x9" Grey w/ White & Dark Streaks VFT	2050	SF	MDF Room 2nd flr Storage Room next to 202, 1st Staffroom , 1st flr Storage room, RM 1A,		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

		Todal Odidanoo Onioo
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Page 3

06	12"x12" Beige w/ Brown & White Specks VFT (ABATED 2009)			Rm 306, 107, 101, 103, 102, 105, 106							YES X NO
2016 - Fal	I: No Change	·	<u> </u>	·	1	·					
Comments	s:										
2017 - Fal	I: No Change										
Comments	s:										
2017 - Spr	ring: No Change										
Comments	S:										
					1						
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Categor

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
07	9"x9" Grey w/ White & Dark Specks VFT Mastic	2050	SF	MDF Room 2nd fir Storage Room next to 202, 1st Staffroom, 1st fir Storage room, RM 1A, Youth Guidance Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

Comments:

2017 - Fall: No Change

Comments:

2017 - Spring: No Change

Comments:

Material

Units

Material

Quantity

Material Location

HA No

Material Description

08	12"x12" Beige w/ Brown & White Specks VFT Mastic (ABATED 2009)		Rm 306, 107, 101, 103, 102, 105, 106		Miscellaneous			YES	X NO
2016 - Fall: N	lo Change	•				•			
				_					
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	g: No Change								
Comments:				-					
L				1					

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	09	9"x9" Sand w/ White & Black Streaks VFT (ABATED 2009)			Throughout (See Hatching)		Miscellaneous					YES X NO
_						1						

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

10	9"x9" Sand w/ White & Black Streaks VFT Mastic (ABATED 2009)		Throughout (See Hatching)	Miscellaneous			YES	X NO
2016 - Fall: N	lo Change				·	·		
Comments:								
2017 - Fall: N	lo Change							
Comments:	<i>y</i> .							
2017 - Spring	g: No Change							
Comments:								

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	9"x9" Green w/ White Streaks VFT	600	SF	Rm 106 and Gymnasium North Office & storage room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

12	9"x9" Green w/ White Streaks VFT Mastic	600	SF	Rm 106 and Gymnasium North Office & storage room		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			·							
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:											
					I						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	12"x12" Grey w/ Grey & White Specks VFT (ABATED)			Rm 302, 204							YES	X NO
2016 - Fal	II: No Change]				•			

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

14	12"x12" Grey w/ Grey & White Specks VFT Mastic (ABATED)		Rm 302, 204	Miscellaneous				YES	X NO
2016 - Fall: N	o Change	•			•		•		
Comments:									
2017 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:		 							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Light Brown w/ Brown & Cream Streaks VFT (ABATED 2009)			Throughout (See Hatching)		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

18	9"x9" Light Brown w/ Brwn & Cream Strks VFT Mastic (ABATED 2009)		Throughout (See Hatching)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change	·	•		•	•	•	•	•		
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change			_							
Comments:											
]							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Green w/ White & Green Specks VFT (ABATED 2009)			Room 206, 303							YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	12"x12" Green w/ White & Green Specks VFT Mastic (ABATED 2009)			Room 206, 303							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. 140 Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	9"x9" Blue w/ White Streaks VFT (ABATED 2009)			1st, 2nd, 3rd FI		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o onange											
2047 Caria	. No Change											
2017 - Spring Comments:	: No Change				_							
- Commondo												

22	9"x9" Blue w/ White Streaks VFT Mastic (ABATED 2009)	S		1st, 2nd, 3rd FI		Miscellaneous					YES	X NO
2016 - Fal	I: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	3:											
2017 - Spr	ring: No Change											
Comments	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

	••	Material Besonption	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Added	Smerit Gategory
23		9"x9" Tan w/ White & Dark Brown Streaks VFT (ABATED 2009)			East, West & Central Stairwells		Miscellaneous					YES	X NO
	6 - Fall: N nments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Material

Units

Material

Quantity

Material Location

HA No

Material Description

9"x9" Blue w/ White Streaks

24	9"x9" Tan w/ White & Dark Brown Streaks VFT Mastic (ABATED 2009)			East, West & Central Stairwells		Miscellaneous					YES	X NO
2016 - Fall:	No Change			·	<u> </u>							
Comments												
	No Change											
Comments												
2017 - Spri	ng: No Change				_							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
25	9"x9" Green w/ White & Green Specks VFT	250	SF	Engineers Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments	:											

Type

Material

Category

Friable

Damage

Type

Damage Quantity Damage

Units

Change in Assessment Category

Material

Units

Material

Quantity

Material Location

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

		Quantity	Units		Type	Category		Туре	Quantity	Units		
26	9"x9" Green w/ White & Green Specks VFT Mastic	250	SF	Engineers Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
2017 - Fall: N	No Change				_							
Comments:												
2017 - Sprin	g: No Change											
Comments:	g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
27	12"x12" White w/ Grey Specks VFT (ABATED 2009)			Principals Office							YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Sprin	g: No Change				_							
Comments:	g. 110 Oriango											

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

28	12"x12" White w/ Grey Specks VFT Mastic (ABATED 2009)			Principals Office							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	12"x12" Coffee w/ Brown & White Streaks VFT	70	SF	Lunchroom Offices		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
30	12"x12" Coffee w/ Brown & White Streaks VFT Mastic	70	SF	Lunchroom Offices		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	, re onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	1' x 1' Ceiling Tile Glue (Mastic)	10000	SF	Throughout (See Hatching)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				_							
	, 10 Onango											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	Exterior Window Caulk	20000	LF	Exterior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:	-											
2017 - Spring	ı: No Change				-							
Comments:	, G											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	Sink Coating	32	SF	Room 101, 103, 106, 108, 201, 203, 301, Clinic (110)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	ı: No Change											
Comments:	, onango]							
	·		·		1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34	12 x 12 inch Beige w/Streaks VFT	600	SF	Food Storage Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
34 A	12 x 12 inch Beige w/Streaks VFT Mastic	600	SF	Food Storage Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change			<u>-</u>								
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
35	12"X 12" Beige w/white spots floor tile	1400	SF	Lunchroom faculty dining		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	ı: No Change				-							
Comments:	. No Onango				-							
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
	,	Quantity	Units		Туре	Category		Туре	Quantity	Units		
36	12"X 12" Beige w/white spots FI. Tile MASTIC	1400	SF	Lunchroom, faculty dining		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]			•		•		
Comments:	io Oriango											
2047 Falls N	la Changa											
2017 - Fall: N	io Change				<u>.</u>							
Commonto.												
2017 - Spring	: No Change											
Comments:												

37	12 x 12 Grey with Grey Streaks Floor Tile	30000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor Storage and Auditorium		Miscellaneous	No	None	0		YES	X NO
•	•		-	*	•	•			•	•	•	
0040 5 11 1					1							
2016 - Fall: N	No Change											
Comments:												
2017 Spring	g: No Change											
2017 - Spilit	g. No Change											
Comments:												
Comments.												

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37M	12 x 12 Grey with Grey Streaks Floor Tile Adhesive	30000	SF	1st, 2nd and 3rd Floor Corridors, 3rd Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

2017 - Fall: No Change

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
38	12 x 12 Green with Streaks Floor Tile	4800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd Ivl storage room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38M	12 x 12 Green with Streaks Floor Tile Mastic	4800	SF	Classrooms 206, 210, 303, 304, 310, 106, 2nd fl storage room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 Light Blue with Streaks Floor Tile	6600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change				7						
Comments:											
2017 - Sprir	ng: No Change										
Comments:					_						
2017 - Fall:	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39M	12 x 12 Light Blue with Streaks Floor Tile Mastic	6600	SF	Classrooms: 102, 204, 212, 302, 308, 312, 1st, 2nd and 3rd Floor Corridors, lunchroom storage room		Miscellaneous	No	None	0		YES X NO

				g
		•	•	
2016 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12 x 12 White with Blue Streaks Floor Tile	12000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors, 2nd fl faculty room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40M	12 x 12 White with Blue Streaks Floor Tile Adhesive	12000	SF	Classrooms: 105, 107, 109, 201, 203, 205, 207, 209, 301, 305, 307, 308, 1st Floor Unisex Washroom, Lunchroom, Workers Dressing Area, 1st, 2nd and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	12 x 12 Brown with White Streaks Floor Tile	5200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	g. 140 Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41M	12 x 12 Brown with White Streaks Floor Tile Mastic	5200	SF	Classrooms 202, 208, 300, 306, Main Office, and 1st, 2nd, 3rd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Chango]							
Comments:	io Change				1							
= =					⊣							

2017 - Spring: No Change

Comments:

42	12 x 12 Turquoise with Straks Floor Tile	569	SF	1st, 2nd and 3rd Floor Corridors	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42M	12 x 12 Turquoise with Straks Floor Tile Adhesive	569	SF	1st, 2nd and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

43	Burgandy with Colored Streaks Carpet Adhesive	3200	SF	Rooms 101, 103, 108, and 110		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:]										
Comments:					-							
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:					=							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Type

Loc

50

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		

1465

LF

Material

Quantity

Material

Units

Material Location

Boiler Rm, Unfinished

Pipe Spaces, All Pipe

Chases

HA No

С

Material Description

MJP on Fiberglass Pipe

Insulation

D	TSI Pipe Insulation	445	SF	Boiler Rm pipe overhead a large hole that has a potential for friable release		TSI	Yes	Dist	75		YES	X NO
2016 - Fal	l: No Change											
Comments:												
2017 - Spring: No Change												
Comment	<u> </u>											
2017 - Fal	I: No Change											
Comment												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
E	Aircell Pipe Insulation	150	LF	Lunchroom Store Rm		TSI	Yes	None	0		YES	X NO
2016 - Fal	I: No Change	•		•	<u> </u>	1	•	1	1			
Comments:												
2017 - Fall: No Change												

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
F	Storage Tank Insulation	300	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
G	Boiler Gasket	30	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units		
J	Table Top	16	SF	Boiler Rm		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
К	HVAC Duct Jacket over Fiberglass Duct Insulation	1000	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	-											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
L	Burgundy with Colored Specks Carpet Mastic	2400	SF	Room 108, Library (101 and 103)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
М	Red Carpet Mastic	500	SF	Room 309		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:	<u> </u>											
					J							

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Skir	nner North								
Date: 10/10	/2017								
									
the Asbestos Ma	you in accordance with Illinois and Federal Asbestos Regulations, that a copy of anagement Plan is available at each school during school hours by appointment. iew the Asbestos Management Plan must be made at least 24 hours in advance.								
The last inspect	advised that CPS conducts asbestos inspections of all Schools every three years. ion was completed in 2016. Illances are conducted every six months.								
CHECK ONE									
A copy of	this notice was sent home in each child's backpack.								
A copy of	A copy of this notice was printed in the school's newsletter and sent home with each child								
A copy of	this notice was printed in the school's calendar and sent home with each child								
Other.									
A COPY OF	THIS NOTICE MUST BE PLACED IN THE								

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 22591

SCHOOL'S ASBESTOS MANAGEMENT PLAN.