## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

23401

**Oracle Unit:** 

Address: 3730 N Laramie Avenue Region: 01 Mail Room: Asbestos Surveyor: Edgerley, Mr. Craig X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/17/2018 Email Address: cedgerley@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Material Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Boiler Room (Building YES 05 None X NO Water Tank Insulation TSI 1911) 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

William P Gray Elementary School

School:

3620

**Building ID:** 

06	MJP E/F/V on Aircell Pipe Insulation	10	LF	Room 211, Platform/Stage/Dressing Rooms, North Warm Air Chamber (Building 1911)		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:					1							
2017 - Fall: I	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
07	Friable Brick and Mortar			Basement Area (Building 1911)							YES	X NO
2016 - Fall: I	No Change				]							
Comments:												
2017 - Fall: I	No Change				_							
Comments:												

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	Friable Masonry and Mortar			Basement East, Ceiling (Building 1911)							YES	X NO
2016 - Fall: N	lo Change											
Comments:					+							
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change				4							
Comments:					-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
20	MJP on Mag Block Pipe Insulation	10	LF	Engine and Tank Room (Building 1911)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	ı: No Change				-							
Comments:	i. 140 Onange				=							
Comments:					1							

22	Mag Block Pipe Insulation	50	LF	Engine and Tank Room (Building 1911)	TSI	Yes	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Aircelll Pipe Insulation	90	LF	Rooms 109 and 211, Stage/Platform and Dressing Room, North Warm Air Chamber (Building 1911)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Friable	Type	Quantity	Units	Change in Assessment Category
24	Cardboard Pipe Insulation	300	LF	Boiler Room, Engine and Tank Room, Room 105 Toilet (Building 1911)		TSI	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	MJP on Cardboard Pipe Insulation	38	LF	Boiler Room, Engine and Tank Room, Room 105 Toilet (Building 1911)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	MJP on Fiberglass Pipe Insulation	200	LF	Engine & Tank Rooms, Boiler Room, 1st, 2nd & 3rd Floor Boys & Girls Toilet Pipe Chases (Building 1911)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
9
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Hard Coat Plaster	70000	SF	Throughout (Building 1911)		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	2'x4' White Ceiling Tile	30000	SF	Throughout Building 1911		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Fall: No	o Change											
Comments:	-											
2017 - Spring:	· No Change											
Comments:	. No Change											
								_				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	1'x1' Peg Hole Ceiling Tile (Above 2'x4' Ceiling Tile)	400	SF	Room 211 (Building 1911)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Fall: No	o Change											
Comments:	J											
2017 - Spring:	· No Change											
Comments:	. Ho ondingo											

HA No

30	Canvas Wall Cover			Room 204 Closet and Room 105 (Building 1911)							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	go											
					]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
31	2'x4' Smooth Ceiling	1500	SF	Kitchen - 1999		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				1							
Comments:	io oriarigo											
2017 - Spring	ı: No Chango											
Comments:	J. INO CHAILIYE				-							
Comments:					4							

Category

Asbestos

Type

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage Quantity

Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
32	2'x4' White w/ Grooves Ceiling Tile	15000	SF	Throughout - 1999		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2017 - Spring	: No Change												
Comments:	J												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
33	Drywall	500	SF	MDF Room - 1999		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:	<u> </u>												
2017 - Fall: N	lo Change												
Comments:													
2017 - Spring	g: No Change												
Comments:	j. 140 Orialigo												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
34	Drywall Compound	150	SF	MDF Room - 1999		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
35	Spray on Fireproofing	15000	SF	Throughout 1999		Surface	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

36	Drywall Tape	150	LF	MDF Room - 1999		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
	No Change											
Comments:												
	ng: No Change											
Comments:												
					ı							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
37	12"x12" Violet-Streaked VFT	250	SF	Principal's Office ( Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 Falls	No Change	•	•		1	•	•	•	•		•	

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37A	12"x12" Violet-Streaked Mastic	250	SF	Principal's Office (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
38	Black Table Tops	160	SF	Room 305 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	ng: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
39	Fire Curtain	1600	SF	Assembly Hall Stage (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:					-							
2017 - Spring	: No Change				]							
Comments:					-							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	Terrazzo	12000	SF	1st, 2nd and 3rd Floor Corridors, all Vestibules and Stairwells - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	-											
2017 - Fall: N	o Change				_							
Comments:	-											
2017 - Spring	: No Change				-							
Comments:	-				]							
					_							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
41	Carpet Mastic	3500	SF	Rooms 602A-E (1999) and 2nd Floor Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>											
2017 - Fall:	No Change				=							
Comments:												
	ng: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	Asphalt Flooring			Corridors		Miscellaneous	No	Unknown	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
	ng: No Change											
Comments:					_							
2017 - Fall:	No Change											
Comments:					4							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

Α	12"x12" White w/ Brown Streaks VFT (Painted Over)	2500	SF	Assembly Hall/Gym (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments	5:				]							
	ing: No Change											
Comments	3:											
	l: No Change											
Comments	3:				_							
					<b>⊒</b>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
AA	12"x12" Peach w/ White Specks VFT	800	SF	Room 103 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change				1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Units

В	9"x9" Green w/ White Streaks VFT	800	SF	Rooms 211 and 311 (Building 1911)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:											
2017 - Sprir Comments:	ng: No Change										
2017 - Fall: Comments:	•										
					J						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ВВ	12"x12" Peach w/ White Specks VFT Mastic	800	SF	Room 103 (Building 1911)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
С	Light Green Linoleum (Painted Over)	800	SF	Assembly Hall/Gym (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
CC	12"x12" Beige w/Tan Streaks VFT	16000	SF	Throughout 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	<b>.</b>											
2017 - Fall: N	o Change											
Comments:	<b>y</b> -											

D	12"x12 White w/ Brown Streaks VFT Mastic (Painted Over)	2500	SF	Assembly Hall/Gym (Building 1911)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			•			·	·		
Comments:										
2017 - Spring	j: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:	-									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
DD	12"x12" Beige w/ Tan Streaks VFT Mastic	16000	SF	Throughout 1999		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Е	9"x9" Green w/ White Streaks VFT Mastic	800	SF	Rooms 211 and 311 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
EE	12"x12" Light Green w/ Dark Green Streaks VFT	2000	SF	Throughout 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	, <u>.</u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	Light Green Linoleum Mastic (Painted Over)	800	SF	Assembly Hall/Gym (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	_											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
FF	12"x12" Light Green w/ Dark Green Streaks VFT Mastic	2000	SF	Throughout 1999		Miscellaneous	No	None	0		YES	Х NO
2016 - Fall: N	o Change											
Comments:	Ğ											
2017 - Spring	: No Change											
Comments:	<b>-</b>											
2017 - Fall: N	o Change											
Comments:	-											

G	12"x12" White w/ Brown Speckles VFT	2340	SF	Room 204, 204 Closet (MDF Room) and Room 206 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change	•		•	]	•	•	•	•	•	•	
Commen					]							
2017 - Fa	all: No Change				-							
Commen	ts:				]							
2017 - S	oring: No Change				]							

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GG	24"x24" Dark Green W/ Specks VFT	500	SF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Н	12"x12" White w/ Brown Speckles VFT Mastic	2340	SF	Room 204, 204 Closet (MDF Room) and Room 206 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				]	•	•	•	•	•	•	
Comments:	<b>.</b>											
2017 - Fall: I	No Change				-							
Comments:												
2017 - Sprin	g: No Change											

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
НН	24"x24" Dark Green W/ Specks VFT Mastic	500	SF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

1	12"x12" Dark Brown Speckles VFT	400	SF	Room 109 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
								1				
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
II	24"x24" Beige w/ Specks VFT	300	SF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

J	12"x12" Dark Brown Speckles VFT Mastic	400	SF	Room 109 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				1							
Comments	s:				]							
2017 - Fal	II: No Change											
Comments	S:				-							
2017 - Spi	ring: No Change											
Comments	S:				1							
					J							
HA No	Material Description	Material	Material	Material Location	Achostos	Material	Eriable	Damago	Damago	Damaga	Change in Access	emont Catagory

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Fliable	Type	Quantity	Units	Change in Assess	Smerit Category
JJ	24"x24" Beige w/ Specks VFT Mastic	300	SF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												

2017 - Spring: No Change Comments:

Material Description

HA No

2017 - Fall: No Change Comments:

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
К	12"x12" Beige w/ Dark Brown Speckles VFT	265	SF	Engineers Office (Building 1911)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2017 - Spring	ı: No Chango				_								
Comments:	i. No Change												
Commonto.													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
KK	Tan Linoleum	5000	SF	Gym - 1999		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				$\neg$								
Comments:	<u> </u>												
2017 - Spring	ı: No Chango												
Comments:	i. No Change												
2017 - Fall: N	lo Change												
Comments:					_								

L	12"x12" Beige w/ Dark Brown Speckles VFT Mastic	265	SF	Engineers Office (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	<u> </u>	•		1							
Comments	:											
2017 - Fall	: No Change											
	•											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
					1							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	ı: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			

Quantity

5000

Material

Units

Units

SF

Material

Quantity

Material Location

Gym - 1999

HA No

LL

Material Description

12"x12" Beige w/ Dark

Tan Linoleum Mastic

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
М	9"x9" Green w/ White Speckles VFT	20	SF	007 Toilet (Building 1911) NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
ММ	Beige Vinyl Baseboard	400	LF	Throughout Corridors - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>				]							
2017 - Spring	: No Change				-							
Comments:	3											
2017 - Fall: N	o Change				<u> </u>							
Comments:	<b>y</b> -				]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
N	9"x9" Green w/ White Speckles VFT Mastic	290	SF	007 Toilet (Building 1911) (NOT OBSERVED)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change				]							
					-							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
					]							
		-				_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
NN	Beige Vinyl Baseboard Mastic	400	LF	Throughout Corridors - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	•											
2017 - Spring	: No Change				<u> </u>							
Comments:	·····go				-							
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
0	12"x12" Light Brown w/ White Speckles VFT	1040	SF	Room 101 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:					-							
2017 - Spring	: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
00	Rust Vinyl Baseboard	2500	LF	Throughout Classrooms - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	•				1							
2017 - Spring	: No Change				1							
Comments:	•											
2017 - Fall: N	o Change				-							
Comments:	<b>-</b>											
					J							

	T					T		_	_			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Р	12"x12" Light Brown w/ White Speckles VFT Mastic	1040	SF	Room 101 (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	_											
2017 - Fall: N	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:	g											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		,
PP	Rust Vinyl Baseboard Mastic	2500	LF	Throughout Classrooms - 1999		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	10 Onango											
2017 Cravin	a. No Chonas											
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	<u> </u>											

Q	12"x12" Coffee w/ White Speckles VFT	600	SF	Main Office/Public Area, Clerk's Space (Building 1911)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change	-								
2017 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
QQ	Green Vinyl Baseboard	240	LF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

R	12"x12" Coffee w/ Speckles VFT Mastic	600	SF	Main Office/Public Area, Clerk's Space (Building 1911)		Miscellaneous	No	None	0	YES	X NO
	•	•	•				•	-	-		
2016 - Fall: No Change											
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
RR	Green Vinyl Baseboard Mastic	240	LF	Rooms 402 and 503 - 1999		Miscellaneous	No	None	0		YES X NO

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

YES X NO
Change in Assessment Category
YES X NO

2017 - Spring: No Change

Comments:

U	12"x12" Brown w/ White Streaks VFT	100	SF	Engine /Tank Storage Room (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments												
2017 - Fall:	No Change				-							
Comments					]							
2017 - Spri	ng: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
V	12"x12" Brown w/ White Streaks VFT Mastic	100	SF	Engine/Tank Storage Room (Building 1911)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments												
2017 - Fall:	No Change				-							
Comments	<u> </u>				7							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

W	12"x12" Dark Brown VFT	10	SF	Engineer's Room (Building 1911)		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	•											
					•							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units	3	,
Х	12"x12" Dark Brown VFT Mastic	10	SF	Engineer's Room (Building 1911)		Miscellaneous	No	None	0		YES	X NO
	•	•				•						
2016 - Fall: N	o Change											
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Υ	12"x12" Off White VFT	70	SF	Speech Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
YY	12"x12" Off-White VFT Mastic	70	SF	Speech Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
L												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Z	12"x12" Beige w/brown speckles VFT	100	SF	Speech Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	r. No Change											
Comments:	9. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units	3	,
ZZ	12"x12" Beige w/brown speckles VFT Mastic	100	SF	Speech Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	r. No Change											
Comments:	J. 140 Orlange											
2017 Fall: N	lo Chongo											
2017 - Fall: N Comments:	io Change											
Committee its.												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: William P Gray Elementary School
Date: 1/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 23401

SCHOOL'S ASBESTOS MANAGEMENT PLAN.