## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

Stephen K Hayt Elementary School 23621 3850 School: **Oracle Unit: Building ID:** Address: 1518 W Granville Avenue Region: 01 Mail Room: 32 Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES 11 Hard Coat Plaster 0 SF None X NO Throughout - 1905 Bldg. Surface No 0 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

22	9"x9" Beige w/Brown Vinyl Floor Tile	200	SF	Rm 002 1/2 - 1905 Bldg NOT OBSERVED	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Orange w/Brown Vinyl Floor Tile	1130	SF	Assembly Hall - 1905 BldgNOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

24	9'x9' Beige w/Brown Vinyl Floor Tile Mastic	200	SF	Rm 002 1/2 - 1905 Bldg NOT OBSERVED	Miscellaneous	No	None	0	YES	X NO
2016 Fall N	la Changa									
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	r: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" Orange w/Brown Vinyl Floor Tile Mastic	1130	SF	Assembly Hall - 1905 BldgNOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	12"X12" Sand w/Brown Vinyl Floor Tile	400	SF	Engineers office, Room 305 wardrobe - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12"X12" Sand w/Brown Vinyl Floor Tile Mastic	400	SF	Engineers office, Room 305 wardrobe - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

28	12"x12" White Vinyl Floor Tile	480	SF	Public Space, 2nd Flr. Teacher Toilet - 1905 Bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fall Comments	: No Change :							•			
2017 - Fall Comments	: No Change										
	ing: No Change				_						

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" White Vinyl Floor Tile Mastic	480	SF	Public Space, 2nd Flr. Teacher's Toilet- 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
30	9"x9" Maroon Vinyl Floor Tile	700	SF	Room 100, 102 closet, 102 Toilet, clerks space (Under Carpet) 200B - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:					]							
2017 - Fall: N	No Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	9"x9" Maroon Vinyl Floor Tile Mastic	700	SF	Room 100, 102 closet, 102 Toilet, (Private office not observed), clerks space (Under Carpet) Public Space (Under HA 28) 200B - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

32	9"x9" Black Vinyl Floor Tile	25	SF	2nd Floor Boys Toliet Vestibule - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
	g: No Change											
Comments:												
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
33	9"x9" Black Vinyl Floor Tile Mastic	25	SF	2nd Floor Boys Toliet Vestibule - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							

Type

Material

Category

Friable

Damage

Туре

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Quantity

Damage

Units

34	12"x12" Gray Vinyl Floor Tile	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:	No Change											
2017 - Spri Comments:	2017 - Spring: No Change Comments:											
				T	]		T = · · ·		1-			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

500

Material

Quantity

Material

Units

SF

Material Location

Room 305 - 1905 Bldg.

HA No

35

Material Description

12"x12" Gray Vinyl Floor Tile Mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
36	12"x12" Tan Vinyl Floor Tile	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change				_							
Comments:	J											
2017 - Spring	· No Change				-							
Comments:	. 140 Ondrigo				-							
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
	material 2000 pilot	Quantity	Units	material Eccation	Туре	Category		Type	Quantity	Units		comon category
37	12"x12" Tan Vinyl Floor Tile Mastic	500	SF	Room 305 - 1905 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	J											
2017 - Fall: N	o Change				-							
Comments:	o onange				1							
	NI OI											
2017 - Spring	: No Change				-							
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	9"x9" Brown Vinyl Floor Tile	700	SF	Room 300, 3rd Fl Teachers Toilet - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	·									

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	9"x9" Brown Vinyl Floor Tile Mastic	700	SF	Room 300, 3rd Fl Teachers Toilet - 1905 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
41	Yellow Marble Linoleum			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
42	Yellow Marble Linoleum Mastic			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	Gray Marble Linoleum			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
44	Gray Marble Linoleum Mastic			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
45	Beige Linoleum			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	gritte eriange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	material 2 coonputors	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units		oomom category
46	Beige Linoleum Mastic			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Fall: N	Jo Change											
Comments:	10 Orlange											
	NI 01											
	g: No Change											
Comments:												
Commonts.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
47	Drywall			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	,											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Ass	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
48	Drywall Compound			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Oriange											
	2.											
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
49	2'x2' Yellow Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	j. 110 Onango											
	I.M. C. I.B. C. C.	1	T	T. M. A. S. L. L. C.		1	Term	T 5	1.5	1.5	To:	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
50	2'x2' Blue Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51	2'x4' Smooth Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	1. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIANO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Asse	ssifient Category
52	2'x4' Textured Ceiling Tile			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Chango											
Comments:	io Change											
2017 - Spring	g: No Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
53	Black Vinyl Baseboards	1500	LF	Throughout - 1992		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
54	Black Vinyl Baseboard Mastic			Throughout - 1992		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
60	12"x12" Blue VFT			Throughout - 1997		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											
Comments:	No Chanas											
2017 - Spring Comments:	g: No Change											
	I Material Description	I Marradal	I Maradal	I Matadalla anda		I Maradal	Lecus	I B	Damas	I Barrage	Ohanna's Assa	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
61	12"x12" Blue VFT Mastic			Throughout - 1997		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
62	12"x12" Yellow VFT			1st Floor Corridor, 2nd Floor Corridor - 1997		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change											
Comments:					4							
2017 - Fall: N	lo Change											
Comments:					4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
63	12"x12" Yellow VFT Mastic			1st Floor Corridor, 2nd Floor Corridor - 1997		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change				-							
Comments:	-											
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
64	2'x2' Textured CT			Throughout - 1997		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	g: No Change											
Comments: 2017 - Fall: N	lo Change											
Comments:	io onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
65	Drywall			Throughout - 1997		Miscellaneous					YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:	-							,				

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
66	Drywall Compound			Throughout - 1997		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				- -							
Comments:					1							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	ı: No Change				1							
Comments:	, 110 Onango				1							
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onlange in Assi	ossinent Oategory
67	Carpet Mastic			Room 210 (Library), Main Office Area - 1997		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					]							
2017 - Fall: N	lo Chango				_							
Comments:	io Change				1							
2017 - Spring	յ։ No Change											
Comments:					-							
					_							

Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Vinyl Baseboards			Throughout - 1997		Miscellaneous		None			YES	X NO
o Change											
: No Change											
o Chango											
o Change											
Material Description	Material	Material	Material Location	Ashastas	Material	Eriable	Damaga	Damago	Damaga	Change in Asse	
Material Description	Quantity	Units	Material Location	Type	Category	Fliable	Type	Quantity	Units	Change in Asse	ssment Category
Vinyl Baseboard Mastic			Throughout - 1997		Miscellaneous		None			YES	X NO
-											
. No change											
o Change											
	Vinyl Baseboards  o Change  : No Change  o Change  Material Description	Vinyl Baseboards  O Change  : No Change  O Change  Material Description Material Quantity  Vinyl Baseboard Mastic  O Change  : No Change	Vinyl Baseboards  O Change  : No Change  Material Description  Vinyl Baseboard Mastic  O Change  Material Quantity  Vinyl Baseboard Mastic  O Change  : No Change	Vinyl Baseboards  Change  No Change  Material Description  Vinyl Baseboard Mastic  Vinyl Baseboard Mastic  No Change  Throughout - 1997  Material Description  Material Units  Throughout - 1997  Throughout - 1997  Throughout - 1997	Quantity Units   Type	Quantity   Units   Type   Category	Quantity   Units   Type   Category	Quantity   Units   Type   Category   Type	Quantity   Units   Type   Category   Type   Quantity	Quantity   Units   Type   Category   Type   Quantity   Units	Quantity   Units   Type   Category   Type   Quantity   Units   Type   Quantity   Quan

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
70	12"x12" Red VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments												
2017 - Spri	ing: No Change				_							
Comments												
2017 - Fall	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
70A	12"x12" Red VFT (MASTIC)	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				]							
Comments	· ·											
2017 - Fall	: No Change											
Comments	· ·											
2017 - Spri	ing: No Change											
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
71	12"x12" Lt. Gold VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	Ğ											
2017 - Sprine	g: No Change				_							
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
71A	12"x12" Lt. Gold VFT	1500	SF	1st floor Corridor & SE & SW 1st floor stairwell landings and basement - Bldg. 1905		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	g to Oriango				]							
2017 - Fall: N	lo Change				=							
Comments:	40 Onange				1							

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
72	12"x12" tan w/ black dots VFT	400	SF	auditorium aisles		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
72A	12"x12" tan w/ black dots VFT MASTIC	400	SF	auditorium aisles		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change									<u>.</u>		
Comments:												
2017 - Sprir	ng: No Change				_							
Comments:												
2017 - Fall:	No Change				$\dashv$							
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
73	Carpet MASTIC	200	SF	private office		Miscellaneous	No	None	0		YES	X NO
2016 - Fal Comments	l: No Change											
2017 - Fal Comments	l: No Change				-							
2017 - Spr Comments	ring: No Change				-							
Commona	,				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
74	12"x12" gold VFT	2000	SF	Room 002, auditorium, teacher's lounge 2nd fl, rm 223, 3rd floor elevator lobby		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change				]							
Comments	3:				-							
	l: No Change											
Comments	S:				_							
2017 - Spr	ing: No Change				1							

Comments:

74A	12"x12" gold VFT MASTIC	2000	SF	room 002, auditorium, teacher's lounge 2nd fl, room 223, 3rd floor elevator lobby		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	<del>J</del> -				]							
2017 - Sprin	g: No Change				-							
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:	-											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
75	12"x12" red VFT	700	SF	teacher's lounge 2nd fl, auditorium, rm 223		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				 ]							
Comments:												
2017 - Sprin	g: No Change				1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
75A	12"x12" red VFT MASTIC	700	SF	teacher's lounge 2nd fl, auditorium, rm 223		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
А	Boiler Gasket #1	7	SF	Boiler Room - 1905		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:	<u> </u>											
					J							

HA No

Change in Assessment Category

		Quantity	Units		Type	Category		Type	Quantity	Units		
D	Boiler Gasket #2	7	SF	Boiler Room - 1905		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:												
2017 - Fall:	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Q	Aircell Pipe Insulation	40	LF	Engine Room, W Basement Corridor, 002 Vestibule, 002 1/2 - 1905 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	J											
2017 - Fall:	No Change											
Comments:	Ü											

Friable

Damage

Damage

Asbestos

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Material Material Location

Damage Change in Assessment Category

R	Cardboard Pipe Insulation	100	LF	Pump Room, Boiler Toliet, 002 Vestibule, Boiler Room, Electric Room - 1905 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
S	Pre-Formed Pipe Insulation	1000	LF	Engine Room, Boiler Toliet, Boiler Room - 1905 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	MJP E/F/V on Aircell Pipe Insulation	10	LF	Engine Room, W Basement Corridor, 002 Vestibule, 002 1/2 - 1905 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
V	MJP on Fiberglass Pipe Insulation	120	LF	Throughout - 1905		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	MJP on Mag Block Pipe Insulation	75	LF	Engine Room, Boiler Toliet, Boiler Room - 1905 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Stephen K Hayt Elementary	y School
Date: 1/11/2018	
the Asbestos Management Plan is avai	Illinois and Federal Asbestos Regulations, that a copy of lable at each school during school hours by appointment. Igement Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducted in 20 Asbestos surveillances are conducted 6	
CHECK ONE	
A copy of this notice was sent home	e in each child's backpack.
A copy of this notice was printed in	the school's newsletter and sent home with each child
A copy of this notice was printed in	the school's calendar and sent home with each child
Other.	
A COPY OF THIS NOTICE MUST	RE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 23621

SCHOOL'S ASBESTOS MANAGEMENT PLAN.