Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

23921

Oracle Unit:

Address: 3149 N. Wolcott Avenue Region: 01 Mail Room: 33 Asbestos Surveyor: Massa, Mr. Walter W X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/8/2017 Email Address: wwmassa@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Material Damage Damage Quantity Units Type Category Quantity Type 3rd Flr. Tchrs Toilet & YES X NO Lounge, Rm 004, 108, 12"x12" White w/ Brown 01 2426 SF Main Off., Tchrs Tlt Miscellaneous No None 0 Streaks VFT Across from 109. Lunchroom 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Friedrich L. Jahn Elementary of the Fine Arts

School:

4170

Building ID:

02	12"x12" Beige w/ White Streaks VFT	800	SF	Room 301 & Wardrobe		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03	12"x12" Brown w/ Tan Streaks VFT	120	SF	Room 205 & Library Wardrobe (Under Carpet) Not Observed		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:	•											

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

04	9"x9" Gray w/ Black Streaks VFT - NOT OBSERVED	460	SF	Principal's Office & Vestibule (Under Carpet)	Miscellaneous	No	None	0		YES	X NO
•	•			•	•	•	•	•	•		
2016 - Fall: N	lo Change										
Comments:	-										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:	<u> </u>										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Beige w/ Brown Streaks VFT	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
06	Battleship Green Linoleum - NOT OBSERVED			Room 107 NOT OBSERVED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	n rio onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
07	12"x12" Light Green w/ Brown Streaks VFT - NOT OBSERVED	500	SF	Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io onango											
2017 - Fall: N	lo Change											
Comments:	io Change											
	N. O.											
2017 - Spring Comments:	g: No Change											
Comments.					1							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	9"x9" Red VFT	100	SF	Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	-											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	2'x4' White Wormy Ceiling Tile (Tectum)	750	SF	Room 302		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	-											
2017 - Fall: I	No Change											
Comments:	J											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
1					1							

HA No

Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12"x12" White w/ Brown Streaks VFT Mastic	1302	SF	3rd Flr. Tchrs Toilet & Lounge, Rm 004., 108, Main Off., Tchrs Tlt Across from 109, Lunchroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	9"x9" Gray w/ Black Streaks VFT Mastic - NOT OBSERVED	420	SF	Principal's Office & Vestibule (under carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
14	Battleship Green Linoleum Mastic (Not Observed)	750	SF	Room 107 (Not Observed)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change				+							
Comments:	J											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Transite Wall Panel	640	SF	Kitchen Storage, Tank Room (Behind Drywall)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü											
2017 - Fall: N	lo Change				=							
Comments:	3-											

2017 - Spring: No Change

Comments:

16	2"x18" Border Black VFT	25	SF	Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 Falls N	la Changa											
2017 - Fall: N	io Change											
Comments:												
0017 0 :	N. 01											
	g: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
	9"x9" Brown w/ Red			Room 002 (Under								
17	Streaks VFT - NOT OBSERVED	50	SF	Tile/Wood) NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
	OBSERVED			OBSERVED	_			Į.	Į.		I	
2016 - Fall: N	lo Change											
Comments:												
]							
2017 - Fall: N	lo Change											
Comments:	-]							

Category

Asbestos

Type

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

18	9"x9" Green w/ White Streaks VFT	1000	SF	Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26)	Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	•	•	•	•	•	•	•	•	•	
Comments											
2017 - Fall	: No Change										
Comments	:										
2017 - Spri	ing: No Change										
Comments	: :										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Beige w/ White Streaks VFT Mastic	800	SF	Room 301 & Wardrobe		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20	9"x9" Green w/ White Streaks VFT Mastic ABATED (2013)			Room 205 Library (Under Carpet), Room 001 (Under HA # 07 & 26) - NOT OBSERVED ABATED (2013)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	12"x12" Brown w/Tan Streaks VFT Mastic ABATED (2013)			Room 205 & Library Wardrobe ABATED (2013)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	Ü											
2017 - Fall: N	lo Change				-							
Comments:]							
2017 - Spring	g: No Change				_							
Comments:	, : : : : : : : : : : : : : : : : : : :]							
]							

22	9"x9" Beige w/ Brown Streaks VFT Mastic	450	SF	Auditorium Stage and Stage Stairs, Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				7							
Comment												
2017 - Fa	II: No Change				_							
Comment	is:				_							
	ring: No Change											
Comment	ts:				_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
23	2"x18" Border Black VFT Mastic	25	SF	Room 003		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	9"x9" Red VFT Mastic	750	SF	Room 003		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	9"x9" Brown w/ Red Streaks VFT Mastic (Under Wood) - NOT OBSERVED	50	SF	Room 002 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	, g											

26	12"x12" Light Green w/ Brown Streaks VFT Mastic - NOT OBSERVED	500	SF	Room 002, 001 NOT OBSERVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change	·		·]						
Comments:											
2017 - Fall: N	No Change										
Comments:					 						
2017 - Spring	g: No Change										
Comments:					 						
]						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	12" x 12" Blue VFT	50	SF	Principals Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	12" x 12" Blue VFT Mastic	50	SF	Principals Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					4							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				=							
Comments:	-											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	12" x 12" Peach VFT	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>											
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				+							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	12" x 12" Peach VFT Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	,gc											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
31	12 x 12 inch Light Blue w/White Specks VFT	650	SF	Room 002		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
	-											
2017 - Fall: N Comments:	-											
2017 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											

31A	12 x 12 inch Light Blue w/White Specks VFT Mastic	650	SF	Room 002	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:	No Change	· ·		1		•	•			
2017 - Sprir Comments:	ng: No Change									
2017 - Fall: Comments:	<u> </u>									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
32	Carpet Mastic	1000	SF	Main Office, Rooms 005, 205		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change

Material Description

Comments:

HA No

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
33	12 x 12 Tan Floor Tile	750	SF	Room 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												
	No Change											
2017 - Sprir Comments:	ng: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
34	12 x 12 Tan Floor Tile Mastic	750	SF	Room 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:												
2017 - Sprir Comments:	ng: No Change											

35	12 x 12 Grey Floor Tile	60	SF	Main Office, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	12 x 12 Grey Floor Tile Mastic	60	SF	Main Office, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

37	12 x 12 White Floor Tile	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	ıll: No Change]					·	•	
Comment					1							
Commen					1							
2017 - Fa	III: No Change				-							
Comment	ts:											
2017 - Sp	oring: No Change											
Comment	ts:											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12 x 12 White Floor Tile Mastic	2500	SF	1st and 2nd Floor Corridors, 1st Boys and Girls Washrooms		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
39	12 x 12 Yellow Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Fall: N	lo Change				_							
Comments:	ge											
2017 - Spring	ı: No Chango											
Comments:	i. No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domoso	Domoso	Domose	Change in Ass	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Assi	essment Category
40	12 x 12 Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Chango											
Comments:	lo Change											
	NI OI											
2017 - Spring	: No Change											
Comments:												

41	12 x 12 Blue Floor Tile	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change]						
Comments	S:										
2017 - Spr	ring: No Change										
Comments	S:				1						
	l: No Change										
Comments	S:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12 x 12 Blue Floor Tile Mastic	24	SF	1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

43	12 x 12 Green Floor Tile	250	SF	Teacher's Toilets across Room 109	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring	: No Change									
Comments: 2017 - Fall: N	o Change									
Comments:										

Asbestos

Type

Material

Category

Material

Friable

Friable

Damage

Damage

Type

Damage

Quantity

Damage

Damage

Damage

Units

	material 2 occupation	Quantity	Units	material <u>L</u> ocalion	Туре	Category	1110010	Туре	Quantity	Units	onange m 7.000
44	12 x 12 Green Floor Tile Mastic	250	SF	Teacher's Toilets across Room 109		Miscellaneous	No	None	0		YES
2016 - Fall:	No Change										
_	Comments:										
2017 - Sprir	ng: No Change										

Comments: 2017 - Fall: No Change Comments:

Material

Material

Units

Material

Quantity

Material

Material Location

Material Location

HA No

HA No

Material Description

Material Description

Change in Assessment Category

Change in Assessment Category

X NO

45	12 x 12 Light Blue Floor Tile	650	SF	Room 002		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Quantity

650

Material

Units

Units

Room 002

SF

Material

Quantity

Material Location

HA No

46

Material Description

12 x 1 2 Light Floor Tile

Mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
47	12 x 12 Royal Blue Floor Tile	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Fall: N	o Change				-							
Comments:	- Change											
2017 - Spring	: No Change											
Comments:	. No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Fliable	Type	Quantity	Units	Change in Assi	essinent Category
48	12 x 12 Royal Blue Floor Tile Mastic	1500	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 Spring	2017 - Spring: No Change											
	Comments:											
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
49	12 x 12 Off White Floor Tile	900	SF	Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	12 x 12 Off White Floor Tile Mastic	900	SF	Room 001		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
2017 - Spring	· No Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
51	Terrazzo	1800	SF	Room 005, vestibules, 1st Floor Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:												
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
52	Ceramic Tile Grout	1300	SF	2nd Floor Restroom (206) and Basement Restroom		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:												
Comments:												
	ng: No Change											
Comments:												
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
53	Ceramic Tile Adhesive	1300	SF	2nd Floor Restroom (206) and Basement Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
					I							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
D	Mag Block Breeching ABATED (2016)			Boiler Room ABATED (2016)		TSI					YES	X NO
2016 - Fall: N	No Change]							
Comments:	_											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	_											
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

Е	Aircell Pipe Insulation	150	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen		TSI	Yes	None	0	YES	X NO
		•	•	•	İ	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	40	LF	Passage by Rm. 003, Tank Room, Lunchroom/Kitchen		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
G	Mag Block Insulation	40	LF	Tank Room, Kitchen/Lunchroom, Engine Room, Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ıg: No Change											
Comments:	ig. 110 Onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
Н	Tank Room,					TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	rto Griango											
2017 - Fall:	No Change			· · · · · · · · · · · · · · · · · · ·								
Comments:	140 Orlango											

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
I	Cardboard Pipe Insulation ABATED (2013)			Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets - ABATED (2013)		TSI		None			YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Orlango											
Commenter					1							
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
			_		1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
J	MJP E/F/V on Cardboard Pipe Insulation	7	LF	Passage by Room 003, Girls Play Room, Tank Room, Boiler Room Toilets		TSI	Yes	None	0		YES	X NO
2016 Fall N	lo Chango				1							
2016 - Fall: N	No Change				4							
Comments:												
2017 - Fall: No Change					1							
Comments:												

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	MJP E/F/V on Fiberglass Pipe Insulation	68	LF	Throughout (See Hatching)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	_											
2017 - Fall: N	o Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L	Aircell Duct Insulation	1200	SF	Lunchroom/Kitchen		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
М	Mag Block Duct Insulation	1070	SF	Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Friedrich L. Jahn Elementary of the Fine Arts
Date: <u>11/8/2017</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 23921

SCHOOL'S ASBESTOS MANAGEMENT PLAN.