## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2017 - Fall

24591

Mount Greenwood Elementary School **Oracle Unit: Building ID:** Address: 10841 S Homan Region: 06 Mail Room: Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/2/2017 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 1937 - 2nd Floor YES X NO Corridor, Principal's 03A 9x9 Tan Streaked Floor Tile 2600 SF Office & Closet, Miscellaneous No None 0 Classrooms, 2nd Floor Landing, Clinic 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

School:

4940

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
03AA	9x9 Tan Streaked Floor Tile Mastic	2600	SF	1937 - 2nd Floor Corridor, Principal's Office & Closet, Classrooms, 2nd Floor Landing, Clinic		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03B	9x9 tan floor tile w/streaks	5830	SF	1947 - room 200, 202, 2nd floor corridor		Miscellaneous	No	Loc	0		YES X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03BB	9x9 tan floor tile w/streaks mastic	5830	SF	1947 - room 200, 202, 2nd floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
03C	9x9 olive green floor tile	1325	SF	1947 - assembly hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
					_							

03CC	9x9 olive green floor tile mastic	1325	SF	1947 - assembly hall	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
2017 - Fall: N	lo Chango									
Comments:	o Change									
2017 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04A	12x12 off white w/brown specks floor tile	11545	SF	1937 - rms. 104,105,107,108,111,113 ,116,210,205,206,209,21 1,212,213,214,teachers lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

9x9 olive green floor tile

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04AA	12x12 off white w/brown specks floor tile mastic	11545	SF	1937 - rms. 104,105,107,108,111,113 ,116,210,205,206,209,21 1,212,213,214,teachers lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04B	12x12 gray w/specks floor tile	380	SF	1937 - Room 114		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  2017 - Fall: No Change Comments:	
2017 - Spring: No Change Comments: 2017 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Fall: No Change	Comments:
Comments: 2017 - Fall: No Change	
2017 - Fall: No Change	2017 - Spring: No Change
0	Comments:
0	
Comments:	2017 - Fall: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04BB	12x12 gray floor tile mastic	380	SF	1937 - Room 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Spring Comments:	: No Change											
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04C	12x12 tan w/specks floor tile	380	SF	1937 - Room 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Fall: N Comments:	o Change											
2017 - Spring Comments:	: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04CC	12x12 tan w/specks floor tile mastic	380	SF	1937 - Room 114		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04D	12x12 gray w/white floor tile	780	SF	1937 - Room 112		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												

04DD	12x12 gray w/white floor tile mastic	780	SF	1937 - room 112		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:					<u> </u>							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

	Material Becompiler	Quantity	Units	Waterial Education	Туре	Category	Tilabio	Type	Quantity	Units	onango m 7 locoo	omone category
04E	12x12 off white w/brown specks floor tile	5310	SF	1947 - rm. 102,103,104,106,201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Damage

Quantity

Damage

Units

04EE	12x12 off white w/brown specks floor tile mastic	5310	SF	1947 - rm. 102,103,104,106,201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							
Comments:												
2017 - Fall:	No Change				1							
Comments:	:											
2017 - Sprii	ng: No Change											
Comments:	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

475

Material

Quantity

Material

Units

SF

Material Location

1947 - room 101 (part of checkerboard pattern)

HA No

04F

Material Description

12x12 dark burgandy floor

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

04FF	12x12 dark burgandy floor tile mastic	475	SF	1947 - room 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
					I							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIATO	Waterial Description	Quantity	Units	Waterial Eocation	Type	Category	THADIC	Type	Quantity	Units	Onlange in Assess	Sment Gategory
04G	12x12 light burgandy floor tile	475	SF	1947 - room 101 (part of checkerboard)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

2017 - Spring: No Change Comments:

HA No

Material Description

2017 - Fall: No Change

Comments:

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
04GG	12x12 light burgandy floor tile mastic	475	SF	1947 - room 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
06	transite duct	600	SF	tunnel		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
7	Smooth Plaster	120000	SF	1937 Bldg - Throughout bldg		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					1							
2017 - Fall: N	o Change											
Comments:					-							
2017 - Spring	: No Change				=							
Comments:												
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
8	Black and White Terrazzo	2400	SF	1937 Stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					1							
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
					]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
9	Tan and Brown Mosaic Ceramic Tile Grout	3200	SF	1937 Bldg - Washrooms and Vestibules		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:					_							
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	ı: No Change											
Comments:	J. 140 Onange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asses	ssment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	SSMEIR Category
9M	Tan and Brown Mosaic Ceramic Tile Adhesive	3200	SF	1937 Bldg - Washrooms and Vestibules		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Chango											
Comments:	g. No Change											
2017 - Fall: N	lo Change				_							
Comments:					4							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
10	12 x 12 White with Light Blue Speckled Floor Tile	5000	SF	1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				_							
Comments:	. No Chango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
10M	12 x 12 White with Light Blue Speckled Floor Tile Mastic	5000	SF	1st Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				_							
Comments:	. 140 Onlange											
0047 Fall N	- Oh											
2017 - Fall: N	o Change				$\dashv$							
Commonto.												

11	Tan and Brown Mosaic Ceramic Tile Grout	1500	SF	Boys Washrooms, Vestibule and Teachers Lounge Toilet		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fa	II: No Change	*	•		1	•	•	•	•	•	•	
					4							
Comment	S:											
2017 - Fa	II: No Change											
Comment	s.											
00.11110110	·-				1							
2017 Sp	ring: No Change				-							
2017 - Sp	ning. No Change											
Comment	s:											

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Boys Washrooms,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11M	Tan and Brown Mosaic Ceramic Tile Adhesive	1500	SF	Boys Washrooms, Vestibule and Teachers Lounge Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12	Brown and White Terrazzo	2400	SF	1947 Stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	Multi Tan Color Mosaic Ceramic Tile Grout	1800	SF	1947 - Girls Washrooms and Assembly Hall, West, East Vestibules		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	Ü											
2017 - Fall: N	o Change											
Comments:	o onango											
2017 - Spring	: No Change											
Comments:	. 110 Onango											
					]							

13M	Multi Tan Color Mosaic Ceramic Tile Adhesive	1800	SF	1947 - Girls Washrooms and Assembly Hall, West, East Vestibules		Miscellaneous	No	None	0	YES	X NO
0040 F.II N	. 01	•	•		1	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	•										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	Smooth Plaster	60000	SF	1947 Bldg - Throughout		Surface	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
15	Multi-color Carpet Mastic	800	SF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	: No Change				-							
Comments:	J											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	12" x 12" White with Black Speckles Floor Tile	1400	SF	Book Room, Store Room and Hallway Outside Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	o onango											
2017 - Spring	: No Change				<u> </u>							
Comments:	. 140 Onlange				1							

17	12" x 12" White with Black Speckles Floor Tile Mastic	1400	SF	Book Room, Store Room and Hallway Outside Engineer Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•		•	]	•	•	•	•	•		
Comments:	<u> </u>				]							
2017 - Fall: N	lo Change											
Comments:					 							
2017 - Spring	g: No Change											
Comments:					1							
					1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	Boiler Gaskets	160	LF	Boiler Room		TSI	Yes	None	0		YES X NO
0040 = 11.1					1						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
19	Incinerator Fire Birck	400	SF	Coal Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	aircell pipe insulation	2800	LF	basement		TSI	Yes	None	31		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											

		Quantity	Units		Type	Category		Type	Quantity	Units		
В	aircell cementitious fittings	360	LF	basement		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
С	aircell duct	1600	LF	unexcavated area		TSI	Yes	None	120		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
CM-1	blue carpet mastic (Not Observed)	0	SF	1937 - library, engineer's office & part of office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	]										
Comments:					1							
2017 - Spring	: No Change				-							
Comments:					1							
2017 - Fall: N	lo Change											
Comments:	•											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
CM-2	Blue Carpet Mastic	450	SF	Principal's Office & Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change					]							
Comments:					=							
2017 - Spring: No Change					1							
Comments:												
2017 - Fall: No Change												
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
E	holding tank - mag insulation	300	SF	boiler room		TSI	Yes	Loc	10		YES	X NO
2016 - Fall: Comments:	No Change											
	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
F	Cardboard pipe insulation	1300	LF	Basement and all 1st floor toilets		TSI	Yes	None	0		YES	X NO
2016 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:					I							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
G	Cardboard cementitious fittings	150	LF	Basement and all 1st floor toilets		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Н	1'x1' Ceiling Tile	2000	SF	Auditorium		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: No Change												
Comments:												
	g: No Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
1	1'x1' Ceiling Tile Mastic	2000	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
J	Mudded Fittings on Fiberglass Pipe Runs	200	LF	Basement, Unexcavated Area, Beneath Gym, Boiler Rm.		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Mount Greenwood Elementary School
Date:12/2/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 24591