Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

24941

Oracle Unit:

5510 N Christiana Avenue Address: Region: 01 Mail Room: Asbestos Surveyor: Dye, Ms. Venguanette X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 2/2/2018 Email Address: vdye@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Off White w/Beige Main Office & Storage, YES 02 300 SF X NO Miscellaneous No None 0 Streaks VFT 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Mary Gage Peterson Elementary School

School:

5410

Building ID:

03	9"x9" Green VFT	900	SF	Room 111 (Under Carpet), 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
05	12"x12" Off White w/ Beige Streaks VFT Mastic	300	SF	Main Office & Storage - 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06	9"x9" Green VFT Mastic	900	SF	Room 111 (Under Carpet), 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	.											
2017 0 :	N. O.											
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07	12'x12" Off White w/ Beige VFT (not observed)	2050	SF	1st and 2nd Floor Corridor -1945		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	10 Onango											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
zo opini	g 10 Onango											

Comments:

08	12'x12" Off White w/ Beige VFT Mastic (not observed)	2050	SF	1st and 2nd Floor Corridor, 1945		Miscellaneous	No	None	0	YES	X NO
0040 5	all. No Observe				1						
2016 - F	fall: No Change										
Comme	nts:										
					1						
0047 5	- II NI - Oli				1						
2017 - F	fall: No Change										
Comme	nts [.]										
001111110					1						
2017 - 8	Spring: No Change										

Type

Material

Category

Damage Quantity

Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9'x9" Gray w/ Black Streaks VFT	750	SF	Room 202, 1925		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:room 202 now 204
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	9'x9" Gray w/ Black Streaks VFT Mastic	750	SF	Room 204, 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				-							
Comments:	<u> </u>											
2017 - Fall: N	o Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	12"x12" Tan VFT	100	LF	Engineers Office, 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	J											
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	· No Change				-							
Comments:	. 110 Change											
				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13	12"x12" Tan VFT Mastic	100	SF	Engineers Office, 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					+							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				4							
Comments:	J. NO Change				+							
Commonto.												
								•		•		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	Hard Coat Plaster	23000	SF	Throughout, 1945							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	io Griarigo				1							
2017 2												
2017 - Spring	g: No Change				4							
Comments:					4							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
98	Exterior Window Caulk	3800	LF	Exterior Windows, 1925							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change				+							
Comments:	io oriange											
	T	1	T	T	1	T		T	T _		T =	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
99	Interior Window Caulk	3800	LF	Interior Windows, 1925							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change				+							
Comments:	io oriange											
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	12" x 12" White w/ Brown Specks VFT (Removed 2006)		SF	Room 308-311, 308 Storeroom-311 Storeroom, Boys & Girls Toilet, Hallway, 2000 Modular Building		Miscellaneous	No	None			YES X NO
2016 Fall: N	lo Chango				1						

2016 - Fall: No Change
Comments:no longer on site
2017 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:removed modular building

HA No	M	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	SI	2" x 12" White w/ Brown Specks VFT Mastic Removed 2006)		SF	Room 308-311, 308 Storeroom-311 Storeroom, Boys & Girls Toilet, Hallway, 2000 Modular Building		Miscellaneous	No	None			YES X NO

2016 - Fall: No Change
Comments:no longer on site
2017 - Fall: No Change
Comments:
2017 - Spring: Other
Comments:removed modular building

102	2' x 2' White w/ Grooves Ceiling Tile (Removed 2006)	SF	Room 308-311, 308 Storeroom-311 Storeroom, Hallway, 2000 Modular Building				YES	X NO
0040 =				7				
2016 - Fa	ill: No Change							
Comment	ts:no longer on site							
	y			1				
2017 - Sp	oring: Other							
Comment	ts:removed modular building			1				
				1				
2017 - Fa	III: No Change							

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
103	Terrazzo	2000	SF	Throughout 1st & 2nd floor classrooms -1948 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

104	Terrazzo	2000	SF	Throughout 1st & 2nd floor classrooms - 1925 Blgd.		Miscellaneous	No	None	0		YES	X NO
2016 Fo	II: No Change			·	1							
Comment	S:											
2017 - Fa	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

Yes

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:	-		

Quantity

1100

Material

Units

Units

SF

Material

Quantity

Material Location

Throughout 1st & 2nd

Library 225, 227

HA No

105

Material Description

9"x9" Red VFT (Under

Carpet)

Change in Assessment Category

X NO

105A	9"x9" Red VFT Mastic (Under Carpet)	1100	SF	Library 225, 227		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	go											
2017 - Sprin	g: No Change				-							
Comments:]							
2017 - Fall: I	No Change											
Comments:					 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
106	12"x12" White w/Red Specks VFT	11050	SF	1st and 2nd Floor Corridor, Main Office, 1925		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	······g-											
2017 - Fall: I	No Change											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

106A	12"x12" White w/Red Specks (Mastic)	11050	SF	1st and 2nd Floor Corridor, Main Office, 1925		Miscellaneous	No	None	0		YES	X NO
	•	•	•	•	- -	•		•	•	•		
2016 - Fall: I	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					1							
					1							
2017 - Sprin	g: No Change				1							
Comments:					1							
					1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	12"x12" White w/Red Specks VFT	2000	SF	1st and 2nd Floor Corridor, 1945		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
107A	12"x12" White w/Red Specks VFT (Mastic)	2000	SF	1st and 2nd Floor Corridor, 1945		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				=							
Comments:	U											
2017 - Spring	ı: No Change				=							
Comments:	,go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
108	12"x12" Red VFT	456	SF	1st and 2nd Floor Corridor, 1925 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				٦							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				+							
2017 - Spring Comments:	g: No Change											
Comments:												
					- - - -							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
108A	12"x12" Red VFT (Mastic)	456	SF	1st and 2nd Floor Corridor, 1925 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	-											
2017 - Fall: N	o Change				_							
Comments:												
2017 - Spring	: No Change											
Comments:	Ţ											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
109	12"x12" Red VFT	130	SF	1st and 2nd Floor Corridor, 1945 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:]							
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:]							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
109A	12"x12" Red VFT (Mastic)	130	SF	1st and 2nd Floor Corridor, 1945 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
2017 - Spring Comments:	j: No Change											
2017 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
110	Firedoor	3	EA	Projector Room, Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change				- - -							
2017 - Fall: N Comments:	lo Change											

		Quantity	Units		Type	Category		Type	Quantity	Units		
111	Decorative Plaster	800	SF	Stage, Auditorium and Balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
112	2'x4' Ceiling Tile w/Grooves	9000	SF	Throughout 2nd Floor, 1925 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
113	2'x4' Ceiling Tile w/Grooves	3500	SF	Throughout 2nd Floor, 1945 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
2017 - Spring	g: No Change											
Comments:	-]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
114	Carpet Mastic above HA105 and HA105A	1100	SF	Library Room 215 and 225, 227		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	g: No Change				1							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
115	Fireproof Stage Curtains	3000	SF	Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring: No Change												
Comments: 2017 - Fall: N	lo Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
А	Blown Insulation	12000		Attic, 1925							YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: No Change												
Comments: 2017 - Spring: No Change												
Comments:	g. INO Change											

											·	
D	Cardboard Pipe Insulation	70	LF	1st & 2nd Floors Boy's & Girl's Toilets, 1925		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	J				- -							
2017 - Fall: N	lo Change				1							
Comments:	•				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
Н	MJP E/F/V on Fiberglass Pipe Insulation	0		Bathroom Pipe Chases, North and South Unexcavated Area, 1925		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	•											
2017 - Spring	g: No Change				1							
Comments:		1										

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

L	Aircell Pipe Insulation	250	LF	Vestibule, Boy's & Girl's Toilets, & SW Unexcavated Area, 1925		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>				1							
	g: No Change				_							
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category
М	MJP E/F/V on Aircell Pipe Insulation	30	LF	Auditorium West Stage Vestibule, Boy's & Girl's Toilets, & SW Unexcavated Area, 1925		TSI	Yes	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	Boiler Gaskets	6	SF	Boiler House		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Mary Gage Peterson Elementary School Date: 2/2/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 24941

SCHOOL'S ASBESTOS MANAGEMENT PLAN.