Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

25121

Oracle Unit:

Building ID: Address: 1010 E. 72nd St. Region: 05 Mail Room: Asbestos Surveyor: Walker, Esther X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/16/2018 Email Address: ewalker25@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES 01 9x9 floor tile (1961) X NO Miscellaneous material removed 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Paul Revere Elementary School

School:

5610

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
02	12x12 light grey floor tile	15000	SF	classroom/storage rooms (1961)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				1							
Comments:	J. NO Change				1							
]							
<u> </u>	T	1	T	T	T						1	_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
03	carpeting (1961)			material removed		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Chango				-							
Comments:	io Change				-							
2017 - Spring	g: No Change											
Comments:		_										
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
04	hardcoat plaster	40000	SF	1961 building		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	,											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	material 2 conputer	Quantity	Units	material zecation	Туре	Category		Туре	Quantity	Units	onango mi / toos	Joennam Catagory
05	old spray-on insulation			1961 building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Chango											
Comments:	io Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
06	new spray-on ceiling insulation			1961 building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
07	hardcoat plaster			1938 building gym		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
08	9x9 brown floor tile	390	SF	classroom 205 (1902), formerly teachers room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	12x12 beige floor tile	10000	SF	throughout classrooms (1902), room 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
10	hardcoat plaster	49000	SF	1902 Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11	canvas wall covering (1902)			material removed		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	ı: No Change											
Comments:	<i>y</i>											

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
12	2x4 ceiling tile	7000	SF	(1902) building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13	firedoors	8	EA	building 1938		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	firedoors	6	EA	building 1902		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	,g											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
1,777	Material Besonption	Quantity	Units	Waterial Education	Type	Category	THADIO	Туре	Quantity	Units	Orlange in 71000	oddinom Odlogory
15	light grey floor tile mastic			1961 - classrooms, storage rooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	io Oriange											
	g: No Change											
Comments:												
<u> </u>												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16	12x12 grey floor tile	1700	SF	1961 - corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	. No Onlange											
[T	T		Tagain a	T		1	T	T =	T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
17	12x12 grey floor tile mastic			1961 - corridors		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Chango											
Comments:	i. No Change											
Comments.												
<u> </u>												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
18	12x12 purple floor tile	360	SF	1961 - corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
19	12x12 purple floor tile mastic	360	SF	1961 corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				\neg							
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	12x12 pink floor tile	600	SF	classrooms - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 Spring	v No Chango											
2017 - Spring Comments:	J. NO Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12x12 pink floor tile mastic			1961 - classrooms		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	go											
2017 - Spring	g: No Change				_							
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
23	12x12 beige floor tile mastic			throughout classroms - 1902		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change				ĺ							
Comments:	•]							
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change				_							
Comments:]							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	12x12 tan floor tile	3500	SF	auditoruim - 1938		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:]							
2017 - Fall: N	No Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							
					1							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

		Quantity	Units		Type	Category		Type	Quantity	Units		
25	12x12 tan floor tile mastic			auditorium - 1938		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
26	12x12 grey floor tile	2200	SF	main corridor - 1938		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	,											

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	∖ssessr	nent Category
27	12x12 grey floor tile mastic			main corridors - 1938		Miscellaneous		None			YES		X NO
2016 - Fall: No	o Change]								
Comments:													
2017 - Fall: No	o Change												
Comments:													
2017 - Spring:	· No Change												
Comments:	. 110 Change												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in /	Assessr	nent Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	g		
28	9x9 brown floor tile	150	SF	gym storage room - 1938		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: No	o Change												
Comments:	•												
2017 - Fall: No	o Change												
Comments:	o onango												
2017 Spring	· No Chango												
2017 - Spring: Comments:	. No Change												
Comments.													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	9x9 brown floor tile mastic	150	SF	gym storage room - 1938		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	g: No Change]							
Comments:					_							
2017 - Fall: N	lo Change]							
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	brown carpet mastic			main office area - 1961		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	g: No Change				<u> </u>							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	-]							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	purple carpet mastic			1st floor classrooms - 1961		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	drywall			pumproom (1902) and corridors		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
33	drywall compound			pump room - 1902		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIA NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Asse	SSITIETII Calegory
34	drywall			1938 main corridor		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Chango											
Comments:	io Change											
2017 - Spring	g: No Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
36	stucco ceiling plaster			main corridor		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37	stucco ceiling plaster			corridors and classrooms - 1961		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
38	transite table tops			classroom 203 - 1902		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io change											
HA No	Material Description	Matarial	Matarial	Material Location	Ashastas	Matarial	Friable	Damana	Damana	Damana	Channa in A	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
А	fiberglass duct wrap			mechanical room, building 1961		TSI		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	_											
2017 - Spring	g: No Change				_							
Comments:	j. 110 Onango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
В	duct expansion joint			mechanical room - 1961		TSI		None			YES	X NO
2016 - Fall: N	lo Change]							
2017 - Spring Comments:	g: No Change				- - -							
2017 - Fall: N Comments:	lo Change				- - -							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
С	fiberglass insulation					TSI					YES	X NO
2016 - Fall: N Comments:	lo Change		1					1		1		

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Е	univents	38	EA	1961 building		TSI	No	None	0		YES	X NO
2016 - Fal Comments	l: No Change s:											
2017 - Spi	ing: No Change											
Comments	S:											
2017 - Fal	l: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
F	boiler insulation under metal jacklet	600	SF	boiler room - 1902		TSI	No	None	0		YES	X NO
2016 - Fal	l: No Change											
Comments												
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spi	ing: No Change				_							
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
G	tank insulation - material removed			pump room - 1902		TSI					YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Н	aircell pipe insulation	100	LF	fan room - 1902		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
I	fiberglass insulation			pump room - 1902		TSI					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
J	fittings on fiberglass	50	JOINTS	1902 building		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:	10 Onlango											
2017 Spring	g: No Change											
Comments:	g. No Change											
2 3												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
К	cardboard insulation - REMOVED			boiler room - 1902		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
L	cardboard joint insulation- REMOVED			1902 building		TSI					YES	X NO
2016 - Fall: N	lo Change				\neg							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
М	aircell duct insulation - REMOVED			fan room - 1902		TSI					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
N	hot water tank insulation- REMOVED			tank room - 1902		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
0	duct expansion joint			fan room - 1902		TSI					YES	X NO
2016 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Р	pre-form pipe insulation	75	LF	coal room - 1902		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g: No Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Q	duct insulation jacket	75	LF	crawlspace below auditorium stage		TSI	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	n. No Change											
Comments:	J. 140 Orlange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
	material Decemporation	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units		Jemeni Galegory
R	aircell joint insulation	7	LF	boiler/pump room - 1902		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Fall: N	lo Change											
Comments:	io Oriange											
2017 - Spring: No Change												
Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
S	preform pipe joint insulation	10	LF	coal room - 1902		TSI	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					4							
2017 - Spring	j: No Change				1							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Т	Aircell pipe insulation	40	LF	1902 bldg - Pump room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	U											
2017 - Spring	ı: No Change											
Comments:	1. 110 Onlango				1							
2017 Fall: No Change												
2017 - Fall: No Change Comments:					=							
Commond.					†							

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Pau	ul Revere Elementary School
Date:1/12	/2018
the Asbestos M	you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. view the Asbestos Management Plan must be made at least 24 hours in advance.
The last inspec	advised that CPS conducts asbestos inspections of all Schools every three years. etion was completed in 2016. eillances are conducted every six months.
CHECK ONE	
A copy o	of this notice was sent home in each child's backpack.
A copy o	of this notice was printed in the school's newsletter and sent home with each child
A copy o	of this notice was printed in the school's calendar and sent home with each child
Other.	
A COPY OF	THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 25121

SCHOOL'S ASBESTOS MANAGEMENT PLAN.