Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

25571

Oracle Unit:

Building ID: Address: 5900 N Winthrop Avenue Region: 01 Mail Room: 32 Asbestos Surveyor: Liberty, Mr. Steve X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/5/2017 Email Address: sliberty@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Off White w/ Main Office - 1914 YES X NO 01 SF Speckles VFT NOT 80 Miscellaneous No None 0 **OBSERVED** NOT OBSERVED 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

George B Swift Elementary Specialty School

School:

6130

02	12"x12" Off White w/ Speckles VFT Mastic NOT OBSERVED	80	SF	Main Office - 1914 NOT OBSERVED	Miscellaneous	No	None	0		YES	X NO
	•	•	•	•	•	•	-	•	•		
2016 - Fall	: No Change										
Comments	;;										
2017 - Fall	: No Change										
Comments											
2017 - Spr	ing: No Change										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Beige VFT	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm. 106 - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

04	9"x9" Beige VFT Mastic	740	SF	Room 106 (under the carpet) and Storage Rm. Next to Rm.106 -1914		Miscellaneous	No	None	0		YES	X NO
0040 5 11	N. O.			•	7							
2016 - Fall	: No Change											
Comments	s:											
2017 - Fall	: No Change											
Comments):											
2017 - Spr	ing: No Change											
Comments	:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage Quantity

Quantity

20

Damage

Units

Units

YES

X NO

Change in Assessment Category

2016 - Fall: No	2016 - Fall: No Change										
Comments:											
2017 - Fall: No	o Change										
Comments:											
2017 - Spring:	: No Change										
Comments:	-										

Quantity

900

Material

Quantity

Material

Units

Units

SF

Material Location

Room 106 (under the

Room 205 - 1914

HA No

05

Material Description

12"x12" White w/ Tan VFT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
06	12"x12" White w/ Tan VFT Mastic	900	SF	Room 205 - 1914		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	o Change]								
Comments:					_								
2017 - Fall: N	o Change												
Comments:					-								
2017 - Spring	: No Change				1								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
07	12"x12" Off White VFT	1400	SF	Stage & Stage Storage's - 1914		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:													
2017 - Fall: N	o Change												
Comments:	<u> </u>												
2017 - Spring	: No Change				1								
Comments:]								
					J								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
08	12"x12" Off White VFT Mastic	1400	SF	Stage & Stage Storage's - 1914		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	ı: No Change											
Comments:	,g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
09	Red Linoleum	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA41) - 1914		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change							•				
Comments:	go											
2017 - Fall: N	lo Change											
Comments:	io Change											
0047 0 1	N. Olasas											
2017 - Spring	g: No Change											
Comments:												
					J							

10	Red Linoleum Mastic	400	SF	Rooms 108 (Under HA 39) & 109 (Under HA 41) - 1914		Miscellaneous	No	None	0	YES	X NO
0040 Falls	Na Ohanan	•	•	•	1	•	•	•	•	•	
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
					-						

Type

Material

Category

Material Location

Rooms 108 (Under HA

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	Hard Coat Plaster	30000	SF	Throughout - 1914		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Damage Quantity

Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	2'x2' Transite Ceiling Panel	3100	SF	Natatorium (Pool), men's and women's bath/shower room - 1914		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" White w/ Light Brown Spots VFT	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

14	12"x12" White w/ Light Brown Spots VFT Mastic	120	SF	Rooms 201,301,101 (speech), 2nd & 3rd Floor Teacher Toliets - 1914	Miscellaneous	No	None	0		YES	X NO
•		•	•	•	•		•	•	•	•	
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
0047 0	N. Olasasas										
2017 - Spring	: No Change										
Comments:											
Comments.											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	Carpet Mastic OBSERVED ONLY IN ROOM 104	600	SF	Rooms 101, 102, 103, 104, 108, & 109 - 1914 OBSERVED ONLY IN ROOM 104		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

16	12"x12" White w/ Light Brown Spots VFT	16200	SF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No Change Comments:											
Comments	<u>:</u>											
2017 - Fall:	No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	•											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

16200

Material

Quantity

Material

Units

SF

Material Location

Throughout - 1999

Addition

HA No

17

Material Description

12"x12" White w/ Light Brown Spots VFT Mastic

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
18	12"x12" Red VFT	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change			·]							
Comments:												
0047 5.11	N. Observe											

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

2010 Tall: 140 Chango
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Material Description

Material

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Red VFT Mastic	540	SF	Rooms 112, 113, 213, 311, & 314 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

20	12"x12" Green VFT	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments	3:											
2017 - Fal	I: No Change											
Comments												
2017 - Spr	ring: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12"x12" Green VFT Mastic	540	SF	Rooms 114, 215, 312, & 313 - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

				l .								
22	12"x12" Rust VFT	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
				·	- 1	•				•	•	
2016 - Fa	III: No Change											
Comment	ts:											
2017 - Fa	III: No Change											
Comment	ts:											

Type

Material

Category

Damage

Type

Friable

Damage Quantity Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	12"x12" Rust VFT Mastic	540	SF	Rooms 111, 112, 217, 310, & 315 - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

2017 - Spring: No Change

Comments:

Material Description

Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
24	Rust Linoleum	264	SF	Lunchroom, & Elevator - 1999 Addition		Miscellaneous	No	None	40		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	Rust Linoleum Mastic	354	SF	Lunchroom, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	-											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	-											
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

26	Green Linoleum	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	40		YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•	•	•	•	
Comments:]							
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
					_							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Green Linoleum Mastic	780	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

28	Beige Linoleum	2405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition	Miscellaneous	No	None	40		YES	X NO
2016 - Fall: N	lo Change		•	•	•	•	•	•	•	•	
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Beige Linoleum Mastic	2405	SF	Lunchroom, Serving Area, & Elevator - 1999 Addition		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units	3	3 ,
30	2'x4' Smooth Ceiling Tile	10000	SF	Throughout - 1999 Addtion		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	V											
2017 - Fall: I	No Change											
Comments:					1							
	g: No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
31	2'x4' Dot Ceiling Tile	12000	SF	Kitchen: (Toliet, Corridor, & Office), Serving Area, Food Storage, & Dishwash - 1999 Addition		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				1							

Material

Damage

Damage

Damage

Friable

Material

Material

Material Location

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
32	Vinyl Baseboard	8000	LF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	-											
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	Vinyl Baseboard Mastic	8000	LF	Throughout - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
34	Drywall	3000	SF	Throughout - 1999 Addition		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
35	Drywall Compound	150	SF	Throughout - 1999 Addition		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	:											
	: No Change											
Comments	:											
2017 - Spr	ing: No Change											
Comments	:			<u> </u>								

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
36	Carpet Mastic	700	SF	Library - 1999 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:					-							
Г					_	Т	T =	Γ -	T -	T _		_
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	Spray-on Insulation	7000	SF	Throughout Above Drop Ceilings - 1999 Addition		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					_							
2017 - Fall:	No Change											
Comments:					_							
	ng: No Change											
Comments:					-							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

		Quantity	Units		Туре	Category		Туре	Quantity	Units	1	
38	Terrazo	7000	SF	Throughout 1999 Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	-]							
2017 - Spring	ı: No Change											
Comments:					 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39	12"x12" Light blue with light blue specks VFT	80	SF	Main Office - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:	·											

Asbestos

Friable

Damage

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

39 A	12"x12" Light blue with light blue specks VFT (MASTIC)	80	SF	Main Office - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change				1							
Comments]							
2017 - Fall	: No Change				-							
Comments	S:]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
40	12"x12" White with Blue specks VFT	200	SF	Room 108 - 1914 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments	•											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

40 A	12"x12" White with Blue specks VFT (MASTIC)	200	SF	Room 108 - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments	S:											
2017 - Spi	ring: No Change											
Comments	S:				_							
	I: No Change											
Comments	3:				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
41	12"x12" Beige with White specks VFT	200	SF	Room 109 - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
41 A	12"x12" Beige with White specks VFT (MASTIC)	200	SF	Room 109 - 1914 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				-							
2017 - Spring Comments:	g: No Change											
2017 - Fall: N	No Change											
Comments:												
LIA No	Material Description	Matarial	Matarial	Material Legation	Ashastas	Material	Talabla	Damana	I Damasa	Damana	Channa :- A	C-t
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
42	12" x 12" BLUE, VFT	80	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	-											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
42A	12" X 12" blue, mastic	80	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<i>y y</i> -											
2047 Falls N	Ja Changa											
2017 - Fall: No Comments:	No Change				_							
Comments.					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
43	12" X 12" yellow, VFT	70	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
0047 Fall N	Ja Ohanana											
2017 - Fall: N	No Change				_							
Comments:					-							
2017 - Spring	g: No Change				7							
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
43A	12" X 12" yellow, Mastic	70	SF	1st and 2nd floor corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Chongo											
Comments:	o Change											
Comments.					-							
					•							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
44	Carpet mastic	600	SF	Rm 104 (Removed from Rms 101, 102, 103, 108, and 109)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>				-							
0045 5 11 11												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				-							
Comments:												

45	12" X 12" white with blue specks, VFT	6000	SF	1st and 2nd floor corridors; Rm 108		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change]							
Comments	S:											
2017 - Fal	I: No Change											
Comments	S:											
2017 - Spr	ring: No Change											
Comments	S:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

6000

Material

Quantity

Material

Units

SF

Material Location

1st and 2nd floor

corridors; Rm 108

HA No

45A

Material Description

12" X 12" white with blue

specks, Mastic

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
46	Fire Door	10	EA	Balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					4							
	g: No Change											
Comments:					4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
47	12" X 12" white with gray specks, VFT	320	SF	Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:					_							
	g: No Change											
Comments:					4							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
47A	12" X 12" white with gray specks, Mastic	320	SF	Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
48	Carpet mastic	400	SF	Auditorium, between isles		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	2017 - Fall: No Change											
Comments:	o Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
49	Drywall System			1919 Building		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall: N	lo Change											
Comments:	g: No Change											
2017 - Fall: N Comments:	lo Change											
Comments.												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
11/(140	Waterial Besonption	Quantity	Units	Waterial Eddaron	Туре	Category	Thabic	Туре	Quantity	Units	Change in 71000	oddinent dategory
50	2'x4' Ceiling Tile			1919 Building		Miscellaneous	Yes	Unknown			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

А	Aircell Pipe Insulation	16	LF	Room 202 & 2nd Floor Corridor - 1914	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Aircell Pipe Insulation	4	LF	Room 202 & 2nd Floor Corridor - 1914		TSI	Yes		0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
С	Mag Block Pipe Insulation	168	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	110 Onlango				1							
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	T	T	T	1	T	1	T =		T =		1	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
D	MJP E/F/V on Mag Block Pipe Insulation	50	LF	North & South Engine Rooms, Boiler Room, Natatorium, Natatorium Entry Hall - 1914		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Chango				7							
Comments:	INO Change				\dashv							
Comments.					\dashv							
2017 - Sprir	ng: No Change				1							
Comments:												

2017 - Fall: No Change

Comments:

E	Cardboard Pipe Insulation	100	LF	Room 202 & 208, Room 202 & 208 Closets, 2nd Floor Corridor - 1914		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Changa	•	•	•	1	•	•	•	•	•	•	
2016 - Fall. N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-]							
					1							
2017 - Spring	: No Change											
Comments:					1							
					1							

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Cardboard Pipe Insulation	8	LF	Room 202 (old 208), Room 202 (old 208) Closet, 2nd Floor Corridor - 1914		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Change in Assessment Category

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
G	MJP E/F/V on Fiberglass Pipe Insulation	90	LF	Throughout - 1914		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	2017 - Fall: No Change Comments:											
2017 - Spring Comments:	g: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Н	Boiler Rope	50	LF	Boiler Room - 1914		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N Comments:	g: No Change					•		<u>, </u>	,		•	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

Page 34

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	George B Swift Elementary Specialty School
Date:	11/1/2017
the Asbesto	otify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of os Management Plan is available at each school during school hours by appointment. o review the Asbestos Management Plan must be made at least 24 hours in advance.
The last ins	e be advised that CPS conducts asbestos inspections of all Schools every three years. spection was completed in 2016. urveillances are conducted every six months.
CHECK ON	<u>IE</u>
A co	ppy of this notice was sent home in each child's backpack.
X A co	ppy of this notice was printed in the school's newsletter and sent home with each child
A co	ppy of this notice was printed in the school's calendar and sent home with each child
Othe	er.
A COPY	OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 25571