## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

Mancel Talcott Elementary School 25581 6140 School: **Oracle Unit: Building ID:** Address: 1840 W. Ohio Street Region: 02 Mail Room: Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2018 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 12"x12" Beige w/Light Room B-16 (Entry) - 1895 YES 01A 850 SF X NO Miscellaneous No None 0 Streaks VFT 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
02	12"x12" White w/Beige Speckles VFT	1400	SF	Basement, West side Lunchroom - 1895 Bldg.	1,712	Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				<u> </u>							
Comments:												
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprir	ng: No Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
03	12"x12" White w/Beige Speckles VFT Mastic	1400	SF	Basement, West side Lunchroom - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							
2017 - Fall:	No Change				_							
Comments:												
2017 - Sprir	ng: No Change				-							
Comments:	· · · · · ·				1							

04	12"x12" Coffee w/Light Speckles VFT	750	SF	Room B-2 - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	•											
2017 - Spring	g: No Change				1							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
05	12"x12" Coffee w/Light Speckles VFT Mastic	750	SF	Room B-2, Engr. Office - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	Onango											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

Comments:

06	12"x12" Light Brown w/Dark & White Streaks VFT (NOT OBSERVED)		Main Office - 1895 Bldg.	Miscellaneous	None	0	YES	X NO
2016 - Fall: N	lo Change	· · · · · · · · · · · · · · · · · · ·						
Comments:								
2017 - Fall: N	lo Change							
Comments:								
2017 - Spring	g: No Change							
Comments:	-							

Type

Material

Category

Friable

Damage

Type

12"x12" Lt Brown w/Dark &		
O6A White Streaks VFT Mastic (NOT OBSERVED) 800 SF Main Office - 1895 Bldg. Miscellaneous No None (	0	YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

		-							_			
08	12"x12" Dark Brown w/Beige & Orange Speckles VFT (Not Observed)	800	SF	Room B-7 (Under Carpet) - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				1							
Comments												
2017 - Fall	I: No Change											
Comments	S:				1							
2017 - Spr	ring: No Change				_							
Comments	S:				=							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09	12"x12" Dk Brn w/Beige & Orange Spckls VFT Mastic (NOT OBSERVED)	800	SF	Room B-7 - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				]							
Comments												
2017 - Fall	I: No Change				_							
_	- U-				4							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" White w/Gray & White Speckles VFT	2000	SF	2nd Floor: Teacher's Lunchroom, 1st Flr Staff & Conference Offices - 1895 Bldg.#104 MDF Room.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change				7						
Comments:	J										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White w/Gray & White Speckles VFT Mastic	2000	SF	2nd Floor: Teacher's Lunchroom, 1st Flr Staff & Conference Offices:1895 Bldg.#104 MDF Room.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:	-		

12 Aircell Pipe Insulation 1200 LF Electrical Room, Fan Room, Room B-13, Basement Corridor, & Auditorium Stairwell - 1925 TSI Yes None 0	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	12	Aircell Pipe Insulation	1200	LF	Room, Room B-13, Basement Corridor, & Auditorium Stairwell -		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Pink w/White Speckles VFT	2400	SF	Rooms: 101, 107 & 219 (poss under carpet Not Observed); 1895 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

15	12"x12" Pink w/White Speckles VFT Mastic	2400	SF	Rooms: 101, 107 & 219 (poss under carpet Not Observed); 1895 Bldg.	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change s:	<u> </u>								
2017 - Fal Comments	I: No Change s:									

Type

Material

Category

Damage Quantity

Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	Aircell Duct Insulation	1150	SF	Basement Corridor - 1925		TSI	Yes	Loc	4		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

2017 - Spring: No Change

Comments:

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
18	MJP E/F/V on Aircell Pipe Insulation	78	LF	Throughout - 1895		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	Jo Change				7							
Comments:	10 Onlange											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	a: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	12"x12" White w/Brown & Pink Speckles VFT	600	SF	Room 202 (Under Carpet- Not Observed), Engineer's Bathroom - 1895 Bldg.	71	Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	Jo Change				7							
Comments:	10 Onlange											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r. No Change											

Material

Damage

Friable

Damage

HA No

Comments:

Material Description

Material

Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	12"x12" White w/Brown & Pink Speckles VFT Mastic	600	SF	Room 202 (Under Carpet), Engineer's Bathroom & Principal's Office - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
21	Mag Block Pipe Insulation	1	LF	Engine Room - 1895		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

2017 - Spring: No Change

Comments:

22	Boiler Gaskets	100	LF	Boiler Room - 1895 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<b></b>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

TSI

Asbestos

Type

Material

Category

Friable

Damage

Type

Dist

5

Yes

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

100

Material

Quantity

Material

Units

LF

Material Location

Boiler Room, Pump Room, All Pipe Chases, & Boiler Corridor - 1895

HA No

23

Material Description

MJP E/F/V on Fiberglass

Pipe Insulation

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Cardboard Pipe Insulation	500	LF	Throughout - 1895		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	Aircell Pipe Insulation	1200	LF	Throughout - 1895		TSI	Yes	Dist	9		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												

HA No

26	12"x12" Beige w/Light Streaks VFT Mastic	850	SF	Room B-16 (Entry) - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
27	9"x9" Brown w/Red Streaks VFT (Not Observed)	500	SF	Engineer's Office - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Quantity

Material

Units

Material Location

HA No

Material Description

28	9"x9" Brown w/Red Streaks VFT Mastic (Not Observed)	500	SF	Engineer's Office - 1895 Bldg.	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Pink w/Light Speckels VFT	2400	SF	1st, 2nd & 3rd Floor Corridors - 1925 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29A	12"x12" Pink w/Light Speckles VFT Mastic	2400	SF	1st, 2nd & 3rd Floor Corridors - 1925 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	Blue Linoleum Mastic	2500	SF	Gymnasium - 1925 Bldg.		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
31	12"x12" Gray w/Red & White Speckles VFT	800	SF	Room 312 - 1925 Bldg.	71 -	Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7		•					
Comments:	<u> </u>											
2017 - Fall: N	No Change				-							
Comments:	<u> </u>											
2017 - Spring	g: No Change				1							
Comments:	g											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
31A	12"x12" Gray w/Red & White Speckles VFT Mastic	800	SF	Room 312 - 1925 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	go											
2017 - Spring	g: No Change				4							
Comments:	g. No Onange				=							
2017 - Fall: N	No Change											
Comments:												

33	MJP E/F/V on Aircell Pipe Insulation	63	LF	Electrical Room, Fan Room, Room B-13, Basement Corridor - 1925		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	Blue Linoleum Sheeting	2500	SF	Gymnasium - 1925 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	ı		<u> </u>	1		•	•	1	·	
Comments:	<u> </u>											
					-1							

Category

Asbestos

Type

Friable

Damage

Type

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Damage

Quantity

Damage

Units

35	9"x9" Brown w/White & Dark Streaks VFT	200	SF	Room 312 Closet (20 Cracked & Chipped Tiles)- 1925 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change			<u> </u>	]					•	
Comme											
2017 - F	all: No Change										
Comme											
2017 - S	Spring: No Change										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	9"x9" Brown w/White & Dark Streaks VFT Mastic	200	SF	Room 312 Closet - 1925 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
37	Drywall Joint Compound	400	LF	Basement Room B2, Boys & Girls Ceiling. Bathroom & 203 & Teacher's Lounge - 1895 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fal	I: No Change				1							
Comments					]							
2017 - Fal	l: No Change											
Comments	S:				-							
2017 - Spr	ing: No Change											
Comments	S:											

Material

Damage

Friable

Damage

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	Cardboard Pipe Insulation	120	LF	Room B-13, Basement Corridor, & Auditiorium Stairwell - 1925		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Material Material Location

HA No

Material Description

39 MJP E/F/V on Fiberglass Pipe Insulation 100 SF Engine Room, & Fan Room - 1925, Boys & Girls, Pipe Chases, Attic	YES X NO
Above Room 1895	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
HA No Material Description Material Quantity Material Location Asbestos Type Material Friable Damage Quantity Units Damage Units	Change in Assessment Category
40 Aircell Duct Insulation 825 SF East Basement Corridors, B-7 (Fan Room), Janitor's Toliet, & Receiving Room - 1895	YES X NO
2016 - Fall: No Change	
Comments:	

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
41	MJP E/F/V on Cardboard Pipe Insulation	3	LF	Room B-13, Basement Corridor - 1925		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change											

Comments.
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	MJP E/F/V on Cardboard Pipe Insulation	12	LF	Throughout - 1895		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

44	12"x12" Brown w/White Streaks VFT (Not Observed)	850	SF	Room 106 - 1895 Bldg.	Miscellaneous	No	None	0	YES	X NO
	, , , , , , , , , , , , , , , , , , ,		ļ	ļ	<u> </u>	ļ	ļ	ļ	 ļ	
2016 - Fal	I: No Change									
Comments	S:									
2017 - Fal	I: No Change									
Comments	s:									
2017 - Spi	ring: No Change									
Comments	<u> </u>									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	12'x12' Brown w/White Streaks VFT Mastic (Not Observed)	850	SF	Room 106 - 1895 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

46	12"x12" Beige w/White Streaks VFT	900	SF	Rooms 102 & 109 - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				]							
Comment												
2017 - Fa	II: No Change				-							
Comment												
2017 - Sp	ring: No Change											
Comment	S:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
47	12"x12" Beige w/White Streaks VFT Mastic	900	SF	Rooms 109 & 102 - 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											

Comments:
2017 - Spring: No Change

Material Description

Comments:

HA No

Material

Units

Material

Quantity

Material Location

Damage

Units

48	12"x12" Tan w/Beige & Dark Streaks VFT (Not Observed)		Main Office - 1895 Bldg.		Miscellaneous				YES	X NO
0010 5 11		•	•	1	•	•	•	•	•	
2016 - Fall:	No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
2017 - Sprir	ng: No Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
49	12"x12" Tan w/Beige & Dark Streaks VFT Mastic (NOT OBSERVED)			Main Office - 1895 Bldg.		Miscellaneous	No				YES	X NO
2016 - Fall:	U											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12"x12" Tan w/Beige &

Change in Assessment Category

Damage

Quantity

Damage

Units

50	12"x12" Blue w/White Streaks VFT	210	SF	Library Closet , Rm 302- 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change				7							
Commen					]							
2017 - Fa	all: No Change				1							
Commen	ts:											
2017 - Sp	oring: No Change				-							
Commen	ts:				]							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51	12"x12" Blue w/White Streaks VFT Mastic	210	SF	Library Closet, Rm 302- 1895 Bldg.		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
52	Hard Coat Plaster			Throughout - 1925 Bldg.							YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
53	Hard Coat Plaster			Throughout - 1895 Bldg.							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	g: No Change				-							
Comments:	y. 110 Onlango				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
54	1'x1' Ceiling Tile	3500	SF	Room 308, Room 308 Closet, 3rd Floor Library, 3rd Flr Corridor & 316, 317, 310 & closet, 307, 306, 305 - 1895 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	2'x4' Ceiling Tile	3500	SF	3rd Floor E-W Corridor & Main Office - 1895 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
56	2'x4' Ceiling Tile (Tectum Panels)	40	SF	Basement Northeast Exit - 1895 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
2017 - Fall	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		,
57	Canvas Cover			1st Floor Office Supply Safe - 1895 Bldg.							YES	X NO
2016 - Fall:	No Change				1							
Comments												
2017 - Fall:	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	1'x1' White w/Grooves Ceiling Tile	3500	SF	Rooms: 301 & 304, Room 309 Closet, 206, 207, 209, 210, 110 & Wardrobe 101- 1895 Bldg.		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	1'x1' White w/Small Holes Ceiling Tile	2000	SF	Rooms: 107, 208 & 318 - 1895 Bldg.		Miscellaneous	Yes	None	0		YES X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
60	Tank Lagging	280	SF	Pump Room - 1895 Bldg.		TSI	Yes	Loc	25		YES	X NO
2016 - Fall: N	No Change				]							
Comments:					-							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
61	Red/Blue Speck Carpet Mastic	850	SF	Room B-7		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					]							
					j							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
62	Brown Carpet Mastic	800	SF	Room 202		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
63	Brick Patterned Sheet Flooring	154	SF	205		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	<b>-</b>											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g o onango											
				·								

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63A	Brick Patterned Sheet Flooring Adhesive	154	SF	205		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
64	Pergo Flooring	1000	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change				+							
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
65	Green Carpet Adhesive	160	SF	Gymnasium Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					4							
2017 - Spring	j: No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
66	12"x12" Tan w/Light Brown Streaks Floor Tile (Not Observed)	800	SF	1925 Bldg. Room 312		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				=							
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

67	12"x12" Tan w/Light Brown Streaks Floor Tile Adhesive (Not Observed)	800	SF	1925 Bldg. Room 312		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				]	•	•	•	•	•	•	
Comment					1							
2017 - Fa	II: No Change											
Comment	S:				 							
2017 - Sp	ring: No Change				]							
Comment	s:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
68	Terrazzo - Multi Colored White & Black Spotted	1000	SF	NE Stairwell 1st to 3rd Floor, JC's 1st -3rd Floors; Bldg 1895		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
68A	Terrazzo Multi Colored Black, White Spotted	1000	SF	NW Stairwell, Main Corridor 1925 Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessment Category
69	2 x 2 White Sculpted CT	700	SF	#302 Bldg 1895		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	J											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	g. 110 Onango											

70 Brown Linoleum 6 SF Phone Booth Flooring Miscellaneous No None 0 YES Bldg 1895	X NO
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
71	Brown Linoleum & Mastic	6	SF	Room #205 Museum Phone Booth Flooring Bldg 1895		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
72	2 x 2 Off White Ceiling Tile	500	SF	Basement B-8 1895 Bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	g: No Change											
Comments:	<i>y.</i>											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
73	12 x 12 White with Blue & Peach Specks VFT	500	SF	Rm#106 Bldg 1895		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	to onango											
2017 Spring	g: No Change											
Comments:	g. No Change											
2 3					1							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
74	12 X 12 White w/ Blue & Peach Specks Mastic	500	SF	Rm#106 Bldg 1895		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				$\exists$							
2017 - Fall: No Change Comments:												
2017 - Spring: No Change												
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asset	ssment Category
TIANO	Waterial Description	Quantity	Units	Waterial Education	Туре	Category	Thabic	Туре	Quantity	Units	Onange in Assec	33ment Oatogory
75	Carpet Mastic Red w/ Orange Diamond Pattern	450	SF	Basement - B-8 Bldg 1895		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Mancel Talcott Elementary School
Date:	1/11/2018
	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
	tos Management Plan is available at each school during school hours by appointment.
Requests	to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also pleas	se be advised that CPS conducts asbestos inspections of all Schools every three years.
The last in	nspection was completed in 2016.
Asbestos	surveillances are conducted every six months.
CHECK VI	NIE
CHECK OI	<u>NC</u>
A c	copy of this notice was sent home in each child's backpack.
A c	copy of this notice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	ner.
0"	<del></del>
4 00 D	AV OF THE MOTIOF MUCT BE BLACED IN THE
A COP	Y OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 25581

SCHOOL'S ASBESTOS MANAGEMENT PLAN.