Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

25621

Oracle Unit:

Address: 223 N. Keeler Region: 03 Mail Room: Asbestos Surveyor: Thompson, Darren X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/15/2017 Email Address: dthompson72@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 1908 Building -YES 001 X NO Plaster Surface Throughout 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

George W Tilton Elementary School

School:

6210

Building ID:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|----------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 001A | Smooth Plaster | | | 1908 Building - Throughout | | Surface | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 002 | Rough Plaster | | | 1966 Addition - Throughout | | Surface | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | to change | | | | | | | | | | | |
| | Na Ohaana | | | | | | | | | | | |
| Comments: | g: No Change | | | | | | | | | | | |
| Comments. | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------|-------------------------------------------------|----------------------|-------------------|--------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 005 | 9" x 9" Brick Red w/Beige Streaks Floor Tile | 10200 | SF | 1908 Building - Throughout, 1, 2, 3, 4, Floor Hallways & 118 | | Miscellaneous | No | None | 0 | | YES X NO |
| 2016 - Fall: N | lo Change | • | • | | | • | • | • | | | |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------------------|----------------------|-------------------|----------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 006 | 9" x 9" Brick Red w/Beige Streaks FT Mastic | 10200 | SF | 1908 Building - Throughout, 1, 2, 3, 4, Floor Hallway Room 118 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change | |
|--------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | essment Category |
|----------------|-------------------------------------------------------|----------------------|-------------------|---------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|---------------|------------------|
| 007 | 12" x 12" Lt. Brn w/Grey Streaks Floor Tile Mastic | | | 1908 Building - Throughout (see comments for locations) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: I | No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Fall: I | No Change | | | | _ | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Sprin | g: No Change | | | | | | | | | | | |
| Comments: | g. 110 O.I.ago | | | | | | | | | | | |
| | | | | |] | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | essment Category |
| 800 | 12" x 12" Lt. Brown w/Grey Streaks Floor Tile | | | 1908 Building - Throughout | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: I | No Change | | | |] | | | | | | | |
| Comments: | J | | | | | | | | | | | |
| 2017 - Fall: I | No Change | | | | _ | | | | | | | |
| Comments: | No Change | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | g: No Change | | | | _ | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| | | | | | _ | | | | | | | |

| 009 | 2' x 2' Rough Ceiling Tile | 1908 Building - 1st Floor Hallway | Miscellaneous | | | YES | X NO |
|----------------|----------------------------|--------------------------------------|---------------|--|--|-----|------|
| 2016 - Fall: N | lo Change | |] | | | | |
| Comments: | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | |
| Comments: | | | | | | | |
| | g: No Change | | | | | | |
| Comments: | | | | | | | |
| | | | ı | | | | |

Type

Material

Category

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------------------|----------------------|-------------------|------------------------------------------------------------------------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 010 | 9" x 9" Tan w/Beige & Choc. Streaks Floor Tile | 16900 | SF | 2nd floor hallway, 3rd floor hallway, main office, and classrooms: 110, 110A, 112, 114, 208-212, 214, 308-312, and 314 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

| HA No | Material Description | Material Quantity | Units | Material Location | Asbestos Type | Material Category | Friable | Type | Damage Quantity | Units | Change in Asses | sment Category |
|-----------------------------|--------------------------------------------------|----------------------|-------|------------------------------------------------------------------------------------------------------------------------------------|------------------|----------------------|---------|------|--------------------|-------|-----------------|----------------|
| 011 | 9" x 9" Tan w/Beige & Choc. Floor Tile Mastic | 16900 | SF | 2nd floor hallway, 3rd floor hallway, main office, and classrooms: 110, 110A, 112, 114, 208-212, 214, 308-312, and 314 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N Comments: | lo Change | | | | | | | | | | | |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|----------------------|-------------------|-------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 012 | Sheet Rock Board Material | | | 1908 Building - Throughout | | Miscellaneous | | | | | YES X NO |

| 2016 - Fall: No Change | |
|--------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |

| | | Quantity | Units | | Туре | Category | | Type | Quantity | Units | | |
|----------------|--------------------------------------------------|----------------------|-------------------|---------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 013 | Joint Compound on Sheetrock Board Material | | | 1908 Building - Throughout | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | _ | | | | | | | |
| Comments: | U | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| | | | | | _ | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 014 | Black Flooring Beneath 9" x 9" Red Floor Tile | | | 1908 Building - Throughout (see comments for locations) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | J | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | _ | | | | | | | |
| Comments: | Ţ. | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | _ | | | | | | | |
| Comments: | ,gc | | | | | | | | | | | |
| | | | | | J | | | | | | | |

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|--------------|-----------------------|----------------------|-------------------|-------------------------------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 015 | Interior Brick | | | 1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Washrooms | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | 1 | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Sprin | ng: No Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 016 | Interior Brick Mortar | | | 1908 Building - 1st - 4th Floor Hallways, 2nd-4th Floor Girls and Boys Washrooms | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments: | Gago | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | - | | | | | | | |
| Comments: | 140 Change | | | | | | | | | | | |
| 2017 Cprin | ag: No Chango | | | | - | | | | | | | |
| Comments: | ng: No Change | | | | - | | | | | | | |
| Comments. | | | | | <u> </u> | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 017 | Black Vinyl Baseboard | | | 1908 Building - Throughout, Foyers | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 018 | Black Vinyl Baseboard Mastic | | | 1908 Building - Throughout, Foyers | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | , and the second | | | | | | | | | | | |
| | | | | | | | | | | | | |

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | | |
|--------------|--------------------------|----------------------|-------------------|--------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 019 | Black Border Tile | 500 | SF | 1908 Building - Lobby, and 3rd Floor Hallways | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: | : No Change | | | | 7 | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall: | : No Change | | | | 1 | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | - | | | | | | | |
| Comments | : | | | | | | | | | | | |
| | | | | | _ | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 020 | Black Border Tile Mastic | 500 | SF | 1908 Building - Lobby, and 3rd Floor Hallways | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: | : No Change | | | | | | | | | | | |
| Comments | : | | | | | | | | | | | |
| 2017 - Fall: | : No Change | | | | = | | | | | | | |
| Comments | • | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| | | | | | _ | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessm | nent Category |
|----------------|-------------------------------------------------------|----------------------|-------------------|-----------------------------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|---------------|
| 021 | 12" x 12" Lt. Beige w/Light Brn Streaks Floor Tile | 6000 | SF | 1908 Building - Rooms 100, 101A, 104, 105, 203, 205, Library, 1st Floor Foyers | | Miscellaneous | No | None | 0 | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | 7 | | | | | | | | |
| Comments: | Ţ. | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | _ | | | | | | | | |
| Comments: | io onango | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | | | | | | | | | |
| Comments: | ,go | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessm | nent Category |
| 022 | 12" x 12" Lt. Beige w/Lt. Brn Streaks FT Mastic | 6000 | SF | 1908 Building - Rooms 100, 100A, 104, 105, 203, 205, Library, 1st Floor Foyers | | Miscellaneous | No | None | 0 | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | 1 | | | | | | | | |
| Comments: | | | | | _ | | | | | | | | |
| 2017 Fall N | lo Chango | | | | | | | | | | | | |
| 2017 - Fall: N | io Change | | | | - | | | | | | | | |
| Comments. | | | | | | | | | | | | | |

2017 - Spring: No Change

Comments:

| 023 | 9" x 9" Leaf Green w/Beige Streaks Floor Tile | 6 | SF | 1908 Building - Room 205 | Miscellaneous | No | None | 0 | YES | X NO |
|----------------------------|--------------------------------------------------|---|----|-----------------------------|---------------|----|------|---|-----|------|
| 2016 - Fall: No | o Change | | | | | | | | | |
| 2017 - Fall: No | o Change | | | | | | | | | |
| 2017 - Spring Comments: | : No Change | | | | | | | | | |

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------------------|----------------------|-------------------|-----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 024 | 9" x 9" Leaf Green w/Beige Streaks FT Mastic | 6 | SF | 1908 Building - Room 205 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

Material

Quantity

Material

Units

Material Location

HA No

Material Description

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------------------|--------------------------------------------------|----------------------|-------------------|--------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 025 | 9" x 9" Cherry Red w/Beige Streaks Floor Tile | 90 | SF | 1908 Building - Engineer's Office | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| 2017 - Spring Comments: | g: No Change | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 026 | 9" x 9" Cherry Red w/Beige Streaks FT Mastic | 90 | SF | 1908 Building - Engineer's Office | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |

| | | Quantity | Units | | Type | Category | | Туре | Quantity | Units | | |
|----------------|----------------------------------------------------|----------------------|-------------------|-----------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|----------------|
| 027 | 9" x 9" Black w/Beige Streaks Floor Tile | | | 1908 Building - Room 203 | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | Ü | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | sment Category |
| 028 | 9" x 9" Black w/Beige Streaks Floor Tile Mastic | | | 1908 Building - Room 203 | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | J | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| | | | | | | | | | | | | |

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|-------------------------|-----------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 029 | Exterior Window Caulk - ABATED | | | 1908 Building - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | : No Change | | | | 1 | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 030 | Exterior Door Caulk | | | 1908 Building - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 7 | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | + | | | | | | | |
| Comments: | lo Ondrigo | | | | 1 | | | | | | | |
| 2017 Caring | u No Chango | | | | | | | | | | | |
| 2017 - Spring Comments: | i. No Change | | | | - | | | | | | | |
| Commonto. | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|--------------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 031 | Exterior Brick - Non AHERA | | | 1908 Building - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| | | | | | _ | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 032 | Exterior Brick Mortar - Non AHERA | | | 1908 Building - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Spring | g: No Change | | | | - | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 033 | Exterior (window side) Wall Caulk - Not AHERA | | | 1908 Building - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Spring | : No Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| | | | | | _ | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | ssment Category |
| 034 | Exterior Window Caulk - Non Ahera ABATED | | | 1966 Addition - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 7 | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | = | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | _ | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|--------------------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 035 | Exterior Door Caulk - Non AHERA, ABATED | | | 1966 Addition - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Spring | : No Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 036 | Exterior Window Glazing Non AHERA | | | 1966 Addition - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 7 | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | - | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|--------------------------------------|----------------------|-------------------|--------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 037 | Exterior Brick - Non AHERA | | | 1966 Addition - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Spring | : No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 038 | Exterior Brick Mortar - Non AHERA | | | 1966 Addition - Exterior | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 1 | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | = | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | : No Change | | | | 1 | | | | | | | |
| Comments: | . <u> </u> | | | | | | | | | | | |
| | | | | | | | | | | | | |

| | | Quantity | Units | | Type | Category | | Type | Quantity | Units | | |
|----------------|----------------------------------------------------|----------|----------|-------------------------------------------------------------------------------------------|----------|---------------|---------|--------|----------|--------|-----------------|-------------------|
| 039 | 9" x 9" Beige & Brn. w/Choc. Streaks Floor Tile | | | 1908 Building - Auditorium, Assistant Principal's Office, Conference Room by 100 | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 1 | | | | | | | |
| Comments: | io Change | | | | | | | | | | | |
| Comments. | | | | | 1 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material | Material | Material Location | Asbestos | Material | Friable | Damage | Damage | Damage | Change in Asses | ssment Category |
| | material 2 conputer | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | | Joine in Galogoly |
| 040 | 9" x 9" Beige & Brown w/Choc. Streaks FT Mastic | | | 1908 Building - Auditorium, Assistant Principal's Office, Conference Room by 100 | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | io chango | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 Corio | v. No Change | | | | - | | | | | | | |
| 2017 - Spring | j: No Change | | | | | | | | | | | |

Asbestos

Damage

Friable

Damage

HA No

Comments:

Material Description

Material

Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|----------------|---------------------------------------------------|----------------------|-------------------|---------------------------------------------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| 041 | 12" x 12" Lt. Off-white & Cream Mix Floor Tile | 2378 | SF | 1966 Addition - Lunchroom, Main Office Washroom/Vault, Kitchen Serving Area, Kitchen Office | | Miscellaneous | No | None | 0 | | YES X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | |
| Comments: | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | |
| Comments: | | | | | | | | | | | |
| 2017 - Spring | : No Change | | | | - | | | | | | |
| Comments: | | | | | | | | | | | |
| | | | | | J | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
| 042 | 12" x 12" Lt. Off-White w/Cream FT Mastic | 2378 | SF | 1966 Addition - Lunchroom, Main Office Washroom/Vault, Kitchen Serving Area, Kitchen Office | | Miscellaneous | No | None | 0 | | YES X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | |

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------|----------------------|-------------------|-----------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 043 | Blue Vinyl Baseboard | | | 1966 Addition - Kitchen Serving Area | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 044 | Blue Vinyl Baseboard Mastic | | | 1966 Addition - Kitchen Serving Area | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Spring | g: No Change | | | | = | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

| 045 | 9" x 9" Choc. Mix w/Off- White Streaks Floor Tile | 1750 | SF | 1966 Addition - 1st, 2nd and 3rd Floor Hallways | | Miscellaneous | No | None | 0 | | YES | X NO |
|------------|------------------------------------------------------|----------|----------|-------------------------------------------------|----------|---------------|---------|--------|--------|--------|------------------|----------------|
| 2016 - Fal | II: No Change | | | |] | | | | | | | |
| Comment | S: | | | | 1 | | | | | | | |
| 2017 - Fal | II: No Change | | | | | | | | | | | |
| Comment | S: | | | | 1 | | | | | | | |
| 2017 - Sp | ring: No Change | | | | = | | | | | | | |
| Comment | S: | | | | 1 | | | | | | | |
| | | | | | J | | | | | | | |
| HA No | Material Description | Material | Material | Material Location | Asbestos | Material | Friable | Damage | Damage | Damage | Change in Assess | sment Category |

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

| TIANO | Material Description | Quantity | Units | Iviaterial Eocation | Type | Category | Filable | Type | Quantity | Units | Change in Assess | Sillerit Gategory |
|-----------------------------|-----------------------------------------------------|----------|-------|----------------------------------------------------|------|---------------|---------|------|----------|-------|------------------|-------------------|
| 046 | 9" x 9" Choc. Mix w/Off- white Streaks FT Mastic | 1800 | SF | 1966 Addition - 1st, 2nd and 3rd Floor Hallways | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: I Comments: | No Change | | | | | | | | | | | |

2017 - Fall: No Change Comments:

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Units

Material

Quantity

Material Location

Page 23

Change in Assessment Category

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------------|----------------------|-------------------|----------------------------------------------------------------------------------|----------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 047 | Cream Rubber Floor Adhesive | | | 1908 Building - 1st Floor Hallway (West Corridor) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| 2017 - Fall: N | lo Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | = - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 048 | Partition Bridging Floor Compound | | | 1966 Addition - 2nd Floor Hallway (between original building and addition) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| | | | | | J | | | | | | | |

| 049 | 9" x 9" Lt. Brown w/Beige Streaks Floor Tile | 42 | SF | 1966 Addition - Room 209 | | Miscellaneous | No | None | 0 | | YES X NO | |
|---------------------------|-------------------------------------------------|----------|----------|-----------------------------|----------|---------------|---------|--------|----------|--------|----------------------------|------|
| 2016 - Fall: Comments: | No Change | | | |] | | | | | | | |
| 2017 - Fall: Comments: | No Change | | | | | | | | | | | |
| 2017 - Sprii Comments: | ng: No Change | | | | | | | | | | | |
| HA No | Material Description | Material | Material | Material Location | Asbestos | Material | Friable | Damage | Damage | Damage | Change in Assessment Categ | norv |
| I IA NO | Material Description | Quantity | Units | Material Location | Type | Category | i nable | Type | Quantity | Units | Change in Assessment Categ | jury |

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

42

Material

Quantity

Material

Units

SF

Material Location

1966 Addition - Room

209

HA No

050

Material Description

9" x 9" Lt. Brown w/Beige

Strks Floor Tile Mastic

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|-------------------------------------------|----------------------|-------------------|------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 051 | Countertop Masonite Material | | | 1966 Addition - Lunchroom | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 052 | Countertop Masonite Backing Insulation | | | 1966 Addition - Lunchroom | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | · | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|---------------------------------|----------------------|-------------------|--------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 053 | Black Vinyl Baseboard | | | 1966 Addition - Main Office Areas | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 054 | Black Vinyl Baseboard Mastic | | | 1966 Addition - Main Office Areas | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | ssment Category |
|----------------|---------------------------------|----------------------|-------------------|------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|-----------------|
| 055 | Sheet Rock | | | 1966 Addition - Lunchroom | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | ssment Category |
| 056 | Joint Compound on Sheet Rock | | | 1966 Addition - Lunchroom | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------------------------|----------------------|-------------------|------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 057 | Smooth Plaster | | | 1966 Addition - Throughout | | Surface | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | | | | | 1 | | | | | | | |
| 2017 - Spring | g: No Change | | | | - | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| 2017 - Fall: N | lo Change | | | | - | | | | | | | |
| Comments: | | | | | - | | | | | | | |
| | | | | | 1 | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 058 | Rough Ornamental Ceiling Plaster (Acoustical) | | | 1966 Addition - Main Office Areas, Rooms 110, 112, and 114 | | Surface | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | |] | | | | | | | |

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | | |
|-------------|---------------------------|----------------------|-------------------|-------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 059 | Black Ceiling Pipe Filler | 5 | LF | 1908 Building - 2nd Floor Girls Toilet | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall | : No Change | | | |] | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Spri | ing: No Change | | | | 1 | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall | : No Change | | | | - | | | | | | | |
| Comments | : | | | | | | | | | | | |
| | | | | | J | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 060 | Pipe Coating Material | | | 1966 Addition - Crawl space | | TSI | | None | | | YES | X NO |
| 2016 - Fall | : No Change | | | | 1 | | | | | | | |
| Comments | : | | | | | | | | | | | |
| 2017 - Fall | : No Change | | | | - | | | | | | | |
| Comments | : | | | |] | | | | | | | |
| 2017 - Spri | ing: No Change | | | | - | | | | | | | |
| Comments | : | | | | | | | | | | | |
| | | | | | _ | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessi | ment Category |
|----------------|---------------------------|----------------------|-------------------|--------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|---------------|
| 061 | Stack Fire Brick Material | | | 1908 Building - Boiler Room | | Miscellaneous | | | | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessi | ment Category |
| 062 | Incinerator Brick | | | 1908 Building - Boiler Room | | Miscellaneous | | | | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| | | | | | | | | | | | | | |

| | | Quantity | Units | | Type | Category | | Type | Quantity | Units | | |
|--------------|-------------------------------------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 063 | Sink Bottom Caulk Material | 12 | LF | 1966 Addition - Rooms 112, and 212 | | Surface | Yes | None | 0 | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | _ | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | - | | | | | | | |
| Comments | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 064 | Interior Window Glazing Compound Abated 2002 | | | 1966 Addition - Throughout | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | | | | | | | | |
| Comments | : | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | = | | | | | | | |
| Comments | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

| 065 | Caulk Between Ceramic and Metal Windows Abated 2002 | | | 1966 Addition - Throughout | | Miscellaneous | | | | | YES | X NO |
|----------------|-----------------------------------------------------------|----------------------|-------------------|-----------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|--------------|--------------------|
| 2016 - Fall: N | No Change | | | |] | • | • | • | • | • | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| 2017 - Sprin | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| | | | | | J | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in As | ssessment Category |
| 066 | Black Flooring | | | 1908 Building - 1st Floor Teacher's Lounge next to 104 (museum) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | No Change | | | |] | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| 2017 - Sprin | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | · | | | | | | | | | | | |

Type

Material

Category

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | sessment Category |
|-----------------|------------------------------------------|----------------------|-------------------|-----------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|---------------|-------------------|
| 067 | Pink Mix Flooring Material | | | 1908 Building - 1st Floor Teacher's Lounge (Museum) | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: No | o Change | | | |] | | | | | | | |
| Comments: | _ | | | |] | | | | | | | |
| 2017 - Spring: | No Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: No | o Change | | | | - | | | | | | | |
| Comments: | o onango | | | | - | | | | | | | |
| | | | | |] | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | sessment Category |
| 068 | Stairway Floor Material (Stair Tread) | | | 1908 Building - 3rd Floor by Library | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: No | o Change | | | |] | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: No | o Change | | | | _ | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring: | No Change | | | | <u> </u> | | | | | | | |
| Comments: | . INO Ondinge | | | | - | | | | | | | |
| | | | | |] | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
|----------------|----------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 069 | Roofing Material | | | 1908 Building - Exterior Non-AHERA | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | : No Change | | | | 1 | | | | | | | |
| Comments: | J | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 070 | Roofing Material | | | 1966 Addition - Exterior Not AHERA | | Miscellaneous | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | 7 | | | | | | | |
| Comments: | J | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | - | | | | | | | |
| Comments: | io onango | | | | | | | | | | | |
| 2017 - Spring | ı: No Chango | | | | - | | | | | | | |
| Comments: | i. No Change | | | | 1 | | | | | | | |
| | | | | | | | | | | | | |

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | <u> </u> | |
|--------------|-----------------------------------|----------------------|-------------------|--------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 071 | Boiler Interior Materials | 100 | SF | 1908 Building - Boiler Room | | Miscellaneous | No | Unknown | 0 | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments: | _ | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | - | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Sprin | ng: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| 072 | Incinerator Interior Materials | 80 | SF | 1908 Building - Boiler Room | | Miscellaneous | No | Unknown | 0 | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| 2017 - Sprin | ng: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessr | ment Category |
|----------------|------------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|---------------|
| 074 | Purple Carpet Adhesive | | | Room 104 (Now Supply Room) | | Miscellaneous | | None | | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | | |
| Comments: | | | | | _ | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | | |
| | g: No Change | | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | | |
| | | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessr | ment Category |
| 075 | Floor Tile | | | Beneath Tiles in First Floor Foyer | | Miscellaneous | | None | | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| | | | | | _ | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|----------------------|----------------------|-------------------|---------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 076 | Floor Tile Mastic | | | Beneath Tiles in First Floor Foyer | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | , | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | ssment Category |
| 077 | Vault Door Core | 25 | SF | Office 1966 Bldg. | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | Ü | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | to onango | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | g. No Change | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|------------------------------------|----------------------|-------------------|-------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 078 | 12" x 12" Red Floor Tile | 1000 | SF | 2nd and 3rd Floor Corridors 1908 Bldg. | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 079 | 12" x 12" Red Floor Tile Mastic | 1000 | SF | 2nd and 3rd Floor Corridors 1908 Bldg. | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

HA No

Change in Assessment Category

| | Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Onlange in Asses | sment Category |
|-----------------------------------------|-------------------------------------------------------|-----------------------------------------------------------------------|----------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------------------|
| ue Carpet Adhesive | 1570 | SF | Room 206 and Library | | Miscellaneous | No | None | 0 | | YES | X NO |
| Change | | | |] | | | | | | | |
| | | | | _ | | | | | | | |
| Change | | | | 1 | | | | | | | |
| | | | | | | | | | | | |
| o Change | | | | 1 | | | | | | | |
| o change | | | | - | | | | | | | |
| | | | |] | | | | | | | |
| atorial Description | Motorial | Motorial | Material Legation | Ashastas | Motorial | Erioblo | Domogo | Domogo | Domogo | Change in Asses | oment Cotegory |
| aterial Description | Quantity | Units | Material Location | Type | Category | Filable | Type | Quantity | Units | Change in Asses | Smerit Category |
| ab Table Tops | 150 | SF | Room 102 | | Miscellaneous | No | None | 0 | | YES | X NO |
| Change | | | | 1 | | | | | | | |
| • | | | | | | | | | | | |
| Change | | | | _ | | | | | | | |
| 90 | | | | | | | | | | | |
| o Changa | | | | | | | | | | | |
| o Change | | | | 1 | | | | | | | |
| | | | | 1 | | | | | | | |
| a a b b c b c b c b c b c b c b c b c b | hange hange Change Iterial Description Table Tops | hange Change Change Material Description Table Tops hange hange | hange Change Change Material Description Table Tops 150 SF Material Units SF Change | hange Change Change Material Description Table Tops 150 SF Room 206 and Library Material Material Material Location Quantity Discription SF Room 102 Room 102 | hange Change Change Material Description Table Tops 150 SF Room 206 and Library Material Location Type Asbestos Type Asbestos Type Asbestos Type And Table Tops Asbestos Type | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous hange hange Change O Change Iterial Description Material Quantity Units Material Location Type Category Table Tops 150 SF Room 102 Miscellaneous hange hange | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous No hange Change O Change Iterial Description Material Quantity Units Date Tops 150 SF Room 102 Miscellaneous No Miscellaneous No Material Friable Category Miscellaneous No Miscellaneous No Material Friable Category Miscellaneous No hange hange | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous No None hange Change Change Iterial Description Material Quantity Units Material Location Type SF Room 102 Miscellaneous No None hange Table Tops 150 SF Room 102 Miscellaneous No None | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous No None 0 hange Change Asbestos Type Category Friable Damage Type Quantity Table Tops 150 SF Room 102 Miscellaneous No None 0 hange | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous No None 0 hange Change O Change Iterial Description Material Quantity Units Type Category Type Quantity Units Type Category Type Quantity Units Miscellaneous No None 0 Miscellaneous No None 0 Damage Type Quantity Units One | e Carpet Adhesive 1570 SF Room 206 and Library Miscellaneous No None 0 |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|---------------------------------------|----------------------|-------------------|-----------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 082 | Chalk Board/Poster Board Adhesive | 3700 | SF | Classrooms | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | o Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | o Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | : No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asser | ssment Category |
| 084 | 12"x12" Off White/Beige Floor Tile | 270 | SF | Room 203 Closet and Washroom, Rm 102 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | o Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| 2017 - Fall: N | o Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | · No Change | | | | | | | | | | | |
| Comments: | , ito onango | | | | | | | | | | | |
| | | | | | | | | | | | | |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessi | ment Category |
|------------------------------------------------------------------------------------------|----------------------------------------------|----------------------|-------------------|-------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------|--------|---------------|
| 085 | 12"x12" Off White/Beige Floor Tile Mastic | 270 | SF | Room 203 Closet and Washroom | | Miscellaneous | No | None | 0 | | YES | | X NO |
| 2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments: | lo Change | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in A | ssessı | ment Category |
| 086 | 12"x12" Off White/Beige Floor Tile | 935 | SF | Auditorium, 1908 Hallway, Auditorium & Room 100 | | Miscellaneous | No | None | 0 | | YES | | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | - | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | | | | | | | | | |
| Comments: | ,go | | | | 7 | | | | | | | | |

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | | |
|----------------|----------------------------------------------|----------------------|-------------------|----------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 087 | 12"x12" Off White/Beige Floor Tile Mastic | 935 | SF | Auditorium | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 088 | 9"x9" Red/Gray Floor Tile | 336 | SF | 101A (Assistant Principal's Office) | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| | | Quantity | Units | | Type | Category | | Type | Quantity | Units | | |
|-------------|-------------------------------------|----------------------|-------------------|----------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|---------------|------------------|
| 089 | 9"x9" Red/Gray Floor Tile Mastic | 336 | SF | 101A (Assistant Principal's Office) | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall | : No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall | : No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Ass | essment Category |
| 090 | Carpet Adhesive | | | Room 206 (Library) | | Miscellaneous | | None | | | YES | X NO |
| 2016 - Fall | : No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Fall | : No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| 2017 - Spri | ng: No Change | | | | | | | | | | | |
| Comments | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | | |
|----------------|---------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 91 | Gray Vinyl Sheeting | 50 | SF | Elevator (1966) | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: I | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: I | No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 92 | Gray Vinyl Sheeting Adhesive | 50 | SF | Elevator (1966) | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: I | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: I | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | g: No Change | | | | | | | | | | | |
| Comments: | | | | | 4 | | | | | | | |
| | | | | | | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
|----------------|--------------------------------------|----------------------|-------------------|---------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| 93 | 2' x 2' Smooth White Ceiling Tile | 1750 | SF | 1966 Building West Main Foyer & Stairway | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | | 1 | | | | | | | |
| Comments: | | | | |] | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | 1 | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| 94 | Purple Carpet Adhesive | 500 | SF | 1966 Building Room 114 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | |] | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | - | | | | | | | |
| Comments: | | | | |] | | | | | | | |
| 2017 - Spring | g: No Change | | | | - | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| | | | | | _ | | | | | | | |

HA No

Change in Assessment Category

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asso | essment Category |
|-----------------------------|----------------------------------------------|----------------------|-------------------|-------------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| Α | Tank Insulation - ABATED | | | 1908 Building - Tank Room/Boiler Room | | TSI | | | | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | V | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | | | | | | | | |
| Comments: | ,go | | | | | | | | | | | |
| | | | | |] | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asso | essment Category |
| С | Joint Compound on Fiberglass Pipe Insulation | 75 | LF | 1908 Building - Boiler Room, Pipe Chases, and throughout facility | | TSI | Yes | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | |] | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | ı: No Change | | | | | | | | | | | |
| Comments: | J. 140 Change | | | | | | | | | | | |
| 2017 Fall: N | lo Chango | | | | | | | | | | | |
| 2017 - Fall: N Comments: | io Change | | | | | | | | | | | |
| 2011111011101 | | | | | 1 | | | | | | | |

| D | Paperwrap Pipe Insulation | 210 | LF | 1908 Building - Boiler Room, Tunnel, and possibly in inaccessible areas throughout facility | TSI | Yes | None | 0 | YES | X NO |
|---------------------------|---------------------------|-----|----|------------------------------------------------------------------------------------------------------|-----|-----|------|---|-----|------|
| 2016 - Fall: Comments: | • | | | | | | | | | |
| 2017 - Sprin Comments: | ig: No Change | | | | | | | | | |
| 2017 - Fall: Comments: | | | | | | | | | | |

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------------------|----------------------|-------------------|--------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| Е | Joint Compound on Paperwrap Pipe Insulation | 21 | LF | 1908 Building - Boiler Room, Tunnel, and throughout facility | | TSI | Yes | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

Material

Quantity

Material

Units

Material Location

HA No

Material Description

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | sment Category |
|--------------|-------------------------------------|----------------------|-------------------|-----------------------------------------------------------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|----------------|
| F | Aircell Pipe Insulation | 150 | LF | 1908 Building - Boiler Room, Tank Room, and Throughout Facility | | TSI | Yes | None | 0 | | YES | X NO |
| 2016 - Fall: | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | _ | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Sprin | ıg: No Change | | | | _ | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | sment Category |
| Н | Mag-block Pipe Insulation | | | 1908 Building - Throughout Facility | | TSI | | | | | YES | X NO |
| 2016 - Fall: | No Change | | | | 7 | | | | | | | |
| Comments: | - | | | |] | | | | | | | |
| 2017 - Sprin | g: No Change | | | | 1 | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| 2017 - Fall: | No Change | | | | _ | | | | | | | |
| Comments: | · · · · · · · · · · · · · · · · · · | | | | 1 | | | | | | | |
| | | | | | 1 | | | | | | | |

| 114 11 | TALL STEP STATE | 1 84 4 1 1 | 1 14 / 11 | I was a state of | 1 4 1 4 | 1 | F - 11 | _ | | | 01 . 4 | |
|----------------|----------------------------------------------|----------------------|-------------------|--------------------------------|----------|----------|---------|--------|--------------------|-----------------|----------------|------------------|
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos | Material | Friable | Damage | Damage Quantity | Damage Units | Change in Asse | essment Category |
| | | Quantity | Units | | Туре | Category | | Type | Quantity | Units | | |
| 1 | Joint Compound on Mag- | | | 1908 Building - | | TSI | | | | | YES | X NO |
| | block Pipe Insulation | | | Throughout Facility | | | | | | | | <u> </u> |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | - | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material | Material | Material Location | Asbestos | Material | Friable | Damage | Damage | Damage | Change in Asse | essment Category |
| | | Quantity | Units | | Type | Category | | Туре | Quantity | Units | | |
| J | Joint Compound on Aircell Pipe Insulation | 19 | LF | 1908 Building - Boiler Room | | TSI | Yes | None | 0 | | YES | X NO |
| | . ipo inculation | | | 1100 | | | | | | | | |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | <u> </u> | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |

| K | Joint Compound on Fiberglass Pipe Insulation | 100 | LF | 1966 Addition - Throughout Facility, Crawl Space | | TSI | Yes | Dist | 10 | | YES | X NO |
|----------------|----------------------------------------------|-----|----|--------------------------------------------------------|---|-----|-----|------|----|---|-----|------|
| | • | • | | | 1 | - | • | - | - | • | | |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | <u>-</u> | | | | | | | | | | | |
| | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Type

Material

Category

| L Beige Terrazzo 3000 SF Bathrooms Miscellaneous No None 0 YES XNO | HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------------------------------------------------------------------|-------|----------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| | L | Beige Terrazzo | 3000 | SF | Bathrooms | | Miscellaneous | No | None | 0 | | |

| 2016 - Fall: No Change | |
|--------------------------|--|
| Comments: | |
| | |
| 2017 - Fall: No Change | |
| Comments: | |
| | |
| 2017 - Spring: No Change | |
| Comments: | |
| | |

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

| | | Quantity | Units | | Type | Category | | Type | Quantity | Units | • | |
|----------------|------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-----------------|-----------------|
| М | Carpet Mastic | 1000 | SF | Room 307, Museum | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asses | ssment Category |
| N | 9 x 9 White Floor Tile | 500 | SF | Room 118 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | No Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| | | | | | | | | | | | | |

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

| | | Quantity | Units | | Туре | Category | | Туре | Quantity | Units | <u></u> | |
|----------------|-------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|----------------|------------------|
| 0 | 9 x 9 Floor Tile Mastic | 500 | SF | Room 118 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| | | | | | | | | | | | | |
| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Asse | essment Category |
| Р | 12 x 12 Grey Floor Tile | 700 | SF | Room 114 | | Miscellaneous | No | None | 0 | | YES | X NO |
| 2016 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| 2017 - Spring | g: No Change | | | | | | | | | | | |
| Comments: | | | | | _ | | | | | | | |
| 2017 - Fall: N | lo Change | | | | | | | | | | | |
| Comments: | | | | | | | | | | | | |
| L | | | | | | | | | | | | |

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|----------------------|-------------------|-------------------|------------------|----------------------|---------|----------------|--------------------|-----------------|-------------------------------|
| Q | 12 x 12 Grey Floor Tile Mastic | 700 | SF | Room 114 | | Miscellaneous | No | None | 0 | | YES X NO |

| 2016 - Fall: No Change |
|--------------------------|
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

| School: George W | Tilton Elementary School |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| Date: 11/15/2017 | |
| | |
| | |
| the Asbestos Manager | accordance with Illinois and Federal Asbestos Regulations, that a copy of ment Plan is available at each school during school hours by appointment. Asbestos Management Plan must be made at least 24 hours in advance. |
| The last inspection wa | d that CPS conducts asbestos inspections of all Schools every three years. s completed in 2016. s are conducted every six months. |
| CHECK ONE | |
| A copy of this no | tice was sent home in each child's backpack. |
| A copy of this no | tice was printed in the school's newsletter and sent home with each child |
| A copy of this no | tice was printed in the school's calendar and sent home with each child |
| Other. | |
| | |
| A COPY OF THIS | NOTICE MUST BE PLACED IN THE |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.