Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

John Whistler Elementary School 25831 6420 School: **Oracle Unit: Building ID:** Address: 11533 S Ada Region: 06 Mail Room: Asbestos Surveyor: Johnson, Mr. Brian Evertte **CHECK HERE IF NO CHANGE TO ASBESTOS** 11/2/2017 Survey Date: Email Address: bejohnson1@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No Asbestos Material Description Material Material Material Location Material Friable Damage Damage Damage Change in Assessment Category Category Quantity Units Type Type Quantity Units 9x9 brown/white streaks flr X NO YES 01A 1680 SF Rm 122,119 Miscellaneous No None 0 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

01B	9x9 light gray/brown and white streak floor tile	3390	SF	Rooms 123, 120, 117, 116		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	•]							
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall: I	No Change				_							
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

		-		
01C	9x9 tan.brown and white streak floor tile	8600	SF	Rooms 105, 121,118, 217, 218, 219, 221, 220, 223, 222
0040 = 11 14	01			
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				

Material

Quantity

Material

Units

Material Location

HA No

Material Description

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
01D	9x9 light gray/white streaks floor tile	1975	SF	2nd floor cooridor		Miscellaneous	No	Loc	5		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				_							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
06A	9x9 tan/white streak floor tile (abated)			Main office, principals office, office store room, and vault ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	g: No Change				1							
Comments:	-											
2017 - Fall: N	lo Change				_							
Comments:												
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

06B	9x9 light gray/white streak floor tile	2720	SF	Rooms 115, 129, 126, 125, 216, and adjustment room	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change				•		•	•		
2017 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
06C	9"x9" Beige w/Brown Streaks Floor tile	2522	SF	Rooms 124, 127(Kitchen) and 128		Miscellaneous	No	None	0		YES X NO

204C Fall, No Change	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Damaged	
Comments:MULTI AREA DAMAGED	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

09A	9x9 white/green streaked floor tile	1680	SF	Rooms 114,115, in 1957 bldg	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	Vo Change									
Comments:	NO Change									
2017 - Fall: I										
Comments:	ILES DISTURBED									
2017 - Sprin	g: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09B	9"x9" Brown w/White Streaks Floor Tile	881	SF	1957 Bldg: Men's Washroom and Teacher's Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09C	9"x9" Gray w/ White and Black Streaks Floor Tile	3242	SF	Rooms 113,115,110,103,and 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	ı: No Change											
Comments:	,go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09D	9x9 tan/beige streak floor tile	1680	SF	Rooms 112 and 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	ı: No Change											
Comments:	n no onango											
2017 - Fall: N	lo Change											
Comments:	o onange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09E	9x9 tan/green and orange streak flr tile	1680	SF	Rooms 111 and 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	: No Change											
Comments:	· ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09F	9x9 tan/white specks floor tile	2158	SF	Rooms 108 and 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09G	9x9 green/white specks floor tile	1080	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09H	9x9 black/white streak flr tile	840	SF	Rm 100, 110, 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	•											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											

HA No

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
12	Acoustical spray on plaster	1860	SF	Ceiling of Teachers Lounge (1957 Bldg)		Surface	Yes	Loc	3		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	V				1							
2017 - Sprine	g: No Change				-							
Comments:												
2017 - Fall: N	No Change				-							
Comments:	5											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	Baseboard			6 FT in each classroom		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	<u> </u>				1							
2017 - Spring	g: No Change				-							
Comments:	•				1							
2017 - Fall: N	No Change				-							
Comments:	J]							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
14	baseboard mastic			6 LF in each classroom		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:					_							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
15	Insulation in fire doors	8	Each	boiler room doors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J											
2017 - Spring	g: No Change				_							
Comments:	g. He enange											
2017 - Fall: N	lo Change				_							
Comments:	10 Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
16	Fire brick (incenerator)	20	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
17	Transite (incinerator)	3	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18A	Boiler gasket	40	LF	1966 boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					=							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	90											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
10,4140	Waterial Besonption	Quantity	Units	Waterial Education	Туре	Category	Tildbio	Туре	Quantity	Units	Change in 7.00cc	ooment category
18B	Boiler gasket			1957 boiler room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	go											
2017 Carina	u No Chongo											
2017 - Spring Comments:	g. No Change											
Commonts.												

		Quantity	Units		Type	Category		Type	Quantity	Units		
20	Vibration dampener cloth			1966 mechanical room, 2nd floor		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	V				1							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21A	9x9 white/green streak floor tile mastic under 12x12	1680	SF	Rooms 114 and 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	· ·				1							
2017 - Fall: N	No Change				-							
Comments:	Ŭ											

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

21B	9x9 brown/white streak floor tile mastic	881	SF	Mens toilet & teachers lounge in 1957 bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				7							
Comment	u				- -							
2017 - Fal	II: No Change				-							
Comment	S:]							
2017 - Sp	ring: No Change]							
Comment	S:				-							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA NO	Material Description	Quantity	Units	iviaterial Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
21C	9x9 grey/black and white streak floor tile mastic	3242	SF	rooms 113, 115, 110, 103, and 104		Miscellaneous	No	None	0		YES	X NO
 2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Units

Material

Quantity

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21D	9x9 tan/beige streak floor tile mastic	1680	SF	Rooms 112 and 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21E	9x9 tan/green and orange streak floor tile mastic	1680	SF	Rooms 111 and 101		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	-											
2017 - Fall: N	o Change				1							
Comments:	U											
2017 - Spring	: No Change				-							
Comments:												

21F	9x9 tan/white specks floor tile Mastic	2158	SF	Rm 108,109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	go											
2017 - Fall: [Damaged											
	BY OUTSIDE DOOR											
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21G	9x9 green/white specks floor tile mastic	1080	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change				_							
Comments:	y -											

Type

Material

Category

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21H	9x9 black/white streak floor tile mastic	840	SF	Rm 100, 110, 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	G											
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23A	9x9 tan/white streak floor tile mastic			Main office, principals office, office store room, and vault		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				7							
Comments:	J											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. 110 Onango				_							

23B	9x9 light gray/white streaks flr tile mastic	2720	SF	Rooms 115, 129, 126, 125, 216, and adjustment room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•	•	•		•	•	•	•	•		
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	-											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23C	9"x9" Beige w/ Brown Streaks VFT Mastic (abated)			Rooms 128, 127, Kitchen and 124		Miscellaneous	No				YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
24	Baseboard			Classrooms, lobby and main office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	Baseboard mastic			1962 classrooms, lobby, and main office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
26A	9x9 brown/white streak floor tile mastic	1680	SF	Room 122 and 119		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change				+							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
26B	9x9 light gray/brown & white strike floor tile mastic	3390	SF	Rooms 123, 120, 117, and 116		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				+							
Comments:												
2017 - Sprin	ng: No Change				-							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categ
26C	9x9 tan/brown and white streaks floor tile mastic	8700	SF	Rooms 105, 121, 118, 217, 218, 219, 221, 220, 223, 222, and coaches office in gym		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change										
Comments:											
				<u> </u>							
2017 - Spring	2017 - Spring: No Change										
Comments:											

Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26D	9x9 light gray/white streaks floor tile masic	1975	SF	2nd floor corridors		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26E	9"x9" Light Green Floor Tile with White Streaks Mastic	1040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:WATER DAMAGE

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Carpet mastic			Library (room 107)		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Deteriorated	
Comments:OLD, WORN,SHERREDING	

		Quantity	Units		Type	Category		Type	Quantity	Units		
28	Mastic under 1x1 acoustical ceiling tile			1966 throughout corridors and all purpose room		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	J											
2017 - Spring	g: No Change											
Comments:	g. 140 Onlango				-							
2017 Fall: F	Domogod											
2017 - Fall: D	Jamaged MULTI AREA DAMAGE	D			_							
					<u> </u>							
	Two dipoles		T. s. s. s. s. s.	I se e e e		T	Levis	T 5	T 5	T 5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
29	Mastic under 1x1 acoustical			1962 classrooms, office and corridors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	·											
2017 - Fall: [Damaged				-							
	MULTI AREA DAMAGE	D			-							
]							

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	Mastic under 1x1 acoustical ceiling tile			1957 classrooms and library		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
31	Baseboard			1957 bldg - 6 LF in each classroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	-											
2017 - Spring	: No Change											
Comments:	-											
2017 - Fall: D	eamaged											
	ULTI AREA DAMAGE	D										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	Baseboard mastic			1957 bldg - 6 LF in each classroom		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
33	window glazing			throughout 1966 bldg windows		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	g: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:												

34	Plaster	67000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							
Comments												
	ng: No Change											
Comments	:											
2017 - Fall	Damaged											
Comments	:CEILING DAMAGES											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
35	Brown, Tan and White Ceramic Tile Grout	25	SF	Teacher's Longe Toilet (Room 148)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

2017 - Fall: No Change

Comments:

Material Description

36	Brown, Tan and White Ceramic Tile Adhesive	25	SF	Teacher's Longe Toilet (Room 148)		Miscellaneous	No	None	0		YES	X NO
	2016 - Fall: No Change Comments:											
2017 - Spri	ing: No Change]							
2017 - Fall:												
Comments	SKEATTECHED				<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Damaged	
Comments:BY OUTSIDE DOORS	

352

Material

Quantity

Material

Units

SF

Material Location

Rooms 106, 108, 109,

and Principal's Office

Toilet

HA No

37

Material Description

Grey and Green Ceramic

Tile Grout

38	Grey and Green Ceramic Tile Adhesive	352	SF	Rooms 106, 108, 109, and Principal's Office Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	1	Į.	10101	1	!	!	!		-		
Comments												
2017 - Spr	ing: No Change				_							
Comments	_ · · ·]							
2017 - Fall	: No Change											
Comments):											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	Grey Carpet Mastic	728	SF	Room 114		Miscellaneous	No	None	0		YES X NO

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
40	Purple and Grey Ceramic Tile Grout	280	SF	North Center Girls Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
41	Purple and Grey Ceramic Tile Adhesive	280	SF	North Center Girls Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	-											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											

43	12 x 12 Dark Blue Floor Tile	575	SF	Gym Stage and Gym Storage Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	to onango											
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
43M	12 x 12 Dark Blue Floor Tile Mastic	575	SF	Gym Stage and Gym Storage Room		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

44	Brown and White Ceramic Tile Grout	1148	SF	SE Boys and Girls Restrooms and 2nd Floor Boys Restroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change		*]		•	•	•	•		
Comments												
0047 0	's Ne Obsesse											
	ing: No Change											
Comments	S:											
2017 - Fall	: No Change				1							
Comments);											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Brown and White Ceramic Tile Adhesive	1148	SF	SE Boys and Girls Restrooms and 2nd Floor Boys Restroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

46	2 x 4 White Ceiling Tile	13472	SF	Rooms 116 - 123, and 216 - 223		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N	No Change]						
Comments:					-						
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:	·			·							

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
47	9 x 9 Tan Speckled Floor Tile	1448	SF	Main Office and Assistant Principals Office		Miscellaneous	Yes	Loc	6		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

47M	12 x 12 Tan Speckled Floor Tile Mastic	1448	SF	Main Office and Assistant Principals Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	g: No Change									
2017 - Fall: N Comments:	lo Change									

Asbestos

Type

Material

Category

Material

Friable

Friable

Damage

Damage

Type

Damage

Quantity

Damage

Damage

Damage

Units

1		Quantity	Units		Туре	Category		Туре	Quantity	Units	
48	Light Grey Ceramic Tile Grout	504	SF	Lobby Boys and Girls Restrooms		Miscellaneous	No	None	0		YES
2016 - Fall: N	lo Change]						
Comments:	<u> </u>										
2017 - Fall: Damaged											
Comments:F	Comments:FLOOR TILE FROM DRAIN REPAIR										

2017 - Spring: No Change

Comments:

HA No

HA No

Material Description

Material Description

Material

Material

Units

Material

Quantity

Material

Material Location

Material Location

Change in Assessment Category

Change in Assessment Category

X NO

49	Light Grey Ceramic Tile Adhesive	504	SF	Lobby Boys and Girls Restrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J				- -							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change				1							
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
50	Grey Speckled Terrazzo	7525	SF	Throughout School Corridors, except 2nd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: D	Deteriorated				_							
Comments:WORN AT STAIRS AND ENTRYS												
2017 - Spring: No Change												
Comments:	1 0											

Category

Asbestos

Type

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage Quantity

Damage

Units

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51	12" X 12" blue-streaked VFT	1600	SF	Rooms 102 and 112		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments												
2017 - Fall:	No Change											
Comments												
2017 Cpri	na: No Chongo				_							
Comments	ng: No Change				_							
Comments	•											
						_	•			•		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51A	12" X 12" blue-streaked, Mastic	1600	SF	Rooms 102 and 112		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments												
2017 Falls	No Changa				_							
Comments	No Change											
Comments	•											
2017 - Spri	ng: No Change	•	·									
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
52	12" X 12" tan streaked VFT	3800	SF	Room 107/Library Rooms 114 and 133 Rooms 116/117 (Lunchroom)		Miscellaneous	No	None	0		YES	Х NO
2016 - Fall:	No Change											
Comments:	Ţ.											
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
52A	12" X 12" tan-streaked, Mastic	3800	SF	Room 107/Library Rooms 114 and 133 Rooms 116/117 (Lunchroom)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
53	12" X 12" white-streaked VFT	100	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•										
Comments:												
2017 - Sprin	g: No Change											
Comments:	 											
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
53A	12" X 12" white-streaked, Mastic	100	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	•											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	ig. No Change											
Louinnents.												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
54	12" X 12" blue VFT	80	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
		_										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
54A	12" X 12" blue, Mastic	80	SF	Coach's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					_							
	g: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
01E	9"x9" Light Green w/White Streaks Floor Tile	1040	SF	Gym Storage Room, Janitor Closets, Second Floor Storage, Stage Entrances, Storage Room by Stage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
9
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	Preform insulation- breaching	25	LF	Boiler room-1966 bldg		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED

В	Hard fittings on fiberglass insulation	150	LF	throughout 1966 bldg boiler room and corridors		TSI	Yes	Loc	0		YES	X NO
2016 - Fall	: No Change				1							
Comments					+							
Comments).				1							
2017 - Spr	ing: No Change											
Comments												
					1							
	: No Change											
Comments	S:											
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
	Hard fittings on fiberglass			Throughout 1957 bldg First Floor Boiler Room							YES	X NO
С	insulation	150	LF	(on pipe near E wall) and		TSI	Yes	Dist	5			INO

Type

Material

Category

Friable

Damage

Туре

С	insulation	150	LF	(on pipe near E wall) and corridors
2016 - Fall	: No Change			
Comments	•			
2017 - Spri	ng: No Change			
Comments				
2017 - Fall	: No Change			
Comments				

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

D	Preform boiler breeching	50	LF	1957 boiiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: D	Damaged											
	IULTI AREA DAMAGE	:D										
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
E	Boiler insulation mag block	450	SF	1957 boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: D)amaged											
	NDER SIDE EXPOSE	D]							
2017 - Spring	r. No Change				-							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	Hard fittings on fiberglass insulation	125	LF	1962 bldg throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:	_				=							
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Spray-on Fireproofing	1700	SF	1966 - Boiler Room and 2nd Floor Mechanical Room		Surface	Yes	Dist	300		YES	X NO
2016 - Fall: N	o Change				1							
Comments:												
2017 - Spring	: No Change				-							
Comments:	i i i o o nango											
2017 - Fall: N	o Change				=							
Comments:	o onange											
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Н	12"x12" Blue Floor Tile	500	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: D)amaged											
	IULTI AREA DAMAG	ED										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	12"x12" Blue Floor Tile Mastic	500	SF	Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change						•		•			
Comments:	go											
2017 - Spring	ı: No Change											
Comments:	J											
2017 - Fall: D)amaged											
	BOVE SMALL FREE	ZER										

J	1'x1' Acoustic Ceiling Tile	9500	SF	1966 - Corridors and All Purpose Room	Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: R Comments:TI	epaired LES REPLACED									

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

1966 - Corridors and All

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	1'x1' Acoustic Ceiling Tile	7700	SF	1962 Classrooms and Corridors - Except in Rooms 116, 117, 118, 119, 120, 121, 122, 123, 216 and 217		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Damaged	
Comments:MULTI AREA DAMAGED	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
L	1'x1' Acoustic Ceiling Tile	7700	SF	1957 Classsrooms and Library		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Damaged
Comments:MULTI AREA DAMAGED

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John Whistler Elementary School
Date:12/10/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.