Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

25991

Oracle Unit:

Address: 4251 N Clarendon Avenue Region: 01 Mail Room: 32 Asbestos Surveyor: Dye, Ms. Venguanette X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 2/2/2018 Email Address: vdye@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Material Damage Quantity Units Type Category Type Quantity West Hallway, Kitchen, YES X NO 01 Hard Coat Plaster SF No 10000 Gym Foyer, 1st Floor Surface None 0 Corridor - 1963 Bldg. 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Joseph Brennemann Elementary School

School:

6600

Building ID:

02	Acoustical Plaster	2500	SF	Rooms 125 & 126, Kitchen Hallway, Lunchroom - 1963 Bldg.		Surface	No	None	0	YES	X NO
2016 - Fall: N	lo Change]				·		
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring Comments:	: No Change										
	·			·]						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	12"x12" Beige w/Brown & White Streaks VFT	7600	SF	Rooms: 101,102, 112, 113, 120, 121, 122, 123 & 124, Foyer outside All Purpose Room, 103, 104, (under carpet) - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

		,				0,			,			
07	2'x4' White Ceiling Tile	2500	SF	1st Fl: Rms. 001,002,003 & 004; Teacher's Toilet;Electric Closet - 1970 Bldg.		Miscellaneous	Yes	None	0		YES	Х NO
2016 - Fal	I: No Change				1							
Comments	Ţ											
2017 - Fal	I: No Change											
Comments	Ţ											
2017 - Spr	ring: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
08	2'x2' White Ceiling Tile	4050	SF	All purpose Room - 1963 Bldg.		Miscellaneous	Yes	Loc	60		YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Fal	I: No Change				-							
Comments												
					4							

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	2'x4' Pressboard Ceiling Tile	1800	SF	Rooms: 101, 114 & 124 - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: I	No Change]						
Comments:											
2017 - Fall: I	No Change				-						
Comments:											
2017 - Sprin	g: No Change				-						
Comments:											
					J						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" White w/Brownish Streaks VFT Mastic- Not Observed	420	SF	1st Floor Annex Connection Hallway - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: I	No Change				1						
Comments:]						
2017 - Fall: I	No Change										

Comments:

Comments:

2017 - Spring: No Change

		Quantity	Units		Type	Category		Type	Quantity	Units		
11	Cove Base Mastic	1800	SF	Rooms: 107, 110 & 118 - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:					=							
2017 - Sprir	ng: No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
11A	Brown Cove Base Mastic	1100	LF	Rooms: 001, 002 & 004 - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:]							
					_							

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" Beige w/Brown & White Streaks VFT Mastic	7600	SF	Rooms: 101,102, 112, 113, 120, 121, 122, 123 & 124, Foyer outside All Purpose Room, 103, 104, (under carpet) - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White w/Brownish Streaks VFT- NOT OBSERVED	0	SF	1st Floor Annex Connection Hallway - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
16	12"x12" Brown w/White & Dark Brown Streaks VFT	7800	SF	Rooms: 106, 107, 108, 109, 110, 111, 114, 115, 116, 117, 118, 119 - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	J											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ıg: No Change											
Comments:	.g to onallgo											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
16A	12"x12" Brown w/White & Dk Brown Strks VFT Mastic	7800	SF	Rooms: 106, 107, 108, 109, 110, 111, 114, 115, 116, 117, 118, 119 - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	. to change											
2017 - Sprin	ıg: No Change											
Comments:	ig. No Change				1							

2017 - Fall: No Change

Comments:

	•	'	Type	Category		Type	Quantity	Units	
2" Beige w/White & 6418 CRVED	18 SF	South, North & West Hallways - 1963 Bldg. VFT not observed - Assumed under existing VFT		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17A	12"x12" Beige w/White & Brown Streaks VFT Mastic- NOT OBSERVED	6410	SF	South, North & West Hallways - 1963 Bldg. Not observed - Assumed under existing VFT		Miscellaneous	No	None	0		YES X NO

_	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

18	12"x12" Light Brown w/Light Streaks VFT	2000	SF	Rooms 125 & 126, Lunchroom - 1963 Bldg.		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:					-						
2017 - Fall:											
Comments:					-						
	ng: No Change										
Comments:											
					J						

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18A	12"x12" Light Brown w/Light Streaks VFT Mastic	2000	SF	Rooms 125 & 126, Lunchroom - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change	•		_]						

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

19	12"x12" Brown w/Light Streaks VFT	2000	SF	Rooms 125 & 126, Lunchroom 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change]							
Comment					1							
2017 - Fa	II: No Change				1							
Comment	is:				1							
2017 - Sp	ring: No Change											
Comment	ts:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sment Category
19A	12"x12" Brown w/Light Streaks VFT Mastic	2000	SF	Rooms 125 & 126, Lunchroom- 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Comments:	o Change											

Comments:

HA No

Material Description

Material

Quantity

Material

Units

2017 - Fall: No Change Comments:

2017 - Spring: No Change

20	9"x9" Black w/Beige Streaks VFT	120	SF	Engineer's Office - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fal	II: No Change]						
Comment	S:]						
2017 - Fal	II: No Change				_						
Comment	S:										
2017 - Sp	ring: No Change										
Comment	s:				1						
					J						
LIA NI-	Material December	Matarial	Matarial	Metavial Lagation	A = = = + = =	Matarial	Estable.	Damas	Damas	D	Change in Assessment Catagonic

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sment Category
20A	9"x9" Black w/Beige Streaks VFT Mastic	120	SF	Engineer's Office - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											

2017 - Spring: No Change Comments:

Material Description

2017 - Fall: No Change Comments:

HA No

Material

Units

Material

Quantity

Material Location

21	12"x12" Black w/Light Streaks VFT	30	SF	West Stage Hallway - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	J.											
2017 - Fal	ll: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21A	12"x12" Black w/Light Streaks VFT Mastic	30	SF	West Stage Hallway - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12"x12" Black w/White Streaks VFT	24	SF	Basement: Storage/Locker Room - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change								Ĭ		
Comments:											
2017 - Fall: N	lo Change										

2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22A	12"x12" Black w/White Streaks VFT Mastic	24	SF	Basement: Storage/Locker Room - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

23	12"x12" Brown w/Light Brown & White Streaks VFT	2200	SF	Rooms 001, 002, 003 & 004 - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change	•	•	•]	•	•	•	•	•	•	
Commen												
2017 - Fa	all: No Change				_							
Commen	ts:											
2017 - S	oring: No Change											

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	12"x12" Brown w/Lt Brown & White Stks VFT Mastic	2200	SF	Rooms 001, 002, 003 & 004 - 1970 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25	12" x 12" Green VFT	40	SF	Electric Closet - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change											
Comments	S:											
2017 - Fall	I: No Change											
Comments	S:											
2017 - Spri	ing: No Change											
Comments	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
25A	12"x12" Green VFT Mastic	1910	SF	Electric Closet - 1970 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Spri	ing: No Change											
Comments												
2017 - Fall	017 - Fall: No Change											
Comments												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	12" x 12" Blue VFT (under existing VFT)	850	SF	West Hallway (under existing VFT) -1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change	•										
Comments:	o Change											
2017 - Fall: N	o Change											
Comments:												

Н	A No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
26	6A	12" x 12" Blue VFT Mastic (under existing VFT)	850	SF	West Hallway (under existing VFT) -1963		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	12"x12" White w/Blue & Red Strks VFT	175	SF	Mens Toilet, Womens Toilet, Room 125 Toilet, Room 126 Toilet - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	•											
2017 - Fall:	No Change				1							
Comments:												
2017 - Sprir	ng: No Change											
Comments:	ig. 140 Ondrigo				1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27A	12"x12" Wht w/Blue-Red VFT Mastic	175	SF	Mens Toilet, Womens Toilet, Room 125 Toilet, Room 126 Toilet - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Sprin	ng: No Change				-							
Comments:	ig. No Change				-							

2017 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28	9 x 9 inch Beige w/Black Streaks VFT	30	SF	Rooms 125, 126 Coat Room/Book Shelves - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 Fall:	No Chango			· -	7		• -	•			

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
28A	9 x 9 inch Beige w/Blk Streaks VFT Mastic	30	SF	Rooms 125, 126 Coat Room/Book Shelves - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	Fire Doors	9	EA	All-purpose Rm (6 units); Boiler Rm (2 units); To Eng. Hall (1unit); All units in 1960 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	y											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
30	Vinyl Baseboard Mastic	2500	LF	Throughout 1963 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	io onango											
2017 - Fall: N	lo Change				-							
Comments:	to orialigo				1							
					1							

2017 - Spring: No Change

Comments:

31	Carpet Mastic	800	SF	Office, Counselor's Office (1963 Bldg)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	110 Change											
2017 - Fall:	No Change											
Comments:					-							
2017 - Sprir	ng: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
32	2'X4' Ceiling Tiles	5000	SF	All Classrooms, 1963 Bldg		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:					1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
35	Vinyl Baseboard Mastic	800	SF	Throughout 1970 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change				+							
Comments:	. rto Griango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
1,,,,,,	Material Boochpilon	Quantity	Units	Waterial Education	Туре	Category	Tildbio	Туре	Quantity	Units	onango in 71000	oomoni Galogoly
36	Wall Panelling	6000	SF	Throughout 1970 Bldg		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	_											
2017 - Fall: N	o Change				-							
Comments:	o onango											
2017 Caring	. No Chango											
2017 - Spring Comments:	. No Change											
Commond.					_							

		-							-			
37	Spray-on Fireproofing	8600	SF	Boiler Rm Ceiling and Throughout 1963 BLDG (above ceiling tiles/panels)		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>]							
2017 - Fall:	No Change				}							
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
38	12"x12" Tan w/ white streaks VFT	1400	SF	Rooms 125 & 126 - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	·		·]							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
38A	12"x12" Tan w/ white streaks VFT MASTIC	1400	SF	Rooms 125 & 126 - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	ı: No Change											
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				-							
Comments:	io oriango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39	12"x12" Red VFT	2500	SF	Teachers' lounge , hall by GYM, all corridors 1963 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	.o onango											
2017 - Fall: N	lo Change				=							
Comments:	io Change				-							
	No. Ohanan											
2017 - Spring Comments:	g: No Change				-							
Comments.					1							

39A	12"x12" red VFT MASTIC	2500	SF	Teachers' lounge , hall by GYM, all corridors 1963 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			•]	•	•	•	•	•		
Comments:	V											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					J							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Units Units	Change in Assessment Category
40	12"x12" white w/ gray shadows VFT	8000	SF	Throughout Corridors and Hall by Gym - 1963 Bldg.		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
40A	12"x12" white w/ gray shadows VFT MASTIC	8000	SF	Throughout Corridors and Hall by Gym - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	n: No Change											
Comments:	<u>,g</u> -											
2017 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
41	Drywall system	260	SF	Girls and boys washrooms - 1963 Bldg.		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to orialige											

42	12"x12" white w/ light blue & black design VFT	60	SF	Unisex toilet - 1963 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Sprir Comments:	ng: No Change											
2017 - Fall: Comments:	No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

60

Material

Quantity

Material

Units

SF

Material Location

Unisex toilet - 1963 Bldg.

HA No

42A

Material Description

12"x12" white w/ light blue

& black design

		Quantity	Units		Type	Category		Type	Quantity	Units		
43	Carpet MASTIC	1500	SF	Library made up of rooms 103 and 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments): :											
2017 - Spr	ing: No Change											
Comments	S:											
	: No Change											
Comments): -				 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
44	Linoleum white, green & red design- REMOVED SUMMER 2013			Girls' and boys' washrooms		Miscellaneous					YES	X NO
2016 - Fall	: No Change]							
Comments	:											
2017 - Spr	ing: No Change				-							
Comments	:											
	: No Change											
Comments):											
					J							

Asbestos

Damage

Friable

Damage

HA No

Material Description

Material

Material Location

Damage Change in Assessment Category

44A	Linoleum white, green & red design MASTIC- REMOVED SUMMER 2013	3		Boys' and Girls' washrooms		Miscellaneous					YES	X NO
2016 - Fall	: No Change				\neg							
Comments												
2017 - Spr	ing: No Change											
Comments												
2017 - Fall	: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45	12" x 12" Red VFT	200	SF	Corridor- 1970 BLDG		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change							•	•			
Comments	Ţ											
2017 - Spr	ing: No Change											
Comments	:											
2017 - Fall	: No Change				\dashv							

Type

Material

Category

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
45A	12" x 12" Red Mastic	200	SF	COrridor- 1970 BLDG		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
46	Blue Vinyl Flooring Mastic	800	SF	Room 105- 1963 BLDG		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	, J											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
					╛							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
47	Tectum Ceiling Panels	2500	SF	North, Center and South Corridors- 1963 BLDG		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	Heat Reflector Shields	360	LF	West Hall - 1963 Bldg.		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
]							

Е	MJP E/F/V on Fiberglass Pipe Insulation	130	LF	Throughout Basement (See Hatching Maps) - 1963 Bldg		TSI	Yes	None	0		YES	X NO
		•	•	•	·	•	•	-	•	-		
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	Water Main Packing Abated			Basement: Boiler Room - 1963 Bldg.		TSI		None			YES	X NO
2016 - Fall: N	lo Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
G	Aircell Pipe Insulation (Abated)			Basement: Boiler Room - 1963 Bldg.		TSI					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Н	MJP E/F/V on Aircell Pipe Insulation (Abated)			Basement: Boiler Room - 1963 Bldg.		TSI					YES	X NO
2016 - Fall: N	No Change]							
Comments:					1							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:					-							
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

I	Tank Insulation	90	SF	Boiler Room - 1963 Bldg.	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
К	MJP E/F/V on Fiberglass Pipe Insulation	60	LF	Girl's Toilet Utility & Boy's Toilet Utility - 1970 Bldg.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

L	Vibration Damper	100	SF	Air Handling Duct Boiler Room, Fan Storage Room & Engineer's Hallway - 1963 Bldg.		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:													
2017 - Fall: No Change													
Comments:													
2017 - Spring: No Change													
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
М	Acoustic Plaster Ceiling	3000	SF	Corridors- 1963 bldg		Surface	Yes	None	0		YES		X NO
2016 - Fall: I	No Change	-			<u>'</u> 1	1	•	1	•		•		
Comments:													
2017 - Fall: No Change													
Comments:													
					-1								

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: _Joseph Brennemann Elementary School
Date: <u>2/2/2018</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.