Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

26091

Oracle Unit:

Address: 431 North Troy Street Region: 02 Mail Room: Asbestos Surveyor: Robinson, Zurbanus X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 11/16/2017 Email Address: zrobinson8@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Type Quantity YES 01 SF 2 X NO 9"x9" Brown VFT 2400 Miscellaneous No Auditorium Loc 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Morton School of Excellence

School:

6800

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
02	12"x12" Taupe VFT (ABATED 2008)			1st Fir Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402 ABATED 2008							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	- Consuming of											
2017 - Spring	g: No Change											
Comments:	g. 140 Onlange											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07	9"x9" Brown VFT Mastic	2400	SF	Auditorium		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change	•			1							
Comments:	5											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 Spring	y: No Chango											
Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
08	12"x12" Taupe VFT Mastic (ABATED 2008)			1st Fir Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 211, 212, 303, 306, 307, 402 (ABATED 2008)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
09	9"x9" Gray VFT (ABATED)			Lunchroom, Attendance Office, Room 106 - 1st Floor Storage ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					J							

10	9"x9" Gray VFT Mastic (ABATED)			Lunchroom, Attendance Office, Room 106 ABATED		Miscellaneous					YES	X NO
2016 - Fall:	No Change				1							
Comments:	ito chango											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change				_							
Comments:	ig. No Change											
Comments.					4							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	12"x12" Cream VFT (ABATED)			1st Flr Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402ABATED							YES	X NO
2016 - Fall:	No Change				1							
Comments:	110 Gridingo				1							
2017 - Fall:	No Chango				}							
Comments:	No Change											
Comments.					1							
2017 - Sprin	g: No Change				1							
Comments:	<u> </u>				1							

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	12"x12" Cream VFT Mastic (ABATED 2008)			1st Fir Corr., Rm 103, 109, Main Off, Tchrs Lunchrm, 201-203, 205- 207, 211, 212, 303, 306, 307, 402 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments	•				1							
2017 - Fall:	No Change				-							
Comments					1							
2017 - Spri	ng: No Change				-							
Comments												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	12"x12" Brown w/ Rust Streaks VFT (ABATED 2008)			Corridor Outside Auditorium, Room 304 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall:	No Change				7							
Comments												
2017 - Fall:	No Change				-							
Comments												
2017 - Spri	ng: No Change				-							
Comments					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	12"x12" Brown w/ Rust Streaks VFT Mastic (ABATED 2008)			Corridor Outside Auditorium, Room 304 ABATED 2008							YES	X NO
2016 - Fall: I	No Change				\neg							
Comments:	10 Griange											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	5											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	12"x12" Sand VFT (ABATED 8/22/08)			Room 110, 2nd Floor Corridor, Room 305		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change				_							
Comments:												
2017 - Sprin	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12"x12" Sand VFT Mastic (ABATED 2008)			Room 110, 2nd Floor Corridor, Room 305 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	<u> </u>											
2017 - Spring	· No Change				_							
Comments:	. No Change				_							
]							
HA No	Motorial Description	Motorial	Motorial	Material Location	Ashaataa	Motorial	Frieble	Domoseo	Domoseo	Domoso	Change in Asset	nament Catagoni
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	12"x12" Beige VFT (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:	o Change				1							
2017 - Spring	: No Change											
Comments:					-							
					_							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
18	12"x12" Beige VFT Mastic (ABATED 2008)			Main Entrance, 1st Floor Corridor ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	9"x9" Dark Gray VFT (ABATED 2008)			2nd Floor Corridor, 4th Floor Corridor, Room 204		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Type Quantity Units Damage Quantity Units Priable Type Quantity Units Type Type Type Quantity Units Type Type Type Type Type Type Type Type	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Damage Quantity Units No Change Comments: 21 9"x9" Light Green VFT (ABATED 2008) Miscellaneous Mi	20	9"x9" Dark Gray VFT Mastic (ABATED 2008)			Corridors, Room 204		Miscellaneous					YES	X NO
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Type Quantity Units Miscellaneous Damage Quantity Units Miscellaneous Damage Type Damage Quantity Units Miscellaneous Damage Type Quantity Units Miscellaneous Damage Type Damage Quantity Units Miscellaneous Damage Type Quantity Units Miscellaneous Damage Change in Assessment Category 21 9°x9° Light Green VFT (ABATED 2008) Miscellaneous Miscellaneous Miscellaneous Miscellaneous Miscellaneous Damage Change In Assessment Category 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change		lo Change											
Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Quantity Units Material Location Type Category Type Quantity Units Miscellaneous Damage Quantity Units Vest No 21 9'X9" Light Green VFT (ABATED 2008) Miscellaneous Miscellaneous Damage Type Quantity Units Vest No 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	Comments:												
Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Type Category 21 9°X9° Light Green VFT (ABATED 2008) Miscellaneous Damage Type Quantity Units Vinits No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:	2017 - Fall: N	lo Change											
HA No Material Description Material Quantity Units Material Location Type Category Type Damage Quantity Units Damage Quantity Units Type Category Type Quantity Units Type Category Type Quantity Units Type Q	Comments:	Ü											
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Quantity Units Damage Quantity Units Pres X No 21 9°x9° Light Green VFT (ABATED 2008) Miscellaneous	2017 - Spring	r: No Change											
HA No Material Description Material Quantity Units Material Location Type Category Friable Damage Type Quantity Units Change Change in Assessment Category 21 9"x9" Light Green VFT (ABATED 2008) Miscellaneous Mis		g. No Change											
Type Category Type Quantity Units 21 9"x9" Light Green VFT (ABATED 2008) 2nd Floor Corridor ABATED 2008 Miscellaneous Miscellaneous 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change													
Type Category Type Quantity Units 21 9"x9" Light Green VFT (ABATED 2008) 2nd Floor Corridor ABATED 2008 Miscellaneous Miscellaneous 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	15,770	Waterial Boothplion			Material Education			THADIO				Griange in 7,000	comonic catogory
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	21						Miscellaneous					YES	X NO
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	2016 - Fall: N	lo Change											
Comments: 2017 - Spring: No Change	Comments:	go											
Comments: 2017 - Spring: No Change	2017 Fall: N	lo Chongo											
2017 - Spring: No Change		io Change											
Comments:		g: No Change											
	Comments:												

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments: 2019 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Change In Assessment Category 23	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Miscellaneous	22						Miscellaneous					YES	X NO
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Miscellaneous	2016 - Fall: N	No Change]							
Comments: 2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Miscellaneous Miscel	Comments:	V											
2017 - Spring: No Change Comments: HA No Material Description Material Quantity Units Material		No Change				_							
Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Type Quantity Units Throughout (See Hatching Maps) ABATED 2008 23 9° x 9° Beige VFT (ABATED 2008) Miscellaneous Miscellaneo	Comments:												
Comments: HA No Material Description Material Quantity Units Material Location Type Category Friable Type Quantity Units Throughout (See Hatching Maps) ABATED 2008 23 9° x 9° Beige VFT (ABATED 2008) Miscellaneous Miscellaneo	2017 - Sprine	g: No Change				_							
Quantity Units Type Category Type Quantity Units Type Category Type Quantity Units Type Quantity Units Miscellaneous Type Quantity Units Type Quantity Units Miscellaneous Type Quantity Units Type Quantity Units Miscellaneous Type Quantity Units Type Quantity Units Type Quantity Units Miscellaneous Type Quantity Units Type Quantity Quantit	Comments:	<u>g</u>											
Quantity Units Type Category Type Quantity Units Type Category Type Quantity Units Throughout (See Hatching Maps) ABATED Miscellaneous Type Quantity Units Throughout (See Hatching Maps) ABATED Miscellaneous Type Quantity Units Type Xx No 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change													
23 9 8 9 8 9 8 9 9 9 9 9 9 9 9 9 9 9 9 9	HA No	Material Description			Material Location			Friable				Change in Asse	essment Category
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	23				Hatching Maps) ABATED		Miscellaneous					YES	X NO
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change	2016 - Fall: N	No Change				1							
Comments: 2017 - Spring: No Change	Comments:					=							
Comments: 2017 - Spring: No Change	2017 - Fall: N	No Change											
	Comments:												
	2017 Caria	a: No Chango											
		g. No Change											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
24	9"x9" Beige VFT Mastic (ABATED 2008)			Throughout (See Hatching Maps) ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	Ü											
2017 - Spring	r. No Change											
Comments:	,go											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
25	9"x9" Dark Green VFT (ABATED 2008)			Kitchen, Elevator ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				=							
Comments:	g. 140 Offarige											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	9"x9" Dark Green VFT Mastic (ABATED 2008)			Kitchen, Elevator ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	9"x 9" Moss Green VFT (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	9"x9" Moss Green VFT Mastic (ABATED 2008)			Rooms 101, 108 ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	Interior Window Caulk	250	EA	Interior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	<u> </u>											

32	12 x 12 inch Gray w/ White & Brown Streaks VFT (ABATED 2008)	Elevator ABATED 2008		Miscellaneous					YES	X NO
2016 - Fa	II: No Change	<u> </u>	1							
Comment	S:]							
2017 - Fa	II: No Change		-							
Comment	S:									
2017 - Sp	ring: No Change		-							
Comment	S:									
			J							
HA No	Material Description Material	rial Material Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Туре	Quantity	Units	Change in Assessment Gategory
32 A	12 x 12 inch Gray w/ White & Brown VFT Mastic (ABATED 2008)			Elevator ABATED 2008		Miscellaneous					YES X NO
2016 - Fall: Comments:	No Change										

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Units

Material

Quantity

Material Location

HA No

Material Description

12 x 12 inch Gray w/ White

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	Carpet Mastic (ABATED 2008)			Rooms 102, 103, Main Office ABATED 2008		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	12 x 12 inch Brown w/Yellow Streaks VFT	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. 110 Chango											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34 A	12 x 12 inch Brown w/ Yellow Streaks VFT Mastic	80	SF	Gymnasium Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					1							
2017 - Fall: N	o Change											
Comments:					1							
2017 - Spring	: No Change											
Comments:	<u> </u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12 x 12 Burgundy Floor Tile	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	•				1							
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:					=							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35A	12 x 12 Burgundy Floor Tile Mastic	4000	SF	Throughout 2nd and 4th Floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:	_											
2017 - Spring	: No Change				-							
Comments:	Ţ.											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	12 x 12 Light Blue Floor Tile	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Fall: N	o Change				<u> </u>							
Comments:												
2017 - Spring	: No Change											
Comments:												
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
36A	12 x 12 Light Blue Floor Tile Mastic	4000	SF	Throughout 3rd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	12 x 12 Beige Floor Tile	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	3											
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37A	12 x 12 Beige Floor Tile Mastic	31500	SF	Throughout 1st Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
38	12 x 12 Blue Floor Tile	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change				-							
Comments:					1							
2017 - Fall: N	lo Change				-							
Comments:	J											
					_							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
38A	12 x 12 Blue Floor Tile Mastic	4500	SF	Lunchroom and Kitchen & Throughout 1st Floor		Miscellaneous	No	None	2		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39	Incinerator Insulation	50	SF	Engine Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	ng: No Change				-							
Comments:]							
					J							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	Black Spray on Under Sink Coating	20	SF	Room #304 Art Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	Boiler Rope Gasket	40	LF	Boiler/Engine Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				_							
Comments:	J											
2017 - Fall: N	o Change				<u> </u>							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	Vinyl Baseboard Mastic/Adhesive	4500	LF	Throughout Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	Mag Block Tank Insulation	300	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:]							
					_							

С	MJP E/F/V on Fiberglass Pipe Insulation	657	LF	Boiler Room & Above Suspended Ceiling Tiles Throughout 1st - 4th Floors		TSI	Yes	None	0	YES	X NO
2016 - Fall:	No Change										
Comments											
2017 - Fall:	No Change										
Comments											
2017 - Spri	ng: No Change										
Comments											
					1						

Category

Asbestos

Type

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	KILN	15	LF	Throughout 1st Floor & 1st Floor Storage Room		Miscellaneous	Yes	None	0		YES X NO

·		
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		

Material

Quantity

Material

Units

Material Location

HA No

Material Description

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Morton School of Excellence
Date: 11/21/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.