

Chicago Public Schools

6 Month Asbestos Surveillance

2017 - Fall

School: George Leland Elementary School
Address: 512 S. Lavergne

Oracle Unit: 26391
Region: 03

Building ID: 4670
Mail Room: 36

CHECK HERE IF NO CHANGE TO ASBESTOS

Asbestos Surveyor: Baez, Mr. Esteban
Survey Date: 10/11/2017
Email Address: ebaez1@cps.edu

A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via:
 Each child's backpack
 Notice printed in school's newsletter
 Notice printed in school's calendar
 Other

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 2 | Acoustical Wall Plaster | 20000 | SF | 1969 Building | | Surface | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3 B | 12" x 12" Beige Floor Tile | 1000 | SF | 1970 Corridor, Faculty Lounge and Room 509, 506 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3 C | 12" x 12" Light Gray and Brown Floor Tile | 2100 | SF | 1970 Corridor, 504, 507 and 510 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 3A | 12" x 12" White Floor Tile | 2400 | SF | Rooms 502, 503 and 505 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 4 | 12" x 12" Brown Floor Tile | 480 | SF | Kitchen of Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 6 | 2' x 4' Ceiling Tile | 800 | SF | 1970 Building Annex | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 7 | Hard Joint Compound on Fiberglass Insulated Pipes | 50 | LF | 1970 Building | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8 A | Fiberglass Ceiling Insulation | | | 1970 Building | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 8 B | Fiberglass Roof Insulation | | | 1970 Building | | TSI | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 A | 12" x 12" Beige Floor Tile | 100 | SF | Rooms 303, 307, 310 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 10 B | 12" x 12" Green/Brown (Green) Floor Tile | 940 | SF | 4th Floor Corridor and Maintenance Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 15 A | Drywall | | | 1969 Corridors and Room 401 - Trailer removed in 2012 | | | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 16 | 9" x 9" Dark Brown Floor Tile | 170 | SF | Basement Custodial Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 17 | 12" x 12" Light Brown Floor Tile | 700 | SF | Basement Lunch Room-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 18 | 12" x 12" Dark Brown Floor Tile Mastic | 700 | SF | Basement Lunch Room-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 A | 9" x 9" Light Brown Floor Tile | 28000 | SF | Rooms 111-117,210-217,311-317,1st Fl Janitor's Closet,2nd Fl Washroom,3rd Fl Teacher WashRm & Lounge | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 B | 9" x 9" Dark Brown Floor Tile w/ White Streaks | 2250 | SF | 1966 Corridors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19 C | 9" x 9" Light Brown Floor Tile Mastic | 27750 | SF | Rooms 111-117,211-217,311-317,1st Fl Janitor's Closet,2nd Fl Washroom,3rd Fl Teacher WashRm & Lounge | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 19D | 9" x 9" Light Brown Floor Tile | 2250 | SF | 1966 Corridors and Women's Teacher's Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 20 | 12" x 12" Light Brown Floor Tile | 2500 | SF | Rooms 101 & 102, 207 and Engineer's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 | 9" x 9" Taupe Floor Tile | 1800 | SF | Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 B | 12" x 12" Dk. Blue Floor Tile | 1500 | SF | Main Office, 209, 305 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 21 C | 12" x 12" Dk. Blue Floor Tile Mastic | 2500 | SF | Main Office, 305 and 209 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 22 | 12" x 12" Yellow Floor Tile | 2800 | SF | Auditorium, Teacher's Lounge, Rooms 201, 206, 303 & 306 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 | 12" x 12" Brown w/White Streaks Floor Tile | 280 | SF | Teacher's Lounge | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23 B | 9" x 9" Green Floor Tile | 2250 | SF | Lunch Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 23A | 9" x 9" Off-White Floor Tile | 2250 | SF | Lunch Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 | 12" x 12" Brown w/White Streaks Floor Tile Mastic | 280 | SF | Teacher's Lounge | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 A | 12" x 12" White Floor Tile w/ Green Streaks | 1000 | SF | Rooms 207 and 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 24 B | 12" x 12" Blue Floor Tile | | | Main Office, Rooms 205, 209, 305, 307 | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 25 | 12" x 12" Brown w/ Tan Floor Tile | 500 | SF | Rooms 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 26 | 9" x 9" Brown Floor Tile | 1000 | SF | Rooms 204 & 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 30 | Acoustical Ceiling Plaster | 3000 | SF | 1966 Building Corridors | | Surface | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-----------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 31 | Acoustical Ceiling Plaster | 2400 | SF | Rooms 111, 113, & 115 | | Surface | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 | Brown Coat Plaster | | | 1904 Building | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 35 A | Brown Coat Plaster | 2000 | SF | 1933 Building | | Surface | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 A | 9" x 9" Taupe Floor Tile Mastic | 1800 | SF | Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 38 B | 9" x 9" Brown Floor Tile Mastic-Main Building | 1800 | SF | Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 A | 12" x 12" Light Brown Floor Tile Mastic | 2475 | SF | Rooms 101 & 102, and Engineer's Office-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 B | 12" x 12" Yellow Floor Tile Mastic | 2400 | SF | Auditorium, Teacher's Lounge, Rooms 201, 206, 303, 304 & 306-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 C | 12" x 12" Brown w/ Tan Floor Tile Mastic | 2100 | SF | Rooms 204 & 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 39 D | 12" x 12" White Floor Tile w/ Green Streaks Mastic | 2200 | SF | Rooms 202 and 302 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 A | 12" x 12" Beige Mix Floor Tile | 2475 | SF | Rooms 101, 102 and Engineer's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 B | 12" x 12" Green/Brown Floor Tile Mastic-Main Building | 940 | SF | 4th Floor Corridor and Maintenance Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 40 C | 12" x 12" Beige Mix Floor Tile Mastic | 2475 | SF | Rooms 101, 102 & the Engineer's Office-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 B | 12" x 12" Beige Floor Tile Mastic | 1000 | SF | 1970 Corridor, Faculty Lounge and Room 509 & 506 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41 C | 12" x 12" Light Gray and Brown Floor Tile Mastic | 2100 | SF | 1970 Corridor, 504 and 510 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41A | 12" x 12" White Floor Tile Mastic | 2400 | SF | Rooms 502, 503 and 505 in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 41D | 12" x 12" Brown Floor Tile Mastic | 480 | SF | Kitchen of Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 42A | 9" x 9" Dark Brown Floor tile Mastic | 170 | SF | Basement Custodial Room-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-----------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 A | 12" x 12" Lt Brn and 12" x 12" Dk Brn VFT Mastic | 1400 | SF | Basement Lunch Room-Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 B | 12" x 12" White Floor Tile w/ Green Streaks Mastic | 1500 | SF | 207 and 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 43 C | 12" x 12" Blue Floor Tile Mastic | 2500 | SF | Main Office, 205, 209, 305 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 A | 9" x 9" Light Brown Floor Tile Mastic | 2250 | SF | Lunch Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 B | 9" x 9" DKBrown Floor Tile w/ White Streaks Mastic | 2250 | SF | 1966 Corridors | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 C | 9" x 9" Off-White Floor Tile Mastic | 2250 | SF | Lunch Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 D | 9" x 9" Green Floor Tile Mastic | 2250 | SF | Lunch Rooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 44 E | 9" x 9" Light Brown Floor Tile Mastic | 2250 | SF | 1966 Corridors and Women's Teacher's Washroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 45 | Vinyl Baseboards | 18000 | LF | 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 46 | Vinyl Baseboard Mastic | 18000 | LF | 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 47 | Drywall Joint Compound | 600 | SF | Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 48 | Vinyl Baseboard | | | 1970 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 49 | Vinyl Baseboard Mastic | | | 1970 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 50 | 12" x 12" White Floor Tile w/ Green Streaks | 2200 | SF | Rooms 207 and 302 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 51 | Gypsum Layer Behind Steel of Curtain Wall Panels | | | 1970 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 52 | Exterior Drywall Undersiding - Non AHERA | | | South Side of Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 53 | Paper Layer Under Siding - Non-AHERA | | | 1969 Exterior of Building | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 54 | 2' x 4' Ceiling Panels | 15000 | SF | 1969 Building | | Miscellaneous | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 55 | Exterior Brick - Non AHERA | | | 1904 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 56 | Exterior Brick Mortar - Non AHERA | | | 1904 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 57 | Exterior Brick - Non AHERA | | | 1933 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 58 | Exterior Brick Mortar - Non AHERA | | | 1933 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 59 | Exterior Brick - Non AHERA | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 60 | Exterior Brick Mortar - Non AHERA | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 61 | Interior Glazed Block | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 62 | Interior Glazed Brick Mortar | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 63 | Interior Concrete Block | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 64 | Interior Concrete Block Mortar | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 65 | Interior Window Glaze | | | 1904 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 66 | Interior Window Caulk - ABATED | | | 1904 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 67 | Interior Window Glaze | | | 1933 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 68 | Interior Window Caulk - ABATED 1998 | | | 1933 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 69 | Interior Window Glaze - ABATED 1998 | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 70 | Interior Window Caulk | | | 1966 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 71 | Window Glaze Compound | | | 1970 Building - Windows | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 72 | Exterior Window Caulk - Non AHERA | | | 1969 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 73 | Window Glaze "Compound" (Glass Gasket) - ABATED | | | 1969 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 74 | Roof Flashing (Non-AHERA) | | | 1966 Lower Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 75 | Roofing Material (Non-AHERA) | | | 1966 Lower Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 76 | Roof Flashing (Non-AHERA) | | | 1966 Upper Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 77 | Roofing Material (Non-AHERA) | | | 1966 Building Upper Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 78 | Upper Roof Flashing - Non-AHERA | | | 1904 Upper Roof | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 79 | Roofing Material (Non-AHERA) | | | 1904 Upper Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 80 | Roof Flashing - Non-AHERA | | | 1904 Lower Roof | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 81 | Roofing Material (Non-AHERA) | | | 1904 Lower Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 82 | Roof Flashing - Non-AHERA | | | 1933 North Roof | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 83 | Roofing Material (Non-AHERA) | | | 1933 North Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 84 | Roof Flashing - Non-AHERA | | | 1933 Gym Roof | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 85 | Roofing Material (Non-AHERA) | | | 1933 Gym Roof | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 86 | Ceramic Tile | 900 | SF | 1933 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 87 | Ceramic Tile Grout | 900 | SF | 1933 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 88 | Ceramic Tile | 3475 | SF | 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 89 | Ceramic Tile Grout | 3475 | SF | 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 90 | Ceramic Tile | 500 | SF | 1969 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 91 | Ceramic Tile Grout | 500 | SF | 1969 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 92 | Ceramic Tile | 425 | SF | 1970 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 93 | Ceramic Tile Grout | 425 | SF | 1970 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 94 | 12" x 12" Light Brown Mix Floor Tile | 1200 | SF | 1904 Building - 102 Washroom, 103A and 209 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 95 | 12" x 12" Light Brown Mix Floor Tile Mastic | 1200 | SF | 1904 Building - 102 Washroom, 103A and 209 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 96 | 12" x 12" Choc. Brn w/ Wh & Blk Strks Floor Tile | 1500 | SF | 1904 Building - Auditorium | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 97 | 12" x 12" Choc. Brn w/ Wh & Blk Strks FT Mastic | 1500 | SF | 1904 Building - Auditorium | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 98 | 12" x 12" White Floor Tile w/ Brown Streaks | 1500 | SF | 1904 Building - Teachers Lounge & 202 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 99 | 12"x12" White Floor Tile w/ Brown Streaks Mastic | 1500 | SF | 1904 Building - Teachers Lounge & 202 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 100 | 12" x 12" Beige Mix Floor Tile | 1500 | SF | Rooms 203 & 204 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 101 | 12" x 12" Beige Mix Floor Tile Mastic | 1500 | SF | Rooms 203 & 204 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 102 | 12" x 12" Gray Mix Floor Tile | 400 | SF | Rooms 205 & 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 103 | 12" x 12" Gray Mix Floor Tile Mastic | 400 | SF | Rooms 205 & 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 104 | Insulation Inside Pre-Fabricated Walls | 15000 | SF | All Walls in Facility (Annex Building) | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 105 | 12" x 12" Beige w/White & Brown Floor | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 106 | 12" x 12" Beige w/White & Brown Floor Tile Mastic | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 107 | 4" Brown Baseboard | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 108 | 4" Brown Baseboard Adhesive | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 109 | Acoustical Ceiling Plaster | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 110 | Wallboard | | | South Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 111 | Wallboard | | | North Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 112 | Acoustical Ceiling Plaster | | | North Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 113 | 12" x 12" Beige w/White & Brown Floor | | | North Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 114 | 12" x 12" Beige w/White & Brown Floor Mastic | | | North Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 115 | 4" Brown Baseboard | | | North Trailer- Trailers removed from site in 2012 | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 116 | 4" Brown Baseboard Adhesive | | | North Trailer | | Miscellaneous | | None | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 117 | Chalk Boards and Poster Boards | 3300 | SF | Throughout Classrooms in 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 118 | Chalk Boards and Poster Boards | 4800 | SF | Throughout Classrooms in Main Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 119 | Chalk Boards and Poster Boards | 900 | SF | Throughout Classrooms in Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 120 | Light Brown Linoleum on Counter Tops | 90 | SF | Throughout Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 121 | Light Brown Linoleum Adhesive on Counter Tops | 90 | SF | Throughout Annex Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 122 | Light Brown Linoleum on Counter Tops | 1302 | SF | Throughout 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 123 | Light Brown Linoleum Adhesive on Counter Tops | 1302 | SF | Throughout 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 124 | Gray Linoleum on UV Tops | 21 | SF | Main Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 125 | Gray Linoleum Adhesive on UV Tops | 21 | SF | Main Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 126 | 1' x 1' Spline Ceiling Tile | 2250 | SF | Lunchrooms | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------|-------------------|----------------|-------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 127 | Black Sink Undercoating | 10 | SF | Kindergarten Classrooms | | Surface | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------|-------------------|----------------|----------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 128 | Sink and Urinal Caulk | 18 | LF | Washrooms of 1966 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 129 | Yellow Linoleum on Counter | 120 | SF | Basement Lunch Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------------|-------------------|----------------|---------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 130 | Yellow Linoleum Adhesive on Counter | 120 | SF | Basement Lunch Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 131 | 12"x12" Yellow Floortile | 1200 | SF | Basement Cafeteria, 1st Floor Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 132 | 12"x12" Yellow Floortile mastic | 1200 | SF | Basement Cafeteria, 1st Floor Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 133 | 12"x12" Blue Floortile | 1200 | SF | Basement Cafeteria, 1st Floor Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-------------------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| 134 | 12"x12" Blue Floortile Mastic | 1200 | SF | Basement Cafeteria, 1st Floor Lunchroom | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| A | Spray On Structural Fire Proofing Material | | | 1966 Building | | Surface | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--------------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| C | Air Cell Pipe Insulation | 220 | LF | 1904 Building | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| D | Paperwrap Pipe Insulation | 300 | LF | 1904 Basement and Pipe Chases | | TSI | Yes | Dist | 130 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| E | Mag Block Steam Line Insulation - ABATED 1998 | | | 1904 Playroom, Boiler Room, and Pump Room | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F-A | Hard Joint Compound off Fiberglass Insulated Pipes | | | 1904 Bldg. (This insulation was installed in 1974 with new pump) | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| F/B | Hard Joint Compound off Fiberglass Insulated Pipes | 65 | LF | 1904 Building | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| G | Duct Cement | 30 | LF | Basement of 1904 Building | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| H | Tank Insulation | 225 | SF | 1904 Basement | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| I | Boiler Gaskets | 90 | LF | Boiler Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| J | Hard Joint Compound off Air Cell Insulated Pipes | 48 | LF | 1904 Boiler Room and fan room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| K | Hard Joint Compound off Paperwrap Insulated Pipes | 70 | LF | 1904 Playroom, Boiler Room, Pump Room and Play Room | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|---------------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| L | Hard Joint Compound on Mag Block Pipe Insulation | 220 | LF | Steam Supply in Boiler and Pump Rooms | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| M | Hard Joint Compound off Fiberglass Insulated Pipes | 150 | LF | 1966 Building | | TSI | Yes | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MCM-1 | Carpet Mastic | 1000 | SF | Main Building Parent Office & Main Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFT-1 | 12"x12" White w/Gray Floor Tile Mastic | 2500 | SF | Main Bldg- Rooms 202,203,204,302 and Teachers Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFT-2 | 12"x12" Lt. Blue Floor Tile | 1000 | SF | Main Building Rooms 205 & 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFT-3 | 12"x12" Brown Speckled Floor Tile | 1500 | SF | Main Bldg.-Rooms 101, 207 and Principal's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|-----------------------------------|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFT-4 | 12"x12" Brown & Orange Floor Tile | 500 | SF | Main Building Room 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|--|-------------------|----------------|---|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFTM-1 | 12"x12" White w/Gray Floor Tile Mastic | 2500 | SF | Main Bldg-Rooms 202,203,204,302 and Teachers Room | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|------------------------------------|-------------------|----------------|-------------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFTM-2 | 12"x12" Lt. Blue Floor Tile Mastic | 1000 | SF | Main Building-Rooms 205 & 307 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|--|-------------------|----------------|--|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFTM-3 | 12"x12" Brown Speckled Floor Tile Mastic | 1500 | SF | Main Bldg.-Rooms 101, 207 and Principal's Office | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|--------|--|-------------------|----------------|------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MFTM-4 | 12"x12" Brown & Orange Floor Tile Mastic | 500 | SF | Main Building Room 304 | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|--------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MT-1 | Gray Terrazzo | 10000 | SF | Main Building Stairwells | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|----------------------|-------------------|----------------|---------------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| MT-2 | Beige Terrazzo | 10000 | SF | Annex Building Stairwells | | Miscellaneous | No | None | 0 | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

| HA No | Material Description | Material Quantity | Material Units | Material Location | Asbestos Type | Material Category | Friable | Damage Type | Damage Quantity | Damage Units | Change in Assessment Category |
|-------|---|-------------------|----------------|-------------------|---------------|-------------------|---------|-------------|-----------------|--------------|---|
| N | Hard Joint Compound off Fiberglass Insulated Pipes | | | 1969 Building | | Miscellaneous | | | | | <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO |

| |
|--------------------------|
| 2016 - Fall: No Change |
| Comments: |
| |
| 2017 - Spring: No Change |
| Comments: |
| |
| 2017 - Fall: No Change |
| Comments: |
| |

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

ALL LEA Responsibilities, for this school, will be met.



Robert Christlieb

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

NOTICE TO PARENTS AND STAFF REGARDING THE
ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: George Leland Elementary School

Date: 10/11/2017

This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.

Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.

CHECK ONE

- A copy of this notice was sent home in each child's backpack.
- A copy of this notice was printed in the school's newsletter and sent home with each child
- A copy of this notice was printed in the school's calendar and sent home with each child
- Other.
-

A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.

VFT = Vinyl Floor Tile

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.