Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

26771 Belmont-Cragin Elementary School 4600 School: **Oracle Unit: Building ID:** 5252 W. Palmer Street Address: Region: 02 Mail Room: 29 Asbestos Surveyor: Salgado, Mr. Francisco X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/10/2017 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type 9"x9" Brown w/ Red & Throughout 1952 (See YES 01 SF X NO 9050 Miscellaneous No 50 Loc White Streaks VFT Hatching Maps) 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

02	9"x9" Brown w/ Red & White Streaks VFT Mastic	9050	SF	Throughout 1952 (See Hatching Maps)		Miscellaneous	No	Loc	50		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J-]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
03	9"x9" White w/ Brown Spots VFT	920	SF	107, Cafeteria, Kitchen Storage Room (206C - NOT OBSERVED) - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	<u> </u>				-							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
04	9"x9" White w/ Brown Spots VFT Mastic	920	SF	107, Cafeteria, Kitchen Storage (Room 206C -NOT OBSERVED) -1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	to onango				_							
					1							
2017 - Fall: N	No Change											
Comments:	-				1							
]							
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05	9"x9" Brown w/ Yellow VFT	8600	SF	Room 107, Kitchen East Storage (Cafeteria - Not OBSERVED) -1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	Jo Change				7							
Comments:	NO Onange				1							
Comments.					1							
2017 - Fall: N	No Change				1							
Comments:	<u> </u>											

2017 - Spring: No Change

Comments:

06	9"x9" Brown w/ Yellow VFT Mastic	8600	SF	Room 107, Kitchen East Storage (Cafeteria - Not OBSERVED) -1952		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change]						
Comments:]						
2017 - Fall: N	No Change										
Comments:	•]						
2017 - Spring	g: No Change										
Comments:	.				1						
					J						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
07	9"x9" Orange VFT - NOT OBSERVED	600	SF	Main Office Toilet - 1952		Miscellaneous	No	None	0		YES X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
08	9"x9" Orange VFT Mastic NOT OBSERVED	600	SF	Main Office Toilet - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change				-							
Comments:	Ţ.											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09	9"x9" Grey w/ White Streaks VFT	300	SF	Gym Office - 1952		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	Ü											
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change				<u> </u>							
Comments:												
]							

10	9"x9" Grey w/ White Streaks VFT Mastic	300	SF	Gym Office - 1952		Miscellaneous	No	None	0		YES X NO	0
2016 - Fall: Comments	: No Change]							
	: No Change											
2017 - Spri	ng: No Change											
Comments					}							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Ca	ategory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

575

Material

Quantity

Material

Units

SF

Material Location

Main Office & Vault -

1952

HA No

11

Material Description

9"x9" Gray w/ Black Streaks VFT

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	9"x9" Gray w/ Black Streaks VFT Mastic	575	SF	Main Office & Vault - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	9"x9" Gray VFT	100	SF	Room 107 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	9"x9" Gray VFT Mastic	100	SF	Room 107 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change				- - -							
2017 - Spring	: No Change				- -							
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	9"x9" Green VFT	150	SF	Social Hall SW Closet and Rooms 114 and 115 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	: No Change				- -							

16	9"x9" Green VFT Mastic	150	SF	and Rooms 114 and 115 - 1952		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change]						
Comments:											
2017 - Fall: I	No Change										
Comments:											
					=						
	g: No Change										
Comments:											
	_										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	9"x9" Beige w/ Orange & Green VFT (NOT OBSERVED)			South West Stairwell to Penthouse - 1952 (NOT OBSERVED)							YES	X NO
2016 - Fal	II: No Change			, , , , , , , , , , , , , , , , , , , ,]			1	1	1		

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Units

Material

Quantity

Material Location

Social Hall SW Closet

HA No

Material Description

18	9"x9" Beige w/ Orange & Green VFT Mastic (NOT OBSERVED)			South West Stairwell to Penthouse - 1952 (NOT OBSERVED)							YES	X NO
2016 - Fal	I: No Change			•]	•	•	•	•	-		
Comments	S:				1							
2017 - Fal	l: No Change											
Comments	S:				-							
2017 - Spi	ring: No Change											
Comments	S:				 							
					1							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

X NO

Material Location

Room 106 and

Concession Room - 1952

	1		
2016 - Fall: N	lo Change		
Comments:	<u> </u>		
Comments.			
2017 - Fall: N	lo Change		
Comments:			
2017 - Spring	: No Change		
Comments:			

Quantity

800

Material

Quantity

Material

Units

Units

SF

HA No

19

Material Description

12"x12" Tan w/ Brown &

White Spots VFT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	12"x12" Tan w/ Brown & White Spots Mastic	800	SF	Room 106 and Concession Room - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	i i i o o i ango											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12"x12" White w/ Tan Streaks VFT	500	SF	Main Office - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:	o change											
	NI OI]							
2017 - Spring	: No Change											
Comments:												

22	12"x12" White w/ Tan Streaks VFT Mastic	500	SF	Main Office - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	l: No Change]							
Comments	S:											
2017 - Fall	: No Change											
Comments	S:											
	ing: No Change											
Comments	S:				_							
					∃							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

1800

Material

Quantity

Material

Units

SF

Material Location

Room 102, Kitchen and

Janitor's Break Room (Room 105) - 1952

HA No

23

Material Description

12"x12" Gray w/ White Spots VFT

24	12"x12" Gray w/ White Spots VFT Mastic	1800	SF	Room 102, Kitchen and Janitor's Break Room (Room 105) - 1952		Miscellaneous	Yes	None	0		YES	X NO
		•	<u> </u>	•	1	•	•	•	•	•	•	
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
]							
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIATIO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onange in Asse.	Sameric Category
25	12"x12" Tan w/ White & Gray Streaks VFT	4800	SF	NW, SE, and Central Locker Rooms, Locker Office/Training Room - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - F Commer	all: No Change nts:											

2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Material

Quantity

Material

Units

HA No

Material Description

26	12"x12" Tan w/ White & Gray Streaks VFT Mastic	4800	SF	NW, SE and Central Locker Rooms, Locker Office / Training Room - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				7							
Comments												
2017 - Fal	II: No Change				-							
Comments	S:]							
2017 - Spi	ring: No Change				_							
Comments	S:			<u> </u>								
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asset	ssment Category
27	12"x12" Green VFT	800	SF	Room 103 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change	•	•	•	<u> </u>	•	•	•	•	•		
Comments	<u> </u>											
2017 - Fal	II: No Change				1							
					1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
28	12"x12" Green VFT Mastic	800	SF	Room 103 - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	U											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
29	12"x12" White w/ Blue Spots VFT	5500	SF	Social Hall - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	o o											
2017 - Fall: N	o Change											
Comments:	o onango											
2017 Spring	· No Chango											
2017 - Spring Comments:	. No Change											

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
30	12"x12" White w/ Blue Spots VFT Mastic	5500	SF	Social Hall - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>				=							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	12"x12" Beige w/ Brown & White Streaks VFT (NOT OBSERVED)			Rooms 203 and 204 - 1952 (NOT OBSERVED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	•											
2017 - Fall: N	lo Change				-							
Comments:	•				1							
2017 - Spring	g: No Change				-							
Comments:	<i>-</i>				1							
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

34	12"x12" Beige w/ Brown & White Streaks VFT Mastic (NOT OBSERVED)		Rooms 203 and 204 - 1952 (NOT OBSERVED)		Miscellaneous					YES	X NO
		•		1	•	•	-	•	-		
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2017 - Spring	: No Change										
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	9"x9" Beige VFT	1250	SF	Room 208 -NOT OBSERVED, Engineers Storage - 1952		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

36	9"x9" Beige VFT Mastic	1250	SF	OBSERVED, Engineers Storage - 1952		Miscellaneous	No	None	0		YES	X NO
	No Change	·]							
Comments:					_							
2017 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
37	12"x12" Dark Brown VFT (NOT OBSERVED)			Room 208 - 1952 (NOT OBSERVED)							YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
38	12"x12" Dark Brown VFT Mastic (NOT OBSERVED)	400	SF	Room 208 - 1952		Miscellaneous	No		0		YES	X NO
2016 - Fall: N	o Change				7							
2017 - Fall: N	o Change											
2017 - Spring	: No Change				_ _ _							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
39	12"x12" Orange VFT	800	SF	Room 101 - 1952		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
40	12"x12" Orange Mastic	800	SF	Room 101 - 1952		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
41	1'x1' Peg Hole Ceiling Tile			Throughout 1952							YES	X NO
2016 - Fall: N	lo Change							•				
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>	·										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	2'x4' Dot Wave Ceiling Tile			Rooms 206A and 206B, Assistant Principal's Office, Main Office and Social Hall - 1952							YES X NO
2016 - Fall: N	No Change				7						
Comments:	<u> </u>										
2017 - Fall: N	No Change										
Comments:	<u> </u>										
2017 - Spring	g: No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	1'x1' Grooved Ceiling Tile			Main Office (East Area), North & South Basement Corridors - 1952							YES X NO
2016 - Fall: N	No Change				7						
Comments:											
2017 - Fall: N	lo Change										
Comments:	10 Change										

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
44	2'x2' Ceiling Tile			Main Office - 1952							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45	9"x9" Tan w/ Red & White VFT	3400	SF	Rooms 108B, 116, 117, 118 and 119		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change											
Comments:	o onango											
2017 Spring	· No Chango											
2017 - Spring Comments:	. No Change											
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
46	9"x9" Tan w/ Red & White VFT Mastic	3400	SF	Room 108B, 116, 117, 118 and 119 - 1961		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	9"x9" White w/ Brown VFT	2400	SF	Throughout 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
48	9"x9" White w/ Brown VFT Mastic	2400	SF	Throughout 1961 (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
49	9"x9" Orange VFT (NOT OBSERVED)	350	SF	Chorus Room - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	2 2											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
50	9"x9" Orange VFT Mastic (NOT OBSERVED)	350	SF	Chorus Room 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:					-							
2017 - Spring	: No Change				=							
Comments:					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
51	9"x9" Brown w/ White VFT	4700	SF	Library SE Office, Rooms 10, 11, 012 and 012A - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	Ü											
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	· No Change											
Comments:	. 110 Onango											

52	9"x9" Brown w/ White VFT Mastic	4700	SF	Library SE Office, Rooms 10, 11, 012 and 012A - 1961		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:											
2017 - Fall:	No Change										
Comments:											
2017 - Spri	ng: No Change				-						
Comments:	<u> </u>										
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	9"x9" Orange w/ Yellow VFT	4200	SF	Library and Library NE Office - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
54	9"x9" Orange w/ Yellow VFT Mastic	4200	SF	Library and Library NE Office - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>]							
2017 - Fall: N	o Change											
Comments:	_											
2017 - Spring	: No Change				1							
Comments:	Ŭ											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
55	9"x9" White w/ Silver VFT	350	SF	Room 214 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>]							
2017 - Fall: N	o Change				1							
Comments:	Ü											
2017 - Spring	: No Change				_							
Comments:]							
]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
56	9"x9" White w/ Silver VFT Mastic	350	SF	Room 214 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change				1							
Comments:	J											
2017 - Spring	ı: No Change				4							
Comments:	. No Onlange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	ssessment Category
	material Decempsion	Quantity	Units	material 200ation	Туре	Category		Type	Quantity	Units	onango m / k	occoment category
57	9"x9" Beige w/ Tan VFT	1500	SF	Rooms 212 and 213 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Chango				-							
Comments:	lo Change											
2017 - Spring	r: No Change											
Comments:					-							
					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
58	9"x9" Beige w/ Tan VFT Mastic	1500	SF	Rooms 212 and 213 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	v											
2017 - Spring	: No Change											
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
59	9"x9" White w/ Red VFT	2400	SF	Rooms 17, 109, 108, 110, 111, 112, 113,116, 118 and 119 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	90											
2017 - Spring	ı: No Change											
Comments:	. Ho ondrigo											

60	9"x9" White w/ Red VFT Mastic	2400	SF	Rooms 17, 109, 108, 110, 111, 112, 113,116, 118 and 119 - 1961	Miscellane	ous No	None	0	YES	X NO
2016 - Fa	all: No Change		<u> </u>							
Commer										
2017 - Fa	all: No Change									
Commer										
2017 - S	pring: No Change									
_0.7	Pring. 110 Chango									

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61	9"x9" White w/ Green VFT	200	SF	Rooms 15, 16, 114 and 115 - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

62	9"x9" White w/ Green VFT Mastic	200	SF	Room 15, 16, 114 and 115 - 1961		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	: No Change]						
Comments											
2017 - Fall:	: No Change										
Comments	:]						
2017 - Spri	ng: No Change										
Comments											
					J						
LIA NI-	Material Description	Meterial	Matarial	Metavial Lagation	A = = = + = =	Matarial	Falable	Damasa	Damasa	D	Change in Assessment Catagonic

Type

Material

Category

Friable

Damage

Type

Damage Quantity

	HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sment Category	
	63	9"x9" Gray w/ Black & Orange VFT	1550	SF	Music Storage, Room 17 - 1961		Miscellaneous	No	None	0		YES	X NO	
-	2016 - Fall: No Comments:	o Change												

2017 - Fall: No Change Comments:

2017 - Spring: No Change

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Damage

Units

64	9"x9" Gray w/ Black & Orange VFT Mastic	1550	SF	Music Storage, Room 17 - 1961		Miscellaneous	No	None	0		YES X NO	
2016 - Fall: Comments:	: No Change :											
2017 - Fall: Comments:	: No Change :											
2017 - Spri Comments:	ng: No Change :											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Cate	egory
11/1140	Waterial Description	Quantity	Units	Material Education	Type	Category	THADIC	Type	Quantity	Units	Change in 7.03033ment date	gory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

3100

Material

Quantity

Material

Units

SF

Material Location

Rooms 13, 13B, 14, 14B,

18 and 19 - 1961

HA No

65

Material Description

9"x9" Tan w/ Brown &

White Spots VFT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
66	9"x9" Tan w/ Brown & White Spots VFT Mastic	3100	SF	Room 13, 13B, 14, 14B, 18 and 19 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	, ,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
67	9"x9" Gray VFT	150	SF	NE Band Office - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io onange											
2017 Cprins	v No Chango											
Comments:	g: No Change											
Comments.	omments.											

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
68	9"x9" Gray VFT Mastic	150	SF	NE Band Office - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
69	9"x9" White w/ Gray VFT	350	SF	Music Storage - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

70	9"x9" White w/ Gray VFT Mastic	350	SF	Music Storage - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Sprin	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
71	9"x9" Cream VFT	4500	SF	Rooms 108, 109, 110, 111, 112 and 113 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

72	9"x9" Cream VFT Mastic	4500	SF	Room 108, 109, 110, 111, 112, 113 - 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:												
]							
2017 - Fall: No Change]							
Comments:]							
	g: No Change											
Comments:												
]							
	1	T	T	1	T	T	T =	T _	T =		T	
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage Quantity	Damage Units	Change in Assess	sment Category
		Quantity	UTIILS		Туре	Category		Туре	Quantity	UTIILS		
73	9"x9" Green w/ White VFT	3000	SF	Rooms 114, 115 and 116 - 1961		Miscellaneous	No		0		YES	X NO
2016 - Fall: N	Jo Changa				7							
	No Change				-							
Comments:					-							
2017 - Fall: N	No Change				1							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Cate	egory
74	9"x9" Green w/ White VFT Mastic	3000	SF	Rooms 114, 115 and 116 - 1961		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	lo Change]								
Comments:					<u> </u>								
2017 - Fall: N	lo Change				-								
Comments:	U												
2017 - Spring	ı: No Change				-								
Comments:	i. 110 Onlango		-										
]										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssessment Cate	egory
		Quantity	Units		Туре	Category		Туре	Quantity	Units			
75	Lab Table Tops	300	SF	Room 108 - 1961		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	lo Change]								
Comments:													
2017 - Fall: N	lo Change				_								
Comments:													
2017 Spring	17 - Spring: No Change												
Comments:													
231111101110.]											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
76	White Plaster			1st Floor South Janitors Closet - 1961							YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Fall: N	lo Change											
Comments:					-							
	g: No Change											
Comments:			4									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
77	Hard Coat Plaster			Throughout 1961							YES	X NO
2016 - Fall: N	lo Change											
Comments:					4							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
78	1'x1' Grooved Ceiling Tile			Throughout 1961							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:	g. 140 Onango		_									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asse	ssment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
79	Lab Table Tops			Rooms 208 and 211 - 1952							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change				_							
Comments:	017 - Fall: No Change Comments:											
	2017 - Spring: No Change											
	g: No Change				_							
Comments:					-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Catego	
80	Terrazzo	4000	SF	Throughout, 1st Floor and Stairwells		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
81	Carpet Mastic	2200	SF	Social Hall, Rooms 206A, 206B -NOT OBSERVED		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	2017 - Fall: No Change											
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												
					J							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
82	12"x12" Blue with White Streaks Floor Tile	10400	SF	Room 201-205, 206A, 206B, 207-211, 215, Physics Penthouse stairwell -1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
83	12"x12" Blue with White Streaks Floor Tile Mastic	10400	SF	Room 201-205, 206A, 206B, 207-211, 215, Physics Penthouse stairwell -1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				٦							
Comments:												
2017 - Fall:	No Change				_							
	mments:											

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
84	Carpet Adhesive	4600	SF	Gym Office, Main Office (100A - 100K) and Assistant Principal's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:	.											
2017 - Fall: I	No Change											
Comments:	Ü											
2017 - Sprin	g: No Change				1							
Comments:	<u> </u>											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
85	12"x12" Beige w/white specs VFT	5800	SF	East and West Lunch Room and Teacher's Lounge (1952 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Sprin	a. No Change				1							
Comments:	7 - Spring: No Change nments:											

2017 - Fall: No Change

Comments:

86	12'x12' Beige w/ white spots Mastic	5800	SF	East & West Lunch and Teacher's Lounge (1953 Building)		Miscellaneous	No	None	0		YES	X NO
		*	•	•	7	•	•	•	•	•	•	
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
			•	_	=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	ment Category
	· ·	Quantity	Units		Type	Category		Type	Quantity	Units		0 ,
			+	_	+	1	+	 	+	 		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change		
Comments:		
Commente.		
0047 O N. Ol		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		

12"x12" Blue Speckled VFT 1000

Material

Quantity

Material

Units

Material Location

West Lunchroom - 1952

HA No

87

Material Description

YES

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
88	12"x12" Blue Speckled Mastic	1000	SF	West Lunchroom - 1952		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Fall: N Comments:	o Change											
2017 - Spring Comments:	: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
89	12"x12" Dark Blue Speckled VFT	100	SF	East Lunchroom - 1952		Miscellaneous	No	None	0		YES	X NO
Comments: 2017 - Fall: N Comments:	2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
90	12"x12" Dark Blue Speckled Mastic	100	SF	East Lunchroom - 1952		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:					4								
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change				4								
Comments:	omments:												
	T	1	T	T	T	T	1	T		T	I		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assess	ment Category
91	Fire-Proof Door	100	EA	Throughout (1952 Building)		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall: N	No Change				7								
Comments:													
2017 - Fall: N	No Change				-								
Comments:													
2017 - Spring	17 - Spring: No Change												
Comments:	g. No Change				1								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
92	9"x9" Green w/white streaks VFT	2000	SF	015 and 016 (1961 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 Spring	ı: No Chango											
2017 - Spring Comments:	i. No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
93	9"x9" Green w/white streaks Mastic	2000	SF	015 and 016 (1961 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				\neg							
Comments:	Ü											
2017 - Fall: N	2017 - Fall: No Change											
Comments:												
2017 - Spring	r No Change											
Comments:												

94	12"x12" Gray w/white speckles VFT	150	SF	MDF Room (1961 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change				7							
Comment	S:											
2017 - Fal	II: No Change											
Comment	s:				_							
2017 - Sp	017 - Spring: No Change											
Comment	s:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
95	12"x12" Gray w/white speckles Mastic	150	SF	MDF Room (1961 Building)		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

96	12"x12" Blue w/light blue speckles VFT	150	SF	MDF Room (1961 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments]							
2017 - Spri	ing: No Change											
Comments	s:											
2017 - Fall:	: No Change											
Comments): -				 							
					J							
LIA No	Motorial Description	Motorial	Motorial	Motorial Location	Achootoo	Motorial	Erioblo	Domogo	Domogo	Domogo	Change in Assess	amont Catagoni

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
97	12"x12" Blue w/light blue speckles Mastic	150	SF	MDF Room (19621 Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

98	12"x12" Beige Speckled VFT	900	SF	Room 104 (1952 Building)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change]						
Comments:]									
	g: No Change										
Comments:											
	2017 - Fall: No Change										
Comments:					-						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99	12"x12" Beige Speckled Mastic	900	SF	Room 104 (Building 1952)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

100	12"x12" Blue w/white streaks VFT	1200	SF	Room 218 (1961 Building)		Miscellaneous	No	None	0		YES	X NO
2016 Falls	No Change	•	•	•	1	•	•	•	•	•		
2016 - Fall:	No Change											
Comments:												
					1							
2017 - Sprin	g: No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												

Material

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	12"x12" Blue w/white streaks Mastic	1200	SF	2nd Floor Corridor and Room 218 (1961 Building)		Miscellaneous	No	None	0		YES X NO

2010 5 11 11 21	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
102	Terrazzo	12000	SF	Throughout (1952 Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
103	Drywall System	1000	SF	Library New Offices		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

Α	Aircell Pipe Insulation	1463	LF	Hatching Maps)		TSI	Yes	None	0		YES	X NO
2010 = 11	N. O.				1							
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	-											
2017 - Sprin	g: No Change											
Comments:												
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

176

Material

Quantity

Material

Units

LF

Material Location

Throughout 1952 (See Hatching Maps)

HA No

В

Material Description

MJP E/F/V on Aircell Pipe

Insulation

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

С	Cardboard Pipe Insulation	235	LF	Throughout 1952 (See Hatching Maps)		TSI	Yes	None	0	YES	X NO
					Ī						
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											

Type

Material

Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Cardboard Pipe Insulation	129	LF	Throughout 1952 (See Hatching Maps)		TSI	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	MJP E/F/V on Fiberglass Pipe Insulation	63	LF	Social Hall, Kitchen, Closet Under SE Stairs, Cafeteria, Under NE Gym Stairs, North Locker Room - 1952		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Boiler Jacket Insulation	750	SF	Boiler Room - 1952		TSI	Yes	Dist	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
G	Tank Insulation	450	SF	Boiler Room - 1952		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Н	Boiler Flue Insulation	900	SF	Boiler Room - 1952		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:	-											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
I	Spray Applied Accoustical Plaster			SW Penthouse - 1952							YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	j: No Change]							
Comments:					_							
2017 - Fall: N	lo Change				-							
Comments:	_]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
J	Hard Coat Plaster			Throughout 1952 Building							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	· · ·											
2017 - Spring	ı: No Change				1							
Comments:	,]							
2017 - Fall: N	lo Change				-							
Comments:	9]							
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	Vibration Damper Cloth			3rd Floor Penthouse - 1952							YES	X NO
2016 - Fall: N	lo Change]							
Comments:					_							
2017 - Spring	g: No Change											
Comments:					1							
2017 - Fall: N	lo Change]							
Comments:					_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L	MJP E/F/V on Fiberglass Pipe Insulation	100	LF	Above 2nd Floor Ceilings Throughout 1961		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:]							
2017 - Spring	g: No Change				-							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
					_							

HA No

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Belmont-Cragin Elementary School	
Date:10/10/2017	
This is to notify you in accordance with Illinois and Federal Asbestos Regulat the Asbestos Management Plan is available at each school during school hot Requests to review the Asbestos Management Plan must be made at least 2.	urs by appointment.
Also please be advised that CPS conducts asbestos inspections of all School The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.	s every three years.
CHECK ONE	
A copy of this notice was sent home in each child's backpack.	
X A copy of this notice was printed in the school's newsletter and sent home wi	th each child
A copy of this notice was printed in the school's calendar and sent home with	each child
Other.	
A COPY OF THIS NOTICE MUST BE PLACED IN THE	

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 26771