Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

Gerald Delgado Kanoon Elementary Magnet School 29071 **Building ID:** 3370 School: **Oracle Unit:** Address: 2233 S. Kedzie Region: 03 Mail Room: Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/19/2017 Email Address: jjheneghan@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Material Damage Quantity Units Type Category Quantity Type YES 2' x 4' Ceiling tile X NO Miscellaneous Throughout building 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
2	Spray-on Fire Proofing			Throughout school		Surface					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change				-							
Comments:	g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
3	12" x 12" Beige w/ Brown Specks Floor Tile	30000	SF	Throughout building in all classrooms and hallways except washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:					=							
2017 - Fall: N	lo Change				-							
Comments:	io onango											
2017 - Spring	g: No Change											
Comments:	g. 140 Onange				-							
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4	12" x 12" Beige w/Brown Specks Floor Tile Mastic	30000	SF	Throughout building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
5	Baseboard			Throughout building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	: No Change											
Comments:	·											

		Quantity	Units		Туре	Category		Type	Quantity	Units		
6	Baseboard Mastic			Throughout building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	, J											
2017 - Fall: N	lo Change											
Comments:	g-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
7	Vault Door Insulation	60	SF	Main Office (Room 100D/Storage), Room 218		TSI	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to onlango											
2017 - Fall: N	lo Chango											
Comments:	to Change											
	N. Observe											
Comments:	g: No Change				_							
Comments.					_							

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	nent Category
8	Transite Counter Top	150	SF	Science Lab (Room 201)		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:					-								
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	No Change				_								
Comments:													
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	nent Category
9	Vibration Collar (isolation cloth)	100	LF	Ductwork throughout building - mechanical areas		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change]								
Comments:	<u> </u>												
2017 - Fall: N	No Change												
Comments:	To Onlango												
2017 - Spring	g: No Change												
Comments:	g. 110 Onango												
·				·									

		Quantity	Units		Type	Category		Type	Quantity	Units		
10	Hard plaster on walls & ceiling			Small Gymnasium (Handball Court)		Surface					YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				-							
Comments:	g											
2015 5 11 1												
2017 - Fall: N	No Change				4							
Comments:					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asse	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11	2' x 4' Metal covered ceiling tile			Throughout classrooms on the 1st & 2nd floors		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J											
2017 - Fall: N	No Change				-							
Comments:	10 Onlange				+							
Comments.					1							
2017 - Spring	g: No Change				1							
Comments:	-											
				·								

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	Duct interior lining			Mechanical/Fan Rooms		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13	Folding Doors Cloth Cover			Rooms 120 &122		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
14	Black pipe insulation			Mechanical/Fan Rooms		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to change											
LIANI	I Maradal Basadada	Maradal	I Marta dal	I Maria dalla andra	A -11	I Marcadal	Estate.				T Observe to Asser	0-1
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
15	Duct Exterior Insulation			Mechanical/Fan Room		TSI					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Onange				-							
]							
2017 - Fall: N	lo Change											
Comments:												
L					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
16	Interior window caulk			Throughout school		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	n rio Griango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	essment Category
TIANO	Waterial Description	Quantity	Units	Waterial Location	Type	Category	Thabic	Type	Quantity	Units	Onange in Asse	ossinent Oategory
17	Exterior window caulk - not AHERA			Exterior of building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Chango											
Comments:	io Change											
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18	Exterior window glaze - not AHERA			Exterior of building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
19	Lower Roof Field - not AHERA			Lower roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	Lower Roof Flashing - not AHERA			Lower roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	Upper Roof Field - not AHERA			Upper roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
22	Upper Roof Flashing - not AHERA			Upper roof		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
23	Stage Lights Electrical Insulation	20	LF	Auditorium		TSI	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

24	Carpet Mastic	18000	SF	108,110,114,200,202- 208,210,214,218,220- 224,226,228,230,232,234		Miscellaneous	No	None	0		YES	X NO
		•	•	•	İ	•		•	•	•		
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	-											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Sink Coating	135	SF	200, 201, 202, 204, 206, 208, 210, 212, 205, 214, 218, 220, 222,223, 224, 226,105,108, 110, 112, 114, 116, 118,120,122		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

26	12" x 12" White w/Blue Specks FT	2400	SF	Room 105,112,118		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	S:											
2017 - Fal	II: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
27	12" x 12" White w/Blue Specks FT Mastic	2400	SF	Room 105, 112, 118		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

28	12" x 12" Blue Speckled Floor Tile	225	SF	Room 105, 112, 118, and 212	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:	No Chango									
2017 - Fall: Comments:	No Change									
2017 - Sprin	g: No Change									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12" x 12" Blue Speckled Floor Tile Mastic	225	SF	Room 105, 112, 118, and 212		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
30	Beige Ceramic Floor Tile Grout	4000	SF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change				٦							
Comments												
2017 - Fall	I: No Change				-							
Comments	Ţ											
	ring: No Change											
Comments	3:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
TIATO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Type	Quantity	Units	Onange in As	ocosment Oategory
31	Brown Ceramic Baseboard Grout	600	LF	All 1st and 2nd Floor Washrooms, 1st Floor Janitors Closets, and Kitchen Area		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Fall	I: No Change											
Comments	s:											

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
32	Interior Door Caulk	1280	LF	All door on 1st and 2nd floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	ı: No Change											
Comments:	, ,											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
33	Burgandy Carpet Mastic	4600	SF	Main Office, Conf Room, Faculty Lounge, Asst Prin Office, Rms 106C and D, Student Services,		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Onange											
2017 - Spring Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	4" Black Vinyl Baseboard	600	LF	Assembly Hall, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				+							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
35	4" Black Vinyl Baseboard Adhesive	600	LF	Assembly Hall, 1st and 2nd Floor Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change				+							
Comments:	J											
2017 - Sprine	g: No Change				-							
Comments:	<i>y</i>											
•					1							

HA No

		Quantity	Units		Type	Category		Type	Quantity	Units		
36	Wall Expansion Joint Caulk	300	LF	Assembly Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				\neg							
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37	Drywall Ceiling	400	SF	Room 221		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: I	No Change				\neg							
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
38	Drywall Ceiling Joint Compound	50	SF	Room 221		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				\exists								
Comments:													
2017 - Fall: N	No Change												
Comments:	_												
2017 - Sprin	g: No Change												
Comments:	g. No Onange												
F	1	T	T	I	1	T	1 =		T =	T			
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in I	Assess	sment Category
39	Drywall Ceiling Joint Tape	32	LF	Room 221		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: I	No Change												
Comments:													
2017 - Fall: N	No Change												
Comments:	-												
2017 Sprin	a: No Chango												
Comments:	g: No Change												
Commonts.													

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
40	12" X 12" Beige Speckled Floor Tile (Patch)			2nd Floor Hall outside room 234 and Stairs		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	12" X 12" Beige Speckled Floor Tile (Patch)			2nd Floor Hall outside room 234 and Stairs		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring: No Change												
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
42	Gray Skid Pad Covering Adhesive	25	SF	Elevator		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:	V											
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
43	Ceramic Wall Tile Grout	20	SF	Janitors Closets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												

HA No

	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
44	Ceramic Wall Tile Adhesive	20	SF	Janitor's Closets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				\exists							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				_							
Comments:	. No onango											
HA No	Motorial Description	Material	Motorial	Material Location	Ashaotaa	Material	Friable	Domoso	Domogo	Domoses	Change in Acce	essment Category
HA NO	Material Description	Quantity	Material Units	Material Location	Asbestos Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
		Miscellaneous	No	None	0		VEC	X NO				
45	Gray Carpet Adhesive	4000	SF	Assembly Hall							YES	X
45 2016 - Fall: N		4000	SF	Assembly Hall	<u> </u>						TIES	<u> </u>
		4000	SF	Assembly Hall				1	1		LITES	<u> </u>
2016 - Fall: N Comments:	lo Change	4000	SF	Assembly Hall							LITES	
2016 - Fall: N	lo Change	4000	SF	Assembly Hall							LITES	<u> </u>
2016 - Fall: N Comments: 2017 - Fall: N Comments:	lo Change	4000	SF	Assembly Hall							LITES	<u> </u>
2016 - Fall: N Comments: 2017 - Fall: N	lo Change	4000	SF	Assembly Hall							LITES	<u> </u>
45	Gray Carpet Adhesive	4000	SF	Assembly Hall							TES	Ľ

46	12"x12" Grey w/Dark Grey Streaks VFT	3300	SF	Rooms 116,120,122		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:	No Change											
2017 - Sprii Comments:	2017 - Spring: No Change Comments:											
HA No Material Description Material Material Location						Material	Friable	Damago	Damago	Damage	Change in Assessme	ont Catagory
HA NO	Material Description	Quantity	Units	Material Location	Asbestos Type	Category	Filable	Damage Type	Damage Quantity	Units	Change in Assessine	ent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

3300

Material

Quantity

Material

Units

SF

Material Location

Rooms 116,120,122

HA No

47

Material Description

12"x12" Grey w/Dark Grey

Streaks VFT Mastic

48	12"x12" Beige w/White Streaks VFT	2740	SF	Room 208, 210, 212, 214, 226		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
2017 - Spring: No Change											

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
49	12"x12" Beige w/White Streaks VFT Mastic	740	SF	Room 208, 210, 212, 214, 226		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	12"x12" Red VFT	30	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
51	12"x12" Red VFT Mastic	30	SF	Room 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
52	Grey Patterned Carpet Mastic	1430	SF	Room 225(Library)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
В	Hard Joint Compound on Fiberglass Pipe Runs			Throughout school (above ceiling tiles)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Gerald Delgado Kanoon Elementary Magnet School
Date: 12/22/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 29071

SCHOOL'S ASBESTOS MANAGEMENT PLAN.