Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

29161

LaSalle Elementary Language Academy **Oracle Unit: Building ID:** Address: 1734 N. Orleans Street Region: 02 Mail Room: 33 Asbestos Surveyor: Rosas, Mr. Manuel X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/17/2017 Email Address: mrosas@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Friable Damage Change in Assessment Category Material Asbestos Material Damage Damage Quantity Units Type Category Quantity Type Lunchroom, Rms YES X NO 101,107,207 & 1st FI 02 9"x9" Brown Floor Tile 2400 SF Boy's Toilet. Landing by Miscellaneous No None 0 Boiler Room toilet. Mainteanance Room 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

School:

4420

03	9"x9" Gray Floor Tile	1500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change	•	•	•]	•	•	•	•	•	
Comments:	•				1						
2017 - Fall: N	lo Change				-						
Comments:	Ŭ										
2017 - Spring	g: No Change				_						
Comments:											

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Brown w/ white and gray streaks VFT	2000	SF	Room 109, 110, & 1st Floor Northeast Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
06	Brown Hard Coat Plaster	28000	SF	Throughout		Surface	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					=							
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change				_							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
09	9"x9" Brown Floor Tile Mastic	2400	SF	Lunchroom, Rms 101,107,207,1st Fl Boy's Toilet, Landing by Boiler Room Toilet		Miscellaneous	No	None	0		YES	Х МО
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:												
	ng: No Change											
Comments:												

10	9"x9" Gray Floor Tile Mastic	1500	SF	Office and Equipment Room, Engineer's office, Boiler room Stairway		Miscellaneous	No	None	0		YES	X NO
	•	•	•		· 1	•	=	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r: No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" White Floor Tile Mastic W/ Gray specks	1500	SF	Room 109, 110, & 1st Floor Northeast Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

12	12"x12" White w/ Beige Floor Tile	2000	SF	Principal's Office, Main Office, Health Suite, Faculty Room, and Stage	Miscellaneous	No	None	0	YES	X NO
2016 -	Fall: No Change	· .		·	·					
Comm										
2017 -	Fall: No Change									
Comm	nents:									
2017 -	Spring: No Change									

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" White w/ Beige Floor Tile Mastic	2000	SF	Principal's Office, Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	12" x 12" Ceiling Tiles w/Grooves	21000	SF	Throughout		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				-							
Comments.					-							
2017 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	12" x 12" Light Brown Streaked Floor Tile	900	SF	Enance to gym, hall by room 111 and 111A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	go											
2017 - Fall: N	lo Change											
Comments:												
0047 On sin a	N.a. Obasaasa				4							
2017 - Spring	j: No Change											

Comments:

15A	12" x 12" Light Brown Streaked Floor Tile Mastic	900	SF	Entrance to gym, hall by room 111 and 111A		Miscellaneous	No	None	0		YES	X NO
0040 Falls N	In Ohanan				1							
2016 - Fall: N	io Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
		•]							
LIA NI-	Material December	NA - Card - L	NA = (= = 2 = 1	Material Land Con	A -1 t	NA-12-1	Education .	D	D	D	Ol ' - A	

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
16	12" x 12" Gray Streaked Floor Tile	2700	SF	Room 111, 111A, Room doorway 206A, elevator, rooms 215 and 112,200, 201, and 2nd fl. corridor		Miscellaneous	No	None	0		YES X NO	
-					1							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Page 7

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessn	nent Category
16A	12" x 12" Gray Streaked Floor Tile Mastic	2700	SF	Room 111, 111A, doorway 206A, elevator, 2nd fl. corridor and rooms 215, 112, and 200, 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Spring: No Change												

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9" x 9" Green Streaked Floor Tile	4000	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

17A	9" x 9" Green Streaked Floor Tile Mastic	3200	SF	Rooms 206, 206A, 205, 204, 203, 209, 209A replacements		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change	<u> </u>		<u> </u>]						
Comments:	Comments:										
2017 - Sprii	ng: No Change										
Comments:											
2017 - Fall:	No Change										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	12 x 12 VFT Lt. Blue Mixed Speckled	1200	SF	2nd Floor Corridor and Lunch Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

19	12 x 12 Mastic Lt. Blue Mixed Speckled	1200	SF	2nd Flr Corridor and LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: No Change Comments:												
2017 - Sprii Comments:	2017 - Spring: No Change											
				T]	T	1		T =	T =		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

450

Material

Quantity

Material

Units

SF

Material Location

LunchRoom

HA No

20

Material Description

12 x 12 VFT Yellow Mixed

Speckled

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

21	12 x 12 Mastic Yellow Mixed Speckled	450	SF	LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments					1							
2017 - Fal	l: No Change				_							
Comments	S:				_							
	ring: No Change											
Comments	S:				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
22	12 X 12 VFT Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change]							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

23	12 x 12 Mastic Dark Blue with Lt. Blue Specs	600	SF	Rm 200 & Lunch Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change]							
Comment	is:											
2017 - Fa	II: No Change											
Comment	is:											
2017 - Sp	oring: No Change											
Comment	ts:											
					J							
HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
24	12 x 12 VFT Pink with Specs	200	SF	Rm. 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	go]							
2017 - Fall: N	No Change				-							

Comments:

2017 - Spring: No Change

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
25	12 x 12 Mastic Pink with Specs	200	SF	Rm. 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
26	12 x 12 VFT Dark Green Mixed Speckled	200	SF	LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	o change											
2017 Carina	No Change				4							
2017 - Spring Comments:	j. No Change				\dashv							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	12 x 12 Mastic Dark Green Mixed Speckled	200	SF	LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	Ü											
2017 - Spring	: No Change				_							
Comments:	i i i o o i a i go											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
28	12 x 12 VFT Lt. Green Mixed Speckled	200	SF	LunchRoom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	-											
2017 - Fall: N	o Change											
2017 - Fall: N Comments:	o Change											
Comments:												

12 X 12 Mastic Lt. Green Mixed Speckled	200	SF	LunchRoom		Miscellaneous	No	None	0		YES	X NO
No Change											
140 Ondrigo											
No Change											
a. Na Chanas				-							
ig: No Change				-							
				-							
Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	Quantity	Units		Туре	Category		Type	Quantity	Units		
12 x 12 VFT Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teacher's toilet		Miscellaneous	No	None	0		YES	X NO
	Mixed Speckled No Change No Change g: No Change Material Description 12 x 12 VFT Dark Brown	Mixed Speckled No Change No Change g: No Change Material Description Material Quantity 12 x 12 VFT Dark Brown 700	Mixed Speckled No Change No Change g: No Change Material Description Material Quantity 12 x 12 VFT Dark Brown 700 SF SF	Mixed Speckled No Change No Change g: No Change Material Description Material Quantity 12 x 12 VFT Dark Brown Mixed Speckled No Change Material Material Material Material Units 12 x 12 VFT Dark Brown Mixed Speckled 700 SF Rm 202 and 1st Floor Men & Womens	Mixed Speckled No Change No Change g: No Change Material Description Material Quantity Material Location LunchRoom Asbestos Type 12 x 12 VFT Dark Brown Mixed Speckled No Change Material Material Location Asbestos Type 12 x 12 VFT Dark Brown Mixed Speckled No Change	Mixed Speckled No Change No Change G: No Change Material Description Material Quantity Material Location LunchRoom Miscellaneous Miscellaneous	Mixed Speckled 200 SF LunchRoom Miscellaneous No No Change g: No Change Material Description Material Quantity Units Material Location Asbestos Type Category	Mixed Speckled 200 SF LunchRoom Miscellaneous No None No Change The property of the control of	Mixed Speckled 200 SF LunchRoom Miscellaneous No None 0 No Change Type Category Priable Damage Type Quantity 12 x 12 VFT Dark Brown Mixed Speckled Type Seekled Mone 10 No Change Material Description Material Units Rem 202 and 1st Floor Men & Womens Mixed Speckled Mone 10 No None 0 No None 0 No None 0 No None 0 No None 0	Miscellaneous No None 0 No Change To Change Material Description Material Quantity Units Material Location Asbestos Type Category Type Quantity Units Material Units Material Location Miscellaneous No None 0 No None 0 None No None N	Mixed Speckled 200 SF LunchKoom Miscellaneous No None 0 YES No Change The second of

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

Damage

Units

31	12 x 12 Mastic Dark Brown Mixed Speckled	700	SF	Rm 202 and 1st Floor Men & Womens Teachers Toilet		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change		<u> </u>		1					•	
Comments:					= - -						
2017 - Fall:	No Change				-						
Comments:											
2017 - Sprir	ng: No Change				1						
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Rm 202 and 1st Floor

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	Drywall	2000	SF	1st and 2nd Floor Boys and Girls Bathroom		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
017 - Fall: No Change	
Comments:	
017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

33	Carpet Mastic	700	SF	Room 208		Miscellaneous	No	None	0		YES X	NO
2016 - Fall:	: No Change				1							
Comments	:											
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments	:				1							
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment	Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

34	12 x 12 VFT Gray Mixed Speckled	2400	SF	Rm 107, 105, 103, 101, 210, 212, 213	
2016 - Fall: N	o Change				
Comments:					
0047 F.II N	. 01				
2017 - Fall: N	o Change				
Comments:					
2017 - Spring	: No Change				
Comments:					

Quantity

Material

Units

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

X NO

35	12 x 12 Mastic Gray Mixec Speckled	2400	SF	Rm 107, 105, 103, 101, 210, 212, 213	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:										
2017 - Fall: Comments:										
2017 - Sprir Comments:	ng: No Change									

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12 x 12 VFT Cream with Brown Specs	1200	SF	Rm 102 and 100		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
37	12 X 12 Mastic Cream with Brown Specs	1200	SF	Rm 102 and 100		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	o Change												
Comments:					_								
2017 - Fall: N	o Change												
Comments:													
2017 - Spring	: No Change			-									
Comments:	go												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	ment Category
38	1x1 Ceiling Tile	1000	SF	Gymnasium Stage		Miscellaneous	Yes	Loc	20		YES		X NO
2016 - Fall: N	o Change				7								
Comments:	•												
2017 - Spring	: No Change				_								
Comments:													
2017 - Fall: N	o Change				4								
Comments:	o onango				1								

39	Vinyl Baseboard Brown	3500	SF	1st and 2nd Corridors, Rooms 206, 209, 210, 213	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
A	Breeching Insulation	3250	SF	Boiler Room		TSI	Yes	Loc	10		YES	X NO
2016 - Fall: N Comments:	lo Change											

Comments:
2017 - Spring: No Change

Material Description

Comments:

2017 - Fall: No Change

HA No

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
В	Tank Insulation	250	SF	Boiler Room		TSI	Yes	Loc	4		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
	g: No Change											
Comments:			_									
2017 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
С	Aircell Pipe Insulation	2494	LF	Above Corridor Ceilings		TSI	Yes	Loc	2		YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Fall: N	No Change				-							
Comments:												
2017 - Spring: No Change												
Comments:]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
D	MJP E/F/V on Aircell Pipe Insulation	856	LF	Above Corridor Ceilings		TSI	Yes	Loc	5		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	: No Change											
Comments:	•											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
E	Cardboard Pipe Insulation	1800	LF	Throughout Building (See Hatching Maps)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				_							
Comments:												
2017 - Fall: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
F	MJP E/F/V on Cardboard Pipe Insulation	725	LF	Throughout Building (See Hatching Maps)		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	.											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	Boiler Caulk	40	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	J											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: No Change												
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
Н	Boiler Gasket	30	LF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
I	Duct Dampening Cloth	20	SF	Room 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	·											

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

J	12 x 12 Beige with Brown Specs Floor Tile	6000	SF	1st Floor Hallway;2nd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
					1							
2016 - Fa	I: No Change											
Comment	s:											
2017 - Sp	ring: No Change											
Comment	S:											
2017 - Fa	I: No Change											
Comment	s:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

6000

Material

Units

SF

Material Location

1st Floor Hallway, 2nd floor corridor

Material

Quantity

HA No

Κ

Material Description

12 x 12 Beige with Brown

Specs Floor Tile Mastic

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: LaSalle Elementary Language Academy
Date: 10/20/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.