Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

29201 Mark Sheridan Math & Science Academy 4920 School: **Oracle Unit: Building ID:** Address: 533 W. 27th St. Region: 04 Mail Room: 39 Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/11/2018 Email Address: jjheneghan@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type Throughout 1881 YES X NO 1A Plaster Construction 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
2A	2' X 4' Acoustical Ceiling Tile- Perforated			Rooms 105							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	go											
2017 - Fall: N	o Chango											
Comments:	o Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
2B	2' X 4' Acoustical Ceiling Tile- Lightly Fissured			Room 105							YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o onange											

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

		Quantity	Units		Type	Category		Type	Quantity	Units	<u> </u>	
2C	2' X 4' Fissured & Perforated Ceiling Tile			Room 008							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				+							
Comments:	to onlange				1							
2017 Caring	r. No Chango											
Comments:	g: No Change				+							
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
2D	2' X 4' Gypsum Ceiling Tile			2nd Floor (Men's Room)							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				1							
Comments:	, <u> </u>											
2017 - Fall: N	lo Change				-							
Comments:	to oriange											

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ЗА	12" X 12" Floor Tile (Speckled/Tan)	4500	SF	1st FL-Toilet, 2nd FL- Janitor's Closet, Room 311, 008, 3rd floor hallway, 009,210,108		Miscellaneous	No	None	0		YES X NO
0040 =					7						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3B	12" X 12" Floor Tile (Red/Speckled)	3000	SF	Rooms 106, 206, 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

3C	12" X 12" Floor Tile (Dark Beige)	300	SF	2nd FL- Janitor's Closets (Right & Left), 3rd FL Janitor's Closet	Miscellaneous	No	None	0	YES	X NO
	II: No Change				·					
Comment	S:									
2017 - Sp	ring: No Change									
Comment	S:									
2017 - Fal	II: No Change									

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
3D	12" X 12" Floor Tile (Beige Marbled)	800	SF	Boy's Playroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
3E	12" X 12" Floor Tile (Cream)	800	SF	Girl's Playroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
3F	12" X 12" Floor Tile (White)	800	SF	Room 008		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	J -											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
3G	12" X 12" Floor Tile (Light Tan Patches)	2000	SF	101, 3rd FL Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	j: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
3Н	12x12 Gray FT W/White, Gray Specks	1080	SF	Engineer Office and Adjacent Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4A	Mastic for 12x12 Speckled/Tan Floor Tile	11000	SF	008, 009, 210, Basement LR,See HA 3A Locations, 108, 311, 3rd floor halway, first floor toilet, 2nd floor janitors closet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
4B	Mastic for 12x12 Red/Speckled Floor Tile	2100	SF	Rooms 206, 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:	
2017 - Fall: No Change Comments: 2017 - Spring: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change	Comments:
Comments: 2017 - Spring: No Change	
2017 - Spring: No Change	2017 - Fall: No Change
	Comments:
Comments:	2017 - Spring: No Change
	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4C	Mastic for 12x12 Floor Tile (Dark Beige)			2nd and 3rd Floor Janitor's Closets							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4D	Mastic for 12x12 Floor Tile (Beige Marbled)			Boy's Playroom							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4E	Mastic for 12x12 Floor Tile (Cream)			Girl's Playroom							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
4F	Mastic for 12x12 Floor Tile (White)			room 008							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
4G	Mastic for 12x12 Floor Tile (Light Tan Patches)	40	SF	101, 3rd Floor Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Spring	g: No Change				=							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
4H	12x12 gray FT W/White, Gray Specks Mastic	1080	SF	Engineer Office and Adjacent Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	V				1							
2017 - Spring	g: No Change				-							
Comments:	,											
2017 - Fall: N	lo Change				_							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
5	Plaster Walls			1902 building							YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to change											
	Inc. in the		T	I sa e e e e		Taxa e e e	Levis	T 5	1.5	1.5	To:	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
6	Black Vinyl Cove Base			Basement, 1st, 2nd							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
6A/7	Adhesive for Black Vinyl Cove Base			Basement, 1st, 2nd							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
8	Plaster on Sheetrock			Basement							YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	i. 110 Ondrigo											
2017 - Fall: N	lo Chango											
Comments:	lo Change											
2 3												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
9	Sheetrock			Scattered							YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
2017 - Fall: N Comments:	lo Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
9A	Joint Compound on Sheetrock	Quantity	Units	Scattered	Туре	Category		Туре	Quantity	Units	YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:								,				
2 2												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
11	Caulk			2nd Floor Urinals							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12	4"x4" White Ceramic Tile			2nd Floor Walls							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	, g-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12A	Grout for 4"x4" White Ceramic Tile			2nd Floor Walls							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
12B	Mastic for 4"x4" White Ceramic Tile			2nd floor walls							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13A	Grout for 1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:				·	_							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
13B	Mastic for 1"x1" Pastel Ceramic Tile			2nd Floor Restroom Floors							YES	X NO
2016 - Fall: I	No Change											
Comments:	_											
2017 - Fall: I	No Change											
Comments:	J											
2017 - Sprin	g: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom							YES	X NO
2016 - Fall: I	No Change											
Comments:	Ţ.											
2017 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change				\dashv							
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

14A	Grout for 1"x1" Dark Multi- Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom							YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Spi	ring: No Change											
Comments												
	l: No Change											
Comments	S:				_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14B	Adhesive for 1"x1" Dark Multi-Colored Ceramic Tile			Basement Restrooms and Entry to 1st Floor Boy's Restroom							YES	X NO
2016 - Fal	I: No Change				7							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
15	Wood Window Glaze			1881- Interior Hallways							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
1,777	Material Description	Quantity	Units	Waterial Education	Туре	Category	THADIC	Type	Quantity	Units	Orlange in 7,000	Joshiem Galegory
15A	Wood Window Glaze			1902- Interior Hallways							YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	Metal Window Glaze			1976- Interior Abated 1999							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	Metal Window Caulk			1976- Exterior Not AHERA							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					4							
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18	New 2"x8" Brick			Interior							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to onange											
<u> </u>	T		1	T		1		T _	T	1_	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
18A	Mortar for 2"x8" Brick			Interior							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	NO Change											
	g: No Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
19	2"x8" Glazed Brick			Interior Basement Restrooms							YES	X NO
2016 - Fall: N	No Change				\exists							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	10 011411.go											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
1,,,,,,,	Material Becomplien	Quantity	Units	Waterial Legation	Туре	Category	1 Habio	Type	Quantity	Units	Ondingo in 7 too	occomonic Catogory
19A	Mortar for 2"x8" Glazed Brick			Interior Basement Restrooms							YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	Jo Changa											
Comments:	NO Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	Interior Brick			1881- Basement							YES	X NO
2016 - Fall: N	lo Change				\exists							
Comments.												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Chango											
Comments:	io Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20A	Mortar for Interior Brick			1881- Basement							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	Interior Brick			1902- Basement							YES	X NO
2016 - Fall: N	No Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
21A	Mortar for Interior Brick			1902- Basement							YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	\ssess	ment Category
22	8"x16" Glazed Block			Basement Restrooms							YES	<u> </u>	X NO
2016 - Fall: N	lo Change												
Comments:					-								
2017 - Spring	g: No Change												
Comments:	_												
2017 - Fall: N	lo Change				_								
Comments:	io Change												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
22A	Mortar for 8"x16" Glazed Block			Basement Restrooms							YES		X NO
2016 - Fall: N	lo Change												
Comments:	•												
2017 Fall: N	la Changa				_								
2017 - Fall: N	io Change				_								
Comments.													
	g: No Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23	8"x16" Cinderblock			Scattered							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
23A	Mortar for 8"x16" Cinderblock			Scattered							YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	,											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	Exterior Brick- Not AHERA			1881- Exterior							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
24A	Mortar for Exterior Brick- Not AHERA			1881- Exterior							YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r. No Change											
Comments:	g. 110 Chango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	Exterior Brick- Not AHERA			1902- Exterior							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
25A	Mortar for Exterior Brick- Not AHERA			1902- Exterior							YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	g. 110 Chango											

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
26	Ceramic Caulk			2nd Floor Restrooms							YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	Sink Insulation, Sink Under Coating	100	SF	Rooms 102 and 202, 007		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:]							
2017 - Spring	g: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

28	9x9 VFT, Beneath 12x12 VFT	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Sprii Comments:	ng: No Change											
2017 - Fall: Comments:	No Change											
		1]	1	1 =	T-	1 -		La	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

YES

Change in Assessment Category

X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		

1200

Material

Units

SF

Material

Quantity

Material Location

Lunchroom, Beneath

12x12 VFT

HA No

28A

Material Description

Mastic for 9x9 VFT,

Beneath 12x12 VFT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
29	Window Frame Caulk			1881- Interior							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to oriango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIA NO	Material Description	Quantity	Units	Material Education	Type	Category	Thable	Type	Quantity	Units	Change in Asse	SSITIETI Category
30	Window Frame Caulk			1902- Interior							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	1'x1' Ceiling Tile			3rd Floor Hallway							YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	Cloth Window Blinds			1976- Throughout							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	i. 110 Chango											
0047 5 11 11												
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	Window Caulk			1998- Exterior Not AHERA		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	4" Gray Vinyl Baseboard	180	LF	Engineer's Office and Teachers' Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											

35	4" Gray Vinyl Baseboard Adhesive	180	LF	Engineer's Office and Teachers' Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:]							
2017 - Spring	ı: No Change				1							
Comments:												
2017 - Fall: No Change												
Comments:	Ţ.											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
36	Blue Ceramic Floor Tile Grout	60	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:]							
2017 - Spring	ı: No Change				_							
Comments:	,]							
1												

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

37	4" It Gray Vinyl Baseboard	30	LF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	<u> </u>											
2017 - Spring	g: No Change				-							
Comments:	•				1							
2017 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
38	4" Lt Gray Vinyl Baseboard Adhesive	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	·			·	_							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

39	White Ceramic Wall Tile Grout	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	: No Change				-							
Comments:	•]							
2017 - Fall: N	lo Change											
Comments:]							
					j							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
40	White Ceramic Wall Tile Adhesive	30	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	ı: No Change											
Comments:	,											
1												

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41	18"x18" White Ceramic Tile	60	SF	Engineer's Office Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>]							
2017 - Fall: N	o Change				_							
Comments:	<u> </u>											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
42	Blue,Red,Yellow,Purple Multi-Color Carpet Adhesive	1600	SF	Computer Lab and Room 007		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	ir ito onango											
2017 - Fall: N	o Change				<u> </u>							
Comments:	o Change				1							

43	4" Brown Vinyl Baseboard	300	SF	Computer Lab, Room 007 and Lunchroom area		Miscellaneous	No	None	0		YES	X NO
	-				1							
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

300

Material

Quantity

Material

Units

LF

Material Location

Computer Lab, Room

007, Lunchroom Area

HA No

44

Material Description

4" Brown Vinyl Baseboard

Adhesive

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45	Blue Carpet Mastic	1600	SF	Library, 2nd Floor Counselor's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				\neg							
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	J											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
46	Blue Vinyl Baseboard	40	LF	Room 008		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
47	Blue Vinyl Baseboard Adhesive	40	LF	Room 008		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	: No Change				-							
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	io onango				-							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
48	12"x12" Lt Beige Floor Tile	4000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311		Miscellaneous	No	Loc	12		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	Ğ											
2017 - Spring	ı: No Change											
Comments:	i i i i i i i i i i i i i i i i i i i				-							
2017 - Fall: N	lo Chango											
Comments:	io Grange				-							
					1							

49	12"x12" Lt Beige Floor Tile Mastic	4000	SF	Lunchroom/Serving Area, 3rd Floor Hall and MDF Room 311	Miscellaneous	No	Loc	12		YES	X NO
0040 Fall N	- Oh	•	•	•	•	•	•	•	•		
2016 - Fall: N	o Cnange										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	Green Carpet Mastic	1200	SF	Main Office and Asst. Principal's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

51	12"x12" Orange/Rust Floor Tile	3100	SF	Room 202,207,106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Cago											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
52	12"x12" Orange/Rust Floor Tile Mastic	3100	SF	Room 202,207,106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	go											
2017 - Spring	ı: No Change											
Comments:	J. 140 Onlange											
2017 - Fall: N	2017 - Fall: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

											1	
53	Lab Tables	150	SF	Lab Rooms 202 and 309		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	g: No Change				-							
Comments:	,											
2017 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
54	12"x12" Gray Floor Tile w/ White and Black Spots	50	SF	Room 107 Washroom, Boiler Room Stair Landing and Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	y -				-							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

Material Description

55	12"x12" Gray Floor Tile w/Wht & Blk Spots Mastic	50	SF	Room 107 Washroom, Boiler Room Stair Landing and Washroom		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											
]						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
56	Kiln brick	20	SF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Room 107 Washroom,

HA No

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
Α	Fiberglass Pipe Insulation			Throughout							YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
2017 - Spring	ı: No Change												
Comments:	,												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssess	ment Category
	·	Quantity	Units		Туре	Category		Туре	Quantity	Units			
В	Fiberglass Joint Insulation	200	LF	Throughout Bldg. Boiler Room, Mechanical Room and Chases		TSI	Yes	None	0		YES		X NO
2016 - Fall: N	lo Change				1								
Comments:													
2017 - Fall: N	lo Chango												
Comments:	io Change												
2017 - Spring	յ։ No Change												
Comments:													
					J								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
С	Cardboard Pipe Insulation	2000	LF	1902- Basement, 102, 202		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r. No Change				-							
Comments:	g. No Change											
		1	·	T				_			1	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
D	Cardboard Joint Insulation	250	LF	1902- Basement, 102, 202		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:	,go											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
E	Aircell Pipe Insulation	680	LF	1881- Basement and Fan Rooms		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2017 - Fall: I	No Change											
Comments:	go											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
F	Aircell Joint Insulation	81	LF	1881- Basement and Fan Rooms		TSI	Yes	Loc	8		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Fall: I	No Change											
Comments:	110 Onango											
2017 Sprin	g: No Change											
Comments:	g. No Change											
Commonto.												

HA No

		Quantity	Units		Type	Category		Type	Quantity	Units		
G	Boiler Gaskets	40	LF	Inspection Doors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
Н	Boiler Rope Gaskets	30	LF	Clean-Out Doors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												

Material

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
1	Interior Fire Brick	100	SF	Boilers		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
J	Hot Water Make-up Tank Insulation			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
K	Breeching (Brick Lining)			Incinerator							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N	g: No Change											
Comments:	no Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
L	Breeching Liner	150	SF	Boilers		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
М	Refractory Brick	10	SF	Boilers		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N Comments:	lo Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
N	Fire Brick			Incinerator							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
0	Chimney Brick			Boiler Room							YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N Comments:	lo Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asse	ssifient Category
O1	Chimney Brick Mortar			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Р	Chimney Liner Brick			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	3											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
1000	Waterial Description	Quantity	Units	Waterial Education	Туре	Category	Thabic	Type	Quantity	Units	Ondrige in 7.000	ooment oategory
P1	Chimney Liner Brick Mortar			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ü											
2017 - Fall: N	lo Change											
Comments:	io Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
Q	Chimney Soot			Boiler Room							YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring Comments:	g: No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
R- Field	Roof Field - Not AHERA			Roof- Section E							YES	X NO
2016 - Fall: N Comments: 2017 - Spring Comments: 2017 - Fall: N Comments:	g: No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
R- Flash	Roof Flashings - Not AHERA			Roof- Section E							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
TIA NO	Material Description	Quantity	Units	Waterial Location	Type	Category	Thable	Type	Quantity	Units	Change in Asse	ssiment Category
R- X Joint	Expansion Joint			Roof- Section E							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Block Pipe Insulation	30	LF	1881 Building- Throughout Building		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Mark Sheridan Math & Science Academy
Date:1/11/2018
-
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 29201