## **Chicago Public Schools**

## **6 Month Asbestos Surveillance** 2017 - Fall

29251

**Oracle Unit:** 

**Building ID:** Address: 3200 S. Calumet Region: 03 Mail Room: Asbestos Surveyor: Edgerley, Mr. Craig X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/19/2018 Email Address: cedgerley@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's calendar Notice printed in school's newsletter Each child's backpack Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES X NO Spray-on Fireproofing Miscellaneous Boiler room 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

John J Pershing Elementary Humanities Magnet

School:

3090

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
2	2' x 4' Ceiling Tile			North West Stairwell		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					+							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				4							
Comments:	g. No Change											
Commonto:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
3	2' x 2' Ceiling Tile	1200	SF	Office and Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	go											
2017 0 :	N. O.											
2017 - Spring	g: No Change				_							
Comments:					-							
L												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
4,5,6	Plaster	300000	SF	Throughout building		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:	_											
2017 - Spring	· No Change											
Comments:	. No Onlange											
HA No	Material Description	Matarial	Matarial	Material Leastice	A = h = = t = =	Matarial	Telebia	D	D		Change in Assa	
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
7	12" x 12" Beige w/White Streaks Floor Tile			1st, 2nd, and 3rd Floor Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	V											
2017 - Spring	: No Change											
Comments:	. 110 Griarige											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
8	9" x 9" Brown w/White Streaks Floor Tile			Room 115		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
9	9" x 9" Black w/White Streaks Floor Tile			Rooms 111, 127		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	ı: No Change											
Comments:	<i>.</i>											

10,12	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Comments:  2017 - Fall: No Change  Comments:  2017 - Spring: No Change  Comments:  HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Priable Damage Quantity Units Priable Damage Quantity Units Priable Damage Type Quantity Units Priable Damage Quantity Units Priable Damage Quantity Units Priable Damage Quantity Units Priable Damage Type Quantity Units Priable Damage Quantity Units Priable Damage Type Quantity Units Priable Damage	10,12	Aircell Duct Breeching	800	SF	Plenum Chambers		TSI	Yes	None	0		YES	X NO
2017 - Fall: No Change Comments:  2017 - Spring: No Change Comments:  HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Damage Quantity Units No None 0 YES X NO  2016 - Fall: No Change Comments:		lo Change											
Comments:  HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Material Description Type Quantity Units Material Category Units Material Category Type Quantity Units Material Category Units Material Catego	Comments:												
Comments:  HA No Material Description Material Quantity Units Material Location Type Category Type Quantity Units Material Description Type Quantity Units Material Category Units Material Category Type Quantity Units Material Category Units Material Catego	2017 - Fall: N	lo Change											
HA No Material Description Material Units Material Location Asbestos Type Category Friable Damage Type Quantity Units Change in Assessment Category  11 Gasket 20 LF Boiler Room TSI No None 0 TYES X NO  2016 - Fall: No Change Comments:	Comments:												
HA No Material Description Material Units Material Location Asbestos Type Category Friable Damage Type Quantity Units Change in Assessment Category  11 Gasket 20 LF Boiler Room TSI No None 0 TYES X NO  2016 - Fall: No Change Comments:	2017 - Spring	r. No Change											
Quantity Units Type Category Type Quantity Units  11 Gasket 20 LF Boiler Room TSI No None 0 YES X NO  2016 - Fall: No Change  Comments:		j. 110 Onango											
Quantity Units Type Category Type Quantity Units  11 Gasket 20 LF Boiler Room TSI No None 0 YES X NO  2016 - Fall: No Change  Comments:													
Quantity Units Type Category Type Quantity Units  11 Gasket 20 LF Boiler Room TSI No None 0 TYES X NO  2016 - Fall: No Change Comments:	HA No	Material Description	Material	Material	Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
2016 - Fall: No Change Comments:	15,770	Material Becompiler			Material Education			i nabio					oomoni Galogory
Comments:	11	Gasket	20	LF	Boiler Room		TSI	No	None	0		YES	X NO
Comments:	2016 - Fall: N	lo Change											
2017 - Fall: No Change													
	2017 - Fall: N	lo Chango				_							
Comments:		io Change											
2017 - Spring: No Change		g: No Change				_							
Comments:	Comments:					=							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13	12" x 12" Beige w/White Streaks Floor Tile Mastic			1st, 2nd and 3rd Floor Corridors		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	V											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	9" x 9" Black w/White Streaks Floor Tile Mastic		SF	Rooms 111, 127, 1st , 2nd, and 3rd floor corridors edge design		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	o Change											
	NI- Ol-											
2017 - Spring Comments:	: No Change				-							
Commond.												

15	9" x 9" Brown w/White Streaks Floor Tile Mastic	SF	1st, 2nd, and 3rd Floor Corridors edge design	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change								
Comments:	J.								
2017 - Fall: N	lo Change								
Comments:									
2017 - Spring	g: No Change								
Comments:									
			I are a series of	 			_	0	

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12" x 12" Beige w/Brown Streaks Floor Tile	4700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	ssment Category
17	12" x 12" Beige w/Brown Streaks Floor Tile Mastic	4700	SF	Engineers office, Library, elevator lobby 1-3, Rm 231, Teacher's Lounge, Office, Rm 127, 123, 111, 1st and 2nd floor corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	110 Chango				-							
2017 - Fall:	No Chango				1							
Comments:	No Change				<u> </u>							
	ig: No Change				-							
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18	12" x 12" Crème Floor Tile			Rooms 319 and 325		Miscellaneous					YES	X NO
2016 - Fall:	No Change				]							
Comments:	<u> </u>											
2017 - Fall:	No Change				-							
Comments:	Ţ											
2017 - Sprin	ıg: No Change											
Comments:	.g to Onango											
	·			•	]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
19	12" x 12" Crème Floor Tile Mastic			Rm 325		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
20	12" x 12" Brown Floor Tile	1200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg, north bldg adjacent to HA 16		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	- To or one go											
2017 - Fall:	No Change											
Comments:	No Change											
	ng: No Change											
Comments:												

21	12" x 12" Brown Floor Tile Mastic	1200	SF	1st, 2nd, and 3rd Floor Corridors Against Walls, In south bldg		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	II: No Change			<u> </u>	1					•	
Comment					-						
2017 - Fal	II: No Change				-						
Comment											
2017 - Sp	ring: No Change				-						
Comment	S:										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	12" x 12" Cream w/Brown Streaks Floor Tile	1000	SF	(1924 bldg) North West Stairwells in Basement, 1st, and 2nd Floors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23	12" x 12" Cream w/Brown Streaks Floor Tile Mastic	1000	SF	(1924 bldg) North West Stairwells in Basement, 1st and 2nd Floors, Basement Delivery Ramp, Lunchroom, 3rd Floor Stairwell		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:	10 Onango											
2017 Carin	ar No Chongo											
Comments:	g: No Change				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Туре	Quantity	Units	Onange in Asses	Smerit Gategory
24	9" x 9" Tan Floor Tile			Room 127		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				1		•	•				
Comments:	<u> </u>											
2017 - Fall: N	No Change				<u> </u>							
Comments:	- commige											
2017 - Spring	g: No Change			·	1							
Comments:	g. No Change				1							
					1							

		Quantity	Units		Type	Category		Type	Quantity	Units		
25	9" x 9" Tan Floor Tile Mastic			Room 127		Miscellaneous					YES	X NO
2016 - Fall: No	o Change				]							
Comments:												
2017 - Fall: No	o Change				_							
Comments:	•											
2017 - Spring:	: No Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	Carpet mastic -Brown Multi - colored			Basement Room 100, rm 310		Miscellaneous					YES	X NO
2016 - Fall: No	o Change				]							
Comments:	J											
2017 - Spring:	: No Change											
Comments:												
2017 - Fall: No	o Change				-							
Comments:												
					J							

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

		Quantity	Units		Type	Category		Туре	Quantity	Units		
27	Exterior Window Caulk - Not AHERA			Exterior of Windows on South West Side		Miscellaneous	No				YES	X NO
2016 - Fall:	No Change				7							
Comments:	-											
	ng: No Change											
Comments:					-							
2017 - Fall:	No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	Window Glaze - Not AHERA			Exterior of Windows on South West Side		Miscellaneous	No				YES	X NO
2016 - Fall:	No Change				7							
Comments:	-				]							
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
					_							

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
29	Exterior Door Caulk - Not AHERA			Exterior Doors		Miscellaneous	No				YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
30	Brick - Not AHERA			Exterior of Building		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:	_												
2017 - Spring	ı: No Change												
Comments:	•												
2017 - Fall: N	lo Change												
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	Brick Mortar - Not AHERA			Exterior of Building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2017 Falls N	la Changa											
2017 - Fall: N Comments:	io Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
32	9" x 9" Green Floor Tile			Room 111		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<b>V</b>											
2017 - Fall: N	lo Chango											
Comments:	io Change											
Commonto:												
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	9" x 9" Green Floor Tile Mastic			Room 111		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	_											
2017 - Fall: N	o Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
34	12" x 12" Brown w/White Streaks Floor Tile	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	o onange											
2017 Spring	· No Chango											
2017 - Spring Comments:	. NO Change				+							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
35	12" x 12" Brown w/White Streaks Floor Tile Mastic	1200	SF	Lunchroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
36	Roof Flashing - Non AHERA			Roof		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:												

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37	Roof Field - Non AHERA			Roof		Miscellaneous	No				YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
38	Size Unknown Floor Tile (Under Carpet)			Room 100, Office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
39	Size Unknown Floor Tile (Under Carpet) Mastic			Room 100		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
40	9" x 9" Dark Brown Floor Tile			Room 127		Miscellaneous					YES	X NO
	No Change											
12016 - Fall: N	10 01101119											
2016 - Fall: N Comments:												
Comments:	lo Chango											
Comments: 2017 - Fall: N	lo Change											
Comments: 2017 - Fall: N Comments:	-											
Comments: 2017 - Fall: N Comments:	No Change g: No Change											
	No Change							1	1			

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	9' x 9" Dark Brown Floor Tile Mastic			Room 127		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
	g: No Change											
Comments:	, , , , , , , , , , , , , , , , , , ,											
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
42	Red Carpet Adhesive			Auditorium		Miscellaneous		None			YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring Comments:	g: No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
43	Blue Carpet Adhesive			Rooms 200		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. No Change											
<u> </u>				1			T =		T =	1 =	1	-
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
44	Vault Door Liner	15	SF	Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	o Change											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
45	Incinerator Interior Material	160	SF	Boiler Room Addition		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
46	12" x 12" Black Floor Tile against Wall			Room 319		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
47	12" x 12" Black Floor Tile Mastic against Wall			Room 319		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	յ։ No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
48	12"x12" Cream/Gray Speckled Floor Tile			Engineers Office		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units		
49	12"x12" Cream/Gray Speckled Floor Tile-Mastic			Engineer's Office		Miscellaneous		None			YES	X NO
2016 - Fall: N	No Change											
Comments:	•											
2017 - Fall: N	No Change				_							
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Onlange											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Ass	sessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
50	4" Brown Vinyl Baseboard	46	LF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 110 Onango											
			•									

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
51	4" Brown Vinyl Baseboard - Adhesive	46	LF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change				7							
Comments	:											
2017 - Fall	No Change				1							
Comments	<u> </u>											
2017 - Spri	ng: No Change				-							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
52	12"x12" Cream/Beige Speckled Floor Tile	4900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	No Change											
Comments												
2017 Fall	No Change											
Comments					1							
	ng: No Change				_							
Comments	•											

53	12"x12" Cream/Beige Speckled Floor Tile-Mastic	4900	SF	1st, 2nd, 3rd Floor Elevator Areas, Rooms 306, 123, 127, 111, Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				]							
Comments												
2017 - Fall:	: No Change											
Comments	:											
2017 - Spri	ing: No Change											
Comments	:											
HA No	Material Description	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category		
54	6" Black Vinyl Baseboard	100	LF	1st, 2nd, 3rd Floor Elevator Areas		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
	-				-1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
55	6" Black Vinyl Baseboard Adhesive	100	SF	1st, 2nd, 3rd Floor Elevator Areas		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>				=							
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:	Ü											
			_									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
56	2x2 Gypsum Ceiling Tile	800	SF	Kitchen		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>				1							
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change											
Comments:	o onango				_							
				<u> </u>								

HA No

Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u></u>	
57	12x12 Tan Mottle Floor Tile	2500	SF	Lunchroom in Basement		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	_											
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	ı: No Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
58	12x12 Tan Mottle Floor Tile Mastic	2500	SF	Lunchroom in Basement		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	-				]							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
					1							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
59	Lab Counters	10	SF	Room 211		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					]							
2017 - Fall: N	lo Change				_							
Comments:					_							
2017 - Spring	g: No Change											
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	Tan Rubber Floor Adhesive	100	SF	NW Entrance		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					-							
2017 - Fall: N	lo Change											
Comments:	Comments:											
2017 - Spring	g: No Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Type	Category		Type	Quantity	Units		
61	Brown Carpet Adhesive	1800	SF	Multipurpose Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
62	Grey Multipurpose Adhesive	2000	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:	<u>-</u>											

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

		Quantity	Units		Type	Category		Type	Quantity	Units		
63	Decorative Plaster	15000	SF	Auditorium		Surface	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments	): :											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
64	Decorative Plaster Ceiling	5000	SF	Auditorium		Surface	Yes	None	0		YES	X NO
2016 - Fall	: No Change											
Comments												
2017 - Fall	: No Change											
Comments	): 											
	ing: No Change											
Comments	);											

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
65	Terrazzo	5000	SF	1924 Building 1st, 2nd, and 3rd Corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>											
2017 - Fall:	No Change				1							
Comments:												
	g: No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
E	Boiler #1 Insulation	400	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:					4							
	g: No Change											
Comments:					_							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
F	Boiler # 2 Insulation	400	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Н	Fittings Off Fiberglass Pipe Insulation			Fan Rooms and Basement		TSI		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
I	Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Hallway		TSI		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:					]							
2017 - Sprii	ng: No Change				1							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
J	Fittings Off Aircell Pipe Insulation			Boys & Girls Washrms in basement, 1st, 2nd, 3rd floors, Sm Lunchrm, Auditorium, Bsmnt Fan Room		TSI					YES	X NO
2016 - Fall:	No Change				7							
Comments:					1							
2017 - Fall:	No Change				-							
Comments:					]							
2017 - Spring: No Change												
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
К	Mag (Preformed) Pipe Insulation			Basement Corridor and Fan Room		TSI		None			YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L	Fittings Off Mag Pipe Insulation			Basement Corridor and Fan Rooms		TSI		None			YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Sprin	g: No Change				-							
Comments:					]							
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
М	Cardboard Pipe Insulation			Boiler Room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
N	Fittings on Cardboard Pipe Insulation			Boiler Room		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Canvas (Thermal) Pipe Wrap	0		Basement Plenum Chamber		TSI					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John J Pershing Elementary Humanities Magnet
Date: 1/19/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
X A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 29251

SCHOOL'S ASBESTOS MANAGEMENT PLAN.