Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

John H Vanderpoel Elementary Magnet School 29311 6250 School: **Oracle Unit: Building ID:** Address: 9510 S Prospect Avenue Region: 06 Mail Room: Asbestos Surveyor: Alvarado, Edwin X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/5/2017 Email Address: ealvarado36@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Type Quantity YES 03 SF X NO Acoustical Celing Plaster 180 East Vestibule of Gym Yes None 0 Surface 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

07A	12x12 White w/Green Streaks Floor Tile	222	SF	Assitant Principal's Office, Closet/Washroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	. to onango											
2017 - Fall:	No Change				_							
Comments:												
2017 - Sprin	g: No Change				-							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
08A	12 x 12 White w/Green Streaks Floor Tile	410	SF	Gym Office and 1st Floor Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•			1							
Comments:]							
2017 - Fall:	No Change				-							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
09A	12x12 White w/Green Streaks Floor Tile Mastic	300	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	io onango											
					1							
2017 - Fall: N	lo Change				_							
Comments:					_							
2017 - Spring	g: No Change				-							
Comments:	<i>y</i>											
	T	T	T	T	1				T	T		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09B	12x12 White w/Green Streaks Floor Tile	4700	SF	Rooms: 103, 103P, 105, 2nd Floor Corridor, 2nd Floor East Landing, 3rd Floor Corridor	71	Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	to oriange											
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change				1							

Asbestos

Damage

Friable

Damage

Damage

Material Material Location

HA No

Comments:

Material Description

Material

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09C	12x12 Brown Floor Tile (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	-]							
2017 - Spring	ı: No Change				-							
Comments:	,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09D	12x12 White Floor Tile (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	n. No Change				-							
Comments:	j. 110 Onlango				_							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09E	12x12 Tan w/Brown Specks Floor Tile	1600	SF	Library, Room 300 & 305		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Spring	: No Change											
Comments:	· ·											
2017 - Fall: N	lo Change				-							
Comments:	o onango				-							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
09F	12x12 Brown Floor Tile (Checkered)	510	SF	Main Office, Principal's Office, and Janitors Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	· No Change				-							
Comments:	. 110 Ondrigo				-							
2017 Fall: N	lo Chango]							
2017 - Fall: N Comments:	o Change				_							
					1							

09G	12x12 White Floor Tile (Checkered)	510	SF	Main Office, Principal's Office, and Janitors Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•	•	•	•	
Comments:												
2017 - Spri	ng: No Change				-							
Comments:					1							
2017 - Fall:	No Change				=							
Comments:	-				1							

Type

Material

Category

Friable

Damage

Туре

Material Location

Main Office, Principal's

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12x12 White w/Green Streaks Floor Tile Mastic	222	SF	Assistant Pricipal's Office, Closet/Washroom		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
	·
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Damage

Quantity

Damage

Units

									_			
12A	12 x 12 White w/Green Streaks Floor Tile Mastic	410	SF	Gym Office, 1st Floor Hall		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	No Change											
Comments:	go											
2017 - Spring	g: No Change											
Comments:	g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13A	12x12 White w/ Green Streaks Floor Tile Mastic	300	SF	Room 104		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Fall: N	Vo Change											
Comments:												
		<u> </u>										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13B	12x12 White w/Green Floor Tile Mastic	4700	SF	Rooms: 103, 104, 105, 2nd Floor Corridor, 2nd Floor East Landing, 3rd Floor Corridor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N Comments:	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13C	12x12 Brown Floor Tile Mastic (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

13D	12x12 White Floor Tile Mastic (Checkered)	240	SF	Teacher's Lounge/Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change]							
Comments	U											
2017 - Fall	l: No Change											
Comments	S:				1							
	ing: No Change]							
Comments	3:				_							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13E	12x12 Tan w/Brown Specks Floor Tile	1600	SF	Library, Room 300 & 305		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Units

13F	12x12 Brown Floor tile Mastic (Checkered)	510	SF	Main Office, Principal's Office, and Janitors Office	Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change			·		•		•	•	•	
2017 - Spring	r. No Change										
Comments:	g. 140 Change										
2017 - Fall: N	lo Change										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13G	12x12 White Floor Tile Mastic (Checkered)	510	SF	Main Office, Principal's Office, and Janitors Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	Black Mopboard	60	LF	1st Floor Addition Corridor		Miscellaneous	No		0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	Black Mopboard Mastic	60	LF	1st Floor Addition Corridor		Miscellaneous	No		0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12x12 White w/Green Streaks Floor Tile	3300	SF	1st Floor Corridor (Addition)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	2'x4' Ceiling Tile	9100	SF	1st, 2nd and 3rd Floor Corridors		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
18	Tank Insulation	100	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	: No Change				_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
19	Brown Mosaic Ceramic Tile Grout	Quantity 2550	Units	1st, 2nd and 3rd Floor Boys and Girls and Teachers Washrooms	Type	Category Miscellaneous	Yes	None	Quantity 0	Units	YES	X NO
2016 - Fall: N	lo Change			Teachers washiooms		1						
Comments: 2017 - Spring	ı: No Change				_							
Comments:	. No Change				_							
2017 - Fall: N Comments:	lo Change											

20	Brown Mosaic Ceramic Tile Mastic	2550	SF	1st, 2nd and 3rd Floor Boys and Girls and Teachers Washrooms		Miscellaneous	No	None	0	YES	X NO
		•	•	•	1	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
·	·	·		·							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
21	Adobe Mosaic Ceramic Tile Grout	200	SF	Gym Vestibule		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											

2017 - Fall: No Change Comments: 2017 - Spring: No Change

Material

Units

Material

Quantity

Material Location

Comments:

HA No

Material Description

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
22	Adobe Mosaic Ceramic Tile Adhesive	200	SF	Gym Vestibule		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
23	1 x 1 White Fissured Ceiling Tile	2400	SF	Gym		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:	3											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
23M	1 x 1 White Fissured Ceiling Tile Mastic	2400	SF	Gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
24	Plaster	60000	SF	Throughout Main Building		Surface	Yes	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:	-											
2017 - Fall: I	No Change											
Comments:	ito onango											
2017 - Sprin	g: No Change											
Comments:	ig. 140 Offarige											
]							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
25	Plaster	1000	SF	1958 Addition- Corridor		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				1							
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
26	Drywall	600	SF	Teacher's Lounge Ceiling- 1958 Addition		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	•											
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	- Change				<u> </u>							
]							

27	Spray On Fire-Proofing	5000	SF	1958 Addtition		Surface	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	<u> </u>											
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
D	MJP E/F/V on Aircell Pipe Insulation	140	LF	Boiler Room, Crawlspace		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change	-	-]							
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Е	Cardboard Pipe Insulation	110	LF	Boiler Room and Crawl Space		TSI	Yes	Loc	20		YES	X NO
2016 - Fall: N	o Change											
Comments:	o change											
2017 - Spring	: No Change											
Comments:												
0047 Fall N	- Ob				-							
2017 - Fall: N	o Change				1							
Comments:					1							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damaga	Damage	Damago	Change in Assess	smont Catagory
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Quantity	Damage Units	Change in Assess	sillerit Category
F	Aircell Pipe Insulation	200	LF	Boiler Room, Crawlspace, Slop Sink Room, and Fan Room		TSI	Yes	Loc	50		YES	X NO
2016 - Fall: N	o Chongo				7							
	o Change				-							
Comments:					4							
2017 - Fall: N	o Change											
Comments:	o onango				†							
Commonto.					1							
2017 - Spring: No Change												

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
К	MJP E/F/V on Aircell Pipe Insulation	50	LF	Boiler Room, Crawlspace, Fan Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	-											
2017 - Fall: N	o Change											
Comments:	Comments:											
2017 - Spring	2017 - Spring: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
L	Cardboard Pipe Insulation	120	LF	Crawlspace		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	Ţ											
					J							

М	Aircell Pipe Insulation	185	LF	Crawlspace, Fan Room, Gym, and Janitors Closet	TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change	•	•	•	•	•	•	•	•		
Comments:	io onango										
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	ı: No Change										
Comments:	-										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
N	MJP E/F/V on Fiberglass Pipe Insulation	100	LF	Boiler Room and Washrooms		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
0	Incinerator Insulation	50	SF	Boiler Room 1911		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
Р	MJP E/F/V on Cardboard Pipe Insulation	25	LF	Boiler Room and Crawl Space		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Fall: N	lo Change				+							
Comments:												
2017 - Spring	ı: No Change				-							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessment Category
Q	MJP E/F/V on Cardboard Pipe Insulation	20	LF	Crawlspace and 1st Floor		TSI	Yes	Loc	5		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	Ü											
2017 - Fall: N	o Change											
Comments:	o onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessment Category
R	Boiler Gasket	80	LF	Boiler Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. 140 Chango											
2017 - Fall: N	o Chango											
Comments:	o Change											

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: John H Vanderpoel Elementary Magnet School
Date: 12/5/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 29311

SCHOOL'S ASBESTOS MANAGEMENT PLAN.