Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

29361

Oracle Unit:

Address: 8101 S. LaSalle Street Region: 05 Mail Room: Asbestos Surveyor: Colar, Mr. Titus X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/26/2017 Email Address: tcolar@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Material Damage Quantity Units Type Category Quantity Type unexcavated areas. Heat YES X NO 10 aircell pipe insulation LF TSI Yes Dist 1000 plenums, pump room, 40 supply room 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Lenart Elementary Regional Gifted Center

School:

Building ID: 7240

11	aircell fittings	200	SF	plenums, pump room, supply room		TSI	Yes	None	0		YES	X NO
0040 Fall	l. Na Obasasa			•	7							
	l: No Change											
Comments	S:											
2017 - Fal	l: No Change											
Comments	S:											
2017 - Spr	ing: No Change											
Comments	S:											
					=							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
	'	Quantity	Units		Type	Category		Туре	Quantity	Units		0 ,

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		

300

SF

Material

Quantity

Material

Units

Material Location

unexcavated areas

unexcavated areas. Heat

HA No

12

Material Description

aircell duct wrap

YES

13	cardboard pipe insulation	270	LF	unexcavated areas and south heat plenum		TSI	Yes	Dist	30		YES	X NO
2016 - Fall:	No Change				1							
Comments:					-							
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:												
Comments:												
]							
			_				_					
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
14	cardboard pipe fittings	50	LF	unexcavated areas and south heat plenum		TSI	Yes	None	0		YES	X NO

Type

Material

Category

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	rope pipe insulation	60	LF	North and South Fan Rooms		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	· ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	Tank insulation	80	SF	upper tank rm. Boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	oriango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	Aircell pipe insulation.	190	LF	below the upper tank.		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18	Plaster	80000	SF	core walls of tunnel and throughout		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>											
2017 - Spring	ı: No Change				_							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					_							
					_							

19	Braided Pipe Wrap	10	LF	Auditorium stage stair area		TSI	Yes	None	0		YES	X NO
2012 - "					7							
2016 - Fall	: No Change											
Comments	:											
2017 - Spri	ng: No Change											
Comments												
2017 - Fall	: No Change											
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

20	Green Linoleum Flooring Mastic	2000	SF	elevator Lobby on 1st, 2nd, & 3rd Fl.
2016 - Fall: N	No Change			
Comments:	<u> </u>			
2017 - Spring	g: No Change			
2017 - Fall: N	No Change			
Comments:	V			

Material

Quantity

Material

Units

Material Location

2nd Fl. SE Corridor and

HA No

Material Description

Green Linoleum Flooring

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
CM-1	carpet mastic	2750	SF	Room 110, Principals office, main office, general office, copy/store room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:	-				=							
2017 - Fall:	No Change				-							
Comments:	J											
2017 - Sprir	ng: No Change											
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
FT-1	9x9 brown floor tile	2600	SF	engineers office, restroom and auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	·	<u> </u>	<u> </u>]							
Comments:	•											
2017 - Sprir	ng: No Change				-							

Comments:

Comments:

2017 - Fall: No Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FT-2	cream/peach linoleum	1300	SF	lunchroom & boys lockerroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	, ,											
2017 - Fall: N	lo Change											
Comments:	io onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
	material 2 coonpilor	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units		oomom category
FT-3	12x12 teal floor tile (part of checkerboard)	1385	SF	1st floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	r: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change				_							
Comments:					 							

FT-4	12x12 caramel floor tile	3025	SF	1st & 3rd floor corridor (1st floor part of checkerboard)		Miscellaneous	No	None	0	YES	X NO
	•	•	•	*	1	•	-	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:	-										
2017 - Spring	: No Change										
Comments:											
					•						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
FT-5	9x9 green floor tile	725	SF	2nd floor corridor N/S (part of checkerboard)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Comments:

HA No

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category				
FT-6	9x9 tan floor tile	725	SF	2nd floor corridor N/s-part of checkerboard		Miscellaneous	No	None	0		YES	X NO			
	2016 - Fall: No Change														
Comments:					1										
2017 - Spring	: No Change				-										
Comments:															
2017 - Fall: N	o Change				-										
Comments:															
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category			
FT-7	blue linoleum	1500	SF	2nd floor computer lab and 303		Miscellaneous	No	None	0		YES	X NO			
2016 - Fall: N	o Change]										
Comments:															
2017 - Fall: No Change					-										
Comments:					-										
2017 Spring	: No Chango														
2017 - Spring Comments:	i. No Change				-										
2 3]										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category			
FT-8	12x12 white floor tile	250	SF	2nd floor MDF room next to computer lab		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	2016 - Fall: No Change													
Comments:														
2017 - Fall: No Change														
Comments:														
2017 - Spring	g: No Change													
Comments:														
]									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category		
FT-9	brown linoleum	450	SF	2nf floor elevator lobby		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	lo Change]									
Comments:														
2017 - Fall: No Change					-									
Comments:														
2017 - Spring	g: No Change				_									
Comments:	<i>,</i>													

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
FTM-1	9x9 Brown floor tile mastic	2600	SF	engineers office, restroom, and ausitorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:												
2017 - Sprine	g: No Change											
Comments:	<u>g </u>				=							
2017 - Fall: N	No Change				1							
Comments:	10 Onango											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FTM-3	12x12 Teal floor tile mastic	1385	SF	1st floor corridor-part of checkerboard		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:					-							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
FTM-4	12x12 caramel floor tile mastic	3025	SF	1st and 3rd floor corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change				1							
Comments:												
2017 - Fall: No Change					-							
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FTM-5	9x9 green floor tile mastic	725	SF	2nd floor corridor N/S- part of checkerboard		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change]							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring: No Change												
Comments:												
					1							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category			
FTM-6	9x9 tan floor tile mastic	725	SF	2nd floor corridor N/S- part of checkerboard		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	o Change	7												
Comments:														
2017 - Fall: N	o Change													
Comments:														
2017 - Spring	: No Change				=									
Comments:														
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category		
FTM-7	blue linoleum mastic	1500	SF	2nd floor computer lab and 303		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	lo Change				7									
Comments:														
2017 - Fall: No Change					1									
Comments:														
2017 - Spring	: No Change				-									
Comments:	<u> </u>													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	nent Category
FTM-8	12x12 white floor tile mastic	250	SF	2nd floor MDF room next to computer lab		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:	Comments:												
2017 - Spring: No Change													
Comments:					_								
2017 - Fall: N	lo Change												
Comments:													
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessm	nent Category
FTM-9	Green linoleum mastic (not obseved)			2nd floor elevator lobby		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change				7								
Comments:													
2017 - Spring: No Change					_								
Comments:]								
2017 - Fall: N	2017 - Fall: No Change												
Comments:	ŭ]								
					_								

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Lenart Elementary Regional Gifted Center
Date:11/13/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.