## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

31261

**Oracle Unit:** 

Building ID: 7420

Address: 1313 N.Claremont Region: 02 Mail Room: 35 Asbestos Surveyor: Dye, Ms. Venguanette X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 2/2/2018 Email Address: vdye@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type 12"x12" Beige w/ Brown Rooms 302, 315, 133, YES 80 SF X NO 4200 Miscellaneous No None 0 Specks VFT 007, 028, 301, 303 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Jose De Diego Elementary Community Academy

School:

8F	Mag Block Pipe Insulation	700	LF	Boiler Room, Pump Room, East Basement Corridor, Coal Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change		<u> </u>	·	]					·		
Comments:												
2017 - Spring	: No Change											
Comments:					-							
2017 - Fall: N	lo Change				1							
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

Boiler Room, Pump

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
09	12"x12" Beige w/ Brown Specks VFT Mastic	4200	SF	Rooms 302, 315, 133, 007, 028, 301 ,303		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

9G	MJP E/F/V on Mag Block Pipe Insulation	30	LF	Boiler Room, Pump Room, East Basement Corridor, Coal Room		TSI	Yes	None	0		YES	X NO
2016 - Fa	all: No Change	•	•	•	]	•	•	•	•	•	•	
Commen	ts:				] -							
2017 - Sp	oring: No Change				]							
Commen	ts:				-							
2017 - Fa	all: No Change											

Type

Material

Category

Damage

Type

Damage

Quantity

Damage

Units

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9"x9" Beige VFT-NOT OBSERVED	450	SF	Rooms 009, 314 (under carpet)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

10H	MJP E/F/V on Fiberglass Pipe Insulation	300	EA	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
	Comments:											
	2047 0 : N 0											
2017 - Spring: No Change												
Comments:	•											
2017 - Fall:	No Change											
Comments:	1											
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
		Quantity	Units		Type	Category		Туре	Quantity	Units		
44	9"x9" Beige VFT Mastic-	450	0.5	Room 009 (NOT		Missellensen	NI-	Nana			Dyre	X NO
11	NOT OBSERVED IN ROOM 009	450	SF	OBSERVED); Room 314 (Carpet)		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
111	Cardboard Pipe Insulation	3000	LF	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ţ.											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12	Orange Linoleum	30	SF	1st through 3rd Floor Janitors Closets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	ı: No Change				-							
Comments:	, <b>ge</b>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
12J	MJP E/F/V on Cardboard Pipe Insulation	75	EA	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:	- Committee of the comm											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in As	sessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
13	Orange Linoleum Mastic	30	SF	1st through 3rd Floor Janitors Closets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	U											
2017 - Fall: N	2017 - Fall: No Change											
Comments:	10 Oriango											
	a: No Chango											
	2017 - Spring: No Change Comments:											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"x12" White w/ Yellow Specks VFT	18210	SF	Rooms 001, 013, 112, 119, 121, 126, 222, 230, and 318; 1st Floor Teachers Toilet; 2nd and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change				1						
Comments:					]						
2017 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
					_						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" White w/ Yellow Specks VFT Mastic	18210	SF	Rooms 001, 013, 112, 119, 121, 126, 222, 230, and 318; 1st Floor Teachers Toilet; 2nd and 3rd Floor Corridors		Miscellaneous	No	None	0		YES X NO

		•	•	
2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				

16	12"x12" Beige w/ Brown Streaks VFT	8500	SF	Room 019, 101, 102, 104, 105, 120, 305, 332	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments										
2017 - Fall:	No Change									
Comments										
2017 - Spri	ng: No Change									
Comments										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
17	12"x12" Beige w/ Brown Streaks VFT Mastic	8500	SF	Room 019, 101, 102, 104, 105, 120, 305, 332		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
18	12"x12" Brown w/ White Specks VFT	10300	SF	Room 028, 127, 129, 131, 214, 218, 313, 327, 332		Miscellaneous	No	None	0		YES X NO	
2010 Fall No Change						•		•	•	•		-

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	12"x12" Brown w/ White Specks VFT Mastic	10300	SF	Room 028, 127, 129, 131, 214, 218, 313, 327, 332		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
20	9"x9" Brown VFT (NOT OBSERVED)	700	SF	Room 325		Miscellaneous	No	Unknown	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Fall: N Comments:	lo Change											
2017 - Spring Comments:	g: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
21	9"x9" Brown VFT Mastic (NOT OBSERVED)	700	SF	Room 325		Miscellaneous	No	Unknown			YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
22	12"x12" Sand VFT	2700	SF	Public Area, Main Office, Room 130, 227		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
23	12"x12" Sand VFT Mastic	2700	SF	Public Area, Main Office, Room 130, 227		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	12"x12" White w/ Gray Specks VFT	3500	SF	Rooms 114, 122, 321, 329, 228 Library Office & Storage, 2nd Floor Corridor & Storage; Room 319 had hardwood floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change				1						
Comments:	<u> </u>										
2017 - Fall:	No Change	-									
Comments:	-										
2017 - Sprin	g: No Change				1						
Comments:											
					J						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12"x12" White w/ Gray Specks VFT Mastic	3500	SF	Rooms 114, 122, 321, 329, 228 Library Office & Storage, 2nd Floor Corridor & Storage; Room 319 had hardwood		Miscellaneous	No	None	0		YES X NO

11001
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Page 12

26	12"x12" Brown w/ White Dots VFT	250	SF	3rd Floor Teacher's Lounge		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments	<b>Y</b>	- -										
2017 - Fall:	: No Change				-							
Comments	:											
2017 - Spri	ng: No Change											
Comments	:				=							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

_	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

250

Material

Quantity

Material

Units

SF

Material Location

3rd Floor Teacher's

Lounge

HA No

27

Material Description

12"x12" Brown w/ White

Dots VFT Mastic

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
28	12"x12" Gray VFT	150	SF	Kitchen Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					_							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				-							
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
29	12"x12" Gray VFT Mastic	150	SF	Kitchen Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>				]							
2017 - Fall: N	o Change				-							
Comments:	J											
2017 - Spring	: No Change											
Comments:												

30	12"x12" Green VFT	2500	SF	Kitchen Storage, Room 218 Storage, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change	<u> </u>		·	]					·		
Commen												
2017 Fo	II. No Chango											
Comment	II: No Change											
Commen	lo.											
2017 - Sp	ring: No Change											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	12"x12" Green VFT Mastic	2500	SF	Kitchen Storage, Room 218 Storage, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
32	12"x12" White VFT	1200	SF	Room 335		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
33	12"x12" White VFT Mastic	1200	SF	Room 335		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	_											

HA No

						_						
34	9"x9" Gray VFT - NOT OBSERVED	320	SF	Rooms 331		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
2017 - Fall:	2017 - Fall: No Change											
Comments												
2017 - Spri	ing: No Change				1							
Comments												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
35	9"x9" Gray VFT Mastic - Not Observed	320	SF	Rooms 331		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change			•	i i							
Comments												
0047 5 11	N. O											
	: No Change											
Comments	:											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

36	12"x12" White w/ Brown Specks VFT	930	SF	Room 235 & 025 Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments												
2017 - Spr	ring: No Change				-							
Comments												
2017 - Fal	I: No Change				-							
Comments	S:											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37	12"x12" White w/ Brown Specks VFT Mastic	930	SF	Room 235 & 025 Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change				7							
Comments												
2017 - Fall	I: No Change				-							
1-011 1 al												

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Beige w/ Black Specks VFT	3500	SF	Room 024, 223, 229, 231, 233, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES X NO
•					-	•	•	-			

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12"x12" Beige w/ Black Specks VFT Mastic	3500	SF	Room 024, 223, 229, 231, 233, Gymnasium Office & Storage		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" White w/ Green Specks VFT	2400	SF	Room 005, 107, 109 Office, 233, Main Office Toilet, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO
		•	•		· 1	•	•	•	•	•	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12"x12" White w/ Green Specks VFT Mastic	2400	SF	Room 005, 107, 109 Office, 233, Main Office Toilet, 1st Floor Corridor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

											<u> </u>	
42	12"x12" Tan w/ White Specks VFT	2400	SF	Rooms 021, 023		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:					1							
2017 - Fall:	No Change				_							
Comments:					-							
2017 - Sprii	ng: No Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
43	12"x12" Tan w/ White Specks VFT Mastic	2400	SF	Rooms 021, 023		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					1							
2017 - Sprii	ng: No Change											
Comments:					1							
2017 - Fall:	No Change				1							
Comments:	•											

Category

Friable

Damage

Type

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

Damage Quantity Damage

Units

		-							-			
44	12"x12" Brown VFT	140	SF	Room 125 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:	y y -											
2017 - Fall: N	No Change				<u>.</u>							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
45	12"x12" Brown VFT Mastic	140	SF	Room 125 (Under Carpet)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Spring	g: No Change	-										
Comments:	g. 140 Ondrige											
2017 - Fall: N				-								

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
46	12"x12" Blue VFT	400	SF	Room 019		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
47	12"x12" Blue VFT Mastic	400	SF	Room 019		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
48	12"x12" Green w/ White Streaks VFT	2700	SF	Supply Room Basement, Woodshop		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:					-							
2017 - Sprir	ng: No Change				-							
Comments:	<u>g</u> <u>g</u> -											
0047	No Oboros											
2017 - Fall:	No Change				_							
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
49	12"x12" Green w/ White Streaks VFT Mastic	2700	SF	Supply Room Basement, Woodshop		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	. to onango				=							
0047	No Oboros				]							
2017 - Fall:	No Change				_							
Comments:					-							
2017 - Sprin	na. No Change				1							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	Transite Table Tops	500	SF	Rooms 314, 318, and 218		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				=							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
51	Hard Coat Plaster	200000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	•											
2017 - Fall: N	o Change				1							
Comments:	J											
2017 - Spring	: No Change				_							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
52	Interior Window Caulk	150000	LF	Interior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	,											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		
53	Exterior Window Caulk	150000	LF	Exterior Windows		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	. 110 Ondingo											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
54	12" x 12" White w/ Rust Streaks VFT	1200	SF	Room 025, 024		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	ı: No Change											
Comments:	,											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
55	12" x 12" White w/ Rust Streaks VFT Mastic	1200	SF	Room 025, 024		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	lo Change											
2017 - Spring	ı: No Change				_							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
56	2'x4' Dot Ceiling Tile			Room 007		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	,ge											
HA No	Material Description	Material	Material	Material Location	Ashaataa	Material	Friable	Domoso	Domoso	Domogo	Change in Asse	nament Catagoni
HA NO	Material Description	Quantity	Units	Material Location	Asbestos Type	Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
57	2'x4'Dot/Wave Ceiling Tile			Throughout building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	io Oriange											
	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
58	2'x2' dot/wave celing tile			Room 025		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N	lo Change											
	g: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
59	Terrazo	4000	SF	Auditorium Lobby and South Stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments: 2017 - Fall: N Comments: 2017 - Spring Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	Brown Ceramic Tile Grout	1010	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:	No Change				- - -							
	ig: No Change				-							
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
	·	Quantity	Units		Туре	Category		Туре	Quantity	Units		0 ,
61	Brown Ceramic Tile Adhesive	1010	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
62	Blue Ceramic Tile Grout	2300	SF	1st, 2nd, and 3rd Floor Girls Washrooms (All)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				=							
Comments:												
2017 - Spring	: No Change				_							
Comments:	<u> </u>				1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
63	Blue Ceramic Tile Adhesive	2300	SF	1st, 2nd, and 3rd Floor Girls Washrooms (All)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>				=							
2017 - Fall: N	o Change				+							
Comments:	J											
2017 - Spring	: No Change				-							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
64	Gray Ceramic Tile Grout	750	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall:	No Change				= - -							
Comments:												
2017 - Sprin	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
65	Gray Ceramic Tile Adhesive	750	SF	1st, 2nd, and 3rd Floor South Boys Washrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:	•											
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:	.g				1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
66	White Ceramic Tile Grout (Floor and Walls)	2000	SF	Basement Locker Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:	<u> </u>				1							
2017 - Fall: N	o Change				_							
Comments:												
2017 - Spring	: No Change				=							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
68	Multi-color Carpet Adhesive	1100	SF	Rooms 325, 317, 225, 125, 126, 024, 031, and 219		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:	<u> </u>				1							
					J							

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u> </u>	
69	Blue Carpet Adhesive	430	SF	Room 217 and Chief Engineer's Office (015)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				1							
Comments:	•											
2017 - Sprir	ng: No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
70	Red Carpet Adhesive	350	SF	Rooms 117, 217, and 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change				=							
Comments:												
2017 - Sprir	ng: No Change											
Comments:					1							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
71	Maroon Carpet Adhesive	1200	SF	Offices		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. No onange											
LIANI	L Maradal Basadada	NA-t	I Markania I	NASIS COLLEGE CO.	Ashastas	T Marta dal	Leading	D		I B	Dobas and to Assa	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
72	1 x 1 White Fissured Ceiling Tile			Lunch Room (332)		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o Onange											

73	12x12 OffWhite w/ Orange Specks VFT	2200	SF	203,103,712 & 116		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
2017 - Spring	ı: No Change										
Comments:											
2017 - Fall: N Comments:	io Change										
					I						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Categ
74	12x12 OffWhite w/ Orange Specks VFT Mastic	2200	SF	203,103,212 &116		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	g: No Change											

2017 - Fall: No Change

Comments:

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Damage

Units

Change in Assessment Category

75	12x12 White VFT w/ Multi Color Specks	800	SF	118		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	r: No Change										
Comments:											
2017 - Fall: N	lo Change				-						
Comments.					-						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
76	12x12 White w/ Multi Color Specks Mastic	800	SF	118		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
77	Decorative Plaster	2500	SF	Auditorium and Auditorium Lobby		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				$\neg$							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
78	Drywall System	1500	SF	Former Girls Locker Room (Basement)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: No Change												
Comments:	- Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
А	MJP E/F/V on Aircell Pipe Insulation	350	EA	Throughout		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
В	Mag Block Tank Insulation	1000	SF	Pump Room, Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:	<u> </u>											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Aircell Pipe Insulation	2500	LF	Throughout		TSI	Yes	Loc	15		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

Page 41

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School:	Jose De Diego Elementary Community Academy
Date:	2/2/2018
This is to r	notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of
the Asbes	tos Management Plan is available at each school during school hours by appointment.
Requests	to review the Asbestos Management Plan must be made at least 24 hours in advance.
A.1	
	se be advised that CPS conducts asbestos inspections of all Schools every three years.
	spection was completed in 2016. surveillances are conducted every six months.
ASDESIOS	surveillances are conducted every six months.
CHECK O	NE
A c	copy of this notice was sent home in each child's backpack.
	copy of this notice was printed in the school's newsletter and sent home with each child
A C	copy of this hotice was printed in the school's newsletter and sent home with each child
A c	copy of this notice was printed in the school's calendar and sent home with each child
Oth	iei.
A COP	Y OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.