Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

41061

02

Oracle Unit:

Region:

Asbestos Surveyor: Daughrity, Mr. Kenneth Earl X CHECK HERE IF NO CHANGE TO ASBESTOS 11/1/2017 Survey Date: Email Address: kedaughrity@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Notice printed in school's calendar Other Each child's backpack HA No Asbestos **Material Description** Material Material Material Location Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Category Type Quantity Units Throughout (See X NO YES 01 **Drywall Joint Compound** Hatching Maps) 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Frederick A Douglass Academy High School

543 N. Waller Avenue

School:

Address:

6630

Building ID:

Mail Room:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
03	12"x16" Acoustic Ceiling Tile			Room 225, Swimming Pool, Activity Center							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
04	Carpet Mastic			Throughout (See Hatching Maps)							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:	_											
2017 - Spring	ı: No Change											
Comments:												

05	12"x12" Gray VFT	15000	SF	Throughout (See Hatching Maps)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	_									
2017 - Fall: N	o Change									
Comments:										
2017 - Spring	: No Change									
Comments:										

Asbestos

Type

Material

Category

Material Location

Throughout (See

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Fiberglass Pipe Insulation	380	LF	Mechanical Room, Washroom Pipe Chases, 1st & 2nd Flr Storage Rms, Pool Equipment Area		TSI	Yes	Dist	20		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

Damage Quantity

Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
09	12"x12" Gray VFT Mastic	15000	SF	Throughout (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	Ğ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
10	12"x12" Sand VFT	6300	SF	1st Floor Southwest Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	J											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	onango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
11	12"x12" Sand VFT Mastic	6300	SF	1st Floor Southwest Hallway		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	-											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
12	12"x12" Green VFT	9100	SF	Throughout (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
13	12"x12" Green VFT Mastic	9100	SF	Throughout (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	, rio Griango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assu	essment Category
TIATO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Change in Asse	osament Category
14	Textured Plaster			Room 183, 245, 211 D							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Chango											
Comments:	io Change											
2017 - Spring	g: No Change											
Comments:					_							
					_							

		Quantity	Units		Type	Category		Type	Quantity	Units		
15	12" x 12" White w/ Grey VFT	9000	SF	First floor hall outside 109, 1st Floor Attendance Office and Second Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change]							
Comment												
2017 - Fal	II: No Change				-							
Comment	S:											
2017 - Sp	ring: No Change				-							
Comment	S:]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16	12" x 12" White w/ Grey VFT Mastic	9000	SF	First floor hall outside 109, 1st Floor Attendance Office and Second Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comment	•											
2017 - Fal	II: No Change				<u> </u>							
Comment	•											
Comment					1							

Asbestos

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Material

Material Location

Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Miscellaneous	Yes	None	0		YES	X NO
	1 =	T	T _			
Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
TSI	No	None	0		YES	X NO
	Material Category	Category Miscellaneous Yes Material Category Friable	Category Type Miscellaneous Yes None Material Category Friable Damage Type	Category Type Quantity Miscellaneous Yes None 0 Material Category Type Damage Type Quantity	Category Type Quantity Units Miscellaneous Yes None 0 Material Category Type Damage Quantity Damage Quantity Units	Category Type Quantity Units Miscellaneous Yes None 0

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
18	Black Vinyl Baseboard	30000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
19	Black Vinyl Baseboard Mastic	30000	SF	Throughout School		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				=							
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
20	Red Terrazzo	1000	SF	Stairways to 2nd Floor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:					4							
2017 - Spring	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12X12 Gray Speckled VFT	2100	SF	242C, 411D, 413D		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					-							
2017 - Fall: N	lo Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		-			· ·	0 ,		· ·	,		1	
22	12x12 Speckled VFT Mastic	2100	SF	242C, 411D, 413D		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Fall:	No Change											
Comments:]							
2017 - Spri	ng: No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23	12x12 Yellow Speckled VFT	1000	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	:											
2017 - Fall:	No Change				_							
Comments:												
2017 - Spri	ng: No Change				-							
Comments:												

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
24	12x12 Yellow VFTMastic	1000	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25	12x12 Brown Speckled VFT	20	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					-							
2017 - Fall: No Change												
Comments:					-							
2017 - Spring	g: No Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	12x12 Brown Speckled VFTMastic	20	SF	Main Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	Black sink Undercoating	50	SF	Rooms 116A, 116B, 116D, 316A		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: No Change					_							
Comments:												
2017 - Spring: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
28	White Sink Undercoating	20	SF	Kitchen (Rm168)/ Homemaking Lab		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o onango											
	T		T			T	T =			T_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
29	2x4 Black soundproof ceiling tile	10000	SF	Activity center		Miscellaneous	Yes	Loc	6		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Frederick A Douglass Academy High School
Date: 11/1/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.