Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

Roald Amundsen High School 46031 Building ID: 1210 School: **Oracle Unit:** Address: 5110 N. Damen Region: 01 Mail Room: Asbestos Surveyor: Vaughn, Mr. Jeffrey **CHECK HERE IF NO CHANGE TO ASBESTOS** Survey Date: 10/17/2017 Email Address: jvaughn1@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Material Damage Quantity Units Type Category Quantity Type YES 07 9X9 White VFT ABATED X NO Room 222 ABATED Miscellaneous 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

08	12"x12" Tan VFT	325	SF	Room 128		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
9	Lab Table Tops	40	EA	Rooms 317-24 and 321- 16, 322-24, 318-24, 315- 24		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	Ţ											
2017 - Fall: N	No Change				1							
Comments:	Ü											
2017 - Spring	g: No Change				-							
Comments:												

Type

Material

Category

Friable

Damage

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Damage Quantity Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
11	12x12 Tan VFT Mastic NOT OBSERVED	325	SF	Room 128 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
12	9X9 White VFT Mastic ABATED			Room 222 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change				7							
Comments:	V											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
13	Hard Coat Plaster			Throughout		Surface					YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	Jo Change											
Comments:	NO Change											
COMMITTEE NO.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
14	Sculptured Plaster			Auditorium and Auditorium Foyer		Surface					YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 Caria	n. Na Changa											
Comments:	g: No Change											
Comments.												
2017 - Fall: N	No Change											
Comments:												

15	2x4 Ceiling Tile		Club room B, Library, rooms 112,117, 118, 124, 126, 221, 226, 328		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change	•	•]	•	•	•	•	•	•	
Comments:	lo Ondrigo										
2017 - Spring	ı: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12x12 Black VFT	4300	SF	Auditorium, Girls and Boys Locker Room Entrances, Book Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
16A	12x12 Black VFT Mastic	4300	SF	Auditorium, Girls and Boys Locker Room Entrances, Book Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	•											
2017 - Fall: N	No Change				_							
Comments:	Ŭ											
2017 - Sprine	g: No Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	1x1 Rough Ceiling Tile			Club room A, College Faculty		Miscellaneous					YES	X NO
2016 - Fall: N	No Change				7							
Comments:	Ţ.											
2017 - Sprine	g: No Change				-							
Comments:												
2017 - Fall: N	No Change											
Comments:	·-···g-				1							

19	12x12 White w/Beige VFT	4600	SF	Room 117	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: A Comments:re	bated moved during summe	r construc	tion							

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19 A	12x12 White w/Beige VFT Mastic	4600	SF	Room 117, (library- not observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:removed during summer construction
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
20	1x1 White Acoustic Ceiling Tile			Lunch room, Band room, Music room, Study room, Girls Gym		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	o Change				_							
Comments:	o onango				-							
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssessment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
22A	6"x12" Acoustical Tile			Library, Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	o onango											
2017 - Spring	· No Change											
Comments:	. 110 Grango											
2017 - Fall: N	o Chango											
Comments:	o onange				-							
]							

23	12x12 Gray VFT	2900	SF	Clubroom A & B, College Faculty, 117		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: A	bated											
	emoved during summe	er construc	tion.									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
23A	12x12 Grey VFT Mastic	2900	SF	Clubroom A & B, College Faculty, Main Office & 117		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: A	bated											
	emoved during summe	er construc	tion.									
2017 - Spring	ı: No Change											
Comments:												
1					1							

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24	9x9 Green VFT (abated)			Engineers Office (abated)		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
24A	9x9 Green VFT Mastic - ABATED			Engineers Office ABATED		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:				·								

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
25	9"x9" Dark Brown VFT ABATED (2015)			Room 201 ABATED (2015)		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
25A	9x9 Dark Brown VFT Mastic ABATED (2015)			Room 201 ABATED (2015)		Miscellaneous					YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
26	9"x9" Light Brown VFT ABATED			308, 306 & 201 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					-							
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
26A	9"x9" Light Brown VFT Mastic ABATED			308, 306 & 201 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				1							
Comments:]							
2017 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27	9x9 Red VFT ABATED			1st, 2nd, and 3rd floor corridors ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
27A	9x9 Red VFT Mastic ABATED			2nd, and 3rd floor corridors ABATED		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
30	12x12 Off-White VFT			Room 328		Miscellaneous					YES	X NO
2016 - Fall: No	o Change											
Comments:					_							
2017 - Spring:	No Change											
Comments:												
2017 - Fall: No	o Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units	3	,
30A	12x12 Off-White VFT Mastic			Room 328		Miscellaneous					YES	X NO
2016 - Fall: No	o Change											
Comments:	•											
2017 - Fall: No	Change											
Comments:	o change											
2017 Caring	No Change											
2017 - Spring: Comments:	No Change				_							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31	9x9 Brown VFT ABATED			Engineers Bathroom ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
31A	9x9 Brown VFT Mastic ABATED			Engineers Bathroom ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:	V											
2017 - Spring	ı: No Change											
Comments:	, · · · · · · · · · · · · · · · · · · ·											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
32	12x12 Beige VFT (NOT OBSERVED)			Room 322, 321 (NOT OBSERVED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				_							
Comments:					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
32A	12"x12" Red with red streaks VFT MASTIC	100	SF	Room 230		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
33	9x9 Black VFT			1st 2nd 3rd Floor corridors		Miscellaneous					X YES	NO
2016 - Fall: C												

2010 Tall. Other
Comments:none found
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
33A	9x9 Black VFT Mastic			2nd, & 3rd Floor Corridors		Miscellaneous		None			X YES NO

2016 - Fall: Other	
Comments:none found	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
34	12x12 Brown VFT (ABATED)			Room 317 (ABATED)		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	g: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:	_												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessn	nent Category
34A	12x12 Brown VFT Mastic (ABATED)			Room 317 (ABATED)		Miscellaneous					YES		X NO
2016 - Fall: N	lo Change												
Comments:	v												
2017 - Fall: N	lo Change												
Comments:	J												
2017 - Spring	g: No Change												
Comments:	, g												
				<u> </u>									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
35	12x12 White VFT (ABATED)			Rooms 112, 114 Library (ABATED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	ı: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
35A	12x12 White VFT Mastic (ABATED)			Rooms 112, 114 Library (ABATED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	ı: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessm	nent Category
36	12x12 Brown w/Grey VFT	900	SF	Rooms 129, 229		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N Comments:	o Change												
Comments.													
2017 - Spring	: No Change												
Comments:													
2017 Fall: N	o Chango												
2017 - Fall: N Comments:	o Change												
Comments.													
•					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessm	nent Category
36A	12x12 Brown w/Grey VFT Mastic	900	SF	Rooms 129, 229		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	o Change												
Comments:	<u> </u>												
2017 - Fall: N	o Change												
Comments:													
2017 - Spring	: No Change												
Comments:	- ·· y -												

		Quantity	Units		Type	Category		Type	Quantity	Units		
37	12x12 Red VFT	40	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37A	12x12 Red VFT Mastic	40	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

		Quantity	Units		Type	Category		Type	Quantity	Units		
38	9"x9" Red w/ White VFT - ABATED			Engineers Office (ABATED)		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
38A	9"x9" Red w/ White VFT Mastic - ABATED			Engineers Office (ABATED)		Miscellaneous		None			YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 Sprin	ng: No Change											
Comments:					_							
Comments.					_							
<u>l</u>												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
39	2 x 2 ft Blue VFT ABATED			Weight Rooms ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:	g. 140 Onlange				=							
· · · · · ·	T	T	T	1	T		T =			T _	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
39A	2' x2' blue VFT Mastic ABATED			Weight Rooms ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Chango				4							
Comments:	io Change				-							
	g: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
40	2 x 2 ft Dot/Wave Ceiling Tile	1100	SF	Room 230		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	Salmon Linoleum (ABATED)			Rooms: 217, 221, 317, 318, 321, 322, 327 (ABATED)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	· ·											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
41A	Salmon Linoleum Mastic (ABATED)			Rooms 217, 221, 317, 318, 322, 321 and 327(ABATED)		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Fall: N	o Change				1							
Comments:	Ţ.											
2017 - Spring	· No Change				1							
Comments:	. 140 Chango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Туре	Quantity	Units	J	
42	Carpet Mastic ABATED			Main Office, Room 325 & 109 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	Ŭ											
2017 - Fall: N	o Change				-							
Comments:	o onango				1							
2017 Caring	. No Chango											
2017 - Spring Comments:	: No Change											
- Commondo					<u> </u>							

		Quantity	Units		Type	Category		Туре	Quantity	Units		
43	Terrazo	5000	SF	Entryways, Stairs, Lunch Room, Serving Area, Kitchen, 1st & 2nd & 3rd floor corridors, Auditorium vestibule and stairs		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											

Material

Damage

Friable

Damage

Damage Change in Assessment Category

2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12 x 12 Light Tan with Specks VFT ABATED			1st floor corridors ABATED		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

		Quantity	Units		Type	Category		Type	Quantity	Units		
44 A	12"x12" light tan with specks MASTIC -ABATED			1st floor corridors ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45	12"x12" Dark red VFt - ABATED			1st floor corridors ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												

Asbestos

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
45 A	12"x12" Dark red VFT MASTIC - ABATED			1st floor corridor ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
46	12"x12" black with white streaks VFT - NOT OBSERVED	200	SF	Room 230 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change				_							
Comments:	. 110 Onango											
2017 - Fall: N	o Change				_							
Comments:	o onange											

46 A	streaks VFT MASTIC - NOT OBSERVED	200	SF	Room 230 NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	12"x12" Red with red streaks VFT ABATED			Room 230 ABATED		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											

Type

Material

Category

Friable

Damage

Туре

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Damage

Quantity

Damage

Units

48	12"x12" Sand VFT - NOT OBSERVED	150	SF	Room 303		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:	v											
2017 - Sprir Comments:	ng: No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessr	ment Category
TIANO	Material Description	Quantity	Units	Waterial Education	Type	Category	THADIC	Type	Quantity	Units	Change III Assessi	non oalegory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

150

Material

Quantity

Material

Units

SF

Room 303

Material Location

HA No

48 A

Material Description

12"x12" Sand VFT MASTIC

- NOT OBSERVED

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
101	Glue pucks	1000	SF	Above HA 103 in the boys' gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											
2017 - Spring	g: No Change											
Comments:	<u> </u>											
2017 Falls N	Jo Changa				4							
2017 - Fall: N	No Change				_							
Comments.					-							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
102	12"x12" light blue w/ gray specks VFT	260	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	Ü											
2017 - Sprine	g: No Change				-							
Comments:	<u> </u>											
2017 - Fall: N	No Change				=							
Comments:	NO CHAILIGE				\dashv							
Comments.					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
102A	12"x12" light blue w/ gray specks VFT MASTIC	260	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	o onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessment Category
103	2'x2' Ceiling tiles w/ dots	8000	SF	Boys' Gymnasium		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	o oago											
2017 - Spring	· No Change											
Comments:	. 140 Change											
2017 Fall: N	o Chongo											
2017 - Fall: N Comments:	o Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
104	12"x12" black with white specks VFT	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
104A	12"x12" black with white specks VFT MASTIC	500	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	<u> </u>											

HA No

105	12"x12" light brown with brown and tan streaks VFT	250	SF	Rm 303, 3rd floor MDF room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change				1							
Comments												
-	-				1							
2017 - Spr	ing: No Change											
Comments	S:											
	l: No Change				_							
Comments	S:											
]							
LIA NI-	Marcadal Bassadaria	NA-t2-1	Mariadal	Maradallanda	A -bt	L Marta dal	Leann.	D	D	D	Observe to Asses	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
	12"x12" light brown with	- Cuartiny	010		.,,,,	Catego.y		. , p =	Quartity	010		
105A	brown and tan streaks VFT MASTIC	250	SF	Roomj 303, 3rd floor MDF room		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change]							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

HA No

Comments:

Comments:

Comments:

2017 - Spring: No Change

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
106	2'x4' CT	1200	SF	Health center made up of room 307 & boys and girls toilets on the 3rd fl		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	No Change]						
Comments:					-						
2017 - Fall: N	No Change				_						
Comments:											
2017 - Spring	g: No Change				_						
Comments:					-						
					1						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
107	Salmon linoleum ABATED			Health center made up of rm 307 & girls toilets on 3rd fl. ABATED		Miscellaneous					YES X NO
2016 - Fall: N	No Change]						
Comments:											
2017 - Fall: N	No Change				-						
Comments:	-				1						

2017 - Spring: No Change

Comments:

107A	Salmon linoleum MASTIC ABATED			HEalth center made up of rm 307 & Girls toilets on the 3rd fl. ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	vo oriange											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
108	2'x4' ceiling tiles	4000	SF	Rooms 111,113,115,121,123,321		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J.											
		•	•									
2017 - Spring	117 - Spring: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No

Comments:

Comments:

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

109	12"x12" offwhite w/ light gray & gray specs VFT NOT OBSERVED	100	SF	Darkroom NOT OBSERVED		Miscellaneous	No	None	0	YES	X NO
2016 - Fal	II: No Change	<u> </u>	<u> </u>]						
Comment]						
2017 - Fal	II: No Change				-						
Comment	S:										
2017 - Sp	ring: No Change										

Material

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
109A	12"x12" offwhite w/ light gray and white specs VFT Mastic NOT OBSERVED	100	SF	Darkroom NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

110	9"x9" light brown VFT ABATED			Rm 308 & closet next to the dark room ABATED		Miscellaneous					YES	X NO
2016 - Fa	II: No Change	•	•	~]	•	-	•	•	•	•	
Comment												
2017 - Sp	ring: No Change											
Comment	S:											
2017 - Fa	II: No Change				_							
Comment	S:				_							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Asbestos

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
110A	9"x9" light brown VFT MASTIC ABATED			Room 308 & closet next to dark room ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											

2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Material

Units

Material

Quantity

Material Location

Rm 308 & closet next to

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
111	Fire door NOT OBSERVED	2	EA	Stage entrance, projector rm. NOT OBSERVED		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	j: No Change											
Comments:					 							
2017 - Fall: N	lo Change											
Comments:					 							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
112	Terrazzo	23000	SF	1st, 2nd, and 2rd fl. corridors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	-											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	Black lab table tops	154	EA	Rms 315, 318, 322,209,215,217,221		Miscellaneous	No	None	0		X YES NO
2016 - Fall: O	ther										

2016 - Fall: Other
Comments:recieved new tables
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	Aircell Pipe Insulation	350	LF	Basement Air Tunnel, south		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
G	MJP E/F/V on Aircell Pipe Insulation	15	LF	Basement Air Tunnel, South		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	_											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
HA-100	12"x12" white VFT ABATED			First floor Library ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:	<u> </u>											
					┙							

HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
11/110	Waterial Besonption	Quantity	Units	Waterial Education	Type	Category	THADIO	Type	Quantity	Units	Change in 71000	Someth Category
HA-100A	Black Mastic for 12"x12" VFT ABATED			First floor Library ABATED		Miscellaneous		71			YES	X NO
2016 - Fall: I	No Change				7							
Comments:												
	N. 01				_							
	g: No Change				_							
Comments:					_							
2017 - Fall: I	No Change											
Comments:	110 Onango				-							
COMMITTEE NO.					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
K	MJP E/F/V on Fiberglass Pipe Insulation NOT OBSERVED	50	LF	Rooms: 121, 221, 218 NOT OBSERVED		TSI	Yes	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	110 Onango											
2017 - Sprin	g: No Change											
Comments:												
0047	Na Ohanan											
2017 - Fall: I	No Change				4							
Comments:					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
L	12 x 12 Brown with White Specks VFT	960	SF	Rm 222		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
М	12"X 12" White VFT	1200	SF	Health Room (307)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
0	12 x 12 Brown & White VFT	1020	SF	Rm 308		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Q	12 x 12 Brown & White VFT	36	SF	Rm 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
R	12 x 12 Brown, White & Beige VFT	1020	SF	Rm 306		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				\neg							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
S	Terrazzo Red & White	500	SF	3rd Floor Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
Т	12 x 12 Speckled Beige & White VFT	40	SF	Engineer's Bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	-											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
U	12x12 Gray & Black VFT	150	SF	Rms 321 & 322		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change					-							
Comments:												

HA No

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Assessment Category
V	Terrazzo (Red, White & Black)	500	SF	Corridor 2nd Floor		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
W	12" x 12" Beige VFT	120	SF	Engineer's Office		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Other
Comments:none found
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Х	12"x12" Grey & Black VFT	5000	SF	Rms 217, 221, 317, 318, 321, & 322		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:					-							
2017 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
Υ	12"x12" Black & Red VFT	100	SF	Rm 230		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	<u> </u>											
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	o Change											
Comments:					-							
					1							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Z	Terrazzo (Red & White)	300	SF	Corridor 1st Floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Roald Amundsen High School
Date:10/20/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.