Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

46181

Oracle Unit:

Address: 4136 S. California Region: Mail Room: 39 Asbestos Surveyor: Moore, Mr. Kevin H X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/6/2017 Email Address: khmoore@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter X Other School Website Each child's backpack Notice printed in school's calendar HA No Material Description Material Location Asbestos Friable Damage Damage Damage Change in Assessment Category Material Material Quantity Units Type Category Quantity Type 2' x 4' Ceiling Tile Rooms 110, 113, and YES SF X NO 2400 Miscellaneous Yes None 0 w/Lengthwise Fissures 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Thomas Kelly High School

School:

1400

Building ID:

		Quantity	Units		Type	Category		Type	Quantity	Units		
3	2x4 Ceiling tile pinhole w/ random dots	8800	SF	3rd floor kitchen, Auditorium		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	10 Orlange											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
4	1x1 Peg hole ceiling tile			3rd floor kitchen, lunch room, and room 314		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
Comments:	go											
2017 - Spring	g: No Change											
Comments:	g. 110 Onlango											
2017 - Fall: N	No Change											
Comments:	10 Change											

Material

Damage

Friable

Damage

Damage Change in Assessment Category

Material Material Location

HA No

Material Description

Material

5	2x4 ceiling tile w/ random fissures	2500	SF	3rd floor dishwash room, 3rd floor lunch room, room 314	Miscellaneous	Yes	None	0	YES	X NO	
	·	•	•	•	•	-	-				
2016 - Fall: N	lo Change										
Comments:	<u> </u>										
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	lo Change										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
6	2x4 Ceiling tile w/ fissures parallel to width	28000	SF	3rd floor north south hall, Room 309, 2nd floor north wing wall		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
7	1x1 Rough white ceiling tile			Library		Miscellaneous					YES	X NO
2016 - Fall: N Comments:	lo Change											
2017 - Spring	ı: No Chango											
Comments:	g. NO Change											
2017 - Fall: N	lo Change											
Comments:												
HA No	Motorial Description	Motorial	Motorial	Material Legation	Ashastas	Motorial	Frieble	Domoso	Domogo	Domogo	Change in Asse	naamant Catagani
HA NO	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
8	2x2 Rough white ceiling tile			Room 113		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

		Quantity	Units		Type	Category		Type	Quantity	Units	I	
9	1x1 White ceiling tile w/ fissures	768	SF	Room 125		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:	, J											
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
10	6'x12" Pegboard ceiling tile			Auditorium		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											

Material

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
15	9x9 Sand colored FT w/ white & brown streaks	4000	SF	Rooms 301, 302, 303, 304, & 207		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	o Change											
2017 - Spring	: No Change				<u> </u>							

Comments: 2017 - Fall: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15A	Mastic 9x9 sand colored FT w/ wh & bwn streaks	4000	SF	Room 301, 302, 303, 304, & 207		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
19	1x1 White floor tile w/ gray streaks			1st, 2nd, 3rd flr. Hall		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
19A	1x1 White floor tile w/ gray streaks mastic			1st, 2nd, and 3rd floor corridors		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20	1x1 White mottled floor tile			Throughout building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
20A	1x1 White mottled floor tile mastic			Throughout school		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21	1x1 White floor tile w/ green marks			Throughout school		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
21A	1x1 White floor tile w/ green marks mastic			2nd, 3rd flr corridors		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
22	9x9 Dark brown FT w/ white & red streaks			main office, 218, 118		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	.											
2017 - Fall: N	lo Change											
Comments:	go											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Туре	Category		Type	Quantity	Units	_	
22A	9x9 Dark brown FT w/ white & red streaks mastic	200	SF	Main office, 218, 118		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	U											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 - Spring	v: No Change											
Comments:	g. 140 Onange											
COMMITTED IN												

23	1x1 White floor tile w/ tan streaks	1600	SF	111, 211		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
	: No Change										
Comments:					_						
2017 - Fall: N Comments:	lo Change				<u>-</u>						

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23A	1x1 White floor tile w/ tan streaks mastic	1600	SF	111, 211		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

24	1x1 Gray floor tile w/ tan and white streaks	3100	SF	111, 211, Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	a. No Chango				-							
Comments:	g: No Change											
2017 - Fall: N	No Change				-							
Comments:												
	T		T	T	T	T		T _	T _	1 _		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

3100

Material

Quantity

Material

Units

SF

Material Location

111, 211, Library

HA No

24A

Material Description

1x1 Gray floor tile w/ tan &

white streaks mastic

YES

Change in Assessment Category

X NO

		Quantity	Units		Туре	Category		Туре	Quantity	Units	<u></u>	
28	1x1 Black floor tile	8000	SF	auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2017 - Spring	g: No Change											
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
28A	1x1 Black floor tile mastic	8000	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					4							
2017 - Fall: N	lo Change											
Comments:					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39	Smooth hard plaster	200000	SF	Throughout building		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	Water tank jacket insulation	150	SF	Boiler room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change				-							
Comments:												

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
51	Boiler door gasket	50	LF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
53	Kiln fire brick	200	SF	Throughout school		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
56	Incinerator fire brick mortar	50	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Spring	: No Change											
Comments:					1							
2017 - Fall: N	o Change											
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
57	Glazed brick			3rd floor girl's toilet NW corner, 2nd floor NW stairway, 1st floor corridor NE corner		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	-											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>]							
]							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
58	Glazed brick mortar			3rd floor girl's toilet NW corner, 2nd floor NW stairway, 1st floor corridor NE corner		Miscellaneous					YES		X NO
2016 - Fal	I: No Change]								
Comments	<u> </u>												
2017 - Spr	ring: No Change												
Comments	<u> </u>												
2017 - Fal	I: No Change												
Comments													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
59	Cinderblock			1st floor men's toilet SE corner, Boiler room		Miscellaneous					YES		X NO
2016 - Fal	I: No Change]								
Comments	<u> </u>				1								
2017 - Spr	ring: No Change				1								
Comments					†								

2017 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	Cinder block mortar			1st floor men's toilet SE corner, Boiler room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	g: No Change											
Comments:					<u> </u>							
2017 - Fall: N	lo Change											
Comments:					-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
61	Drywall			Basement weight room, drama room , locker room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Spring	j: No Change											
Comments:					-							
2017 - Fall: N	lo Change				-							
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
62	Masonry brick			Boiler room		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
2017 - Spring Comments:	g: No Change											
2017 - Fall: N Comments:	lo Change											
		T		T		T	T =	Τ -		1 -	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
63	Masonry brick mortar			Boiler room		Miscellaneous					YES	X NO
2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
64	Interior window caulk (brown)			Throughout the school		Miscellaneous					YES	X NO
2016 - Fall: N	o Change											
Comments:					1							
2017 - Spring Comments:	: No Change				-							
2017 - Fall: N	o Change											
Comments:			=									
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
65	Clay brick tile			Basement between tempering coils, S wall near fan unit, next to reheat #7, fresh air intake #4		Miscellaneous					YES	X NO
2016 - Fall: N	o Change]							
Comments:	.											
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	<u>_</u>		1									
Comments.												

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Asses	sment Category
66	Clay brick tile mortar			Basement between tempering coils, S wall near fan unit, next to reheat #7, fresh air intake #4		Miscellaneous					YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change				-							
Comments:	Comments:											
			J									
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
67	Terrazzo flooring			1st floor SE corner vest., main entrance vest., NW corner vest.		Miscellaneous					YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>]							
					j							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
68	Boiler mortar	100	SF	Boiler room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				-							
Comments:	-]							
2017 - Fall: N	No Change				-							
Comments:	Ţ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
69	9x9 VAT (Brown w/ white specks) Mastic black	200	SF	Main office, vaults, copy room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Spring	g: No Change				_							
Comments:	-]							
2017 - Fall: N	No Change				-							
Comments:	J]							
1					1							

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Categoria	
70	Brown VAT molding	10	LF	Main office vaults		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
71	Black VAT molding mastic	10	LF	Main office vaults		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	Ü											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	o change											

72	12x12 VFT beige w/ white, brown & tan specks	800	SF	Room 303	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	o Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
73	12x12 VFT beige w/ white, bwn & tan specks, mastic	800	SF	Room 303		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
74	Black Vinyl baseboard	224	LF	Rooms 303 and 304		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
75	Black vinyl baseboard mastic (beige)	224	LF	Rooms 303 and 304		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	-											

76	12x12 VFT cream w/ beige specks	224	LF	Room 304		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments												
2017 - Spr	ing: No Change											
Comments	S:											
2017 - Fall	: No Change											
Comments	S:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

		Quantity	Units		Туре	Category		Туре	Quantity	Units	gg	
77	Mastic (black) 12x12 VFT cream w/ beige specks	800	SF	Room 304		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
2017 - Spring	: No Change				- -							

Comments:
2017 - Fall: No Change

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

Damage

Units

78	12x12 VFT (Beige w/ white & beige specks)	2000	SF	Room 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	r. No Change				-							
Comments:	y. 110 Chango				-							
2017 - Fall: N	lo Change											
Comments:	ge											
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
79	Tan Mastic 12x12 VFT beige w/ white & beige specks	2000	SF	Room 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Spring	<u> </u>											
Comments:												
2017 - Fall: N	lo Change											
Comments:	y -				•							

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

80	Blk mastic 12x12 VFT beige w/ white & beige specks	2000	SF	Room 203		Miscellaneous	No	None	0		YES	X NO
		•	•	•	· 7	•	•	•	•	•	•	
2016 - Fall	: No Change											
Comments	: :											
					1							
2017 - Spr	ing: No Change											
Comments):											
2017 - Fall	: No Change											
Comments	:											
					1							

Type

Material

Category

Friable

Damage

Туре

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
81	Vinyl baseboard dark brown	100	LF	Room 203		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Change in Assessment Category

Damage

Quantity

Damage

Units

82	Light beige mastic vinyl baseboard (dark brown)	100	LF	Room 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
					_							
Comments	:											
2017 - Spri	ng: No Change											
Comments	:											
	•											
2017 - Fall	: No Change				_							
					_							
Comments	•											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
	· ·	Quantity	Units		Type	Category		Type	Quantity	Units		0 ,

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

6000

Material

Quantity

Material

Units

SF

Material Location

221, gym, 109 ,108

HA No

83

Material Description

12x12 VFT green w/ green

specks

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

84	Black mastic 12x12 VFT green w/ green specks	6000	SF	gym		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	o oago											
2017 - Spring	· No Change				-							
Comments:	. 140 Onange											
2017 - Fall: N	o Change				-							
Comments:	o onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
85	12x12 VFT gray flecks w/ grey specks	760	SF	Room 320		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:	o onango											
2017 - Spring	· No Change											
Comments:	. 140 Onange											
2017 - Fall: N	o Change											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
86	Mastic 12x12 VFT gray flacks w/ gray specks	760	SF	Room 203		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	io onango											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
87	12x12 VFT beige w/ multicolors-wht, yel, rust, bge	760	SF	Room 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•					•					
Comments:	10 Orlango											
2017 - Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	No Change											
Comments:												

88	Black mastic 12x12 VFT beige w/ multicolors	3000	SF	Room 201		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Spring	g: No Change				1							
Comments:												
2017 - Fall: N	lo Change				_							
Comments:												
]							
LIA NI-	I Maradal Basadadas	NA-t-d-1	I Martanial	Maradallandon	I A -lat	I Mantager	Leann	D	D	D	Observa in Assess	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
89	12x12 VFT green w/ dark green & white streaks	950	SF	Room 110, 1st floor corridor main entrance,		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				<u> </u>	•	•					
Comments:	<u> </u>				1							

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assessm	nent Category
90	Beige mastic 12x12 VFT green w/ white & green strk	2000	SF	1st floor corridor main entrance, Rm 110		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change												
Comments:					_								
2017 - Sprin	g: No Change				=								
Comments:													
2017 - Fall: N	No Change				-								
Comments:													
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in i	Assessm	nent Category
91	12x12 VFT Cream w/ beige specks			Engineer office		Miscellaneous					YES		X NO
2016 - Fall: I	No Change				٦								
Comments:	•												
2017 - Sprin	g: No Change				-								
Comments:													
2017 - Fall: N	Vo Change				-								
Comments:	10 Orialigo				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
92	Black mastic 12x12 VFT crème w/ beige streaks			Engineer's office		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
93	VFT molding tan w/ white & brown specks			Engineer's office		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	i. 110 Onlango											
2017 - Fall: N	lo Chongo											
Comments:	lo Change											
2 311111011101												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
94	Black mastic VFT molding	20	LF	Engineer's office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
L												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
95	Exterior Brick - Non AHERA			Exterior of building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											

Page 35

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
96	Exterior Brick Mortar - Non AHERA			Exterior of building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
97	Exterior window caulk (Non AHERA)			Exterior of building		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
98	Exterior door caulk (Non AHERA)			Surrounding exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
99	Roof (NON AHERA)			Roof exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
100	Roof flashing (NON AHERA)			Roof exterior		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
105	Electrical wire insulation			Auditorium area		TSI					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:					_							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
106	Wood enclosed door insulation	200	SF	Throughout building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	Ţ.											
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
107	Spray-on fireproofing	2000	SF	Attic		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Sprin	ng: No Change											
Comments:					_							
2017 - Fall:	No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

108	9x9 brown FT w/green, brown, yellow speck	200	SF	319		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall: Comments:	No Change											
2017 - Sprin	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

200

Material

Quantity

Material

Units

319

SF

Material Location

HA No

109

Material Description

9x9 brown FT w/green, brown, yellow speck mastic

Damage

Quantity

Damage

Units

YES

Change in Assessment Category

110	12" x 12" Brown Floor Tile	1900	SF	Room 303, 111, 211		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments	<u> </u>											
2017 - Fall:	: No Change											
Comments	<u>:</u>											
2017 - Spri	ing: No Change											
Comments	<u>:</u>				-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

1900

Material

Quantity

Material

Units

SF

Material Location

Room 303, 11, 211

HA No

111

Material Description

12" x 12" Brown Floor Tile

Mastic

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
112	12" x 12" Beige Floor Tile	1900	SF	Room 218, 111, 211		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 Cprin	a. No Changa											
Comments:	g: No Change											
Comments.					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
113	12" x 12" Beige Floor Tile Mastic	250	SF	Room 218		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	io oago											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											

Comments:

114	12" x 12" Gray Floor Tile	250	SF	Room 118		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:					= - -							
2017 - Sprii	ng: No Change											
Comments:					- -							
2017 - Fall:	No Change				1							
Comments:	•											
					j							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

250

Material

Quantity

Material

Units

SF

Room 118

Material Location

HA No

115

Material Description

12" x 12" Gray Floor Tile

Mastic

YES

X NO

Damage

Quantity

Damage

Units

130	12" x 12" White VFT with green streaks	28000	SF	1, 2, 3 hallways		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change				1							
Comments												
2017 - Spri	ing: No Change]							
Comments	S:				1							
	: No Change]							
Comments): 				-							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	ent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

28000

Material

Quantity

Material

Units

SF

Material Location

1, 2, 3 hallways

HA No

130M

Material Description

12" x 12" White VFT with

green streaks Mastic

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

131	12" x 12" Light Blue Floor Tile	250	SF	Room 118		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	II: No Change											
Comments	S:											
2017 - Fal	II: No Change											
Comments	S:				1							
2017 - Spr	ring: No Change				=							
Comments	S:				1							
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

250

Material

Quantity

Material

Units

SF

Room 118

Material Location

HA No

131M

Material Description

Mastic associated with 12"

x 12" Light Blue FT

YES

Damage

Quantity

0

Damage

Units

Change in Assessment Category

132	12" x 12" Light Green Floor Tile	925	SF	Room 114 & 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change]							
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	:											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
133	12" x 12" Green Floor Tile	475	SF	Room 114 & 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•	•]	•	•	•	•	•	•	

Type

Material

Category

Friable

Damage

Туре

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

134	Mastic associated with HA 132 & HA 133	1400	SF	Room 114 & 106		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: Comments:	No Change										
2017 - Fall: Comments:	No Change										
2017 - Sprin Comments:	g: No Change										
					•						

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
135	12" x 12" Dark Green Floor Tile	4250	SF	Main Office, 3rd Floor Cafeteria		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
135M	Mastic associated with 12" x 12" Dark Green FT	4750	SF	Main Office & 3rd Floor Cafeteria		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	ı: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
136	Lab Benches & Tabletops	2000	SF	Room 207, 301, 302, 303, 304		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>				1							
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>]							
2017 - Spring	: No Change				-							
Comments:	<u> </u>											
1												

HA No

137	12"x 12" Blue Floor Tile	1650	SF	Engineers Office, Teacher's Lounge, Rooms 106 and 108		Miscellaneous	No	None	0		YES	X NO
0040 5 11 1	. 01	•	*	•	1	•	•	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	j: No Change											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
137M	Mastic associated with 12" x 12" Blue Floor Tile	1650	SF	Engineers Office, Teacher's Lounge, Rooms 106 and 108		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
138	12"x 12" Tan Checkered Pattern Floor Tile	800	SF	Room 202		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	3											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
		Quantity	Units		Туре	Category		Type	Quantity	Units		
138M	Mastic associated with 12" x 12" Tan multicolored Floor Tile	800	SF	Room 202		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	r. No Change				_							
Comments:	j. 110 Onango											
		-										

139	12" x 12" Tan Mottled Floor Tile	1550	SF	Rooms 111, 111B, 217, 304	Miscellaneous	No	None	0	YES	X NO
	No Change									
Comments:										
2017 - Fall:	No Change									
Comments:										
2017 - Sprin	ng: No Change									

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
139M	Mastic associated with 12" x 12" Tan Mottled Floor Tile	1550	SF	Rooms 111, 111B, 217, 304		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
140	Acoustical Plaster on Walls	3000	SF	Auditorium (New Building)		Surface	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:												
2017 - Spring	: No Change				-							
Comments:	-											
2017 - Fall: N	o Change				_							
Comments:	J											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
141	Drywall	150000	SF	Various Locations throughout New Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	-]							
2017 - Spring	: No Change				1							
Comments:	•]							

HA No

142	Off-White Spray-on Fireproofing	80000	SF	Support Beams Throughout (New Building)		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	No Change	•	•	•]	•	•	•	•	•		
Comments:	10 Onango											
0047 5 11 1												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
143	Tan, Gray, and Green Terrazzo	15000	SF	1st, 2nd, 3rd Floor Corridors and Stairwells (New Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
144	2' x 2' Ceiling Tile w/ Gouges and Holes	25000	SF	Throughout New Building		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	ı: No Change				_							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
145	12" x 12" Beige w/ light Brown and Green Spots Floor Tile	30000	SF	All Classrooms in New Building		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	go											
2017 - Spring	ı: No Change											
Comments:	j. 140 Ondrigo				-							

146	Mastic Associated w/ 12" x 12" Beige w/ light Brown and Green Spots Floor Tile	30000	SF	All Classrooms in New Building		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change		<u> </u>	·]					•	
Commer	nts:										
2017 - F	all: No Change										
Commer	nts:										
2017 - S	pring: No Change										

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
147	12" x 12" Light Brown Floor Tile Accent	5000	SF	All Classrooms in New Building		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

148	Mastic Associated w/ 12" x 12" Light Brown Floor Tile Accent	5000	SF	All Classrooms in New Building	Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change	*	-		•	•	•	•	•	•	
Comments											
2017 - Fall	: No Change										
Comments): :										
2017 - Spri	ing: No Change										

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
149	12" x 12" Green Floor Tile Accent	5000	SF	All Classrooms in New Building		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

150	Mastic Associated w/ 12" x 12" Green Floor Tile Accent	5000	SF	All Classrooms in New Building		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: No Change											
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
151	12" x 12" Blue Mottled Floor Tile	5000	SF	Rooms 251, 253, 255, 259, 261 (New Building)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

152	Mastic Associated w/ 12" x 12" Blue Mottled Floor Tile	5000	SF	Rooms 251, 253, 255, 259, 261 (New Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Chango]							
	NO Charige											
Comments:												
2017 - Fall:	No Change											
Comments:]							
2017 - Sprin	g: No Change											
Comments:]							
					1							
					<u>-</u> '							
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Friable	Damage	Damage	Damage	Change in Access	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

153	Black Marble Pattern Sheet Flooring	2000	SF	TV Studio Room 351 (New Building)					
2016 - Fall: N	o Change								
Comments:	Comments:								
2017 - Fall: N	o Change								
Comments:									
2017 - Spring: No Change									
Comments:	_		•						

Quantity

Material

Units

Units

Material

Quantity

Material Location

TV Studio Room 351

HA No

Material Description

Black Marble Pattern Sheet

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
154	Mastic Associated w/ Black Marble Sheet Flooring	2000	SF	TV Studio Room 351 (New Building)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	•											
2017 - Fall: N	o Change				1							
Comments:												
2017 - Spring: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
155	Textured Acoustical Plaster	1500	SF	Library (New Building)		Surface	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>											
2017 - Fall: N	o Change				+							
Comments:												
2017 - Spring: No Change												
Comments:					1							

HA No

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: T	Thomas Kelly High School							
Date: 1	0/6/2017							
the Asbestos	ify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of Management Plan is available at each school during school hours by appointment. review the Asbestos Management Plan must be made at least 24 hours in advance.							
The last insp	be advised that CPS conducts asbestos inspections of all Schools every three years. ection was completed in 2016. rveillances are conducted every six months.							
CHECK ONE								
A copy	y of this notice was sent home in each child's backpack.							
A copy	A copy of this notice was printed in the school's newsletter and sent home with each child							
A copy	y of this notice was printed in the school's calendar and sent home with each child							
X Other.	. School Website							
A COPY (OF THIS NOTICE MUST BE PLACED IN THE							

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.