## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

46221

**Oracle Unit:** 

**Building ID:** 

1440

Address: 2501 W. Addison Region: 01 Mail Room: 33 Asbestos Surveyor: Caldwell, Mr. Brian X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 10/11/2017 Email Address: bcaldwell1@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type Unexcavated Areas, Pipe YES X NO Chases - Rms 253, and LF 12 Aircell Pipe Insulation 1300 TSI Yes Loc 4 153D (not observed in 251) -1931 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments:

Albert G Lane Technical High School

School:

14	MJP E/F/V on Aircell Pipe Insulation	98	LF	Unexcavated Areas, Pipe Chases - 1931; Rms 251, 253, and 153D	TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change	•				•	•	•	•		
Comments:											
2017 - Fall: N	lo Change										
Comments:											
2017 - Spring	g: No Change										

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Light Blue w/ Dark Spots Linoleum	1200	SF	Room 115 - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

30	Light Blue w/ Dark Spots Linoleum Mastic	1200	SF	Room 115 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<b>-</b>											
2017 - Fall:	No Change				+							
Comments:												
2017 - Sprin	ıg: No Change				-							
Comments:	g											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
31	2'x4' White w/ Holes & Grooves Ceiling Tile	1200	SF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change			•	<u> </u>							
Comments:												
2017 - Sprin	ıg: No Change				4							
Comments:	ig. No Change											
Comments.												
					<b>⊣</b>							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
32	Drywall	500	SF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:												
Comments:					_							
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:	ig. No Onange											
	Two dipode	T	T	I sa c : 11 c		T	Levis	1.5	T 5	T 5		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
33	Drywall Joint Compound	100	LF	Room 115 - 1931		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Chango				_							
Comments:	INO Change											
Commonto.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
34	Vinyl Baseboard	150	LF	Room 115 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
35	Vinyl Baseboard Mastic	150	LF	Room 115 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"X12" Light beige w/ white and brown streaks VFT	1800	SF	Locker rm & office & storage rm and toilet (361A), 153 A- 1931 bldg		Miscellaneous	No	Loc	40		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36A	12"x12" light beige w/ white and brown streaks VFT MASTIC	1800	SF	Locker rm & office & storage rm and toilet (361A), 153A- 1931 bdlg		Miscellaneous	No	Loc	40		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37	12"x12" dark gray w/white streaks VFT	800	SF	Room 340		Miscellaneous	No	Loc	25		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:	J											
0047 Omnin	No Observe											
2017 - Spring Comments:	g: No Change											
Comments.												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37A	12"x12" dark gray w/ white streaks VFT MASTIC		SF	Room 340		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											

38	12"x12" gray w/ gray and white streaks VFT	1900	SF	Rooms 133, (Not observed 129, 147)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				]							
Comment	ts:											
2017 - Sp	oring: No Change											
Comment	ts:				1							
2017 - Fa	II: No Change											
Comment	ts:											
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
38A	12"x12" gray w/ gray and white streaks VFT MASTIC	1900	SF	Rooms 133, (Not observed 129, 147)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39	12"x12" light green streaked VFT	3500	SF	Serving line room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
39A	12"x12" light green streaked VFT MASTIC	3500	SF	Serving line room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
40	9"x9" Tan w/ brown & white streaks VFT	40	SF	Library stairs landings- 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
40A	9"x9" Tan w/brown & white streaks VFT MASTIC	40	SF	Library stairs landings- 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	•											
2017 - Fall: N	lo Change				_							
Comments:	J											
2017 - Spring	g: No Change											

Comments:

41	12"x12" Green w/ white & black streaks VFT	600	SF	Room 117 - 1931 bldg		Miscellaneous	No	None	0		YES X	NO
2016 - Fall: Comments:	No Change				]							
2017 - Sprir Comments:	ng: No Change											
2017 - Fall: Comments:	No Change											
LIA NI-	I Martin December 1	NA-t	I Maria dal	I Material Landin	Ashastas	Matazal	Lean	D	l D	l D	[ Ohanni	S-1
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment C	ategory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

600

Material

Quantity

Material

Units

SF

Material Location

Room 117 - 1931

HA No

41A

Material Description

12"x12" Green w/ white &

black streaks

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
42	Black/gray lab counter tops	5400	SF	Rooms 439, 435, 431, 438	1,7,1-2	Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1					•		
Comments:					1							
2017 - Sprin	ıg: No Change				-							
Comments:	ig. 140 Change				1							
2017 - Fall:	No Change											
Comments:	140 Change											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
216-FT6	12x12 Dark brown W/black streaks VFT	4400	SF	Main Corridors 12s, 2nd, 3rd, 4th floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•			1							
Comments:	. to onango				_							
2017 Corio	ay No Chango	•										
	g: No Change				-							
Comments:												

2017 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
2016-BBM1	Brown Vinyl Baseboard Mastic	600	SF	Rooms 119, 123, 125		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change				=							
Comments:	<u> </u>											
2017 - Spring	: No Change				-							
Comments:	, reconsider											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	ssessment Category
2016-CT1	2x2 White W/pinhole dots ceiling tile	3900	SF	Rooms 119, 123, 125, 215B		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	lo Change				+							
Comments:	o Griango											
2017 - Spring	: No Chango											
Comments:	. No Change				+							
					]							

2016-CT2 2x2 white Rought with dots ceiling tile 2500 SF Rooms 145A, 138A, 115A, 213, 242A, 2nd floor boys washroom Miscellaneous No None 0	YES X NO
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Type

Material

Category

Friable

Damage

Туре

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-CT3	2x4 White smooth ceiling tile	3000	SF	Rooms 120A, 123A, 220A, 214A, 323C, 320A, 487A, 2nd floor boys bathroom, 4th floor ADA bathroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

2016- DWS1	Drywall system	6700	SF	Rooms 119, 123, 125, 129, 130, 148, 150		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			•	]							
Comments:												
2017 - Fall: N	o Change											
Comments:	Ğ											
2017 - Spring	: No Change											
Comments:	<b>.</b>											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
2016-FD1	Fire Doors rated 3/4 hour	180	SF	2nd Floor boys bathroom, rooms 342A, 437A boys, 4th floor ADA bathroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:	o onango											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
2016-FDR1	Dark Gray fire proofed cloth draperies	3000	SF	Room 209 Auditorium balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	•				]							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
2016-FDR2	LT. Green fire proofed cloth draperies	1000	SF	Room 300 Gymnasium #2		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	_				]							
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:												
		-	-									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT1	2x2 Yellow w/yellow streaks VFT	10170	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT1M	2x2 Yellow w/yellow streaks VFT Mastic	10170	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

2016-FT2	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	2016-FT2		4000	SF	215, 219, 223, 225. 234, 243, 247, 322 322A, 335, 336, 430, 434, 449,4th		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
0047 5 11 N 01
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT2M	2x2 Gray W/Gray streaks VFT Mastic	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225. 234, 243, 247, 322 322A, 335, 336, 430, 434, 449,4th Floor ADA elevator pump		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

		Quantity	Units		Туре	Category		Type	Quantity	Units		
2016-FT3	2x2 Green W/green streaks VFT	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												

Material

Friable

Damage

Damage

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Material Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT3M	2x2 Green W/green streaks VFT Mastic	4000	SF	Rooms 119, 123, 125, 215, 219, 223, 225, 234, 243, 247, 322, 322A, 335, 336, 430, 434, 449		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
2016-FT4	2x2 Blue W/blue gray streaks VFT	150	SF	Rooms 441B, 430, 434		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:	lo Change												
LIA NI-	Maradal Bassadada	NA-1-2-1	I Markadal	I Madadall and a	A - I: 1	T Manager 1	Legania				Observation in		0-1
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	sment Category
2016-FT4M	2x2 Blue W/blue gray streaks VFT Mastic	150	SF	Rooms 441B, 430, 434		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change												
Comments:													
2017 - Spring	ı: No Change												
Comments:	irro onango												
0047 5 11 1													
2017 - Fall: N	lo Change												
Comments:													

2016-FT5	12x12 Beige W/brown and white specks VFT	5000	SF	Rooms 435, 245,(1st, 2nd, 3rd, 4th floor corridors)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change			•	]					•	
Comments:	o Chango				= -						
2017 - Fall: N	o Change				_						
Comments:	Ü				<del>-</del>    -						
2017 - Spring	: No Change				1						
Comments:	•										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Rooms 435, 245,(1st,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
2016-FT5M	12x12 Beige W/brown and white specks VFT Mastic	5000	SF	Rooms 435, 245,(1st, 2nd, 3rd, 4th floor corridors)		Miscellaneous	No	None	0		YES X NO

2016 Falls No Change	
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

		Quantity	Units		Type	Category		Type	Quantity	Units		
2016-FT6M	12x12 Dark brown W/black streaks VFT Mastic	4400	SF	Main Corridors 12s, 2nd, 3rd, 4th floors		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	o onango											
2017 - Spring	: No Chango											
Comments:	i. No Change											
					]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Damage	Damage	Change in Ass	sessment Category
TA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Quantity	Units	Change in Ass	essment Category
AA	Stage Door (Fire curtain)	1000	SF	Auditorium Stage - 1931		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:	. 110 Onango											

Material

Damage

Friable

Damage

Material Material Location

HA No

Material Description

Material

Damage Change in Assessment Category

AAA	2'x 2' ceiling tile; fissured, White	800	SF	corridor		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fa	II: No Change											
Comment	0											
2017 - Sp	ring: No Change				1							
Comment	S:											
2017 - Fa	II: No Change											
Comment	S:											
					<u></u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
RR	1'x1' White Wormy Ceiling			Room 241, 437, Main Office - 1931; 113, 134, Auditorium, 252, 335,							YES	X NO

Type

Material

Category

Friable

Damage

Type

	(bandroom), 446, 400, 402, 403
2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Units

Material

Quantity

Material Location

433, 442, 444

HA No

ВВ

Material Description

Damage

Quantity

Damage

Units

BBB	Acoustical Wall tile, fissured	450	SF	Room 252		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
CC	1'x1' White Wormy Ceiling Tile Mastic			Room 241, 437, Main Office - 1931: 113, 134, Auditorium, 252, 335, 433, 442, 444 (bandroom), 446, 400, 402, 403							YES	X NO

Type

Material

Category

Friable

Damage

Туре

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

CCC	Textured Plaster, Walls and Ceiling	4500	SF	1st floor corridor by main office, Auditorium, Room 202		Surface	Yes	None	0	YES	X NO
		•	•	•	1	•	•	•	-		
2016 - Fall: N	No Change										
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
•					•						

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
CT1	2 x 4 ft Ceiling Tiles with Grooves	800	SF	Engineer's Office		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N Comments:	lo Change											

Comments: 2017 - Fall: No Change

2017 - Spring: No Change

Comments:

HA No

Material Description

Material

Units

Material

Quantity

Material Location

1st floor corridor by main

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
DD	2'x2' White Wormy Ceiling Tile			Serving Area, Lunchroom - 1931; 213, 252, Toilet rooms; 138A, 115A, 145A, 242A, 214A, 215B, 245A, 320A							YES	X NO
2016 - Fall:	No Change				1							
Comments:												
2017 - Fall:	No Change											
Comments:					-							
					-							
	ng: No Change											
Comments:	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
DDD	Terrazzo Floor	30000	SF	All corridors, stairwells, auditorium vestibule, main office lobby		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				1							
Comments:	•											
001= 0												
	ng: No Change											
Comments:	:											
2017 - Fall:	No Change				1							
Comments:												

EE	2'x4' White Wormy Ceiling Tile (Not observed)			Room 125, 447, 112, 117, 119, 123, 205, 330 - 1931							YES	X NO
2016 - Fall:	No Change	•		•	]	•		•	•	•	•	
Comments					1							
2017 - Spri	ng: No Change											
Comments	:				 							
	No Change											
Comments	:				<u> </u>							
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

TSI

Friable

Yes

Damage

Type

Type

Loc

Damage

Quantity

Quantity

10

2016 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			

Quantity

2000

Material

Units

Units

SF

Material

Quantity

Material Location

SW Unexcavated Area -

1931

HA No

FF

Material Description

Aircell Duct Insulation

Change in Assessment Category

Damage

Units

Units

YES

X NO

							1			1		
FT10	12"x12" White w/ Tan Streaks VFT	1200	SF	Room 443 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change	·	<u> </u>	<u> </u>	7							
Comments												
2017 - Spri	ng: No Change				+							
Comments												
2017 - Fall:	: No Change											
Comments	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FT11	12"x12" Dark Brown w/ Black Streaks VFT	16270	SF	All corridors and auditorium - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				7							
Comments												
2017 - Spri	ng: No Change				-							
Comments												
1					1							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

FT12	12"x12" Peach VFT	1600	SF	Rooms 132, 203 -1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:					]							
2017 - Fall:	No Change											
Comments:	:											
	ng: No Change				-							
Comments:	•				-							
L					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT13	12"x12" Off White w/ Brown Specks VFT	1600	SF	Room 220 -1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]		•					
Comments:												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT14	9"x9" Off White w/ Gray Streaks VFT (ABATED)			Lunchroom - 1931		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT15	9"x9" Green VFT (ABATED)			Lunchroom - 1931		Miscellaneous	No				YES	X NO
2016 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	o onango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT16	9"x9" Beige w/ Brown Streaks VFT (ABATED)	1000	SF	(Serving Area - ABATED) Rm 134 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
2017 - Fall: N Comments:	No Change											
	g: No Change				-							
Comments:					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT17	12"x12" White w/ Brown Specks VFT	650	SF	Kitchen - 1931		Miscellaneous	No	Loc	500		YES	X NO
2016 - Fall: N	lo Change											
Comments:					 							
2017 - Fall: N	lo Change											
Comments:					=							
2017 - Spring	g: No Change											
Comments:	•											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT18	12"x12" Beige w/ Wavy Brown VFT	3500	SF	Kitchen - 1931		Miscellaneous	No	Loc	30		YES	X NO
2016 - Fall:	No Change				7							
Comments:	<u> </u>				]							
2017 - Fall:	No Change											
Comments:	<u> </u>				1							
2017 - Sprin	g: No Change											
Comments:					1							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT19	9"x9" Black w/ White Streaks VFT	600	SF	Lunchroom Storage, & Engineer's Office - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	J				]							
2017 - Sprin	ıg: No Change				_							
Comments:												

2017 - Fall: No Change

Comments:

FT20	9"x9" Maroon w/ White Streaks VFT	1500	SF	Engineer's Office - 1931 Gym III 361 mezzanine locker rm.		Miscellaneous	No	Loc	10		YES	X NO
2016 - Fall	I: No Change				]							
Comments	S:				]							
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fall	l: No Change				-							
Comments	S:				-							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
FT21	12"x12" Green w/ White Streaks VFT	200	SF	Engineers Locker Room - 1931		Miscellaneous	No	None	0		YES	X NO

Asbestos Type Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:		•	

Material

Quantity

Material

Units

Material Location

Lunchroom Storage, &

HA No

Material Description

FT22	12"x12" Gray w/ White & Brown Specks VFT	2737	SF	Girl's Locker Room Office, Shower Office, Storage, Laundry, 439, 431, 438 - 1931	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	ı: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT23	6"x6" Black VFT	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
Commonte.	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
FT29	12 x 12 inch White w/Tan Streaks VFT	800	SF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
FT30	12 x 12 inch Pink VFT	1500	SF	Room 146		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	•											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												
					_							

FT4	12"x12" Beige w/ Brown & White Specks VFT	44600	SF	1931- Corridors all floors, 441B, 435, 245, 125 work room, auditorium, men and women toilets		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change												
Comments:					]							
2017 - Spring: No Change												
Comments:					<u> </u>							
2017 - Fall: No Change					-							
Comments:					<u> </u>							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
FT5	9"x9" Peach w/ cream streaks VFT	5200	SF	Vaults in rooms 131, 435, 438, 439, 217, 221, 241, 302A		Miscellaneous	No	None	0		YES	X NO

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

1931- Corridors all floors,

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FT6	6"x6" White VFT	500	SF	Library Loft - 1931 (balcony)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FT7	12"x12" Green VFT	1884	SF	Driver's Education Building room 199 simulator room- 1975		Miscellaneous	No	Loc	100		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	_											
2017 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change				+							
Comments:	,											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT8	12"x12" Gray w/ White Streaks VFT	800	SF	Rooms 144 -1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	-											
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
FT9	12"x12" Sand VFT	3000	SF	Room 447, 116 (not observed in 145, 143) - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				<u> </u>							
Comments:												
2017 - Fall: N	lo Change											
Comments:	to onango											
		•										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
GG	Interior Window Caulk			Throughout - 1931							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	o Change											
<u> </u>	T		1	T		1	1	T _	T	<del></del>	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
НН	Exterior Window Caulk			Throughout - 1931							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Onlange											
2017 - Fall: N	lo Change											
Comments:					_							

I	MJP E/F/V on Fiberglass Pipe Insulation			Boiler Room, Bathroom Pipe Chases, Janitors Closets - 1931							YES	X NO
2016 - Fall: N	lo Change	•	•	•	1	•	•	•	•	•		
Comments:	go											
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	y: No Change											
Comments:	J. NO Change				_							
Comments.					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
II	MJP E/F/V on Fiberglass Pipe Insulation			Janitors Closet, Bathroom Pipe Chases - 1975							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:	Ŭ											
2017 Cmmira	v. No Change											
2017 - Spring	j: No Change											
Comments:					_							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

2017 - Fall: No Change

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
JJ	2'x4' White Ceiling Tile			Drivers Education Building - 1975							YES	X NO
2016 - Fall: N	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall: N	No Change				-							
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
KK	Tan Rubber Flooring	600	SF	Old Dishwasher Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J											
2017 - Sprin	g: No Change											
Comments:	<u> </u>											
2017 - Fall: N	No Change				-							
Comments:	<del>y</del> -											

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
L8	Brown Linoleum- ABATED			Room 124, 128, 133 - 1931							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
L9	Green & White Linoleum			Stage Crew Office - 1931							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
LM10	Brown Linoleum Mastic- ABATED			Rooms 128, - 1931		Miscellaneous		None			YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
LM11	Green & White Linoleum Mastic			Stage Crew Office - 1931							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	j: No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M10	9"x9" Peach w/ cream streaks VFT Mastic	4800	SF	Vaults in rooms 435, 438, 439, 217, 221, 241		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	<u> </u>											
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M11	6"x6" White VFT Mastic	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
	<u> </u>			·								

aneous No None 0 YES X NO
al Friable Damage Damage Quantity Damage Units Change in Assessment Category
aneous No None 0 YES X NO
ia

Type

Material

Category

Friable

Damage

Type

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

Change in Assessment Category

Damage Quantity Damage

Units

M14	12"x12" Sand VFT Mastic	5150	SF	Rooms 447, 116 (Not observed in 145, 143) - 1931		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change	*	•		•	•					
	o Change										
Comments:	2017 - Fall: No Change Comments:										
2017 - Spring Comments:	: No Change										
Comments.											

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
M15	12"x12" White w/ Tan Streaks VFT Mastic	1200	SF	Room 443 - 1931		Miscellaneous	No	None	0		YES	X NO
-	2016 - Fall: No Change											
Comments:					-							
2017 - Fall: N	17 - Fall: No Change											

Comments:
2017 - Spring: No Change

Material Description

Comments:

HA No

Material

Units

Material

Quantity

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M16	12"x12" Dark Brown w/ Black Streaks VFT Mastic	16270	SF	Corridors & Auditorium - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				]							
Comments:					-							
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change				-							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M17	12"x12" Peach VFT Mastic	1450	SF	Rooms 203, 132 -1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	<u> </u>				]							
2017 - Fall: N	o Change				1							
Comments:	J											
2017 - Spring	: No Change											
Comments:					]							

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
M18	12"x12" Off White w/ Brown Streaks VFT Mastic	1600	SF	Room 335, 220 -1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	Ü				1							
2017 - Fall: N	lo Change				-							
Comments:				]								
2017 - Spring	: No Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M19	9"x9" Off White w/ Gray Streaks VFT Mastic - ABATED			Lunchroom - 1931		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					]							
2017 - Spring	: No Change				-							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	-				]							
					_							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

		Quantity	Units		Type	Category		Туре	Quantity	Units		
M20	9"x9" Green VFT Mastic - ABATED			Lunchroom - 1931		Miscellaneous	No				YES	X NO
2016 - Fall:	: No Change				1							
Comments												
2017 - Fall:	: No Change				1							
Comments												
2017 - Spri	ng: No Change				_							
Comments					]							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
M21	9"x9" Beige w/ Brown Streaks VFT Mastic	2000	SF	(Serving Area - ABATED) Rm 134 - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				1							
Comments	:											
2017 - Fall:	: No Change				1							
Comments												
2017 - Spri	ng: No Change				1							
Comments					]							
					]							

Asbestos

Damage

Friable

Damage

Damage Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
M22	12"x12" White w/ Brown Specks VFT Mastic	650	SF	Kitchen - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	Comments:											
2017 - Fall: N	o Change											
Comments:												
2017 - Spring: No Change												
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
M23	12"x12" Beige w/ Wavy Brown VFT Mastic	3500	SF	Kitchen - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Spring: No Change												
Comments:												
2017 Fall: N	o Chango											
2017 - Fall: No Change Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
M24	9"x9" Black w/ White Streaks VFT Mastic	600	SF	Lunchroom Storage, & Engineer's Office - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I Comments: 2017 - Sprin Comments: 2017 - Fall: I Comments:	g: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
M25	9"x9" Maroon w/ White Streaks VFT Mastic	1500	SF	Lunchroom Storage & Engineer's Offices - 1931 Gym III 361 Mezzanine locker rm.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: 1 Comments:												
2017 - Spring Comments: 2017 - Fall: N	g: No Change											

Comments:

M26	12"x12" Green w/ White Streaks VFT Mastic	200	SF	Engineers Locker Room - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				]							
Comments:					]							
2017 - Fall:	No Change											
Comments:					 							
2017 - Sprin	g: No Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

M27	12"x12" Gray w/ White & Brown Specks VFT Mastic	2737	SF	Storage & Laundry, Rooms 439, 431, 438 - 1931
2016 - Fall: N	lo Change			
Comments:				
2017 - Spring	g: No Change			
Comments:				
2017 - Fall: N	lo Change			
Comments:	·			·

Material

Units

Material

Quantity

Material Location

Girls' Locker Room &

Office, Shower Office,

HA No

Material Description

Damage

Units

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M28	6"x6" Black VFT Mastic	500	SF	Library Loft (balcony) - 1931		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					]							
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
M29	12 x 12 inch White w/Tan Streaks VFT Mastic	800	SF	Engineer's Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
2017 - Spring: No Change												
Comments:												

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
M30	12 x 12 inch Pink VFT Mastic	1500	SF	Room 146		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
M31	Carpet Mastic	2400		Rooms: 130, 210, 235, 330, 205, 212, 213		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Fall:	No Change											
Comments:	Comments:											
2017 - Spring: No Change												

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
M9	12"x12" Beige w/ Brown & White Specks VFT Mastic	44600	SF	Corridors all floors, 441B, 435, 245, 125 work room, auditorium men & women toilets - 1931		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Albert G Lane Technical High School
Date: 10/11/2017
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.

Oracle Unit: 46221