Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

	Address: 2001 N. (ark High Scr Orchard	1001					acle Unit: gion:	4632 02	21	Mail Ro	_	
					Asbestos	Surveyor:	Garcia, M	r. Jesus					
CHEC	K HERE IF NO CH	ANGE T	O ASBE	STOS	Survey D	ate:	1/12/2018	3					
					Email Ad	dress:	jgarcia2@	cps.edu					
	A copy of the 2016/20	17 notice to	parents an	d staff regard	ing the asb	estos manag	gement plan not	ifications v	vas distribute	d via:			
	Each child's backp	ack	X Notice	orinted in sch	ool's news	letter	Notice prin	nted in sch	ool's calenda	Oti	her		
HA No	Material Description	Material Quantity	Material Units	Material Loc	ation	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37-01	12"x12" Tan w/ Brown & White Specks VFT	14410	SF	1st, 2nd & 3rd Corridors, Roo Corridors, Roo 1937	om 102		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments	V												
2017 - Spri	ng: No Change												
Comments													
2017 - Fall:	No Change												
Comments	:n/a												
						1							

37-02	12"x12" Tan w/ Brown & White Specks VFT Mastic	14410	SF	1st, 2nd & 3rd Floor Corridors, Room 102 - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	la Changa		•	•	7	•	•	•	•	•	•	
2010 - Fall. N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:n/												

Type

Material

Category

Friable

Damage

Туре

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-03	12"x12" Gray w/ Gray Streaks VFT	3603	SF	2nd Floor Teachers Lounge, Office By Room 207, 207A & Boy's Locker Room - 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

Damage

Quantity

Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-04	12"x12" Gray w/ Gray Streaks VFT Mastic	3603	SF	2nd Floor Teachers Lounge, Office By Room 207, & Boy's Locker Room - 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-05	12"x12" Beige w/ Brown & White Speckles VFT	7236	SF	Rooms 208, 111,103A; NOT OBERVED in Girls Locker Room - 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-06	12"x12" Beige w/ Brown & White Speckles VFT Mastic	7236	SF	Rooms 208, 111,103A; NOT OBERVED in Girls Locker Room - 1937 Bldg		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change			. —			. —				

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-07	12"x12" Off White w/ Tan Streaks VFT	1319	SF	Main Office & Room 101 - 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

37-08	12"x12" Off White w/ Tan Streaks VFT Mastic	1319	SF	Main Office & Room 101 - 1937		Miscellaneous	No	None	0		YES X NO
2016 - Fall: Comments:											
2017 - Fall: Abated Comments:n/a											
2017 - Sprir Comments:	ng: No Change				-						
]	Tage : 1	Levi	T 6	Lo		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage Quantity

37-09	Streaks VFT NOT OBSERVED	Main Office - 1937 (Not Observed)
	·	
2016 - Fal	I: No Change	
Comments	3:	
2017 - Fal	I: Abated	
Comments	s:n/a	
2017 - Spr	ring: No Change	
Comments	3:	

Material

Units

Material

Quantity

Material Location

Main Office - 1937 (Not

HA No

Material Description

12"x12" Black w/ White

Damage

Units

Change in Assessment Category

X NO

YES

37-10	12"x12" Black w/ White Streaks VFT Mastic NOT OBSERVED	Main Office - 1937 (Not Observed)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change]					•	•	
Comment	S:									
2017 - Sp	ring: No Change		-							
Comment	S:									
2017 - Fa	II: Abated		-							

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37-11	12"x12" Tan w/ Gray Streaks VFT	10	SF	Hallway By Principal's Stairs, Main Office - 1937		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

37-12	12"x12" Tan w/ Gray Streaks VFT Mastic	10	SF	Hallway By Principal's Stairs; Main Office - 1937		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: No Change Comments:											
	2017 - Fall: No Change Comments:n/a										
2017 - Spring Comments:	: No Change										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37-15	9"x9" Brown w/ Gray Streaks VFT	12	SF	Room 103 Rear Office - 1937 Bldg		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Material Description

37-16	9"x9" Brown w/ Gray Streaks VFT Mastic	12	SF	Room 103 Rear Office - 1937 Bldg	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Fall:	Abated									
Comments:	n/a									
2017 - Sprii	ng: No Change									
Comments:										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37-17	9"x9" Green w/ White Streaks VFT	491	SF	Room 100A, 100, Room 102 , Room 102 Vault - 1937		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	ment Category
37-18	9"x9" Green w/ White Streaks VFT Mastic	400	SF	Room 100A, 100, 102, Room 102 Vault - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments:												
2017 - Fall: No Change												

Comments:n/a 2017 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-19	9"x9" Gray w/ White Streaks VFT	400	SF	Room 102, 100A, 100 - 1937		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change
omments:
017 - Fall: No Change
omments:n/a
017 - Spring: No Change
omments:

37-20	9"x9" Gray w/ White Streaks VFT Mastic	400	SF	Room 102, 100A, 100 - 1937		Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change]						
Comments	:				1						
2017 - Spri	ng: No Change				-						
Comments	:				-						
2017 - Fall	: No Change										
Comments	:n/a										

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-21	2'x2' Off White Ceiling Tile	4500	SF	Room 308, 301, 111, 312, 106 Throughout - 1937		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-22	Paperwrap Pipe Insulation	1678	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E 232 Office Principals Office; Crawlspaces - 1937		TSI	Yes	Dist	100		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-23	MJP E/F/V on Paperwrap Pipe Insulation	390	LF	Boy's & Girl's Toilets Pipe Chases, Swimming Pool, Tunnels, & N, W, & E Crawlspaces - 1937		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: Abated	
Comments:removed 2012	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-24	MJP E/F/V on Fiberglass Pipe Insulation	300	SF	106, Pool, Tunnels, Crawlspaces, Rifle Storage, Engine Room, Plenum C - 1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-25	Mag Block Pipe Insulation	2845	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Eng Rm, & Plenum - 1937		TSI	Yes	Dist	375		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-26	MJP E/F/V on Mag Block Pipe Insulation	164	LF	Swimming Pool, NS Air Tunnel, NE Crawlspace, Rifle Range & Storage, GMV, Eng Rm, & Plenum - 1937		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
9
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-27	Air Cell Duct Insulation	6450	SF	West & NW Crawl Spaces, Rifle Range & Storage - 1937		TSI	Yes	Dist	100		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:

		Quantity	Units		Type	Category		Type	Quantity	Units		
37-28	Aircell Pipe Insulation	3077	LF	Basement Corridor, Throughout - 1937 Bldg (See Hatching Maps)		TSI	Yes	Dist	10		YES	X NO
2016 - Fall: N Comments:	o Change	-	-			•				,		

Material

Friable

Damage

Damage

Damage

Change in Assessment Category

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a

Material

Material Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
37-29	MJP E/F/V on Aircell Pipe Insulation	465	LF	Throughout - 1937 (See Hatching Maps)		TSI	Yes	Dist	5		YES X NO	

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
37-30	Hard Coat Plaster	120000	SF	Throughout - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Fall: No	o Change											
Comments:n/a												
2017 - Spring:	· No Change											
Comments:	. 140 Onlange											
LIA No.	Material Description	Matarial	Matarial	Material Leasting	Ashastas	Matarial	Frields	Damasa	D	Damana	Change in Asses	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
37-31	Exterior Window Caulk	30000	SF	Throughout - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No	o Change											
Comments:												
2017 - Fall: No	n Change											
Comments:n/a												
2017 - Spring: Comments:	: No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37-37	Exterior Window Caulk	30000	SF	Throughout - 1937		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments:					4							
2017 - Fall:	No Change											
Comments:												
0047 Cm iii	an Na Ohana											
Comments:	ng: No Change				4							
Comments.	·				-							
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37-38	Terrazo	2000	SF	Stairwells - 1937 bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
	ng: No Change				_							
Comments:					4							
2017 - Fall:	No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Co	ategory
37-39	Carpet Mastic	4000	SF	1937 - Bldg., Library and Main Office, 207A, 103, 100 Corridor		Miscellaneous	No	None	0		YES X N	0
2016 - Fall: N	lo Change											

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-40	12 x 12 Mixed Gray Speckled VFT	1200	SF	114K, 134B, 134C Bldg 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

37-41	12 x 12 Mixed Gray Speckled Mastic	1200	SF	114 K, 134 B, 134 C Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Sprir	ng: No Change				1							
Comments:												
2017 - Fall:	No Change				-							
Comments:	<u> </u>											
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
37-42	Beige Linoleum & Mastic	700	SF	Rm 304 Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change	•	•		1	-						
Comments:	<u> </u>]							
2017 - Fall: No Change												
	Comments:n/a											
2017 - Spring: No Change												
<u> </u>	<u> </u>				-1							

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

HA No

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

37-43	Beige Linoleum & Mastic	700	SF	Rm 304 Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change	·	·									
Comments	s:											
2017 - Fal	I: No Change											
Comments	s:n/a											
2017 - Spr	ring: No Change											
Comments	S:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material Location

TIA	INO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sherit Category	
37-	-44	14 x 14 Gray w/ Black Spots VFT	500	SF	Auditorium Lobby Bldg 1937		Miscellaneous	No	None	0		YES	X NO	
	6 - Fall: No nments:	o Change												

2017 - Fall: Abated Comments:n/a 2017 - Spring: No Change

Material

Quantity

Material

Units

HA No

Material Description

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37-45	14 x 14 Gray w/ Black Spots Mastic	500	SF	Auditorium Lobby Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: A	Abated				_							
Comments:n	/a											
2017 - Spring	g: No Change				_							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
37-46	2 x 2 Ceiling Tile	1000	SF	Rm 308, 301 Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	No Change		1									
Comments:n												
2017 - Spring	g: No Change				1							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37-47	14 x 14 Blue Speckled VFT	700	SF	Auditorium Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Fall:												
	ig: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
37-48	14 x 14 Blue Specked Mastic	700	SF	Auditorium Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
	g: No Change											
Comments:					\dashv							
2017 - Fall:	Abated											
Comments:r	n/a											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-49	12 x 12 Mixed Beige Speckled VFT	1575	SF	Rm 308, 206, 110, 108 Bldg 1937		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37-50	12 x 12 Mix Beige Speckled Mastic	1575	SF	Rm 208, 206, 110, 108 Bldg 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

38	12 x 12 Off White with Tan Streaks VFT	1000	SF	162A and B, Councellor's Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: A	Abated									
Comments:n	/a									
2017 - Spring	g: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
39	12 x 12 Off White with Tan Streaks Mastic	1000	SF	162A and B, Councellor's Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

40	Linoleum	6300	SF	172 (PKA 152), 252, 257, 250, 251, 253, and Library		Miscellaneous	No	None	0		YES	X NO
		•	•		1	•	•	•	•	•	•	
2016 - Fall: N	No Change											
Comments:												
Commonic												
2017 - Fall: N	No Change											
Comments:n	/a											
2017 - Sprin	g: No Change											
Comments:												
L												

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	Linoleum Adhesive	6300	SF	172 (PKA 152), 252, 257, 250, 251, 253 and Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
42	Tan Linoleum	700	SF	Room 121, Room 262 & 265		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:n	Ŭ											
2017 - Spring	g: No Change											
Comments:	g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
43	Tan Linoleum Adhesive	700	SF	Room 121; Room 262 & 265		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:												
2017 - Fall: N	lo Change											
Comments:n					_							
	g: No Change											
Comments:					4							

44	2' x 4' Lay In Ceiling Panels	700	SF	Room 121; 110, 109, 108	Miscellaneous	Yes	None	0	YES	X NO
	ıll: No Change									
Commen	ts:									
	III: No Change									
Commen	ts:n/a									
	oring: No Change									
Commen	ts:									

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Insulation in Walls and Vault Door	91	SF	Room 102		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
46	2' x 4' Lay In Ceiling Panels	500	SF	Room 153		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:n/												
0047 Conin	No Observe											
2017 - Spring Comments:	j: No Change				_							
Comments.												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	Linoleum	305	SF	1899 - Science Copy Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	io onango											
2017 - Fall: N												
Comments:n/	a											
2017 - Spring	ı: No Change											
Comments:	, 9-											

48	Linoleum Adhesive	305	SF	1899 - Science Copy Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change]							
Comments												
2017 - Fall	: No Change				1							
Comments	<u> </u>]							
2017 - Spr	ing: No Change				1							
Comments	S:]							
					_							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage Quantity

Quantity

0

Damage

Units

Units

YES

Change in Assessment Category

X NO

OBSERVED)		
2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:n/a		
2017 - Spring: No Change		
Comments:		

Quantity

126

Material

Quantity

Material

Units

Units

Room 102

SF

Material Location

HA No

49

Material Description

12 x 12 Green with White

Floor Tile (NOT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
50	12 x 12 Green with White Floor Tile Adhesive (NOT OBSERVED)	126	SF	Room 102		Miscellaneous	No	None	0		YES X NO
2016 - Fall:	No Change]						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
51	12 x 12 Gray with White Floor Tile (NOT OBSERVED)	126	SF	Room 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

52	12 x 12 Gray with White Floor Tile Mastic (NOT OBSERVED)	126	SF	Room 102 (Not Observed)		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	all: No Change	•	•	•]	•		•	•	•	•	
Commen					1							
2017 - Fa	all: No Change				_							
Commen	ts:n/a											
2017 - Sp	oring: No Change											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
53	12 x 12 Gray with Gray Floor Tile	20	SF	Room 102		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

53A	12 x 12 Gray with Gray Floor Tile Mastic	20	SF	Room 102		Miscellaneous	No	None	0		YES		X NO
2016 - Fal	II: No Change												
Comment													
2017 - Sp	ring: No Change												
Comment													
2017 - Fal	II: No Change												
Comment	·												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessi	ment Category
54	12 x 12 Ceiling Tile	750	SF	Room 111		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fal	II: No Change	1	1			-1	•	1	•	•			
Comment	<u> </u>												
2017 - Fal	II: No Change												
Comment													
					1								

Type

Material

Category

HA No

Material Description

2017 - Spring: No Change

Comments:

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
55	12 x 12 Light Blue with White and Brown Streaks Floor Tile	750	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
56	12 x 12 Light Blue with White and Brown Streaks Mastic	750	SF	Room 111		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: Abated	
Comments:removed 2012	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
61-01	12"x12" White w/ Grey Speckles VFT			1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change				_							
Comments:												
2017 - Fall: N	o Change											
Comments:n/												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
61-02	12"x12" White w/ Gray Speckles VFT Mastic			1st Floor West Corridor By Lobby - 1961		Miscellaneous		None			YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:n/s	· ·											

61-03	12"x12" Black w/ White Speckles VFT	1200	SF	1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None	0	YES	X NO
004C Falls	Na Ohanan				1						
2016 - Fall:	No Change										
Comments:											
Commonto.											
2017 - Sprir	g: No Change										
Comments:											
Comments.											
2017 - Fall:	No Change										
_0	. 10 011011190										

Type

Material

Category

Damage

Type

Friable

Damage Quantity Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-04	12"x12" Black w/ White Speckles VFT Mastic	1200	SF	1st Floor West Corridor By Lobby - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-05	12"x12" Black w/ White Streaks VFT-NOT OBSERVED	620	SF	Audiorium - 1937 (Not observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: Abated
Comments:removed 2012
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-06	12"x12" Black w/ White Streaks VFT Mastic NOT OBSERVED	620	SF	Audiorium - 1937 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: Abated	
Comments:removed 2012	

61-07	12"x12" Coffee w/ White & Brown Streaks VFT	3200	SF	Room 108, Room 257 & North Corridor - 1961	Miscellaneous	No	None	0	YES	X NO
2016 - Fall:										
Comments:										
2017 - Fall:	No Change									
Comments:	n/a									
	ng: No Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-08	12"x12" Coffee w/ White & Brown Streaks VFT Mastic	3200	SF	Room 108 & North Corridor - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
61-09	12"x12" Red VFT	6700	SF	Lunchroom - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
00111110111011	170											
			•	_			•	1	1	_	T	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
61-10	12"x12" Red VFT Mastic	6700	SF	Lunchroom - 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	•											
2017 - Sprin	ng: No Change											
Comments:	ig. No Change											
2017 - Fall:												
Comments:	n/a											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-11	9"x9" Black w/ White Streaks VFT-NOT OBSERVED	434	SF	West Stairwell & Auditorium Stairwell - 1937 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: Abated
Comments:removed 2012

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-12	9"x9" Brown w/ White Streaks VFT NOT OBSERVED	360	SF	Auditorium Balcony - 1937 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: Abated	
Comments:removed 2012	

61-13	9"x9" Brown w/ White Streaks VFT Mastic NOT OBSERVED	360	SF	Auditorium Balcony - 1937 (Not Observed)		Miscellaneous	No	None	0	YES	X NO
	•			•	•	•	•	•	•		
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: A	bated										
Comments:n/	'a]						
2017 - Spring	: Abated]									
Comments:re											
					1						

Type

Material

Category

Friable

Damage

Туре

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-14	9"x9" Gray w/ White Streaks VFT Not Observed in Rooms 109 & 110	2561	SF	Teacher's Lunchroom; Not Observed in Rooms 109 & 110 - 1937		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage

Quantity

Damage

Units

Change in Assessment Category

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Friable	Type	Quantity	Units	Change in Assessment Catego	ry
61-15	9"x9" Gray w/ White Streaks VFT Mastic	2561	SF	Teacher's Lunchroom; Not Observed in Rooms 109 & 110 - 1937		Miscellaneous	No	None	0		YES X NO	
0040 5-11 1		•	•	•	1	•	•	•	•	•	•	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-16	Black w/ White Streaks Linoleum NOT OBSERVED			East and West Stairwells, Auditorium Stairwell - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: Abated	
Comments:removed 2012	
2017 - Fall: No Change	
Comments:n/a	

61-17	Black w/ White Streaks Linoleum Mastic NOT OBSERVED	East and West Stain Auditorium Stairwell 1961	Miscellaneous	No	None	0	YES	X NO
2016 - Fall	: No Change	 •						
Comments								
Commonto	,							
2017 - Fall	: No Change							
Comments	s:n/a							
2017 - Spr	ing: Abated							
Comments	s:removed 2012							

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-18	2'x2' White Speckled w/ Inch Wormy Ceiling Tile	10000	SF	2nd Floor West Corridor - 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-19	1'x1' White Ceiling Tile	7000	SF	2nd FI NW & SW Stairwells, Auditorium, Room 108, 109 & 110 - 1961		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: No Change Comments:]						

2017 - Fall: Abated
Comments:n/a

2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-20	1'x1' Off White w/ Speckles Ceiling Tile	6700	SF	Lunchroom - 1961		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

61-21	1'x1' Off White w/ Large Wormy Ceiling Tile	6700	SF	Teachers Lunchroom by Kitchen - 1961		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: No Change											
Comments:											
2017 - Fall: N	o Change										
Comments:n/	a										
2017 - Spring	: No Change										
Comments:											
					J						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-22	Air Cell Pipe Insulation	935	LF	NW & NE Crawlspaces & Paint Storage - 1961		TSI	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

61-23	MJP E/F/V on Air Cell Pipe Insulation	48	LF	NW & NE Crawlspaces & Paint Storage - 1961		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:					1							
2017 - Fall:	No Change				-							
Comments:	n/a				_							
2017 - Sprir	ng: No Change				1							
Comments:												
					1							
HA No	Material Description	Material	Material	Material Location	Achaetae	Material	Friable	Damage	Damage	Damage	Change in Access	ment Category

Type

Material

Category

ŀ	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
6	61-24	Mag Block Pipe Insulation	2500	LF	NE Crawlspace - 1961		TSI	Yes	Dist	50		YES	X NO
2	2016 - Fall: No	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

61-25	MJP E/F/V on Mag Block Pipe Insulation	100	LF	NE Crawlspace - 1961		TSI	Yes	Dist	20	YES	X NO
2016 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2017 - Fall: No Change											

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-26	Paperwrap Pipe Insulation	350	LF	NE Crawlspace - 1961		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

61-27	MJP E/F/V on Paperwrap Pipe Insulation	37	LF	NE Crawlspace - 1961	TSI	Yes	None	0	YES	X NO
2016 - Fall: N	No Change									
2017 - Spring Comments:	g: No Change									
2017 - Fall: N										

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-28	Aircell Duct Insulation	100	SF	Paint Storage Room - 1961		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

61-29	9"x9" Black w/ White Streaks VFT Mastic	434	SF	West Stairwell & Auditorium Stairwell - 1961		Miscellaneous	No	None	0	YES	X NO
0040	Na Obasasa	7									
2016 - Fall:	No Change										
Comments:											
2017 - Sprin	ng: No Change										
Comments:											
2017 - Fall: No Change											

Asbestos Type Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-30	Carpet Mastic	1000	SF	1961 FA - Engineer's Office and CPS area office, 182		Miscellaneous	No	None	0		YES X NO

2010 5 11 11 21	
2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

61-31	2' x 2' Dot Wave Ceiling Tile (NOT OBSERVED)	500	SF	1961 - FA - Room 153		Miscellaneous					YES	X NO
2016 - Fall: N	No Change]							
Comments:	J											
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: No Change												
Comments:n	/a											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
61-32	Lab Counter Tops	200	SF	Rm 252, 251 Bldg 1961		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:	J											
2017 - Spring: No Change												
Comments:												
2017 - Fall: N	2017 - Fall: No Change											

Type

Material

Category

HA No

Comments:n/a

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

61-33	9 x 9 VFT Gray w/ white streaks	40	SF	Rm 258A Bldg 1961		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						
	g: No Change										
2017 - Fall: No Change Comments:n/a											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

40

Material

Quantity

Material

Units

SF

Material Location

Rm 258A Bldg 1961

HA No

61-34

Material Description

9 x 9 Mastic Gray w/ white

streaks

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

61-35	12 x 12 Gray Speckled VFT	500	SF	Rm 163C Bldg 1961	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: I	No Change									
Comments:	-									
2017 - Sprin	g: No Change									
Comments:										
2017 - Fall: /	Abated									
Comments:r	n/a									

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-36	12 x 12 Gray Speckled Mastic VFT	500	SF	Rm 163C Bldg 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

61-37	12 x 12 Mixed Beige Speckled VFT	1000	SF	Rm 180 and 180 A Bldg 1961		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:]						
2017 - Sprir	ng: No Change										
Comments:											
2017 - Fall:	Abated				-						

Asbestos Type Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-38	12 x 12 Mixed Beige Mastic	1000	SF	Rm 180 and 180A Bldg 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

61-39	12 x 12 Brown Speckled VFT	500	SF	Rms 170 and 172 Bldg 1961	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N										
Comments:n	/a									
2017 - Spring	n: No Change									

Category

Friable

Damage

Type

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
61-40	12 x 12 Brown Speckled Mastic	500	SF	Rms 170 and 172 Bldg 1961		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

61-41	white Specs VFT	600	SF	Rms 154 Bldg 1961		Miscellaneous	No	None	0		YES	X NO
0040 F-II	N. Observe				7							
2016 - Fall	: No Change											
Comments	:											
2017 - Fall	Abated				_							
Comments	:n/a											
2017 - Spri	ng: No Change											
Comments	•											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	

600

Material

Quantity

Material

Units

SF

Material Location

Rm 154 Bldg 1961

HA No

61-42

Material Description

12 x 12 Blue w/ Black and

white Specs Mastic

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-01	12"x12" Gray w/ White Specks VFT	12635	SF	1st, 2nd, & 3rd Floor Corridors, 2nd Fl Womens Toilet, Rooms 229, 125, & 113A (Not Observed)- 1899		Miscellaneous	No	None	0		YES X NO
2016 Fall: N	la Changa				1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-02	12"x12" Gray w/ White Specks VFT Mastic	12635	SF	1st, 2nd, & 3rd Floor Corridors, 2nd Fl Womens Toilet, Rooms 229, 125, & 113A(Not Observed) - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

99-03	12"x12" White w/ Gray Specks VFT	780	SF	Room 215 - 1899		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Spring	2017 - Spring: No Change										
Comments:											
2017 - Fall: N	lo Change										
Comments:n/	Comments:n/a										

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-04	12"x12" White w/ Gray Specks VFT Mastic	780	SF	Room 215 - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

99-05	12"x12" Beige w/ Brown Specks VFT	5200	SF	Rooms 223, 217, 219, 217A, 224, & storage 217B & C - 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change	•						•	•	•	,	
Comments:												
2017 - Fall: N	lo Change]							
Comments:n	/a											
2017 - Spring	g: No Change											

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessi	ment Category
99-06	12"x12" Beige w/ Brown Specks VFT Mastic	5200	SF	Rooms 223, 217, 219, 217A, 224, & 224 Storage (Not Observed) 217B & C - 1899		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

99-07	12"x12" Light Brown w/ Brown & White Specks VFT	2465	SF	Rooms 113A (NOT OBSERVED), 14 & 122 - 1899	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	No Change	•		•						
2017 - Spring Comments:	g: No Change									
2017 - Fall: N	3									

Category

Asbestos

Type

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-08	12"x12" Lt Brn w/ Brown & White Specks VFT Mastic	2465	SF	Rooms 113A & 122(NOT OBSERVED), 14 - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

99-09	12"x12" Brown w/ White Streaks VFT	800	SF	Room 112 (NOT OBSERVED), 14 - 1899	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:										
2017 - Fall: N										
Comments:n	<u>/a </u>									
	g: No Change									
Comments:										

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-10	12"x12" Brown w/ White Streaks VFT Mastic	800	SF	Room 112, 14 - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

99-11	12"x12" Off White w/ Light Brown Streaks VFT	2555	SF	Room 14 Foyer, 29, 23 - 1899	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Fall: N Comments:n/										
2017 - Spring Comments:	: No Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-12	12"x12" Off White w/ Light Brn Streaks VFT Mastic	2555	SF	Room 14 Foyer, 29, 23 (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

Material

Quantity

Material

Units

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-13	9"x9" Tan w/ Brown & White Streaks VFT	11670	SF	Throughout - 1899 (See Hatching Maps) 119, 114 A & B & C, D,E, F, G, 022, 032, 036, Counselors Corridor		Miscellaneous	No	None	0		YES X NO

0040 5 11 11 01
2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-14	9"x9" Tan w/ Brown & White Streaks VFT Mastic	11670	SF	Throughout - 1899 (See Hatching Maps)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

99-15	9"x9" Green w/ White Streaks VFT (NOT OBSERVED)	305	SF	Science Copy Room - 1899		Miscellaneous					YES	X NO
		•	•		·	•	•	•	•	•		
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: A	bated											
Comments:n/	'a											
2017 - Spring	: No Change	•										
Comments:												

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-16	9"x9" Green w/ White Streaks VFT Mastic (NOT OBSERVED)	305	SF	Science Copy Room - 1899		Miscellaneous		None	0		YES X NO

-	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

99-17	9"x9" Tan VFT	1930	SF	Room 14 (Under HA 99- 10) (Not Observed)- 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change]							
Comments												
2017 - Fall	I: No Change											
Comments	s:n/a											
2017 - Spr	ring: No Change											
Comments	S:											
					I							
LIA NI-	Material Description	N 4 - 4 - ul - 1	N 4 - 4 - ul - 1	Material Leasting	A = = = = 4 = =	NA-4	Estable:	D	D	D	Observation Assessed	

Type

Material

Category

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-18	9"x9" Tan VFT Mastic	1930	SF	Room 14 (Under HA 99- 10) (Not Observed)- 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-19	9"x9" Rust VFT	1930	SF	Room 14 (Under HA 99- 10 and 99-17) (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		YES X NO
204C Falls N	la Change	-	•	•	1	-					

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-20	9"x9" Rust VFT Mastic	1930	SF	Room 14 (Under HA 99- 10 and 99-17) (NOT OBSERVED) - 1899		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-21	2'x2' White w/ Wormy Grooves Ceiling Tile	1200	SF	Library, Work Room A & B, 221(NOT OBSERVED) - 1899		Miscellaneous	Yes	None	0		YES X NO
2016 - Fall: N	lo Change			•							

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-22	1'x1' White w/ Wormy Grooves Ceiling Tile	3200	SF	Room 217, 217 A & B, 221- 1899		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

99-23	2'x4' White w/ Wormy Grooves Ceiling Tile	1200	SF	Room 227 - 1899	Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Fall: N Comments:n/										
2017 - Spring Comments:	: No Change									

Type

Material

Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-24	2'x4' White w/ Pin Holes Ceiling Tile	400	SF	Engineers Office - 1899		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

99-25	Transite Table Tops (ABATED)			Rooms 23, 29, 124, 127, 129, 224, 229 - 1899 ABATED		Miscellaneous					YES	X NO
2016 - Fall: N	o Change	•	•	•]	•	•	•	•	•		
Comments:	o Change											
2017 - Fall: N	o Change											
Comments:n/	'a											
2017 - Spring	: No Change											
Comments:												
			•									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-26	Paperwrap Pipe Insulation	708	LF	Throughout (See Hatching Maps) - 1899		TSI	Yes	Dist	80		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

99-27	MJP E/F/V on Paperwrap Pipe Insulation	77	LF	Throughout (See Hatching Maps) - 1899	TSI	Yes	Dist	5	YES	X NO
2016 - Fall:	No Change									
Comments:										
2017 - Spri	ng: No Change									
Comments:										
2017 Falls	No Change									
	No Change									
Comments:	n/a									

Category

Asbestos

Type

Damage Type

Friable

Damage Quantity Damage Units Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-28	Aircell Pipe Insulation	2940	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rms, Store Rm by 14 - 1899		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-29	MJP E/F/V on Aircell Pipe Insulation	587	LF	Rooms 127, 23, 27, 24, & Engineer's Office, Boiler Pump & Sprinkler Rms, Store Rm by 14 - 1899		TSI	Yes	Dist	10		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-30	MJP E/F/V on Fiberglass Pipe Insulation	680	SF	Boiler & Tank Rooms, Basement Corridor, 127, 129, 124, 122, 29, 24 Closet, Engineers Office - 1899		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

99-31	Mag Block Pipe Insulation	100	LF	Basement Corridor - 1899		TSI	Yes	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:											
2017 - Fall: A	bated										
Comments:n/a											
2017 - Spring	g: No Change										
Comments:											

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-32	MJP E/F/V on Mag Block Pipe Insulation	10	LF	Basement Corridor By Plenum Sliding Door - 1899		TSI	Yes	None	2		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-33	Water Tank Insulation	300	SF	Boiler Room - 1899		TSI	Yes	None	0		YES X NO
2016 - Fall: N	lo Change										
	g: No Change										
2017 - Fall: A											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-34	Hardcoat Plaster	100000	SF	Throughout - 1899		Surface	No	None	0		YES X NO
2016 - Fall: N Comments:	2016 - Fall: No Change Comments:										
2017 - Fall: No Change											
Comments:n/a 2017 - Spring: No Change											
Comments:	j. No Change	_									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
99-35	Exterior Window Caulk			Throughout - 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	Ţ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
99-36	Beige Linoleum	6400	SF	Room 121 (Science Room) - 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change											
Comments												
2017 - Spri	ng: No Change											
Comments												
2017 - Fall:	: No Change											
Comments	Ţ											
22												

HA No

Change in Assessment Category

		Quantity	Units		Type	Category		Туре	Quantity	Units	3		
99-37	Beige Linoleum Mastic	6400	SF	Room 121 (Science Room), 229A, 229, 127, 129, 124, 023, 027 - 1899		Miscellaneous	No	None	0		YES	X	0
2016 - Fall:	No Change	<u> </u>											·
Comments:	110 Orlango												
0047 Falls	No Observe												
2017 - Fall:	No Change												
Comments:	n/a												

Friable

Damage

Damage

Damage

Asbestos

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-38	Gray Linoleum NOT OBSERVED	700	SF	1899 Bldg., 121 (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Material

Material Location

Observed)

HA No

2017 - Spring: No Change

OBSERVED

Comments:

Material Description

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
99-38A	Gray Linoleum Mastic- NOT OBSERVED	700	SF	1899 Bldg., Room 121 (Not Observed)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:r	n/a											
2017 - Sprin	g: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
99-39	Terrazzo	3000	SF	Stairwells - 1899 Bldg.		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change						•		•			
Comments:	<u> </u>											
2017 - Fall: I	No Change				-							
Comments:r	<u> </u>											
2017 - Sprin	g: No Change											
Comments:	.g. : : : : : : : : : : : : : : : : : :											

99-40	Carpet Mastic	700	SF	1899 - Bldg. Room 112- Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	g: No Change				_							
Comments:	,											
2017 - Fall: A	bated											
Comments:n	/a											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
99-41	Black Lab Counter Tops	2200	SF	Rm 229, 224 Rm 121, 121C, 023, 027 Bldg 1899		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:					1							
2017 - Fall: N	2017 - Fall: No Change											
	Comments:n/a											
2017 - Spring	2017 - Spring: No Change											

Type

Material

Category

Friable

Damage

Type

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

99-42	Fume Hood	160	SF	Rms 224, 023, 027 Bldg 1899	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	o Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:n/										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-43	12 x 12 Yellow Speckled VFT	1400	SF	Rm 213A, Rm 221, 113A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

HA No

99-44	12 x 12 Yellow Speckled Mastic	1400	SF	Rm 213A Rm 221, 113 A Bldg 1899		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change										
Comments:	•										
2017 - Fall: A	bated										
Comments:n	/a										
2017 - Spring	g: No Change										
Comments:	-										
					l						

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-45	12 x 12 Mixed Beige VFT	2150	SF	Rm 125, 125 Foyer, Rm 122 Bldg 1899		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-46	12 x 12 Mixed Beige Speckled Mastic	2150	SF	Rm 125, 125 Foyer, Rm 122 Bldg 1899		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change]						
Comments:]						
2017 - Fall: N					-						
Comments:n/	'a										
2017 - Spring	: No Change										
Comments:											
]						
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-47	12 x 12 Mixed Gray Speckled VFT		SF	1st Fir Counselor's Corridor, 3rd Fir Elevator Lobby, Basement Elevator Lobby		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change				1						
Comments:	io onango				- -						

2017 - Spring: No Change

2017 - Fall: No Change

Comments:

Comments:n/a

		Quantity	Units		Туре	Category		Type	Quantity	Units		
99-48	12 x 12 Mixed Gray Speckled Mastic		SF	1st Flr Counselor's Corridor, 3rd Flr Elevator Lobby. Basement Elevator Lobby Bldg 1937		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:	<u> </u>											
2017 - Fall: I	No Change											

Material

Damage

Friable

Damage

Damage Change in Assessment Category

2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Material Material Location

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
99-49	Drywall System	400	SF	Rm 213A		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
FA-01	12"x12" Black w/ White Streaks VFT	8500	SF	1st & 2nd Floor Corridors - 1961FA		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change]							
Comments	S:				1							
2017 - Spr	ring: No Change											
Comments	s:good											
2017 - Fall	I: Abated				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-02	12"x12" Black w/ White Streaks VFT Mastic	8500	SF	1st & 2nd Floor Corridors - 1961FA		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-03	12"x12" White w/ Tan Streaks VFT	12800	SF	Band Rm, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - 1961FA, 163B, 257, 172, 176A, 176		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-04	12"x12" White w/ Tan Streaks VFT Mastic	12800	SF	Band Rm, ROTC, 153, 151, 155, 157, 159, 161, 163A, 253 - 1961FA		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-05	12"x12" Cream w/ Tan & White Streaks VFT NOT OBSRVED	6300	SF	Gym - 1961FA (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-06	12"x12" Cream w/ Tan & White Streaks VFT Mastic NOT OBSERVED	6300	SF	Gym - 1961FA- (Not Observed)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:good	

FA-07	12"x12' White w/ Gray Speckles VFT	1600	SF	Lunch Room, 164 - 1961FA	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: A	bated									
Comments:n/	/a									
2017 - Spring	g: No Change									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-08	12"x12' White w/ Gray Speckles VFT Mastic	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

Material

Quantity

Material

Units

Material Location

HA No

Comments:good

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FA-09	12"x12" Black w/ White Speckles VFT	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N Comments:	No Change											
2017 - Spring	g: No Change				-							

2017 - Spring: No Change
Comments:good
2017 - Fall: Abated
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-10	12"x12" Black w/ White Speckles VFT Mastic	1600	SF	Lunch Room, 164 - 1961FA		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:

FA-11	9"x9" Beige w/ White Spots VFT	9475	SF	Throughout - 1961FA (See Hatching Maps) 253B		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change]						
Comments:					-						
2017 - Sprin	g: No Change										
Comments:					 						
2017 - Fall:	No Change										

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-12	9"x9" Beige w/ White Spots VFT Mastic	9475	SF	Throughout - 1961FA (See Hatching Maps)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

FA-13	9"x9" Gray w/ Black Streaks VFT	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change]						
Comments:											
2017 - Spring	g: No Change										
Comments:											
2017 - Fall: A	Abated										
Comments:n	/a										

Type

Material

Category

Damage

Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-14	9"x9" Gray w/ Black Streaks VFT Mastic	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

FA-15	9"x9" Beige w/ Orange & White Spots VFT (NOT OBSERVED)	1900	SF	Rooms 252, Counselors Office, Library, 152- 1961FA		Miscellaneous				YES	X NO
	•	•	•		•	•	•	•	•		
2016 - Fall:	No Change										
Comments:											
2017 - Fall:	Abated										
Comments:	n/a										
2017 - Spri	ng: No Change										
Comments:	-										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

Rooms 252, Counselors

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-16	9"x9" Beige w/ Orange & White Spots VFT Mastic (NOT OBSERVED)	1900	SF	Rooms 252, Counselors Office, Library, 152 - 1961FA		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: Abated
Comments:n/a

Material

Quantity

Material

Units

HA No

Material Description

9"x9" Beige w/ Orange &

FA-17	9"x9" Green w/ Black & White Streaks VFT (NOT OBSERVED)	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change	•	-	•		•	•	•	•	•		
Comments:	· · ·											
2017 - Fall: A	2017 - Fall: Abated											
Comments:n/												
2017 - Spring	g: No Change											
Comments:	-											

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-18	9"x9" Green w/ Black & White Streaks VFT Mastic (NOT OBSERVED)	104	SF	Closet by Boiler Room - 1961FA		Miscellaneous					YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: Abated	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

FA-19	9"x9" Black VFT	350	SF	2nd Floor Slop Sink - 1961FA 156 & 158 Foyer		Miscellaneous	No	None	0		YES	X NO
0040 5 11 1		•	*	•	7	•	•	•	•	•	•	
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: A	Abated											
Comments:n	/a											
				·								
2017 - Spring	g: No Change	•										

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-20	9"x9" Black VFT Mastic	350	SF	2nd Floor Slop Sink - 1961FA		Miscellaneous	No	None	0		YES X NO

204C. Fall No Change
2016 - Fall: No Change
Comments:
2017 - Fall: Abated
Comments:n/a
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

		,			,,	0 ,		· ·	•				
FA-23	1'x1' Small Hole Ceiling Tile NOT OBSERVED	20000	SF	Throughout 1961FA		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change				٦								
Comments:	110 Orlango												
2017 Contin	a. No Change												
Comments:	ig: No Change				-								
2017 - Fall: A													
Comments:r	n/a												
					_								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessi	ment Category
FA-24	1'x1' Medium Hole Ceiling Tile	20000	SF	Throughout - 1961FA		Miscellaneous	Yes	None	0		YES		X NO
2016 - Fall:	No Change												
Comments:	- i c c i i i i i i i i i i i i i i i i												
0047 On sin	an Na Ohanan												
	017 - Spring: No Change												
Comments:	comments:												

Category

Asbestos

Type

HA No

2017 - Fall: Abated Comments:n/a

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage Quantity

Damage Units

Damage

Type

Friable

											·	
FA-25	2'x2' Ceiling Tile	1600	SF	Lunch Room - 1961FA		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Spring	ı: No Change				_							
Comments:	,											
2017 - Fall: A	bated				-							
Comments:n	/a											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
FA-26	Mag Block Pipe Insulation	5165	SF	Boiler Room, All Crawlspaces and Tunnels - 1961FA		TSI	Yes	Dist	500		YES	X NO
2016 - Fall: N	lo Change]							
Comments:					1							
2017 - Fall: No Change												
Comments:n/a												
2017 - Spring	2017 - Spring: No Change											
Comments:												

Category

Asbestos

Type

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity

Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-27	MJP E/F/V on Mag Block Pipe Insulation	285	LF	Boiler Room, All Crawlspaces and Tunnels - 1961FA		TSI	Yes	Dist	100		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-28	MJP E/V/F on Fiberglass Pipe Insulation	145	LF	Northwest Tunnel, Fan Room and Boiler Room - 1961 FA		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	
2017 - Spring: No Change	
Comments:	

	The state of the s										
FA-29	Paperwrap Pipe Insulation	1800	LF	Tunnels, Boiler Room, & Fan Room - 1961FA		TSI	Yes	Dist	400	YES	X NO
2016 - Fall: N	No Change										
2017 - Spring	g: No Change										
Comments:											
0047 5 11 1	1 01										
2017 - Fall: No Change											

Type

Material

Category

Damage

Type

Friable

Damage Quantity Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FA-30	MJP E/F/V on Paperwrap Pipe Insulation	150	LF	Tunnels, Boiler Room, & Fan Room - 1961FA		TSI	Yes	Dist	50		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:n/a	

Material

Quantity

Material

Units

Material Location

HA No

Comments:n/a

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FA-31	Exterior Window Caulk	300	LF	Throughout - 1961FA		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments: 2017 - Fall: Comments: 2017 - Sprir Comments:	No Change n/a ng: No Change											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
FT-001	9x9 Beige Floor Tile	800	SF	Engineer's Office and Maintenance Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments:good												
2017 - Fall: Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FTM-001	9x9 Beige Floor Tile Mastic	800	SF	Engineer's Office and Maintenance Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:n/a
2017 - Spring: No Change
Comments:good

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Lincoln Park High School
Date: 3/5/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.