## **Chicago Public Schools**

## 6 Month Asbestos Surveillance 2017 - Fall

47081

**Oracle Unit:** 

Address: 5039 N. Kimball Ave. Region: 01 Mail Room: Asbestos Surveyor: Dye, Ms. Venguanette X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 2/2/2018 Email Address: vdye@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Quantity Type YES 01 2'x4' Ceiling Tile X NO Throughout 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

Friedrich W von Steuben Metropolitan Science HS

School:

1610

**Building ID:** 

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
02	Hard Coat Plaster			Throughout							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change				_							
Comments:	,g											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		
04	Lab Table			Room 421, 419, 313, 316, 315							YES	X NO
2016 - Fall: N	lo Change											
Comments:	Ţ.											
2017 - Fall: N	lo Change											
Comments:	to Orlange											
	N. Ol											
	g: No Change				_							
Comments:					$\dashv$							

09	9"x9" White w/ Green Streaks VFT	4000	SF	Cafeteria, Cafeteria Managers Office, Cafeteria Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	J											
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
10	1'x1' Acoustical Walls	4320	SF	Cafeteria		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

HA No

2017 - Fall: No Change

2017 - Spring: No Change

Comments:

Comments:

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20A	2'x4' Suspended Horizontal Dot-Wave Ceiling Tile			Room 414, 416							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	j: No Change											
Comments:												
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20B	1'x1' Ceiling Tile			Room 414, 305, 416, 304 Library							YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
21	12"x12" Black VFT	2300	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	. No Onlange											
<u> </u>	T	T	T	T			T =		T		T =	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
30	Fiberglass Joint Compound			Pump Room, Boiler Room, LDB Room							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	Ü											
2017 - Spring	ı: No Change											
Comments:	. No Orlange											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
34	Mag Block Insulation	3100	LF	Boiler Room, Pump Room, Air Tunnel, Filter Room, Basement Corridors, attic space above ceilings for auditorium		TSI	Yes	Dist	25		YES	X NO
2016 - Fall:	No Change				7							
Comments:	•											
2017 - Fall:	No Change				-							
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
35	MJP E/F/V on Mag Block Pipe Insulation	550	LF	Boiler Room, Pump Room, Air Tunnel, Filter Room, Basement Corridors		TSI	Yes	Dist	5		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change				+							
Comments:	<u> </u>											
2017 - Sprin	ng: No Change				-							

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
36	Boiler Tank Insulation	2500	SF	Boiler Room & Pump Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asser	ssment Category
37	Aircell Pipe Insulation	3500	LF	Throughout (See Hatching Maps)		TSI	Yes	Dist	10		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	g: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
40	Duct Insulation	1600	SF	Dirt Floor Store Room , Fan room 4		TSI	Yes	Dist	50		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change				-							
Comments:	_											
2017 - Spring	: No Change				+							
Comments:	Ğ											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
47	12"x12" Black VFT Mastic	2300	SF	Auditorium		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>				1							
2017 - Fall: N	o Change				-							
Comments:												
2017 - Spring	: No Change											
Comments:					_							
					_							

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
50	Blue Linoleum (NOT OBSERVED)			Room 215, 313, 315, 419							YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:					-							
2017 - Spring	: No Change				-							
Comments:					-							
					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51	Blue Linoleum Mastic (NOT OBSERVED)			Room 215, 313, 315, 419							YES	X NO
2016 - Fall: N	o Change				]							
Comments:												
2017 - Fall: N	o Change											
Comments:					  -							
2017 - Spring	: No Change											
Comments:												
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
52	Exterior Window Caulk			Throughout							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	, · · · · · · · · · · · · · · · · · · ·											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
53	Exterior Window Glaze			Throughout	.,,,,,	- Canagary		1,7,10			YES	X NO
2016 - Fall: N	lo Change		1				•			•		
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 Spring	v: No Chango											
Comments:	g: No Change											
201111011101												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
54	Interior Window Glaze			Throughout							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	, reconsinge											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
55	Interior Window Caulk			Throughout		0 7		71			YES	X NO
2016 - Fall: N	lo Change		1				•			•		
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 Spring	y No Chango											
2017 - Spring Comments:	i. No Change											
331111101110.												

56	9"x9" White w/ Green Streaks VFT Mastic	4000	SF	Cafeteria, Cafeteria Managers Office, Cafeteria Storage		Miscellaneous	No	None	0	YES	X NO
2016 - F	all: No Change	·		<u> </u>	]						
Comme	nts:				1						
2017 - F	all: No Change				-						
Comme	nts:										
2017 - S	pring: No Change										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
57	12"x12" White w/ Gold Streaks VFT	25700	SF	3rd Floor. South Corridor, 4th Floor Corridor, 2nd Floor Corridors		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

58	12"x12" White w/ Gold Streaks VFT Mastic	25700	SF	Office 223B, 108A (Security Office), Rm 306, 114 Storage, 1st Floor Corridor		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: 1 Comments:	No Change										
2017 - Fall: N	2017 - Fall: No Change Comments:										
2017 - Spring Comments:	g: No Change										

Asbestos Type Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Friable

Damage

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
59	12"x12" Gray VFT	300	SF	Room 421, Vault & Work Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

60	12"x12" Gray VFT Mastic	300	SF	Room 421, Vault & Work Room		Miscellaneous	No	None	0		YES	X NO
0040 5 11	N 01				1							
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

1250

Material

Quantity

Material

Units

SF

Material Location

Rooms 414 (Under HA 115 & 115A), 314

HA No

61

Material Description

9"x9" Tan w/ Beige Streaks

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
62	9"x9" Tan w/ Beige Streaks VFT Mastic	1250	SF	Rooms 414 (under HA 115 & 115A), 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	<u> </u>				]							
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	ı: No Change				-							
Comments:	i i i i o o i a i go		-									
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	•	Quantity	Units		Type	Category		Туре	Quantity	Units	· ·	
63	9"x 9" Brown VFT	1250	SF	Rooms 414 (Under HA 115 & 115A), 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:												
2017 - Fall: N	lo Change				-							
2017 - Fall: No Change Comments:					-							
	N. O.		=									
Comments:	2017 - Spring: No Change											
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
64	9"x 9" Brown VFT Mastic	1250	SF	Rooms 414 (Under HA 115 & 115A), 314		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:												
	No Change											
	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
65	12"x12" Taupe w/ White Streaks VFT	400	SF	Room 409 (teacher's work room)		Miscellaneous	No	None	0		YES	X NO
	No Change											
Comments:												
2017 - Fall:												
Comments:	Comments:											
2017 - Sprin	na: No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
66	12"x12" Taupe w/ White Streaks VFT Mastic	400	SF	Room 409 (teacher's work room)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Fall: N	o Change				_							
Comments:	<u> </u>											
2017 - Spring	: No Change				1							
Comments:	J											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessment Category
67	9"x9" Green w/ White Streaks VFT	4000	SF	Cafeteria Managers Office, Cafeteria Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				1							
Comments:	_											
2017 - Fall: No Change					1							
Comments:												
2017 - Spring	2017 - Spring: No Change											

Comments:

68	9"x9" Green w/ White Streaks VFT Mastic	4000	SF	Cafeteria, Cafeteria Managers Office, Cafeteria Storage		Miscellaneous	No	None	0		YES	X NO
	·	*	•	•	_	•	•	*	•	•	•	
2016 - Fal	II: No Change											
Comment	s:											
2017 - Fal	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change											
Comment	s:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

2016 - Fall: No Change	
Comments:	
Comments.	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

600

Material

Quantity

Material

Units

SF

Material Location

Cafeteria, Cafeteria

Room 219

HA No

69

Material Description

12"x12" Sand VFT

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
70	12'x12" Sand VFT Mastic	600	SF	Room 219		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I Comments:	No Change											
2017 - Fall: I Comments:	No Change											
	g: No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
71	12"x12" White w/ Tan Spots VFT	1800	SF	Room 126, 219		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I Comments:	No Change											
2017 - Spring: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
72	12"x12" White w/ Tan Spots VFT Mastic	1800	SF	Rooms 126, 219		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				_							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
73	12"x12" White w/ Beige Streaks VFT	2100	SF	Room 212, 217		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:												
2017 - Fall: N	o Change											
Comments:	o Change											
2017 - Spring	: No Change											
Comments:	i. No Change				-							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
74	12"x12" White w/ Beige Streaks VFT Mastic	2100	SF	Room 212, 217		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change							•	•			
Comments:												
2017 - Fall: N	No Change											
Comments:	Ü											
2017 - Spring	g: No Change											
Comments:	g. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	material 2 coonplicit	Quantity	Units	material Essation	Туре	Category		Туре	Quantity	Units	onange mirites	coment category
75	12"x12" Flesh VFT (NOT OBSERVED)	100	SF	Room 216		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	10 Onango											
2047 Corio	a. Na Changa											
	g: No Change				_							
Comments:												

76	12"x12" Flesh VFT Mastic (NOT OBSERVED)	100	SF	Room 216	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Spring	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
77	12"x12" White w/ Black Streaks VFT	3200	SF	Room 213, 213A, 209, 211, 214		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
78	9"x9" Beige w/ Brown Streaks VFT	600	SF	Engineer's Office Corridor(Not Observed) 2nd and 3rd Floor Women's/Teacher's Toilet (208B & 308B)		Miscellaneous	No	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
79	12"x12" Taupe VFT	600	SF	Engineers Office, Office Next to Copy Room		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
80	12"x12" Taupe VFT Mastic	600	SF	Engineers Office, Office Next to Copy Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	r: No Chango											
Comments:	J. NO Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
81	12"x12" Brown/Gray VFT	600	SF	Room 122 (under HA 115 & 115A), 206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	•											
2017 - Spring	ı: No Change				<u> </u>							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	to oriange				-							
					4							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
82	12"x12" Brown/Gray VFT Mastic	600	SF	Room 122 (under HA 115 & 115A), 206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	g											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
83	12"x12" Cream VFT	600	SF	Room 122 (under HA 115 & 115A), 206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				]							
Comments:												
2017 - Spring	g: No Change											
Comments:	g. 140 Onlango											
2017 - Fall: N	No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
84	12"x12" Cream VFT Mastic	600	SF	Room 122 (under HA 115 & 115A), 206		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	-											
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
85	12"x12" Off White VFT	400	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
					J							

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
86	12"x12" Off White VFT Mastic	400	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	-											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
87	12"x12" Light Purple VFT	400	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change				7							
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
88	12"x12" Light Purple VFT Mastic	400	SF	Room 106		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	•											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in As	sessment Category
89	9"x9" Black VFT	200	SF	Basement Break Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Spring	ı: No Change											
Comments:	,											
2017 - Fall: N	lo Change											
Comments:	.c c.iango											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
90	9"x9" Black VFT Mastic	200	SF	Basement Break Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	_											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
91	9"x9" Yellow w/ Orange VFT	200	SF	Basement Break Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	,go											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
92	9"x9" Yellow w/ Orange VFT Mastic	200	SF	Basement Break Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments.												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	y											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	ssment Category
TIA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asse	ssillerit Category
93	Brown Linoleum			Room 413							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 Spring	g: No Change											
Comments:	g. No Change											
2017 - Fall: N	lo Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
94	Brown Linoleum Mastic			Room 413							YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:	_											
2017 - Fall: N	lo Change											
Comments:	io onango											
LIA NI-	Material December	Mara da da l	I Markania I	Material Landon	Ashastas	NA-1-2-1	Estatu.				01	
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
95	White Linoleum			Room 413							YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u>-</u>											
2017 - Fall: N	lo Change											
Comments:	io onango											
2017 Caring	No Change											
2017 - Spring Comments:	: No Change				_							
Comments.												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
96	White Linoleum Mastic			Room 413							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	•											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	sment Category
	·	Quantity	Units		Type	Category		Туре	Quantity	Units		
99	12"x12" White w/ Black Streaks VFT Mastic	3200	SF	Room 213, 213A, 209, 211, 214		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	· No Change											
Comments:	. 140 Ondrige											
2017 Fall: N	o Chango											
2017 - Fall: N Comments:	o Change				-							
231111101110.	comments:											

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
100	9"x9" Beige w/ Brown Streaks VFT Mastic	600	SF	Engineer's Office Corridor(not observed), 2nd and 3rd Floor Women's/Teacher's Toilet(208B & 308B)		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
9
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
101	MJP E/F/V on Aircell Pipe Insulation	650	LF	Throughout (See Hatching Maps)		TSI	Yes	Dist	5		YES X NO

2016 - Fall: No Change Comments:  2017 - Fall: No Change Comments:  2017 - Spring: No Change Comments:	
2017 - Fall: No Change Comments: 2017 - Spring: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change	Comments:
Comments: 2017 - Spring: No Change	
2017 - Spring: No Change	2017 - Fall: No Change
· · · ·	Comments:
· · · ·	
Comments:	2017 - Spring: No Change
	Comments:

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
102	MJP E/F/V on Cardboard Pipe Insulation (Paperwrap)	100	LF	Throughout (See Hatching Maps)		TSI	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	J											
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
103	Texture Plaster			Auditorium Storage							YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

104	12" x 12" Gray w/ White & Dark Gray Speckles VFT	2500	SF	Rooms 409, 419A & 421		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: Comments:	No Change											
2017 - Sprir Comments:	ng: No Change											
2017 - Fall: Comments:	No Change											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Damage	Change in Assessmo	ont Cotogony
TIA INO	iviaterial Description	Quantity	Units	Material Location	Type	Category	FIIable	Damage Type	Damage Quantity	Units	Change in Assessme	eni Calegory

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

2500

SF

Material

Quantity

Material

Units

Material Location

Rooms 409, 419A, 421

HA No

105

Material Description

12"x12" Gray w/ Wht & Drk Gray Speckles VFT Mastic

YES

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	ssessme	ent Category
106	2' x 4' Smooth White Ceiling Tile			1st, 2nd, 3rd, & 4th Fl Boys & Girls Toilets, 3rd Fl Men's Restroom, 1st Fl Girls Locker Rm							YES		X NO
2016 - Fall	: No Change				1								
Comments:					]								
2017 - Spr	ing: No Change												
Comments					]								
2017 - Fall	: No Change				1								
Comments													
					J								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category		
107	Gray w/ Speckles Linoleum			Room 309, 309 Prep Room & Vault							YES	[	X NO
2016 - Fall	: No Change				1								
Comments													
2017 - Spr	ing: No Change				-								
Comments:													

2017 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
108	Gray w/ Speckles Linoleum Mastic			Room 309, 309 Prep Room & Vault							YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o chango											
		T	T		1	T	T =	T_		T_		
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
109	12"x12" White w/ Tan Specks VFT	3000	SF	3rd Floor Center and North Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change				-							
Comments:	J											
2017 - Fall: N	o Change											
Comments:	<u> </u>											

110	12"x12" White w/ Tan Specks VFT Mastic	3000	SF	3rd Floor Center and North Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	I: No Change											
Comments												
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											
Comments	S:											
L												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessr	nent Category

Type

Material

Category

Miscellaneous

No

Friable

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

1150

Material

Quantity

Material

Units

SF

Room 216

Material Location

HA No

111

Material Description

12"x12" White w/Gray Streaks VFT

112	12" x 12 " White w/ Gray Streaks VFT Mastic	1150	SF	Room 216	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
	g: No Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
113	12 x 12 inch White w/Black Streaks VFT	1950	SF	Rooms 118, 120, Library Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

113 A	12 x 12 inch White w/Black Streaks VFT Mastic	1950	SF	Rooms 118, 120, Library Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<b>.</b>											
0047 0 :	NI OI											
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o onango											
Commonto.												
					<u>.</u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	sessment Category
114	Green Terrazzo	5000	SF	Stairwells and Bordering Corridors, Bakery(307), Auditorium Vestibule		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Spring	: No Change											
Comments:												
0045 5 11 11												
2017 - Fall: N	o Change											
Comments:												

Category

Asbestos

Type

HA No

Material Description

Material

Quantity

Material

Units

Material Location

Damage Quantity

Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Type	Quantity	Units	Change in Asse	essment Category
115	12"x12" off white with tan specks VFT	2800	SF	Rooms 414, 416, 122, 2nd Floor Hall by Freight Elevator& Data Offices, 1st Floor Hall by Eng. Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				]							
Comments					1							
2017 - Fall:	: No Change											
Comments					1							
2017 - Spri	ing: No Change											
Comments	:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
115A	12"x12" off white with tan specks Mastic	2800	SF	Rooms 414, 416, 122, 2nd Floor Hall by Freight Elevator& Data Offices, 1st Floor Hall by Eng. Office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	: No Change				]							
Comments					1							
2017 - Spri	ing: No Change				-							
	<u> </u>				-1							

Comments:

Comments:

2017 - Fall: No Change

116	12"x12" light gray with gray & white specks VFT	1200	SF	Kitchen, serving line room, & dish wash room 3rd floor		Miscellaneous	No	None	0	YES	X NO
2016 - Fa	II: No Change				]						
Comment											
2017 - Fa	II: No Change										
Comment	s:										
2017 - Sp	oring: No Change										
Comment	is:										

Category

Asbestos

Type

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
116A	12"x12" light gray with gray & white specks Mastic	1200	SF	Kitchen, servimg line room & dishwash room 3rd floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Material Description

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

117		12"x12" gray with gray & white specks VFT	2000	SF	Kitchen, serving line room & dishwash room 3rd floor		Miscellaneous	No	None	0		YES	X NO
2016 -	· Fall: N	o Change	•	· 	•	]	•	•	•	•	•	•	
Comm													
2017 -	· Fall: N	o Change				_							
Comm		Ţ,											
2017 -	- Spring	: No Change				-							

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
117A	12"x12" Gray with gray & white specks Mastic	2000	SF	Kitchen, Serving line room, Dishwash room 3rd floor		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
118	12"x 12"Beige VFT	180	SF	Room 413 Work Room		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	•											
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
118A	12"x 12"Beige VFT Mastic	180	SF	Room 413 Workroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
119	Gray linoleum with white, blue & red streaks	4800	SF	Room 419 & Vault, 313 & Vaults, 313 office, 315 office & vault, 215 & office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	ı: No Change				-							
Comments:												
2017 - Fall: N	lo Change											
Comments:	o change											
					]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
119A	Gray Linoleum with white, blue & red streaks Mastic	4800	SF	Room 419 & Vault, 313 & Vaults, 313 office, 315 office & vault, 215 & office		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	o onango											
2017 - Fall: N	lo Chango											
Comments:	o change				-							
2017 - Spring	j: No Change											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
120	12"x 12"white with brown specks VFT	800	SF	Room 308, 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:	-											
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
120A	12"x 12"white with brown specks VFT Mastic	800	SF	Room 308, 208		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											

Comments:

121	12"x 12"Beige with white & brown streaks VFT	300	SF	2nd Floor Data offices and closets	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N Comments:	lo Change									
2017 - Spring Comments:	: No Change									
2017 - Fall: N Comments:	lo Change									

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
121A	12"x 12"Beige with white & brown streaks VFT Mastic	300	SF	2nd Floor Data offices and closets		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
122	Decorative Plaster	1900	SF	Auditorium and balcony		Surface	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Spring	g: No Change											
Comments:	-											
2017 - Fall: N	lo Change											
Comments:	Ü											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
123	12"x 12"Ceiling Tile	2000	SF	Auditorium and Balcony		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	, G											
2017 - Fall: N	lo Change											
Comments:												

HA No

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
123A	12" x 12"Ceiling Tile Mastic Pucks	2000	SF	Auditorium and Balcony		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<b>-</b>											
2017 - Spring	· No Change											
Comments:	. 140 Onango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Domogo	Domogo	Domogo	Change in Asses	ssment Category
TA NO	iviaterial Description	Quantity	Units	Material Location	Type	Category	Filable	Damage Type	Damage Quantity	Damage Units	Change in Asses	Sillent Category
124	12"x 12"Off White with tan & white streaks VFT	2000	SF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change			I	 ]	<u> </u>		<u> </u>				
2016 - Fall: N Comments:	o Change							l			<u> </u>	
Comments:		,				I			l		<u> </u>	
Comments: 2017 - Spring											<u> </u>	
Comments:  2017 - Spring Comments:	: No Change										<u> </u>	
Comments: 2017 - Spring	: No Change						l				<u> </u>	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
124A	12"x 12"Off White with tan & white streaks VFT Mastic	2000	SF	Library		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	<u> </u>											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
125	9"x 9"Sand Streaked VFT	140	SF	Library Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	o onango											

HA No

Change in Assessment Category

	T 4 4 4 1 1 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1			The state of the s				_		_	- · · ·	
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage Units	Change in Asse	ssment Category
		Quantity	Units		Туре	Category		Туре	Quantity	Units		
125A	9"x9" Sand Streaked VFT Mastic	140	SF	Library Storage		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change											
Comments:												
2017 - Fall:	No Change				_							
					+							
Comments:					_							
2017 - Sprir	ng: No Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
126	Tectum Ceiling Tiles	13800	SF	3rd Floor Small gym (323), Girls Gym (225), Boy's Gym (221)		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:	cgc											
2017 - Sprir	ng: No Change											
Comments:												
0047	No Oborono				4							
2017 - Fall:	No Change				4							
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
AA	Glue dot on acoustical walls HA# 10	4320	SF	Cafeteria		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	j: No Change											
Comments:												
					<u> </u>							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
ВВ	12"x 12" ceiling tiles			Music Rooms (303, 305)		Miscellaneous					YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												
2017 - Fall: No Change												
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
С	Cardboard Pipe Insulation	3600	LF	Throughout (See Hatching Maps)		TSI	Yes	Dist	10		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change				1							
Comments:	ge											
2017 0 :	N. O.											
2017 - Spring	g: No Change				_							
Comments:					4							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
СС	Glue dot assocate with HA # BB	2000	SF	Music rooms (303,305)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Fall: No Change					4							
Comments:					-							
Confinents.					-							
2017 - Spring: No Change												
Comments:												

s & all	Miscellaneous	No	None	0		YES	X NO
Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
tile in	Miscellaneous	Yes	None	0		YES	X NO
1							
	Туре	Type Category	Type Category	Type Category Type	Type Category Type Quantity	Type Category Type Quantity Units	Type Category Type Quantity Units

Category

Asbestos

Type

HA No

Comments:

Comments:

2017 - Fall: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Quantity

Damage

Units

Damage

Type

Friable

		Quantity	Units		Туре	Category		Туре	Quantity	Units	1	
EE	Glue dots assocate with HA # DD	1000	SF	Small Gym(323)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				1							
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	: No Change											
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FF	Lab Counter tops	2000	SF	405,407,409,413,415,421		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				]							
Comments:												
2017 - Spring	: No Change											
Comments:					1							
2017 - Fall: N	lo Change											
Comments:												
					J							

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
GG	Lab Fume hoods	800	SF	classrooms 407, 409, 413 (work room), 421		Miscellaneous	No	None	0		YES X NO

016 - Fall: No Change
Comments:
017 - Spring: No Change
Comments:
017 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

## NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Friedrich W von Steuben Metropolitan Science HS
Date: 2/2/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

SCHOOL'S ASBESTOS MANAGEMENT PLAN.