Chicago Public Schools

6 Month Asbestos Surveillance 2017 - Fall

Wells Community Academy High School 51071 1640 School: **Oracle Unit: Building ID:** Address: 936 N. Ashland Region: 02 Mail Room: 35 Asbestos Surveyor: Heneghan, James X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/20/2017 Email Address: A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Damage Change in Assessment Category Material Damage Quantity Units Type Category Type Quantity YES 01 12"x12" Tan VFT SF X NO 15000 Miscellaneous No None 0 Throughout 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
01A	12"x12" Tan VFT Mastic	15000	SF	Throughout (See Hatching Maps)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	to change											
		T	1	T	1	T	T =		T =	T =	1	-
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
02	12"x12" White w/ Orange VFT	600	SF	Room 305		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: No Change												
Comments:												
2017 - Spring	2017 - Spring: No Change											
Comments:												

02A	12"x12" White w/ Orange VFT Mastic	600	SF	Room 305		Miscellaneous	No	None	0		YES	X NO
					7							
2016 - Fall:	No Change											
Comments:												
2017 - Sprir	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:												
	·											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

600

Material

Quantity

Material

Units

SF

Material Location

Room 410 (Under HA#

HA No

03

Material Description

12"x12" Grey/Brown w/ White/Brown Streaks VFT

03A	12"x12" Grey/Brown w/ White/Brown Strks VFT Mastic	600	SF	Room 410 (Under HA # 01)	Miscellaneous	No	None	0	YES	X NO
2016 - Fal	I: No Change	•	<u> </u>	·	·					
Comments	s:									
2017 - Spi	ring: No Change									
Comments	S:									
2017 - Fal	I: No Change									

Category

Asbestos

Type

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	9"x9" Brown VFT	2100	SF	2nd Floor Corridor, 1st Floor Women's + Mens Lounge		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

Material Location

HA No

Comments:

Material Description

04A	9"x9" Brown VFT Mastic	4000	SF	2nd Floor Corridor, 1st Floor Women's + Mens Lounge		Miscellaneous	No	None	0		YES	X NO
0040 F-	II. N. C.	•			7							
	II: No Change											
Comment	S:											
2017 - Sp	ring: No Change				_							
Comment												
2017 - Fa	II: No Change				_							
Comment	s:											
					_							
HA No	Material Description	Materia	Materia	I Material Location	Ashestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

No

Friable

Damage

Туре

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

Change in Assessment Category

X NO

2016 - Fall: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		

Quantity

1200

Material

Quantity

Material

Units

Units

SF

Material Location

2nd Floor Corridor, 1st

Rooms 110 & 222

HA No

05

Material Description

12"x12" Off White w/ Blue,

Grey, & Pink Strks VFT

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
05A	12"x12" Off White w/ Blue, Grey, & Pk Mastic	1200	SF	Rooms 110 & 222		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change				1							
Comments:	J											
2017 - Fall: N	lo Change				=							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
06	9"x9" Tan w/ Streaks VFT	100	SF	Basement Switch Gear Room (Break Room)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Fall: N	lo Change				-							
Comments:												
2017 - Spring	2017 - Spring: No Change											
	Comments:											
2 22		1										

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category	
06A	9"x9" Tan w/ Streaks VFT Mastic	100	SF	Basement Switch Gear Room (Break Room)		Miscellaneous	No	None	0		YES X NO		
2016 - Fall: N	o Change												
Comments:													
2017 - Spring	: No Change												
Comments:													
2017 - Fall: N	lo Change												
Comments:	•												
			_										
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category	
07	9"x9" Black VFT	175	SF	1st Floor: Kitchen Storeroom		Miscellaneous	No	None	0		YES	X NO	
2016 - Fall: N	o Change												
Comments:													
2017 - Fall: N	o Change												
Comments:													
2017 - Spring: No Change													
Comments:													

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
07A	9"x9" Black VFT Mastic	175	SF	1st Floor: Kitchen Storeroom		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
08	9"x9" Green VFT	20	SF	1st Floor Engineer's Office Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring: No Change												
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Change in Assessment Category		
08A	9"x9" Green VFT Mastic	20	SF	1st Floor Engineer's Office Closet		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	No Change													
Comments:					_									
2017 - Spring	g: No Change													
Comments:	-													
2017 - Fall: N	No Change				_									
Comments:														
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in /	Assessment Catego	ry	
10	12"x12" Brown VFT	110	SF	1st Floor Engineer's Office		Miscellaneous	No	None	0		YES	X NO		
2016 - Fall: N	No Change													
Comments:	J													
2017 - Fall: N	No Change													
2017 - Fall: No Change Comments:														
2017 - Spring: No Change														
Comments:														

10A	12"x12" Brown VFT Mastic	110	SF	1st Floor Engineer's Office	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change									
Comments:	-									
2017 - Spring	: No Change									
Comments:										
2017 - Fall: N	o Change									
Comments:										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12"x12" Light Brown w/ White & Brown VFT	5200	SF	1st Floor Corridor, Lunchroom & Room 100, Assembly Hall (112), 1st Floor Mens Lounge, Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Material

Quantity

Material

Units

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12"x12" Light Brown w/ White & Brown VFT Mastic	5200	SF	1st Floor Corridor, Lunchroom & Room 100, Assembly Hall (112), 1st Floor Mens Lounge, Main Office		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Brown w/ Black Spots VFT	150	SF	Basement Inside Elevator		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12A	12"x12" Brown w/ Black Spots VFT Mastic	150	SF	Basement Inside Elevator		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	.											
2017 - Spring	: No Change											
Comments:	•											
2017 - Fall: N	o Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
13	9"x9" Light Brown VFT	500	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Fall: N	o Change											
Comments:	J											
2017 - Spring	· No Change											
Comments:												
				<u> </u>								

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
13A	9"x9" Light Brown VFT Mastic	500	SF	1st Floor Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14	9"x9" Grey VFT	300	SF	Engineer's Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	: No Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
14A	9"x9" Grey VFT Mastic	300	SF	Engineer's Closet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:					-							
2017 - Sprine	g: No Change				-							
Comments:	g											
0047 5 11 1]							
2017 - Fall: N	No Change				4							
Comments:					4							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15	12"x12" Grey/Brown w/ White Streaks VFT	1600	SF	1st Floor Serving Room, Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				1							
Comments:	10 Orlange				-							
]							
2017 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change				-							
Legit Opini	g. 110 Onango											

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
15A	12"x12" Lite Brown w/ White Streaks VFT Mastic	1600	SF	1st Floor Serving Room, Kitchen		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments.					-							
2017 - Sprin	g: No Change											
Comments:												
2047 Falls N	Na Changa				-							
2017 - Fall: 1	vo Change				4							
Comments:					_							
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
17	12"x12" Tan w/ Tan Streaks VFT (NOT OBSERVED)	900	SF	Rooms 113 & 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change				7							
Comments:	9											
2017 - Fall: N	No Change				_							
Comments:	10 Onlango											
	g: No Change											
Comments:												

17A	12"x12" Tan w/ Tan Streaks VFT Mastic (NOT OBSERVED)	900	SF	Rooms 113 & 115		Miscellaneous		None	0		YES	X NO
2016 - Fa	II: No Change											
Comment												
Comment	3.											
2017 - Sp	ring: No Change											
Comment												
2017 - Fa	II: No Change											
Comment	s:											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	

Quantity

600

Material

Quantity

Material

Units

Units

Room 118

SF

Material Location

HA No

18

Material Description

12"x12" Off White VFT

12"x12" Tan w/ Tan Streaks

Change in Assessment Category

Damage

Units

Units

YES

X NO

											·	
18A	12"x12" Off White VFT Mastic	600	SF	Room 118		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:	J											
2017 - Spring	ı: No Change				_							
Comments:	,											
2017 - Fall: N	lo Change				-							
Comments:												
]							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
19	12"x12" Black VFT (NOT OBSERVED)	180	SF	1st Floor Engineer's Corridor		Miscellaneous		None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change				-							
Comments:	J											
2017 - Spring	ı: No Change				-							
Comments:												

Category

Asbestos

Type

Damage

Type

Friable

Damage Quantity Damage

Units

HA No

Material Description

Material

Quantity

Material

Units

Material Location

19A	12"x12" Black VFT Mastic (NOT OBSERVED)	180	SF	1st Floor Engineer's Corridor		Miscellaneous			0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Spring	a: No Change				-							
Comments:	, J											
2017 - Fall: N	lo Change				-							
Comments:												
					_							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
20	12"x12" Brown VFT (NOT OBSERVED)	180	SF	1st Floor Engineer's Corridor		Miscellaneous			0		YES	X NO
2016 - Fall: N	lo Change				7							
Comments:	J											
2017 - Spring	a: No Change				-							
Comments:	,ge											
2017 - Fall: N	lo Change				-							
Comments:					7							

Type

Material

Category

Friable

Damage

Type

Material

Units

Material Location

Material

Quantity

HA No

Material Description

Change in Assessment Category

Damage Quantity Damage

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
20A	12"x12" Red VFT Mastic (NOT OBSERVED)	180	SF	1st Floor Engineer's Corridor		Miscellaneous			0		YES	X NO
2016 - Fall: N	o Change											
Comments:												
2017 - Spring	: No Change											
Comments:												
2017 - Fall: N	o Change											
Comments:	<u> </u>											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
50	2'x4' Dotted Ceiling Tile			Room 400							YES	X NO
2016 - Fall: N	o Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:	o onango											
2017 - Spring	: No Change				_							
Comments:	i. 140 Oriange				\dashv							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
51	Blue Dotted Linoleum			Room 400							YES	X NO
2016 - Fall: N	lo Change											
	v. No Change											
Comments:	g: No Change											
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asse	essment Category
	Material Becompiler	Quantity	Units	Material Education	Туре	Category	Tilabio	Туре	Quantity	Units	Orlange III 7 1000	
52	Blue Dotted Linoleum			Room 400							YES	X NO
2016 - Fall: N	lo Change											
Comments:					_							
2017 - Spring	g: No Change											
Comments:					_							
2017 - Fall: N	lo Change											
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
53	9"x9" Red VFT	225	SF	Kitchen Storage and Office Vault		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	-											
2017 - Spring	j: No Change											
Comments:												
2017 - Fall: N	lo Change				=							
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
54	9"x9" Red VFT Mastic	225	SF	Kitchen Storage and Office Vailt		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:												

55	12 x 12 Grey with Light Blue Floor Tile	900	SF	Rooms 113 and 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Spr	ring: No Change				+							
Comments												
2017 - Fall	I: No Change				+							
Comments												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
56	12 x 12 Grey with Light Blue Floor Tile Mastic	900	SF	Rooms 113 and 115		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	I: No Change											
Comments												
2017 - Fall	I: No Change				-							
Comments	•											

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Asbestos

Type

Material

Units

Material

Quantity

Material Location

HA No

Material Description

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
57	Ceramic Tile Grout	700	SF	Restrooms		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments.					 							
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	J. NO Change				_							
осинногие:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
57A	Ceramic Tile Adhesive	700	SF	Restrooms		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:	,ge											
2017 - Fall: N	lo Change				_							
Comments:					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
58	12 x 12 Ceiling Tie	1000	SF	Kitchen and 109		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall	: No Change								•			
2017 - Spr Comments	ing: No Change ::											
2017 - Fall	: No Change											
Comments): 											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
59	12 x 12 Ceiling Tile Adhesive	1000	SF	Kitchen and 109		Miscellaneous	No	None	0		YES	X NO
2016 - Fall	: No Change											
Comments):											
2017 - Fall	: No Change											
Comments												
2017 - Spr	ing: No Change											
Comments	<u> </u>											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
60	12 x 12 Rust Floor Tile	360	SF	1st Floor Engineer's Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	g. 110 Onlango											
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Asses	ssment Category
TIANO	Waterial Description	Quantity	Units	Waterial Education	Type	Category	Thabic	Type	Quantity	Units	Onlange in Asses	Same in Category
61	12 x 12 Rust Floor Tile Mastic	360	SF	1st Floor Engineer's Corridor		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	J											
2017 - Fall: N	lo Change				_							
Comments:	Ü											
2017 - Spring	ı: No Change				=							
Comments:	, : : : : : : : : : : : : : : : : : : :											

HA No

		Quantity	Units		Type	Category		Type	Quantity	Units		
62	Pinhole Ceiling tile	50000	SF	Throughout		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Fall: N	No Change											
Comments:	-											
2017 - Spring Comments:	g: No Change											
Comments.												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asso	essment Category
63	Fume Hood	40	SF	Rm. 400, 310		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	No Change				_							
Comments:	<u>-</u>											
				_								

Material

Damage

Friable

Damage

HA No

Material Description

Material

Material Material Location

Damage Change in Assessment Category

		Quantity	Units		Туре	Category		Туре	Quantity	Units		
64	Black Lab Counter tops	400	SF	Rm. 400		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	essment Category
65	Wolven Wall Panels	600	SF	Rm. 415		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:		<u> </u>										

Asbestos

Friable

Damage

Damage

Damage

Change in Assessment Category

HA No

Material Description

Material

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
66	Gray Lab Counter Tops	2500	SF	Rms 410, 412, 416, 310, 310A, 300, 212		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:					_								
2017 - Fall: N	lo Change												
Comments:					_								
2017 - Spring	: No Change				-								
Comments:	•												
]								
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in A	Assess	ment Category
67	2'x2' Blue Rubber Mats	700	SF	Exercise Room		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	lo Change]								
Comments:	_]								
2017 - Spring	ı: No Change				1								
Comments:	J												
2017 - Fall: N	lo Change												
Comments:]								
]								

68	12"x12" Mixed Beige Speckled VFT	1800	SF	Rms. 312, 302, 212		Miscellaneous	No	None	0		YES		X NO
2016 - Fall: N	No Change				1								
Comments:	10 Change												
0047 0 0	. N. Olasas												
2017 - Spring: No Change													
Comments:													
2017 - Fall: N	No Change												
Comments:													
Commonto													
					_								
LIA NIa	Material Description	Matarial	Meterial	Material Leasting	Ashastas	Matarial	Falala	Damana	Damana	Damasa	Chanas in A		
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in A	ssessi	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units			
69	12"x12" Mixed Beige	1800	SF	Pmc 212 202 212		Missollansous	No	None	0			ĺ	X NO
69	Speckled VFT Mastic	1800	SF	Rms 312, 302, 212		Miscellaneous	INO	None	0		YES		X NO
2016 - Fall: N	No Chango				1								
	NO Change				_								
Comments:													
					_								
2017 - Fall: I	2017 - Fall: No Change												
_	3												

Type

Material

Category

Friable

Damage

Type

Damage

Quantity

Damage

Units

Material

Units

Material

Quantity

Material Location

HA No

Comments:

Comments:

2017 - Spring: No Change

Material Description

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Asses	ssment Category
AA(27)	Aircell Duct Insulation	3000	SF	N. Center, N., & S. Wing Air Tunnels, N. Wing Unfinished (S), S. Wing Unfinished (E), Rifle Range		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
0047 5 11 1	1 01				-							
2017 - Fall: N	lo Change											
Comments:												

Į						l							
	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessm	nent Category
•	BB(28)	Aircell Debris	400	SF	S. Wing Unex., S. Wing (W) Unex., N. Wing S. Unfinished, N. Wing E. Unfinished		TSI	Yes	None	0		YES	X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:

2017 - Spring: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
DD(30)	Aircell Tank Insulation	400	SF	Tank Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:												
2017 - Spring	ı: No Change											
Comments:												
2017 - Fall: N	lo Change											
Comments:												
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
FF(32)	Gasket Insulation	50	SF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	lo Change											
Comments:	<u> </u>											
2017 - Spring	ı: No Change											
Comments:	J											
2017 - Fall: N	lo Change											
Comments:												

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
FT001	12x12 Blue Floor Tile	2800	SF	1st Floor Corridors, 3rd fl store room, 2nd fl exercise room, middle corridor, 3rd and 2nd fl landing		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U(21)	Pre-Formed Heating Insulation (Millboard)	500	SF	Air Tunnels		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:

W(23)	Cardboard Pipe Insulation	1000	LF	Throughout (See Hatching Maps)		TSI	Yes	None	0		YES	X NO
0040 = "												
2016 - Fall	: No Change											
Comments	:											
2017 - Spr	ng: No Change											
Comments	:											
2017 - Fall	: No Change											
Comments	:											
												
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessn	nent Category
		Quantity	Units		Type	Category		Type	Quantity	Units	1	

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

100

Material

Quantity

Material

Units

LF

Material Location

Throughout (See Hatching Maps)

HA No

WW

Material Description

MJP on Cardboard Pipe

Insulation

X(24)	Pre-Formed Pipe Insulation	1000	LF	Boiler Room, Crawlspaces, N. Wing Unfinished (S), W. Center Engine Room, Air Tunnel		TSI	Yes	Dist	60		YES	X NO
2016 - Fall	: No Change											
Comments:												
2017 - Spr	ing: No Change											
Comments	<u> </u>											
2017 - Fall: No Change												
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
XX	MJP on Pre-Form Pipe Insulation	300	LF	Boiler Room, Crawlspaces, N. Wing Unfinished (S), W. Center Engine Room, Air Tunnel		TSI	Yes	Dist	10		YES	X NO
2016 - Fall	· No Change]							

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

HA No

Comments:

Comments:

Comments:

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Material

Quantity

Material

Units

Material Location

Change in Assessment Category

Damage

Units

Y(25)	Aircell Pipe Insulation	26124	LF	Throughout (See Hatching Maps)		TSI	Yes	None	0		YES	X NO
					7							
2016 - Fall:	No Change											
Comments:												
2017 - Sprii	ng: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	-											
					-							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	ment Category
		Quantity	Units		Type	Category		Type	Quantity	Units		

TSI

Asbestos

Type

Material

Category

Friable

Yes

Damage

Туре

None

0

Damage

Quantity

Damage

Units

Change in Assessment Category

X NO

YES

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

5000

Material

Quantity

Material

Units

LF

Material Location

Throughout (See Hatching Maps)

HA No

Z(26)

Material Description

MJP E/F/V on Aircell Pipe

Insulation

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
ZZ	MJP on Fiberglass Pipe Insulation	300	LF	Boiler Room, Pump Room, Engine Room, SW Unfinished, S. Wing Tank Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

Page 37

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Wells Community Academy High School
Date: <u>12/22/2017</u>
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure. Oracle Unit: 51071

SCHOOL'S ASBESTOS MANAGEMENT PLAN.