Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

Hiram H Belding Elementary School 22221 2260 School: **Oracle Unit: Building ID:** Address: 4257 N Tripp Avenue Region: 01 Mail Room: Asbestos Surveyor: Ennis, Donald X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 1/8/2019 Email Address: djennis@cps.edu A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Location Asbestos Friable Damage Change in Assessment Category Material Material Damage Damage Quantity Units Type Category Quantity Type 12"x12" Light Brown w/ 1st, 2nd, Room (MDF) YES X NO 02 SF White & Brown Streaks 2660 Next To 2nd Floor Boy's Miscellaneous No None 0 VFT Toilet - 1901 2016 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Oracle Unit: 22221

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
03	9"x9" Gray w/ Black, Pink, & White Streaks VFT	1200	SF	Rooms 106 - 1901 (under HA # U)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: No Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
04	12"x12" Lt Brown w/ White & Brn Strks VFT Mastic	2660	SF	1st, 2nd, Room (MDF) Next To 2nd Floor Boy's Toilet - 1901		Miscellaneous	No	None	0		YES X NO

Page 2

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9"x9" Gray w/ Blk, Pink, & White Strks VFT Mastic	1200	SF	Rooms 106 -1901 (Under HA #V)		Miscellaneous	No	None	0		YES X NO

ange			
Change			
ange			
Change			
ange			
·			·
			·
	ange Change	Change ange Change	Change ange Change

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	12"x12" Beige w/ Orange, Brown, & Beige Strks VFT	0	SF	Room 301- 1901 Abated 2013		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in	Assess	sment Category
11	12"x12" Beige w/Orange, Brn,&Beige Strks VFT Mastic			Room 301- 1901 Abated 2013		Miscellaneous					YES		X NO
2016 - Fall:	No Change	•	•	·]	•	•	•	•	•	•		
Comments:	Ü												
2017 - Sprii	ng: No Change				-								
Comments:					1								
2017 - Fall:	No Change				-								
Comments:	.												
2018 - Sprii	ng : No Change												
Comments:	<u> </u>				- -								
2018 - Fall:	No Change				-								

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	12"x12" Cream w/ White & Brown Streaks VFT	2150	SF	Room 101 & 201 - 1901		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
13	12"x12" Cream w/ White & Brown Streaks VFT Mastic	2150	SF	Room 101 & 201 - 1901		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	12"X12" Cream w/ Brown Streaks VFT	2600	SF	Rm 200A, Main Office, Principal's Office, Conference RM 109 & Main Office Toilet - 1901 (Office areas under HA # 38)		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15	12"x12" Cream w/ Brown Streaks VFT Mastic	2600	SF	Rm 200A, Main Office, Principal's Office, Conference RM 109 & Main Office Toilet - 1901 (Office areas under HA # 38A)		Miscellaneous	No	None	0		YES X NO
2016 - Fall	2016 - Fall: No Change										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	12"x12" Beige w/ Blue & White Specks VFT	325	SF	Room 204A - 1901		Miscellaneous	No	None	0		YES X NO
					i						

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	12"x12" Beige w/ Blue & White Specks VFT Mastic	325	SF	Room 204A - 1901		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

18	9"x9" Brown w/ White & Black Streaks VFT-NOT OBSERVED	- 1901				YES	X NO
2016 - Fa	II: No Change						
Commen							
2017 - Sp	ring: No Change						
Commen	·						
2017 - Fa	II: No Change						
Commen							
2018 - Sp	oring : No Change						
Commen							
2018 - Fa	II: No Change						
Commen							

Type

Material

Category

Damage

Type

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
19	9"x9" Brown w/ White & Black Streaks VFT Mastic- NOT OBSERVED			- 1901							YES X NO

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9"x9" Tan w/ White Streaks VFT	250	SF	Engineer's Old Office - 1901		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	9"x9" Tan w/ White Streaks VFT Mastic	250	SF	Engineer's Old Office - 1901		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	9" x 9" Gray w/ Black, Pink and White Streaks VFT	2400	SF	Room 107, Room 207 - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24 A	9"x 9" Gray w/ Blk, Pink & White Strks VFT Mastic	2400	SF	Room 107, Room 207 - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	12" x 12" White with Tan Speckles VFT	1100	SF	Room 024 - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2016 - Fall: No Change
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2017 - Spring: No Change Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Fall: No Change
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Spring : No Change Comments: 2018 - Fall: No Change	
2018 - Spring : No Change Comments: 2018 - Fall: No Change	2017 - Spring: No Change
Comments: 2018 - Fall: No Change	Comments:
Comments: 2018 - Fall: No Change	
2018 - Fall: No Change	2018 - Spring : No Change
	Comments:
	2018 - Fall: No Change
Comments:	Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25 A	12" x 12" White with Tan Speckles VFT Mastic	1100	SF	Room 024 - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
26	Hard Coat Plaster			Throughout - 1912							YES	X NO
2016 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	g: No Change											
Comments:												
2017 - Fall:	No Change											
Comments:	-											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall:	No Change											
Comments:	Ţ.											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
27	Hard Coat Plaster			Throughout - 1901							YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Page 13

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
28	Wall Canvas	1000	SF	Throughout - 1908		Miscellaneous	No	None	0		YES	X NO
2016 - Fal	l: No Change]							
Comments	5:											
2017 - Spr	ring: No Change											
Comments	S:											
2017 - Fal	I: No Change											

Comments:

2018 - Spring : No Change Comments:

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	Wall Canvas	1000	SF	Throughout - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
30	Drywall	1000	SF	Counselors Room - 1901		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change											
Comments:					-							
2017 - Spring	g: No Change				=							
Comments:												
2017 - Fall: N	No Change				-							
Comments:					1							
2018 - Spring	g : No Change				-							
Comments:					1							
2018 - Fall: N	No Change				-							
Comments:	<u> </u>											
					J							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
31	Drywall Joint Compound	1500	SF	Counselors Office - 1901		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32	12" x 12" Light Brown w/ White & Brown Streaks VFT	1250	SF	First, Second and Third Floor Corridor(Abated 2013) - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
32 A	12"x12" Lt. Brown w/ White & Brwn Strks VFT Mastic	1250	SF	First, Second and Third Floor Corridor(Abated 2013) - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
35	12"x12" White w/ Blue Specs VFT	600	SF	Room 022 - 1912		Miscellaneous	No	None	0		YES X NO
004C Fall N	- Oh										

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
, v
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
36	12"x12" White w/ Blue Specs VFT	600	SF	Room 022 - 1912		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37	12"x12" Off White w/tan specks VFT	1500	SF	Room 102, Wardrobe, toilet		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
37A	12"x12" Off white w/tan specks VFT MASTIC	1500	SF	Room 102, Wardrobe, Toilet		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" White w/brown & green specks VFT	2000	SF	Main office, Office Storage Room, Office Toilet, Principal's Office, Conference Rm 109		Miscellaneous	No	None	0		YES X NO

2016 Fall: No Change
2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38A	12"x12" White w/brown & green specks VFT Mastic	2000	SF	Main office, Office Storage Room, Office Toilet, Principal's Office, Conference Rm 109		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		,			· .	0 ,		,,	,	<u> </u>	
39	12x12 Light Beige w/ Tan Streaks VFT	100	SF	1st and 2nd floor Unisex toilet- 1901		Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	o Change				1						
Comments:											
2017 - Spring	2017 - Spring: No Change										
Comments:		-									
2017 - Fall: N	o Change										
Comments:					-						
2018 - Fall: N	o Change										
Comments:					=						
2018 - Spring	: No Change										
Comments:					-						
					J						

Type

Material

Category

Miscellaneous

Asbestos

Type

Material

Category

Friable

Friable

No

Damage

Type

None

Damage

Type

Damage

Quantity

Damage

Quantity

0

Damage

Damage

Units

Units

2010 5 11 11 21	 	
2016 - Fall: No Change		
Comments:		
2017 - Spring: No Change		
Comments:		
2017 - Fall: No Change		
Comments:		
2018 - Spring : No Change		
Comments:		
2018 - Fall: No Change		
Comments:		·

Material

Quantity

100

Material Description

Material Description

12x12 Light Beige w/ Tan

Streaks VFT Mastic

Material

Quantity

Material

Material

Units

SF

Units

Material Location

Material Location

toilet-1901

1st and 2nd floor Unisex

HA No

HA No

39A

Change in Assessment Category

Change in Assessment Category

X NO

YES

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12x12 Beige w/mixed beige streaks VFT	1900	SF	301, 3rd floor Corridor bldg 1901		Miscellaneous	No	None	0		YES X NO

		1	
·			·-
2016 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:			
2017 - Fall: No Change			
Comments:			
2018 - Spring : No Change			
Comments:			
2018 - Fall: No Change			
Comments:			
	•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
41	12x12 beige w/mixed beige Mastic	1900	SF	301, 3rd Floor Corridor		Miscellaneous	No		0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12x12 Beige w/ mixed beige Streaks VFT	800	SF	3rd Floor Corridor BLDG 1912		Miscellaneous	No	Loc	0		YES X NO

			<u> </u>
2016 - Fall: No	o Change		
Comments:			
2017 - Fall: No	o Change		
Comments:			
2017 - Spring:	: No Change		
Comments:			
2018 - Fall: No	o Change		
Comments:			
2018 - Spring	: No Change		
Comments:			
	·	·	·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12x12 Beige w/mixed beige streaks Mastic	800	SF	3rd Floor Corridor BLDG 1912		Miscellaneous	No	Loc	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

44	2'x4' Pinhole Ceiling Tile	50	SF	2nd Floor Unisex Toilet, 1st Floor Unisex Toilet		Miscellaneous	Yes	None	0	YES	X NO
0040 F.II N	. 01				1						
2016 - Fall: N	o Change										
Comments:											
2017 - Fall: N	o Change										
Comments:											
2017 - Spring	: No Change										
Comments:											
2018 - Fall: N	o Change										
Comments:											
2018 - Spring	: No Change										
Comments:											
					1						

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Type

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	MJP E/F/V on Fiberglass Pipe Insulation			Engine Room- 1912				None			YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No

Material Description

Material

Quantity

Material

Units

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	Cardboard Pipe Insulation	408	LF	Throughout (See Hatching Maps) - 1901		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
D	MJP E/F/V on Cardboard Pipe Insulation	74	LF	Throughout (See Hatching Maps) - 1901		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Е	Aircell Pipe Insulation	560	LF	Throughout (See Hatching Maps) - 1901		TSI	Yes	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	MJP E/F/V on Aircell Pipe Insulation	50	LF	Throughout (See Hatching Maps) - 1901		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:
·

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
G	Mag Block Pipe Insulation	40	LF	Boiler Room, Tank Room, S. Corridor, Boys Play Room, Engine Room - 1901		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	MJP E/F/V on Mag Block Pipe Insulation	12	LF	Boiler Room, Tank Room, S. Corridor, Boys Play Room, Engine Room - 1901		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

VFT = Vinyl Floor Tile Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

1	Aircell Duct Covering	1000	SF	Room 024 (Old SE Boy's Playroom)- 1912		TSI	Yes	None	0		YES	X NO
2016 - Fall:	No Change				7							
Comments:												
2017 - Sprii	ng: No Change				_							
Comments:												
2017 - Fall:	No Change											
Comments:												
2018 - Sprii	ng : No Change											
Comments:					1							
2018 - Fall:	No Change											
Comments:					1							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
М	MJP E/F/V on Fiberglass Pipe Insulation			Throughout - 1912							YES	X NO

Type

Material

Category

Friable

Damage

Type

Damage

Units

Damage

Quantity

Change in Assessment Category

HA No

2016 - Fall: No Change

Material Description

Material

Units

Material

Quantity

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
N	MJP E/F/V on Fiberglass Pipe Insulation			Throughout - 1901							YES	X NO
2016 - Fall: N	lo Change]							
Comments:	•											
2017 - Fall: N	lo Change											
Comments:												
2017 - Spring	g: No Change											
Comments:												
2018 - Spring	g : No Change											
Comments:												
2018 - Fall: N	lo Change				-							
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
0	Aircell Pipe Insulation	20	LF	Basement South Corridor, Engine Room - 1912		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessme	ent Category
Р	MJP E/F/V on Aircell Pipe Insulation	8	LF	Basement South Corridor, Engine Room - 1912		TSI	Yes	None	0		YES [X NO
2016 - Fall: N	lo Change]				•			

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Q	Mag Block Pipe Insulation	124	LF	Basement South Corridor, Engine Room - 1912		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

Page 29

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
R	MJP E/F/V on Mag Block Pipe Insulation	11	LF	Basement South Corridor, Engine Room - 1912		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
S	Cardboard Pipe Insulation	102	LF	Basement South Corridor - 1912		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Т	MJP E/F/V on Cardboard Pipe Insulation	6	LF	Basement South Corridor - 1912		TSI	Yes	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
U	12"x12" Gray Streaked VFT	1200	SF	Room 106 & Wardrobe		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Ī	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
,	V	12"x12" Gray Streaked VFT Mastic	1200	SF	Room 106 & Wardrobe		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Hiram H Belding Elementary School
Date: 12/21/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE
SCHOOL'S ASBESTOS MANAGEMENT PLAN.