Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

25031

Oracle Unit:

Address: 4650 N Menard Avenue Region: 01 Mail Room: Asbestos Surveyor: BALLEN24 X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/17/2018 Email Address: ballen@learncharter.org A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Location Asbestos Friable Damage Change in Assessment Category Material Damage Damage Quantity Units Type Category Quantity Type Crawl Space, Engine YES X NO Rooms/Auditorium MJP E/F/V on Mag Block 03 LF Tunnel, & All Mechanical TSI Yes None 0 Pipe Insulation Areas. Room 101. Kitchen 2016 - Fall: No Change Comments: 2017 - Fall: No Change Comments: 2017 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Ernst Prussing Elementary School

School:

Oracle Unit: 25031

5510

Building ID:

06	MJP E/F/V on Aircell Pipe Insulation	166	LF	Engine Rm, E. Crawl Space, N. Crawl Space, SW Tunnel, & Aud. Crawl Spaces		TSI	Yes	None	0	YES	X NO
0040 5 11	N. O.				1						
2016 - Fall:	: No Change										
Comments	:										
2017 - Fall	: No Change										
Comments	<u> </u>										
2017 - Spri	ng: No Change										

Material

Category

Friable

Damage

Type

Asbestos

Type

Damage

Quantity

Damage

Units

Change in Assessment Category

Comments:

Material

Quantity

Material

Units

Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	MJP E/F/V on Cardboard Pipe Insulation	121	LF	Main East & Aud. Crawl Space, Main Air Tunnel, Main & S. Air Tunnel, S. Aud. Eng. Rm.		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

	1	Quantity	Units		Туре	Category		Туре	Quantity	Units	
09 Cardb	dboard Pipe Insulation	2255	LF	S. Auditorium, Engine Rm/Assembly Hall Tunnel, SW Tunnel, & Main Tunnel		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	Debris On Dirt Floor	35000	SF	North Crawl Spaces, Main East Crawl Spaces, & SW Tunnel		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

11	Duct Insulation	2000	SF	Main East Crawl Spaces & North Crawl Spaces		TSI	Yes	None	0		YES	X NO
2016 - Fa	all: No Change]							
Commen	•				1							
2017 - Fa	all: No Change				1							
Commen	•											
2017 - Sr	oring: No Change				1							
Commen	· ·											
2018 - Fa	all: No Change				_							
Commen	•											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
12	Aircell Pine Insulation	3558	I.E.	Main East & Aud. Crawl Space, Main Air Tunnel,		TSI	Vec	Loc	30		YES	X NO

TSI

Asbestos

Type

Material

Category

Friable

Yes

Loc

30

Damage

Type

Damage

Quantity

Damage

Units

3558

LF

HA No

12

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

Material Description

Aircell Pipe Insulation

Material

Quantity

Material

Units

Material Location

Main & S. Air Tunnel, S. Aud. Eng. Rm.

		Quantity	Units		Type	Category		Type	Quantity	Units		
13	Mag Block Pipe Insulation	515	LF	Engine Room, Main Tunnel, South Fan Room, North Fan Room, North Engine Room, S. Auditorium Engine Rm		TSI	Yes	None	5		YES	X NO
2016 - Fall: N Comments:	o Change											

Material

Damage

Friable

Damage

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
17	9"x9" Grey w/ Pink Streaks VFT	2000	SF	(Rm 300B Closet, Room 300A)_CLD NOT FiND RMS (Principals & Asst. Principals Off.& Conference Rm) - NOT OBSERVED		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

Damage Change in Assessment Category

25	9"x9" Brown w/ White Streaks VFT	1020	SF	RM 110, MDF RM (103 Closet)	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	lo Change									
Comments:										
2017 - Fall: N	lo Change									
Comments:										
	g: No Change									
Comments:										
2018 - Fall: N	lo Change									
Comments:										

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

H	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	1
2	26	12"x12" Beige w/ Multiple Streaks VFT	12115	SF	1st & 2nd Floor Corridor, Rooms 200 B & 200 A, 212, 214, 114, 111, 101A, 100 Office, Gym Office, Rm 108		Miscellaneous	No	None	0		YES X NO	
_	2016 - Fall: N	o Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No

Material Description

Material

Quantity

Material

Units

28	9"x9" Brown w/ White Streaks VFT Mastic	1020	SF	RM 110, MDF RM (103 Closet)		Miscellaneous	No	None	0	YES	X NO
2016 - Fall:	No Change				1						
Comments:					1						
Comments.											
2017 - Fall:	No Change				-						
Comments:											
2017 0											
	ng: No Change										
Comments:											
2019 Fall:	No Change				-						
					1						
Comments:											
]						

Type

Material

Category

Friable

Damage

Туре

Damage

Quantity

Damage

Units

Material Location

RM 110, MDF RM (103

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
29	12"x12" Beige w/ Multiple Streaks VFT Mastic	12115	SF	1st & 2nd Floor Corridor, Rooms 200 B & 200 A, 114, 111, 101A, 100 Office, 212, 214, Gym Office, Rm 108		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	No Change				Ì						

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

Material Description

Material

Quantity

Material

Units

31		Exterior Window Caulk	2000	LF	Exterior Windows		Miscellaneous	Yes	None	0		YES	X NO
2016 -	Fall: N	o Change				1							
Comm						_							
		o Change											
Comm	ents:					-							
		: No Change											
Comm	ents:					-							
2018 -	Fall: N	o Change				1							
Comm	ents:												
						J							
HA No		Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
					+	+	+			+	+	+	

Type

Material

Category

Miscellaneous

Friable

No

Damage

Type

None

Damage

Quantity

0

Damage

Units

HA No

32

Comments:

Comments:

Comments:

Comments:

2016 - Fall: No Change

2017 - Fall: No Change

2017 - Spring: No Change

2018 - Fall: No Change

Material Description

Interior Window Caulk

Material

Quantity

2000

LF

Material

Units

Material Location

Interior Windows

YES

X NO

33	Blown In Insulation	20000	SF	Attic		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	o Change]							
Comments:												
2017 - Fall: N	o Change											
Comments:					1							
2017 - Spring	: No Change				-							
Comments:					-							
2018 - Fall: N	o Change											
Comments:					 -							
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
				Stairwells, 2nd Floor								

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

Damage

Quantity

0

None

Damage

Units

20000

SF

HA No

34

Material Description

2' x 4' White w/ Speckles

Ceiling Tile

Material

Quantity

Material

Units

Material Location

Corridor, Room 200, 200

B, 213 (Library), 214,

215

Change in Assessment Category

X NO

2016 - Fall: I	No Chango				7						
	No Change										
Comments:											
2017 - Fall: I	No Change				-						
	No Change										
Comments:											
2017 - Sprin	g: No Change										
Comments:											
2018 - Fall: I	No Change										
Comments:	-										
		·									
HA No	Material Description	Material	Material Units	Material Location	Asbestos	Material	Friable	Damage Type	Damage	Damage	Change in Assessment Category
1	1	Quantity	LUDIIIS		Type	Category	1	LVDE	Quantity	Units	1

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

Yes

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

5000

HA No

35

36

Material Description

2' x 2' Tectum Ceiling Tile

2' x 8' Tectum Walls

Material

Units

SF

SF

Material Quantity

2500

Material Location

Gymnasium

Gymnasium

Change in Assessment Category

X NO

X NO

YES

37	Spray Applied Plaster Wall	600	SF	Auditorium Hallway and Stage and Vestibule	Miscellaneous	No	None	0	YES	X NO
2016 - Fall: N	No Change									
Comments:	•									
2017 - Fall: N	No Change									
Comments:										
2017 - Sprin	g: No Change									
Comments:										
2018 - Fall: I	No Change									
Comments:	-									

Type

Material

Category

Damage Quantity Damage

Units

Change in Assessment Category

Damage

Туре

Friable

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
38	12"x12" Gray w/ Brown Streaks VFT	400	SF	Room 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category
39	12"x12" Off White w/ Brown Streaks VFT	400	SF	Rooms 210 and 113		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change											

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
40	12"x12" Light Blue w/ White Streaks VFT	1458	SF	Room 215, 105, 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	ssment Category
41	2'x4' White Plain Ceiling Tile	1400	SF	Rooms 200 A, 101 A, 212		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: I	No Change											
Comments:												
2017 - Fall: I	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:	g. No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
42	12"x12" Gray w/ Brown Streaks VFT Mastic	400	SF	Room 210		Miscellaneous	No	None	0		YES X NO

2016 - Fall: N	o Change		
Comments:			
2017 - Fall: N	o Change		
Comments:			
2017 - Spring	: No Change		
Comments:			
2018 - Fall: N	o Change		
Comments:			

2018 - Fall: No Change

Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
43	12"x12" Off White w/ Brown Streaks VFT Mastic	400	SF	Rooms 210 and 113		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	lo Change										

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
44	12"x12" Light Blue w/ White Streaks Mastic	1458	SF	Room 215 (Under Carpet), 105, 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
45	Terrazzo	4800	SF	Assembly Rear Stage Stairs, Vestbule, and Balcony Stairs; Stairwell Treads & Landings & Vestibules; Rm 215 Stairs; 1st and 2nd Floor Corridor Border & Classroom Entrances; Rm 200 & Closet; Vestbule in Rm 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category	
46	Decorative Plaster	200	SF	Assembly Hall Stage		Miscellaneous	No	None	0		YES X NO	

2016 - Fall: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

47	Drywall, Tape and Compound	300	SF	Rms 114 and 200B		Miscellaneous	Yes	None	0	YES	X NO
2016 - Fall: I Comments:	No Change										
2017 - Fall: I Comments:	2017 - Fall: No Change Comments:										
2017 - Sprin Comments:	2017 - Spring: No Change Comments:										
2018 - Fall: I Comments:	No Change										

Type

Material

Category

Damage

Туре

Friable

Damage

Quantity

Damage

Units

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
48	Drywall, Tape and Compound	5000	SF	Throughout 1999 Mobile		Miscellaneous	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Material

Quantity

Material

Units

Material Location

HA No

Material Description

49	2'X4' White Ceiling Tiles	3500	SF	Throughout 1999 Mobile		Miscellaneous	No	None	0		YES	X NO
2016 - Fall:	No Change]							
Comments:												
2017 - Fall:	No Change											
Comments:	<u> </u>											
2017 - Sprin	ng: No Change											
Comments:					-							
2018 - Fall:	No Change				-							
Comments:												
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assess	sment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

50	12"x12" White w/Streaks VFT	3500	SF	Throughout 1999 Mobile					
2016 - Fall: N	o Change								
Comments:									
2017 - Spring	: No Change								
Comments:									
2017 - Fall: N	o Change								
Comments:									
2018 - Fall: No Change									
Comments:			•						

Quantity

Units

Material

Units

Material

Quantity

Material Location

HA No

Material Description

Change in Assessment Category

X NO

2016 - Fall	: No Change										
Comments											
2017 - Fall	: No Change										
Comments	i:										
2017 - Spri	ing: No Change										
Comments	S:										
2018 - Fall	: No Change										
Comments) :										
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessment Category

Type

Type

Material

Category

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Туре

None

Type

None

Damage

Quantity

Quantity

0

0

Damage

Units

Units

Quantity

10500

Units

SF

Material

Units

SF

Material

Quantity

3500

Material Location

Throughout 1999 Mobile

Throughout 2003 Mobile

HA No

50A

51

Material Description

12"x12" White w/Streaks

VFT Mastic

Drywall, Tape, and

Compound

Change in Assessment Category

X NO

X NO

YES

52	2'X4' White Ceiling Tiles	6500	SF	Throughout 2003 Mobile		Miscellaneous	Yes	None	0		YES	X NO
2016 - Fall: N	No Change]							
Comments:	<u> </u>											
2017 - Fall: N	No Change											
Comments:					-							
2017 - Spring	g: No Change											
Comments:					-							
2018 - Fall: N	No Change											
Comments:												
]							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	ment Category

Type

Material

Category

Friable

No

Miscellaneous

Damage

Type

None

0

Damage

Quantity

Damage

Units

53	12"X12" White w/Streaks VFT	6000	SF	Closets & Mechanical Rm in 2003 Mobile
2016 - Fall:	No Change			
Comments:				
2017 - Sprii	ng: No Change			
Comments:				
2017 - Fall:	No Change			
Comments:				
2018 - Fall:	No Change			
Comments:				

Material

Quantity

Material

Units

Material Location

Hallways, Classrooms,

HA No

Material Description

12"X12" White w/Streaks

Change in Assessment Category

X NO

53A	12"X12" White w/Streaks VFT Mastic	6000	SF	Hallways, Classrooms, Closets & Mechanical Rm in 2003 Mobile		Miscellaneous	No	None	0		YES	X NO
2016 - Fa	II: No Change				7							
Comment												
2017 - Fa	II: No Change											
Comment	•											
2017 - Sp	oring: No Change											
Comment	is:											
2018 - Fa	II: No Change											
Comment	is:											
					J							
HA No	Material Description	Material	Material	Material Location	Asbestos	Material	Friable	Damage	Damage	Damage	Change in Assessi	ment Category

Type

Type

Material

Category

Category

Miscellaneous

Friable

No

Damage

Type

Type

None

Damage

Quantity

Quantity

0

Damage

Units

Units

YES

Quantity

250

Units

Boys Toilet

SF

HA No

54

Material Description

Blue Linoleum

Material

Units

Material

Quantity

Material Location

Hallways, Classrooms,

Change in Assessment Category

X NO

2016 - Fall: N	No Change										
Comments:											
2017 - Fall: N	No Change										
Comments:											
	g: No Change										
Comments:											
2018 - Fall: N	No Change										
Comments:											
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category

Type

Material

Category

Miscellaneous

Miscellaneous

Friable

No

No

Damage

Type

None

None

Damage

Quantity

0

0

Damage

Units

Friable = Can be crumbled, pulverized, or reduced to powder by hand pressure.

HA No

54A

55

Comments:

Comments:

Comments:

Comments:

Material Description

Blue Linoleum Mastic

Pink Linoleum

2016 - Fall: No Change

2017 - Spring: No Change

2017 - Fall: No Change

2018 - Fall: No Change

Material

Quantity

250

250

Material

Units

SF

SF

Material Location

Boys Toilet

Girls Toilet

Change in Assessment Category

X NO

X NO

YES

55A	Pink Linoleum Mastic	250	SF	Girls Toilet		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	lo Change]							
Comments:												
2017 - Fall: N	lo Change											
Comments:	-]							
2017 - Spring	ı: No Change											
Comments:												
2018 - Fall: N	lo Change											
Comments:												
					J							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category

Type

Material

Category

Miscellaneous

Friable

No

Damage

Туре

None

Damage

Quantity

0

Damage

Units

2016 - Fall: N	o Change			
Comments:				
2017 - Fall: N	o Change			
Comments:				
2017 - Spring	: No Change			
Comments:				
2018 - Fall: N	o Change			
Comments:		•		

2

EΑ

Material

Quantity

Material

Units

Material Location

Balcony and Projector

Room

HA No

56

Material Description

Fire Doors

YES

X NO

		Quantity	Units		Type	Category		Type	Quantity	Units		
57	Breaching Insulation	100	SF	Boiler Room		TSI	No	None	0		YES	X NO
2016 - Fall: Comments:												
2017 - Fall:												
Comments:					-							
2017 - Sprin	ng: No Change											

Material

Friable

Damage

Damage

Asbestos

Comments:

Material

Material Location

2018 - Fall: No Change Comments:

Material Description

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
58	Lining Insulation	4	SF	Incineration hatch in Boiler Room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2018 - Fall: No Change
Comments:

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
59	Incineration Burner Gasket	2	LF	Boiler Room		TSI	Yes	None	0		YES	X NO
2016 - Fall: N	o Change											

2016 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
60	BEH Baldwin EHRCT Hill Insulation Cement	50	LF	Unfinished Pipe Space		TSI	Yes	None	0		YES X NO

0040 5 11 N1 O1	
2016 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

61	Kaylo Block Insulation	10	SF	Unfinished Pipe Space		TSI	Yes	None	0		YES	X NO
2016 - Fall	: No Change				7							
Comments					<u> </u>							
2017 - Fall	: No Change				1							
Comments					-							
2017 - Spr	ing: No Change				1							
Comments	S:				-							
2018 - Fall	l: No Change				1							
Comments	S:				=							
HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
_	Cornet Mastic	4200	ee ee	Engineer's Office, and Rooms 212, 213-215,		Missellaneous	No	None	0		YES	X NO

Type

Material

Category

Miscellaneous

No

Friable

Damage

Type

None

0

Damage

Quantity

Damage

Units

Material Location

Assembly Aisles, Library

(Rm 213)

4200

SF

HA No

Α

Material Description

Carpet Mastic

Material

Quantity

Material

Units

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Ernst Prussing Elementary School
Date: 12/17/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25031

SCHOOL'S ASBESTOS MANAGEMENT PLAN.