Chicago Public Schools

6 Month Asbestos Surveillance 2018 - Fall

25351

Oracle Unit:

Address: 245 W. 57th St. Region: 05 Mail Room: Asbestos Surveyor: Hicks, Fatina X CHECK HERE IF NO CHANGE TO ASBESTOS Survey Date: 12/11/2018 Email Address: silverdollar59@hotmail. com A copy of the 2016/2017 notice to parents and staff regarding the asbestos management plan notifications was distributed via: X Notice printed in school's newsletter Each child's backpack Notice printed in school's calendar Other HA No Material Description Material Material Material Location Asbestos Material Friable Damage Damage Damage Change in Assessment Category Quantity Units Type Quantity Units Category Type corridors, room 103, X NO 03A SF YES 12x12 white speck floor tile 3150 Miscellaneous No None 0 office (1955 addition) 2016 - Fall: No Change Comments: Area still the same 2017 - Spring: No Change Comments:No Change 2017 - Fall: No Change Comments: 2018 - Spring: No Change Comments: 2018 - Fall: No Change Comments:

Jesse Sherwood Elementary School

School:

5900

Building ID:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05	9x9 maroon floor tile	1020	SF	room 102		Miscellaneous	No	None	0		YES X NO
2016 Fall N	o Chongo										

2016 - Fall: No Change
Comments:only 100 sq ft abated
2017 - Fall: Other
Comments:50 sq ft was abated the rest of the room still has the same tile
2017 - Spring: No Change
Comments:No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
05A	9x9 brown floor tile			gym		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments:Area still the same
2017 - Spring: Abated
Comments:No Change
2017 - Fall: Abated
Comments:Area was abated
2018 - Spring : Abated
Comments:abated new color is white
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08	12x12 gray floor tile	1800	SF	rms 111, 113, 115, kitchen, 217, 216, 209 (1955 bldg)		Miscellaneous	No	None	0		X YES NO

2016 - Fall: Abated
Comments:Area still the same
2017 - Fall: Other
Comments:Kitchen area abated all other rooms the same
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08B	beige specked 12x12 floor tile	4400	SF	2nd floor corridor and room 103		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08C	12x12 brown speck floor tile	1540	SF	1955 addition - 2nd floor teacher toilet, 1st floor corridor		Miscellaneous	No	None	0		YES X NO

	• • •
2016 - Fall: No Change	
Comments:Area still the same	
2017 - Spring: No Change	
Comments:No Change	
2017 - Fall: No Change	
Comments:	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
08D	12x12 beige specked floor tile	3600	SF	1955 addition - rm 218, 217, 216, 213, 202, 201, 200		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: Other
Comments:217 has gray floor tile
2018 - Fall: No Change
Comments:
2018 - Spring : Other
Comments:some rooms have existing color some don't

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10	9x9 maroon floor tile mastic	1020	SF	room 102		Miscellaneous	No	None	0		YES X NO
2016 - Fall: N	o Change										

2016 - Fall: No Change
Comments: only 100 sq ft abated
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
10A	9x9 brown floor tile mastic			gym		Miscellaneous					X YES NO

2016 - Fall: Abated
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: Abated
Comments:tile was abated. present color is white
2018 - Spring : Abated
Comments:abated 2013
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11	12x12 gray floor tile mastic	6500	SF	1955 addition, 109, teachers lounge, 111, 113, 115, kitchen, 217, 216, 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11A	12x12 beige speckled floor tile mastic	4400	SF	1955 addition - 109, teachers lounge, 111, 113, 115, kitchen, 217, 216, 209		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

	HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
	11B	12x12 brown speck floor tile mastic	1540	SF	1955 addition - 2nd floor teacher toilet, 1st floor corridor		Miscellaneous	No	None	0		YES X NO
Г	0046 Fall N	- Oh										

2016 - Fall: No Change	
Comments:Area still the same	
2017 - Fall: No Change	
Comments:	
2017 - Spring: No Change	
Comments:No Change	
2018 - Fall: No Change	
Comments:	
2018 - Spring : No Change	·
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
11C	12x12 beige specked floor tile mastic			2nd floor corridor and room 103		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asses	sment Category
11D	12x12 white speck floor tile mastic	3150	SF	corridors, room 103, office (1955 addition)		Miscellaneous	No	None	0		YES	X NO
2016 - Fall: N	No Change							•				
Comments:Area still the same												
2017 - Spring: No Change												
Comments:N												
2017 - Fall: N	No Change											
Comments:	J											
2018 - Spring	g : No Change											
Comments:	<i>y</i>											
2018 - Fall: N	No Change											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
12	boiler door gasket			boiler room		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Comments:

Page 8

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Asse	ssment Category
13	air duct insulation	480	SF	1950 unexcavated area		Miscellaneous	Yes	Dist	10		YES	X NO
2016 - Fall: N Comments:A	lo Change rea still the same											
2017 - Spring Comments:N					-							
2017 - Fall: N	<u> </u>											
Comments:					-							
2018 - Spring	j : No Change											
Comments:					1							
2018 - Fall: N	lo Change				1							
Comments:	-											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
14	vinyl mop board black			all rooms - 1950 addition		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: Other
Comments:most boards have been covered with white boards
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

		Quantity	Units		Type	Category	Туре	Quantity	Units		
15	black vinyl mop board mastic			1950 addition - all rooms		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change										
Comments:A	rea still the same										
2017 - Fall: N	lo Change										
Comments:	· ·										
2017 - Spring	g: No Change										
Comments:N	o Change										
2018 - Spring	; No Change										
Comments:											
2018 - Fall: N	lo Change										
Comments:	-										

Material

Damage

Friable

Damage

Damage

Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
15B	brown vinyl mopboard			1955 building - room 213, 218		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Material

Material Location

Page 10

		Quantity	Units		Туре	Category	Туре	Quantity	Units		
15C	brown vinyl mop board mastic			all rooms - 1950 building		Miscellaneous				YES	X NO
2016 - Fall: N	lo Change]						
	rea still the same				1						
2017 - Spring											
Comments:No	o Change				-						
2017 - Fall: N	lo Change										
Comments:					=						
2018 - Spring	ı : No Change										
Comments:											
2018 - Fall: N	lo Change				-						
Comments:											
					J						

Material

Friable

Damage

Damage

Material Material Location

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
16	brown vinyl mopboard			1950 building - all rooms		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No

Material Description

Material

Damage Change in Assessment Category

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assess	sment Category
16B	brown vinyl mop board mastic			1955 building - 218, 213		Miscellaneous					YES	X NO
2016 - Fall: N	No Change											
	Area still the same											
2017 - Fall: N	No Change											
Comments:												
2017 - Sprin	g: No Change											
Comments:N	lo Change											
2018 - Sprin	g : No Change											
Comments:												
2018 - Fall: N	No Change											
Comments:												
					_							

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
18	green carpet mastic			1950 building - library		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Ass	essment Category
19	maroon carpet mastic			1955 - room 118		Miscellaneous					X YES	NO
2016 - Fall:	Abated											
Comments:	Area still the same											
2017 - Sprin	ng: No Change											
Comments:	Comments:No Change											
2017 - Fall:	Other											
Comments:	Room doesn't have car	rpet										
2018 - Fall:	No Change											
Comments:												
2018 - Sprin	ng : Other											
	rm.118 is tiled											

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
20	green linoleum			library		Miscellaneous					YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA NO	Material Description	Quantity	Units	Material Location	Type	Category	Filable	Type	Quantity	Units	Change in Assess	sment Category
21	green linoleum mastic			library		Miscellaneous					YES	X NO
2016 - Fall: No	o Change				7							
	ea still the same											
2017 - Spring:	: No Change				1							
Comments:No	Change											
2017 - Fall: No	o Change											
Comments:												
2018 - Fall: No	o Change											
Comments:												
2018 - Spring	: No Change											
Comments:			•									

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
22	9" x 9" Gray Floor Tile	60	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
23	Mastic Associated w/ 9" x 9" Gray Floor Tile	60	SF	Engineer's Washroom		Miscellaneous	No	None	0		YES X NO
					1						

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
24	Tan w/ Gray Linoleum	700	SF	Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
25	Mastic Associated w/ Tan w/ Gray Linoleum	700	SF	Library		Miscellaneous	No	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
_
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
А	mag block insulation	1500	SF	boiler room		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
В	cardboard TSI	1000	LF	boiler room, unexcavated area (1950 bldg)		TSI	Yes	Dist	4		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: Abated
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
B1	cardboard TSI	1000	LF	air tunnel, unexcavated area (1955 addition)		TSI	Yes	Dist	25		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
С	cardboard fittings	100	FITTING	boiler room, fan room, air tunnels, unexcavated area (1950 bldg)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
C1	cardboard fittings	50	FITTING	air tunnel, unexcavted area (1955 addition)		TSI	Yes	Dist	10		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:No Change
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
F	air cell insulation	2000	LF	boiler room, air chamber, unexcavated area, mechanical room, (1950 bldg)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change	
<u> </u>	
Comments:Area still the same	
2017 - Spring: No Change	
Comments:No Change	
2017 - Fall: No Change	
Comments:	
2018 - Spring : No Change	
Comments:	
2018 - Fall: No Change	
Comments:	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
Н	aircell TSI	1000	LF	air tunnels, unexcavated area (1955 addition)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change			
Comments:Area still the same			
2017 - Fall: No Change			
Comments:			
2017 - Spring: No Change			
Comments:No Change			
2018 - Fall: No Change			
Comments:			
2018 - Spring : No Change			
Comments:		•	
	•	•	

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
I	air cell joints & fittings	100	FITTING	boiler room, air chamber, unexcavated area (1950 bldg)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Fall: No Change
Comments:
2017 - Spring: No Change
Comments:No Change
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

HA No	Material Description	Material Quantity	Material Units	Material Location	Asbestos Type	Material Category	Friable	Damage Type	Damage Quantity	Damage Units	Change in Assessment Category
J	aircell TSI joints and fittings	100	FITTING	air tunnels, unexcavated areas (1955 addition)		TSI	Yes	None	0		YES X NO

2016 - Fall: No Change
Comments:Area still the same
2017 - Spring: No Change
Comments:NoChange
2017 - Fall: No Change
Comments:
2018 - Spring : No Change
Comments:
2018 - Fall: No Change
Comments:

Page 20

ALL LEA Responsibilities, for this school, will be met.

Robert Christlieb

NOTICE TO PARENTS AND STAFF REGARDING THE ASBESTOS MANAGEMENT PLAN NOTIFICATION

School: Jesse Sherwood Elementary School
Date: 12/11/2018
This is to notify you in accordance with Illinois and Federal Asbestos Regulations, that a copy of the Asbestos Management Plan is available at each school during school hours by appointment. Requests to review the Asbestos Management Plan must be made at least 24 hours in advance.
Also please be advised that CPS conducts asbestos inspections of all Schools every three years. The last inspection was completed in 2016. Asbestos surveillances are conducted every six months.
CHECK ONE
A copy of this notice was sent home in each child's backpack.
X A copy of this notice was printed in the school's newsletter and sent home with each child
A copy of this notice was printed in the school's calendar and sent home with each child
Other.
A COPY OF THIS NOTICE MUST BE PLACED IN THE

VFT = Vinyl Floor Tile
Oracle Unit: 25351

SCHOOL'S ASBESTOS MANAGEMENT PLAN.